E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	· •	E&A - P20 ²	19.328.000		
Inspector: Jason Brackett					Stage
		Bridgepor	t Development		
			1228-3910-GP1		4
					1
Project Name:		CSW-2	201701381		
For Week Ending:		68136			
Project Location:					
			I S 180th Street, Sarpy Cour	,,	
Grading:	100%	, 0			
Sanitary Sewer:	100%	0			
Storm Sewer:	100%	0			
Paving:	95%	0			
Seeding:	75%				
Utilities:	100%	ó			
Overall Development:	60%	0			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"			+	
	0.00"	11/4/2020	Mostly Sunny 76/40	44.45 AM	
Wednesday: Thursday:	0.00"	11/4/2020	Mostly Sunny 76/40	11:15 AM	
Friday:	0.00"				
Saturday:	0.00"				
	0.00		ł		
Construction Sequencing: Which portion(s) (i.e. drainage ba Grading in Phase I was com	asins) of the site have had a temp		ation of grading, earthwork, or grou	Ind disturbance in the las	t 14 days?
			d disturbance scheduled in the nex	t 14 days?	
Grading in Phase I was com					
What temporary or permanent sta	abilization measures listed in this	s section are being impler	nented?		
			/20). Trails/sidewalks around	the site were backfille	d and partially matted
Checklist Questions:					
	the project free of any significant	t signs of erosion or sodir	nent that would be associated with	the construction activity	2
Yes	the project nee of any significant	signa or erosion or seuli	חיסות לומנ איטעוע של מססטטומוכע Willi	and construction activity	•
Create Corrective Action?					
N/A					
			ns of the project and if stabilization		
No. Void areas around the s Create Corrective Action?	site were seeded and partial	ly matted prior to the 2	1/27/20 inspection, the inspect	or will monitor growth	
No, See Findings section.					
Are waste materials (concrete, co	onstruction material, hazardous,	etc.) being managed prop	erly?		
No					
Create Corrective Action?					
No, See BMPs and Findings	s section.				
Are construction anti-	discont atracta baing maintaine	Ladaguatalu?			
Are construction entrances and a	aujacent streets being maintained				
No					

Crea	te Co	rrectiv	e Act	ion?
No,	See	BMP	sect	ion.

s dust associated with the construction activity adequately controlled on the site?

Yes Create Corrective Action?

N/A

. ., / .

Comments:

Comments: Site was active for homebuilding during the most recent inspection. Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

2) All inactive areas of the site that have no planned ground disturbance within 14 days need to be stabilized.

A. Overgraded lots during homebuilding need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and as-needed. Not done as of the last inspection. All builders were reminded on 5/19/20, 6/20/20, 8/5/20.

B. Void areas south of Camelback Ave need to be stabilized and erosion at the southwest section of the wetland needs to be repaired and stabilized. Gene Graves was informed to complete by 6/1/20. Not done as of the last inspection. Gene Graves was reminded on 6/12/20. Void areas along the south of Camelback have been removed as of the 9/9/20 inspection due to active grading of the property to the south.

3) Trash dumpsters on site need to be emptied if they are above the fill line and trash needs to be picked up to prevent trash and debris from blowing around the site. All builders were informed to complete by 2/12/20. Not done as of the last inspection. All builders were reminded on 5/19/20, 6/20/20, 8/5/20.

A. Trash needs to be picked up around the site. Gene Graves was informed to complete by 5/25/20. Not done as of the last inspection. Gene Graves was reminded on 6/12/20.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
AI 1	Area Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S prevent flooding the inlet		et protection prior to the 4/23/2 nstalled.	20 inspection. Inlet of	Irains to SB 2, to
AI 2	Area Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Commercial S prevent flooding the inlet		et protection prior to the 4/23/2	20 inspection. Inlet o	frains to SB 2, to
AI 3	Area Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - The area inlet inspection.	protection is now incluc	ed with the new grading proje	ect to the south of Bri	dgeport as of the 9/9
AI 4	Area Inlet Protection	See SWPPP	3/12/2020	Active	No
Current Condition:			0 inspection. To prevent floo W is recommended in the find		nlet protection will b
AI 5	Area Inlet Protection	See SWPPP	8/12/2020	Active	No
Current Condition:	installed around the inlet p	prior to the 8/12/20 inspe	eeded/matted prior to the 4/23 action.	3/20 inspection. A si	It fence wrap was
AI 6	Area Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - The area arou	nd the inlet was seeded	/matted prior to the 4/23/20 in	spection.	•
	Stabilized Construction	Cornhusker and S			
CE 1	E se fan a se a se	404-101	1/10/2020	Developer	No
Current Condition:	entrance. The inspector v inspection.	vill monitor trackout and	continue to recommend stree		necessary at the
Current Condition:	Pending - Due to the likely entrance. The inspector v inspection. Stabilized Construction Entrance	/ probability that the Co vill monitor trackout and Cornhusker and S 184th Street	nty Road project will start so continue to recommend stree 1/10/2020	on, rock is no longer et cleaning as-neede Pending	necessary at the d as of the 3/12/20 Yes
Current Condition:	Pending - Due to the likely entrance. The inspector v inspection. Stabilized Construction Entrance Pending - Commercial Se event that the entrance is The entrance needs to be	/ probability that the Co vill monitor trackout and Cornhusker and S 184th Street eding closed off the ent improperly used in the f further closed off. *A s ed to complete by 5/25/2	nty Road project will start so continue to recommend stree 1/10/2020 rance prior to the 4/15/20 insp	on, rock is no longer et cleaning as-neede Pending pection. CE 2 will rer ack Ave should be ir	necessary at the d as of the 3/12/20 Yes nain on this report in installed.
Current Condition: CE 2 Current Condition: CW 1	Pending - Due to the likely entrance. The inspector v inspection. Stabilized Construction Entrance Pending - Commercial Se event that the entrance is The entrance needs to be Gene Graves was informe 6/12/20. All builders were Concrete Washout	/ probability that the Co vill monitor trackout and Cornhusker and S 184th Street eding closed off the ent improperly used in the f further closed off. *A s ed to complete by 5/25/2 informed on 6/20/20. Lot 56	Inty Road project will start so continue to recommend stree 1/10/2020 rance prior to the 4/15/20 insp uture. ign directing traffic to Camelb 0. Not done as of the last ins 1/3/2020	on, rock is no longer et cleaning as-neede Pending pection. CE 2 will rer ack Ave should be in pection. Gene Grav Active	necessary at the d as of the 3/12/20 Yes nain on this report in istalled. es was reminded or Yes
Current Condition: CE 2 Current Condition:	Pending - Due to the likely entrance. The inspector vinspection. Stabilized Construction Entrance Pending - Commercial Se event that the entrance is The entrance needs to be Gene Graves was informe 6/12/20. All builders were Concrete Washout Fair Condition - A lot level began cleaning out the co Seeding finished cleaning prior to the 9/22/20 inspect Rock needs to be added to Gene Graves was informed	v probability that the Coving vill monitor trackout and Cornhusker and S 184th Street eding closed off the entimproperly used in the further closed off. *A s ed to complete by 5/25/2 informed on 6/20/20. Lot 56 concrete washout prior to out the washout prior to out the washout prior to out the approach for the complete by 1/10/2 ed to comple	Inty Road project will start so continue to recommend stree 1/10/2020 rance prior to the 4/15/20 insp uture. ign directing traffic to Camelb 0. Not done as of the last ins 1/3/2020 installed on Lot 56 prior to the the 6/16/20 inspection, the ins o the 6/19/20 inspection. Gen concrete washout to prevent tr 0. Not done as of the last ins	on, rock is no longer et cleaning as-neede Pending pection. CE 2 will rer ack Ave should be in pection. Gene Grav Active a 1/3/20 inspection. of spector will continue e Graves cleaned ou ackout when in use. pection. Commercia	necessary at the d as of the 3/12/20 Yes nain on this report in istalled. es was reminded or Yes Commercial Seeding to monitor. Comme it the concrete wash
Current Condition: CE 2 Current Condition: CW 1	Pending - Due to the likely entrance. The inspector vinspection. Stabilized Construction Entrance Pending - Commercial Se event that the entrance is The entrance needs to be Gene Graves was informe 6/12/20. All builders were Concrete Washout Fair Condition - A lot level began cleaning out the co Seeding finished cleaning prior to the 9/22/20 inspect Rock needs to be added to Gene Graves was informed	v probability that the Coving vill monitor trackout and Cornhusker and S 184th Street eding closed off the entimproperly used in the further closed off. *A s ed to complete by 5/25/2 informed on 6/20/20. Lot 56 concrete washout prior to out the washout prior to out the washout prior to out the approach for the complete by 1/10/2 ed to comple	Inty Road project will start so continue to recommend stree 1/10/2020 rance prior to the 4/15/20 insp uture. ign directing traffic to Camelb 0. Not done as of the last ins 1/3/2020 installed on Lot 56 prior to the the 6/16/20 inspection, the ins o the 6/19/20 inspection. Gen	on, rock is no longer et cleaning as-neede Pending pection. CE 2 will rer ack Ave should be in pection. Gene Grav Active a 1/3/20 inspection. of spector will continue e Graves cleaned ou ackout when in use. pection. Commercia	necessary at the d as of the 3/12/20 Yes nain on this report in istalled. es was reminded or Yes Commercial Seeding to monitor. Comme it the concrete wash

	Inlat Destantion Cap OM/DDD Destantial
IP 2 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to SB 1, to
Current Contaition.	prevent flooding the inlet protection will not be reinstalled.
IP 3	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 4	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 5	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
ID C	
IP 6 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to SB 1, to
Current Condition.	prevent flooding the inlet protection will not be reinstalled.
IP 7	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 8	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 9	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 10	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 11	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroundir area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 12	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroundir
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 13	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroundir
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 14	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroundir
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 15	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroundir area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 16	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/12/20 inspection. Inlet drains to a basin and the surround
ourion contaition.	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 17	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/12/20 inspection. Inlet drains to a basin and the surround
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 18	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled. See SW 3.
IP 19	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled. See SW 3.
IP 20	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to prevent flooding the inlet protection will not be reinstalled.
ID 94	
IP 21 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to See SWPPP
	prevent flooding the inlet protection will not be reinstalled.
IP 22	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to
	prevent flooding the inlet protection will not be reinstalled.
IP 23	Inlet Protection See SWPPP Removed
	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to
Current Condition:	Removed - Commercial Geeding removed the milet protection phon to the 4/25/20 mspection. Thier drains to OD 4, to
Current Condition:	prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed Removed

Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled.	r, 10
IP 25	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled.	4, to
IP 26	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled.	4, to
IP 27	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled.	4, to
IP 28	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled.	4, to
IP 29	Inlet Protection See SWPPP 1/3/2020 Active N	١o
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding maintain inlet protection prior to the 4/23/20 inspection.	ined th
IP 30	Inlet Protection See SWPPP 1/3/2020 Active N	١o
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding maintain inlet protection prior to the 4/23/20 inspection.	ined th
IP 31	Inlet Protection See SWPPP 1/3/2020 Active N	lo
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding maintai inlet protection prior to the 4/23/20 inspection. Sudbeck cleaned out the inlet protection prior to the 8/5/20 inspection.	
IP 32	Inlet Protection See SWPPP 1/3/2020 Active N	١o
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding maintain inlet protection prior to the 4/23/20 inspection. Sudbeck cleaned out the inlet protection prior to the 8/5/20 inspection.	
IP 33	Inlet Protection See SWPPP 1/3/2020 Active N	No
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding maintain inlet protection prior to the 4/23/20 inspection. Sudbeck cleaned out the inlet protection prior to the 8/5/20 inspection.	ined th
IP 34	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB {	5 to
Current Condition.	prevent flooding the inlet protection will not be reinstalled.	5, 10
IP 35	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB \$	5 to
	prevent flooding the inlet protection will not be reinstalled.	0,10
IP 36	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB s prevent flooding the inlet protection will not be reinstalled.	5, to
IP 37	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB s prevent flooding the inlet protection will not be reinstalled.	5, to
IP 38	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB s prevent flooding the inlet protection will not be reinstalled.	5, to
IP 39	Inlet Protection See SWPPP Removed	
Current Candition	Inier Florection See SWFFF Itemoved	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB sprevent flooding the inlet protection will not be reinstalled.	5, to
IP 40	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB	5, to
	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB s prevent flooding the inlet protection will not be reinstalled.	
IP 40	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB sprevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB sprevent flooding the inlet protection will not be reinstalled.	
IP 40 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB sprevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB see SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB sprevent flooding the inlet protection will not be reinstalled.	5, to
IP 40 Current Condition: IP 41 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the star area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.	5, to
IP 40 Current Condition: IP 41 Current Condition: IP 42	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the si area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed	5, to urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.	5, to urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 8 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 8 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 8 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed	5, to urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the starea is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.	5, to urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the se area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the se area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the se area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Inlet Protection See SWPPP Removed - IP 43 drains to SB 5, no inlet protection is needed at this time. <td>5, to urrour</td>	5, to urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43 Current Condition: IP 44	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed - IP 43 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP <td< td=""><td>5, to urrour</td></td<>	5, to urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43 Current Condition: IP 44 Current Condition: IP 45 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - IP 43 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection prior to the 8/5/200 inspection. See SWPPP Removed	5, to urrour urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43 Current Condition: IP 44 Current Condition: IP 45 Current Condition: IP 45 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - IP 43 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP	5, to urrour urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43 Current Condition: IP 44 Current Condition: IP 45 Current Condition: IP 45 Current Condition: Lot 1 Replat 1 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - IP 43 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protections prior to the 8/5/200 inspection. Memoved N	5, to urrour urrour
IP 40 Current Condition: IP 41 Current Condition: IP 42 Current Condition: IP 43 Current Condition: IP 44 Current Condition: IP 45 Current Condition: IP 45 Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 5 prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the st area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed Removed - IP 43 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP Removed Removed - IP 44 drains to SB 5, no inlet protection is needed at this time. Inlet Protection See SWPPP	5, to urrour urrour

			avation of the pool area prio eplat 2 as of the 8/20/20 insp		on. SF 4 is in plac
Lot 8	Individual Lot	Lot 8		Removed	
Current Condition:	Removed - Mercury Cont	ractors sodded the lot pr	rior to the 9/22/20 inspection).	
Lot 8 Replat 1	Individual Lot	Lot 8 Replat 1	2/5/2020	Active	No
Current Condition:		spection. Fools Inc remo	rior to the 2/5/20 inspection wed the silt fence in prepara		
Lot 18	Individual Lot	Lot 18		Removed	
Current Condition:	Removed - Hildy Homes		e 5/13/20 inspection.		
Lot 27	Individual Lot	Lot 27	1/3/2020	Active	Yes
Current Condition:	installed silt fence in the r fence in the rear of the lo construction of the adjoin 1.) The silt fence in the n	rear of the lot and in the r t was observed during th ing lot. ortheast corner of the lot or the lot should be sodde	ruction on the lot prior to the northeast corner prior to the le 8/5/20 inspection, the insp needs to be extended along ed. *Straw wattles would als	1/3/20 inspection. Min bector will recommend r g the north side of the lo	or damage to the s naintenance during of and hooked part-
	 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 	nce should be installed i were informed to complet 20, 9/17/20.	n the front of the lot to preve te by 1/10/20. Not done as te by 6/17/20. Not done as	of the last inspection. N	lercury was remin
Lot 34	Individual Lot	Lot 34		Removed	
Current Condition:	Removed - McCaul sodd	ed the lot prior to the 9/2	/20 inspection.		
Lot 51	Individual Lot	Lot 51	4/27/2020	Active	No
Current Condition:	corner of the lot adjacent	to the curb inlet prior to t od prior to the 9/30/20 in	or to the 4/27/20 inspection. the 7/29/20 inspection. Lan spection, the inspector will i	dmark Performance Gr	oup removed the s
Lot 59	Individual Lot	Lot 59		Removed	
Current Condition:	Removed - Hildy Homes		e 8/20/20 inspection.		
Lot 60	Individual Lot	Lot 60		Removed	
Current Condition:	Removed - Kavan Home	s sodded the lot prior to t	the 7/1/20 inspection.		
Lot 64	Individual Lot	Lot 64		Removed	
Current Condition:	Removed - Kavan Home				
Lot 66	Individual Lot	Lot 66	6/1/2020	Active	No
Current Condition:	installed silt fence in the r	rear of the lot prior to the			
Lot 67	Individual Lot	Lot 67	7/1/2020	Active	No
Current Condition:	installed silt fence in the r		xcavation of the lot prior to the 7/1/20 inspection.	he 7/1/20 inspection. T	he unidentified bui
Lot 70	Individual Lot	Lot 70		Removed	
Current Condition:	Removed - Kavan Home	1	the 7/15/20 inspection.		
Lot 73	Individual Lot	Lot 73		Removed	
Current Condition:			t prior to the 4/27/20 inspect		N ₂ -
Lot 80 Current Condition:		rear of the lot prior to the	4/23/2020 ion of the lot prior to the 4/2 4/23/20 inspection. Nielser 6/20 inspection.		
		reinstalled on either side	om the curb inlet. e of the retaining wall below plete by 6/8/20. Not done as	Ŭ	Nielsen was remin
	2.) Nielsen Custom Hom		blete by 9/23/20. Not done a		
Lot 82	Individual Lot	Lot 82	7/23/2020	Active	No
	Active - Landmark began	construction on the lot p	prior to the 7/23/20 inspectio	n. Landmark installed	silt fence in the rea
Current Condition:	the lot prior to the 8/12/20 installation of the retainin installation of the retainin	0 inspection, the silt fence g wall, the inspector will g wall prior to the 9/30/20	e is not behind all of the gro monitor. Landmark Perform 0 inspection, the inspector v	und disturbance to mak nance Group removed t	he silt fence for
	the lot prior to the 8/12/20 installation of the retainin	0 inspection, the silt fence g wall, the inspector will g wall prior to the 9/30/20	e is not behind all of the gro monitor. Landmark Perform	und disturbance to mak nance Group removed t	he silt fence for

Current Condition:	the lot and will be attribute	ed to Echelon Homes in	n of the lot prior to the 10/28/ the area as of the 10/28/20 in or will monitor for removal.		· · · · ·
	The silt fence in the rea	r of the lot needs to be	repaired.		
	Echelon Homes was inf				
Lot 86	Individual Lot	Lot 86	7/23/2020	Active	No
Current Condition:			n on the lot prior to the 7/23/2 nspection and will now be attr		ting SF 4 in the ai
Lot 87	Individual Lot	Lot 87	ispection and will now be att	Removed	
Current Condition:	Removed - Hildy Homes		e 3/12/20 inspection.	Kenloved	
Lot 89	Individual Lot	Lot 89	7/23/2020	Active	No
Current Condition:			n on the lot prior to the 7/23/2		
			vill be recommended to Hildy		
Lot 91	Individual Lot	Lot 91	4/1/2020	Active	No
Current Condition:			construction on the lot prior	to the 4/1/20 inspection	. The lot backs u
			the area will be sent to Adva		
Lot 93	Individual Lot	Lot 93		Removed	
Current Condition:	Removed - Hildy Constru	ction sodded the lot prio	r to the 9/22/20 inspection.		
Lot 94 Current Condition:	Individual Lot	Lot 94	1/3/2020 the lot prior to the 1/3/20 ins	Active	Yes
	of the lot prior to the 4/27	/20 inspection.	the 4/23/20 inspection. Land		
			o complete by 11/11/20.		
Lot 95	Individual Lot	Lot 95		Removed	
Current Condition:	Removed - Vencil sodded			A	NI-
Lot 100 Current Condition:	Individual Lot	Lot 100	9/30/2020 ne lot prior to the 9/30/20 insp	Active	No
Lot 119	Individual Lot	Lot 119	ot is relatively flat, the insp 2/18/2020 on the lot prior to the 2/18/20	Active	Yes
	 Silt fence or straw wat The silt fence in the re The sidewalk needs to Ideal was informed to 9/17/20. Ideal was informed to 	tles need to be extended ear of the lot is damaged be cleaned. complete by 4/8/20. No complete by 6/17/20. N	/undermined and needs to be t done as of the last inspectic ot done as of the last inspect	e backfilled/repaired. on. Ideal was reminded ion. Ideal was reminde	on 5/19/20, 6/11,
	3.) Ideal was informed to	complete by 9/17/20. N	ot done as of the last inspect	ion	
Lot 126					
	Individual Lot	Lot 126		Removed	
Current Condition:	Removed - Belt Construc	tion sodded the lot prior		Removed	
Lot 128	Removed - Belt Construc Individual Lot	tion sodded the lot prior Lot 128	to the 5/6/20 inspection.		
	Removed - Belt Construc	tion sodded the lot prior Lot 128	to the 5/6/20 inspection.	Removed	Yes
Lot 128 Current Condition:	Removed - Belt Construc Individual Lot Removed - Belt Construc Individual Lot Fair Condition - Carder C SF 4 in the rear, any new inspection. The silt fence	tion sodded the lot prior Lot 128 tion sodded the lot prior Lot 131 onstruction builder bega maintenance to SF 4 in the rear of the lot wa as of the 9/16/20 inspect	to the 5/6/20 inspection. to the 7/23/20 inspection. 4/23/2020 In excavation of the lot prior to the area will be sent to the bi s maintained prior to the 9/16 tion. Carder Construction models	Removed Removed Active o the 4/23/20 inspection uilder when identified a 5/20 inspection. Wattle	Yes 1. The lot backs u s of the 4/23/20 s do not appear
Lot 128 Current Condition: Lot 131	Removed - Belt Construct Individual Lot Removed - Belt Construct Individual Lot Fair Condition - Carder C SF 4 in the rear, any new inspection. The silt fence necessary along the trail a prior to the 9/22/20 inspect 1.) The silt fence is ripped 2.) The portable toilet new 1.) Carder Construction w	tion sodded the lot prior Lot 128 tion sodded the lot prior Lot 131 onstruction builder bega maintenance to SF 4 in in the rear of the lot was as of the 9/16/20 inspect ction, the portable toilet d in the rear of the lot an eds to be secured.	to the 5/6/20 inspection. to the 7/23/20 inspection. 4/23/2020 In excavation of the lot prior t the area will be sent to the bi s maintained prior to the 9/16 tion. Carder Construction mo still needs to be secured. d needs to be patched.	Removed Removed Active o the 4/23/20 inspection uilder when identified a //20 inspection. Wattle oved the portable toilet	Yes n. The lot backs u s of the 4/23/20 s do not appear back from the RO
Lot 128 Current Condition: Lot 131	Removed - Belt Construct Individual Lot Removed - Belt Construct Individual Lot Fair Condition - Carder C SF 4 in the rear, any new inspection. The silt fence necessary along the trail a prior to the 9/22/20 inspect 1.) The silt fence is ripped 2.) The portable toilet need 1.) Carder Construction was reminded on 9/17/20. No Individual Lot	tion sodded the lot prior Lot 128 tion sodded the lot prior Lot 131 onstruction builder bega maintenance to SF 4 in in the rear of the lot wa as of the 9/16/20 inspect ction, the portable toilet s d in the rear of the lot an adds to be secured. vas informed to complete vas informed to complete to done as of the last insp Lot 133	to the 5/6/20 inspection. to the 7/23/20 inspection. 4/23/2020 In excavation of the lot prior t the area will be sent to the bill s maintained prior to the 9/16 tion. Carder Construction mo- still needs to be secured. d needs to be patched. by 9/23/20. by 9/23/20. by 7/22/20. Not done as of pection. 10/13/2020	Removed Removed Active o the 4/23/20 inspection uilder when identified a i/20 inspection. Wattle oved the portable toilet the last inspection. Ca Active	Yes n. The lot backs u s of the 4/23/20 s do not appear back from the RO rder Construction No
Lot 128 Current Condition: Lot 131 Current Condition:	Removed - Belt Construct Individual Lot Removed - Belt Construct Individual Lot Fair Condition - Carder C SF 4 in the rear, any new inspection. The silt fence necessary along the trail a prior to the 9/22/20 inspect 1.) The silt fence is ripped 2.) The portable toilet need 1.) Carder Construction w 2.) Carder Construction w reminded on 9/17/20. No Individual Lot Active - Buckland Homes lot and will be attributed	tion sodded the lot prior Lot 128 tion sodded the lot prior Lot 131 onstruction builder bega maintenance to SF 4 in in the rear of the lot wai as of the 9/16/20 inspect ction, the portable toilet s d in the rear of the lot an adds to be secured. vas informed to complete vas informed to complete to a so of the last insp Lot 133 began excavation of the d to Buckland Homes i	to the 5/6/20 inspection. to the 7/23/20 inspection. 4/23/2020 In excavation of the lot prior t the area will be sent to the bill s maintained prior to the 9/16 tion. Carder Construction mo- still needs to be secured. d needs to be patched. by 9/23/20. by 9/23/20. by 7/22/20. Not done as of bection. 10/13/2020 bot prior to the 10/13/20 insp n the area as of the 11/4/20	Removed Removed Active o the 4/23/20 inspection uilder when identified a /20 inspection. Wattle oved the portable toilet the last inspection. Ca Active pection. SF 4 is in plac inspection. Dirt piles	Yes n. The lot backs us s of the 4/23/20 s do not appear back from the RO back from the RO where construction No the in the rear of to were observed in
Lot 128 Current Condition: Lot 131 Current Condition: Lot 133	Removed - Belt Construct Individual Lot Removed - Belt Construct Individual Lot Fair Condition - Carder C SF 4 in the rear, any new inspection. The silt fence necessary along the trail a prior to the 9/22/20 inspect 1.) The silt fence is ripped 2.) The portable toilet need 1.) Carder Construction w 2.) Carder Construction w reminded on 9/17/20. No Individual Lot Active - Buckland Homes lot and will be attributed	tion sodded the lot prior Lot 128 tion sodded the lot prior Lot 131 onstruction builder bega maintenance to SF 4 in in the rear of the lot wai as of the 9/16/20 inspect ction, the portable toilet s d in the rear of the lot an adds to be secured. vas informed to complete vas informed to complete to a so of the last insp Lot 133 began excavation of the d to Buckland Homes i	to the 5/6/20 inspection. to the 7/23/20 inspection. 4/23/2020 In excavation of the lot prior t the area will be sent to the bill s maintained prior to the 9/16 tion. Carder Construction mo- still needs to be secured. d needs to be patched. by 9/23/20. by 9/23/20. by 7/22/20. Not done as of bection. 10/13/2020 bot prior to the 10/13/20 insp	Removed Removed Active o the 4/23/20 inspection uilder when identified a /20 inspection. Wattle oved the portable toilet the last inspection. Ca Active pection. SF 4 is in plac inspection. Dirt piles	Yes n. The lot backs us s of the 4/23/20 s do not appear back from the RO back from the RO where construction No the in the rear of to were observed in

Lot 135	Individual Lot	Lot 135		Removed	
Current Condition:	Removed - Landmark soc				
Lot 137 Current Condition:	Individual Lot	Lot 137	5/6/2020 on the lot and installed silt fe	Active	Yes
	 The silt fence in the re The portable toilet nee HBC was informed to 	ar of the lot needs to be ds to be moved 50 feet to complete by 6/17/20. No	cleaned out/repaired and ex	tion. HBC was remind	und disturbance. ed on 7/30/20, 9/1
SB 1 (Pond 5)	Sediment Basin	See SWPPP	1/3/2020	Active	Yes
Current Condition:			ed prior to the 1/3/20 inspect		
	Basin is full and needs to	be cleaned out.	. Not done as of the last ins		
SB 2 (Pond 4)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspec		-
SB 3 (Pond 3)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 2% filled	d - The basin was installe	ed prior to the 1/3/20 inspec	tion with a permanent	riser. A plug was
	installed in the upstream i	manhole prior to the 9/2/	20 inspection, the plug is wo	orking effectively.	
SB 4 (Pond 2)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			lled prior to the 1/3/20 inspe		t riser.
SB 5 (Pond 1)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			lled prior to the 1/3/20 inspe		t riser.
SF 1 Current Condition:	Silt fence	See SWPPP	fence prior to the 4/23/20 in	Removed	
SF 2	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		
SF 3	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Commercial S associated with Lot 64.	seeding removed the silt	fence prior to the 4/15/20 in	spection. The remain	ng silt fence will be
SF 4	Silt fence	See SWPPP	1/3/2020	Active	No
Current Condition:			he wetlands and drainagewa		nspection.
SF 5	Silt fence	See SWPPP	famore anima to the A/AE/00 in	Removed	
Current Condition: SF 6	Silt fence	See SWPPP	fence prior to the 4/15/20 in	spection. Removed	
Current Condition:			fence prior to the 4/15/20 in		
SF 7	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - The silt fence	is now included with the	new grading project to the s	south of Bridgeport as	of the 9/9/20 inspe
SF 8	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Silt fence was		/20 inspection.		
SF 9		See SWPPP	() · · · · · · · · · · · · · · · · · ·	Removed	
Current Condition: SF 10	Silt fence	See SWPPP	fence prior to the 4/15/20 in	spection. Removed	
Current Condition:			fence prior to the 4/15/20 in		<u> </u>
SF 11	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		
SF 12	Silt fence	See SWPPP		Removed	
Current Condition: SF 13	Removed - Commercial S Silt fence	See SWPPP	fence prior to the 4/15/20 in	spection. Removed	[
Current Condition:			fence prior to the 4/15/20 in		
SF 14 Current Condition:	Silt fence	See SWPPP	new grading project to the	Removed	of the 9/9/20 inspe
SW 1	Straw Wattles	See SWPPP	1/3/2020	Active	No
Current Condition: SW 2			the SW corner of Lot 39 pric 4/9/2020	or to the 1/3/20 inspect Active	
Current Condition:	Straw Wattles Good Condition - Straw w inspection.	See SWPPP attles were installed at the	he base of the slope west of		No ior to the 4/9/20
SW 3	Straw Wattles	See SWPPP	4/15/2020	Active	No
Current Condition:			traw wattles above the curb		-
		Internal/S 132nd and			

Current Condition:	Fair Condition -	Fair Condition -						
	Minor street cleaning is needed around active lots.							
	All builders were informed	All builders were informed to complete by 8/6/20. Not done as of the last inspection.						
		Camelback Ave and S						
SWPPP Sign	Misc/Other	180th Street	1/29/2020	Active	No			
Current Condition:	intersection of S 180th Statute 1/29/20 inspection. E	Good Condition - E&A inspector installed 3 SWPPP signs at the intersection of S 180th Street and Laquinta Street, at the intersection of S 180th Street and S 181st Street during the 1/29/20 inspection. E&A inspector relocated the SWPPP sign at the Laquinta Street entrance to the south side of the street during the 3/25/20 inspection.						
Inspector Signature:	Jule Month			Reviewed By:	Coto Sul			