E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

6:35 AM - 6:55 PM

7:20 AM

	Lot 19	E&A- P2005.030.000 95 P2005.030.024 (Repla	t 6)		
Inspector: Joe Manning		(- 1	,		Stage
		The Heritage	e.		1 and 3
Project Name:	NER110495				
-	7/8/2023				
For Week Ending:					
Project Location:	East of 156th St	68007			
	The Heritage	Lot 195/Replat 6			
Grading:	100%	90%			
Sanitary Sewer:	100%	95%			
Storm Sewer:	100%	80%			
Paving:	100%	90%			
Seeding:	0%	35%			
Utilities:	2%	80%			
Overall Development:	98%	45%			
RAIN FALL AMOUNTS	Amount in tenths	ate inspected	Weather Conditions	Time	Storm Event Duration
RAIN FALL AWOUNTS	Amount in tentis	ate inspected	Weather Conditions	Time	Storm Event Duration Wee
Sunday:	0.53"				1:00 AM - 4:00 A
Monday:	0.00"	6/12/2023	Sunny 76/50	2:55 PM	
Tuesday:	0.00"	6/13/2023	Sunny 82/58	12:05 PM	
Wednesday:	0.00"		, , , , , , , , , , , , , , , , , , ,		
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
outuruuy.	0.00				Wee
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	6/20/2023	Sunny 91/67	9:40 AM	
Wednesday:	0.00"		•		
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.01"				9:30 AM - 10:00
					Wee
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	6/27/2023	Sunny 85/61	9:50 AM	
Wednesday:	0.01"				5:55 AM - 6:15 A
Thursday:	0.32"				7:35 AM - 8:55 A
Friday:	0.45"	6/30/2023	Cloudy 85/66	1:15 PM	4:15 AM - 8:55 A
Saturday:	0.37"				10:55 AM - 5:55
Sundayı	0.00"				Wee
Sunday:	0.00"	7/2/2022	C	0.05 D25	
Monday:	0.00"	7/3/2023	Sunny 90/68	2:35 PM	
Tuesday:	0.17" 0.33"	7/4/2023 7/5/2023	Cloudy 92/69	9:45 AM 2:05 PM	12:55 AM - 6:55
Wednesday: Thursday:	0.00"	11512023	Showers 78/62	2:05 PW	12:55 AIVI - 6:55
i nursday: Friday:	0.00"				6:25 AM 6:55 D

Tuesday: N/A Wednesday: N/A Thursday: N/A Friday: N/A Saturday: N/A Complaints:

7/8/2023

Cloudy 78/54

0.74"

0.00"

N/A

N/A

Friday:

Saturday:

Sunday:

Monday:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/2006. Grading began on old school site east of Stargrass Road (11/9/2017). Grading activity on site idle (9/9/2020). Storm and sewer installation began in replat 6 (9/27/2021). Street paving in replat 6 (4/12/2022). Street paving in Rainwood Road (8/9/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/2006. Grading began on old school site east of Stargrass Road (11/9/2017). Grading activity on site idle (9/9/2020). Storm and sewer installation began in replat 6 (9/27/2021). Street paving in replat 6 (4/12/2022). Street paving in Rainwood Road (8/9/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Wetlands Mitigation Seeding (5/31/2006), Slopes Seeded/Matted (8/30/2006), Temp. Seeded (9/5/2006), Re-Seeded 5/21/2007, Re-Seeded ROW on 9/5/2007 & 11/14/2007, Erosion seeded in various areas (4/2009), Old Basin 5 was seeded and matted (5/2/2012). The areas that were disturbed when SB 3 and 5 were closed has been seeded (9/10/2016). Area surrounding SB#4 has been seeded (5/22/2018). Stub road at the end of N 149th Street seeded and matted (9/8/2020). Replat 6 was temp seeded (8/9/2021). Rainwood Road ROW and Basin seeded/matted (9/12/2022). Erosion matting was installed along side the riprap under Rainwood road and IP5 (4/17/2023). The entire site was seeded (6/20/23).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

- 1. Site was inactive for home building during the most recent inspection. Replat 6 was inactive for utility installation during the most recent inspection. The Rainwood Road project was inactive during the most recent inspection.
- 2. SB 4 is being partially closed to accommodate the dirt from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots. The basin was working effectively as of the 8/13/18 inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date)

- 1.) No maintenance is required in the BMP section.
- 2.) Commercial Seeding seeded the entire site prior to the inspection on 6/20/23.
- 3.) The lowlying area at the southeast end of rainwood road in Outlot G has a large section that is being eroded and undermining the matting. E&A Inspector informed the SID Department to repair, seed and re-matt the slope by 4/17/2023. E&A inspector will update the report when more information is known. Not done as of last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		Intersection of Rosewood and					
CE 1	Construction Entrance	Rainwood Road	11/21/2017	Pending	No		
Current Condition:	Pending - The inspector will recommend an entrance if it becomes necessary as of the 11/21/2017 inspection.						
CW 1	Concrete Washout	Lot 20		Removed			
Current Condition:	Removed - Boyer Young clea	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.					
CW 2	Concrete Washout	Lot 162		Removed			
Current Condition:	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.						
		Rosewater Prky and Chicory					
IF 1	Inlet Filter	St.		Removed			
Current Condition:	Removed - E&A inspector removed the inlet filter during inspection on 4/15/17.						
Lot 17	Individual Lot	Lot 17		Removed			
Current Condition:	Removed - Metro Homes sodded the lot prior to the inspection on 6/11/21.						
Lot 20	Individual Lot	Lot 20		Removed			
Current Condition:	Removed - Story Homes sodded the lot prior to the inspection on 6/26/21.						
Lot 22	Individual Lot	Lot 22		Removed			
Current Condition:	Removed - Metro Homes so	Removed - Metro Homes sodded the lot prior to the 6/7/22 inspection.					
Lot 24	Individual Lot	Lot 24		Removed			

Current Condition:	Removed - Story Homes soc	ided the lot prior to the 11/11/21	inspection.		
Lot 25	Individual Lot	Lot 25		Removed	
Current Condition:	Removed - Metro Homes so	dded the lot prior to the inspection	on on 6/11/21.		
SF 6	Silt Fence	SB 5		Removed	
Current Condition:	Removed - Commercial See	ding removed the silt fence prior	to the 10/9/18 inspection.	•	•
SF 7	Silt Fence	SB 3		Removed	
Current Condition:	Removed - SF 7 changed to	lot level item (lots 5 and 6) as o	f 5/15/18.		•
SF 8	Silt Fence	Rainwood Road		Removed	
Current Condition:		alled a silt fence check in front on. Boyer Young removed the sil			nce was repaired
SF 9	Silt Fence	The perimeter of the newly graded area		Removed	
Current Condition:	silt fence around the existing to inspection on 4/27/18. Silt inspection. Commercial See backfilled and repaired the si during the 8/12/19 inspectior inspection on 6/10/20. Cente 8/11/20. JBG reinstalled the		ction on 3/5/18. The silt fen int was cleaned up from ad he silt fence prior to the 11/1/ ection. E&A inspector retie out/trenched in the silt fenc id backfilled the undermine the inspection on 6/21/21.	ice in the SE corne jacent lots prior to 6/18 inspection. Co d the silt fence who is in multiple location d silt fence prior to Commercial Seedir	r was repaired prior the 8/13/18 pammercial Seeding ere it was damaged ons prior to the the inspection on ng fixed all silt fence
SB 3	Sediment Basin	South of Wild Indigo St and Prairie Star St.		Removed	
Current Condition:		osed prior to the 8/24/16 inspec			
SB 4	Sediment Basin	South of 149th Dead End	11/14/2005	Active	No
Current Condition:		- Roth Enterprise cleaned off the		nspection. Dustin R	toth removed
	southern riser and removed	dirt to restore drainage prior to in	rspection on 7/2/18.	ı	
		Southwest corner of			
SB 5	Sediment Basin	Rosewater Pkwy and North H.W.S Cleveland Blvd		Removed	
Current Condition:		osed prior to the 8/24/16 inspec	l tion	Removed	
STR	Street Cleaning	Entire Site	2/26/2007	Active	No
Current Condition:		es cleaned the street in front of			
	the street in front of Lot 22 pr	rior to the 3/14/22 inspection. Min Street prior to the 6/7/22 inspe	nino Homes cleaned 149th		
		Replat 6			<u> </u>
CE 1	Construction Entrance	Southwest corner	pion to the investigation of 0.00	Removed	
Current Condition:	Removed - Mark Hopkins pa	Southwest corner ved the construction entrance p		2/22.	No.
Current Condition: CE 2	Removed - Mark Hopkins pa Construction Entrance	Southwest corner ved the construction entrance p Northeast corner	5/27/2021	22/22. Active	No 5/24/22
Current Condition: CE 2 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co	5/27/2021	Active the inspection on	
Current Condition: CE 2	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co	5/27/2021 onstruction entrance prior to	Active o the inspection on Removed	
Current Condition: CE 2 Current Condition: D 1 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi	5/27/2021 Instruction entrance prior to the 5/17/22 insp	Active of the inspection on Removed ection.	5/24/22.
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rei Erosion Control Matting	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map	5/27/2021 construction entrance prior to the 5/17/22 insp 9/12/2022	2/22. Active the inspection on Removed ection. Active	5/24/22. No
Current Condition: CE 2 Current Condition: D 1 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rei Erosion Control Matting	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW	5/27/2021 construction entrance prior to the 5/17/22 insp 9/12/2022	2/22. Active the inspection on Removed ection. Active	5/24/22. No
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW	5/27/2021 construction entrance prior to the 5/17/22 insp 9/12/2022	2/22. Active the inspection on Removed ection. Active	5/24/22. No
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG	Active the inspection on Removed ection. Active e basin to the south Removed removed the fuel ta	No h of Rainwood prior ank from the site prior
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG	Active the inspection on Removed ection. Active e basin to the south Removed removed the fuel ta	No h of Rainwood prior ank from the site prior
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21.	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-w See Rainwood Rd	5/27/2021 Instruction entrance prior to the 5/17/22 insp g prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prio 8/9/2022	Active to the inspection on Removed ection. Active e basin to the south Removed removed the fuel tar to the inspection on Pending	No h of Rainwood prior ank from the site prior on 9/26/22.
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21.	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map	5/27/2021 Instruction entrance prior to the 5/17/22 insp g prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prio 8/9/2022	Active to the inspection on Removed ection. Active e basin to the south Removed removed the fuel tar to the inspection on Pending	No h of Rainwood prior ank from the site prior on 9/26/22.
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on12/6/21. Inlet Protection Good Condition - Commercial	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map al Seeding installed inlet protecti	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior 8/9/2022 ion prior to the inspection of 4/3/2023	Active The inspection on Removed Ection. Active Expected basin to the south Removed Temoved the fuel tar to the inspection of Pending The 6/20/23. Pending	No h of Rainwood prior ank from the site prior on 9/26/22.
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rel Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on12/6/21. Inlet Protection Good Condition - Commercial	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-w See Rainwood Rd SWPPP Map See Rainwood Rd SWPPP Map al Seeding installed inlet protection	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior 8/9/2022 ion prior to the inspection of 4/3/2023	Active The inspection on Removed Ection. Active Expected basin to the south Removed Removed Temoved the fuel tar to the inspection Pending In 6/20/23. Pending	No h of Rainwood prior ank from the site prior on 9/26/22.
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins ret Erosion Control Matting Good Condition - Bluffs Pavito the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection Good Condition - Commercial Inlet Protection Good Condition - Commercial Inlet Protection	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-w See Rainwood Rd SWPPP Map al Seeding installed inlet protectic Along Hibbs st al Seeding installed inlet protectic	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior 8/9/2022 ion prior to the inspection of 4/3/2023 on prior to the inspection of 4/3/2023	Active The inspection on Active The inspection on Removed The inspection Active The basin to the south Removed The fuel tarnot the inspection of the inspect	No h of Rainwood prior ank from the site prior on 9/26/22. No
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition: IP 5	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins ret Erosion Control Matting Good Condition - Bluffs Pavito the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection Good Condition - Commercial Inlet Protection Good Condition - Commercial Inlet Protection	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior 8/9/2022 ion prior to the inspection of 4/3/2023 on prior to the inspection of 4/3/2023	Active The inspection on Active The inspection on Removed The inspection Active The basin to the south Removed The fuel tarnot the inspection of the inspect	No h of Rainwood prior ank from the site prior on 9/26/22. No
Current Condition: CE 2 Current Condition: D1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition: IP 5 Current Condition: PT 01 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rei Erosion Control Matting Good Condition - Bluffs Pavito the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection Good Condition - Commercial Portable Toilet Removed - Mark Hopkins in to the east side of CE 1 prior 12/6/21. Mark Hopkins remo	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Adjacent to CE 2 stalled and secured a portable to the 11/11/21 inspection. Marved the portable toilet prior to the	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior to the inspection on 4/3/2023 on prior to the inspection on 4/3/2023 on prior to the inspection on the inspection of the inspection.	Active the inspection on Removed ection. Active e basin to the south Removed removed the fuel to the inspection of Pending n 6/20/23. Pending n 6/20/23. Removed on 9/27/21. Portable table toilet prior to the inspection of the south of the	No h of Rainwood prior ank from the site prior on 9/26/22. No No No le toilet was moved the inspection on
Current Condition: CE 2 Current Condition: D1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition: IP 5 Current Condition: PT 01 Current Condition: PT 01 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rei Erosion Control Matting Good Condition - Bluffs Pavito the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection Good Condition - Commercial Portable Toilet Removed - Mark Hopkins in to the east side of CE 1 prior 12/6/21. Mark Hopkins remo	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti to the 11/11/21 inspection. Marved the portable to the	5/27/2021 construction entrance prior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior by the inspection of 4/3/2023 con prior to the inspection of 4/3/2023	Active a the inspection on Removed ection. Active be basin to the south Removed removed the fuel to the inspection of Pending an 6/20/23. Pending an 6/20/23. Pending an 6/20/23. Removed on 9/27/21. Portable table toilet prior to the south	No h of Rainwood prior ank from the site prior on 9/26/22. No No No No No No No No No N
Current Condition: CE 2 Current Condition: D1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition: IP 5 Current Condition: PT 01 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rei Erosion Control Matting Good Condition - Bluffs Pavito the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection Good Condition - Commercial Inlet Protection Goo	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Adjacent to CE 2 stalled and secured a portable to the 11/11/21 inspection. Marved the portable toilet prior to the	5/27/2021 Instruction entrance prior to the 5/17/22 insp g/12/2022 If of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior to the inspection of 4/3/2023 If on prior to the inspection of 4/3/2023 If a prior to the inspection of the inspection. 2/6/2023 If a prior to the inspection.	Active the inspection on Removed ection. Active e basin to the south Removed removed the fuel to r to the inspection of Pending in 6/20/23. Pending in 6/20/23. Pending in 6/20/23. Removed on 9/27/21. Portable table toilet prior to to	No h of Rainwood prior ank from the site prior on 9/26/22. No No No No No No A A A A A A A A A A A A A
Current Condition: CE 2 Current Condition: D1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition: IP 5 Current Condition: PT 01 Current Condition: PT 01 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins rei Erosion Control Matting Good Condition - Bluffs Pavito the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on 12/6/21. Inlet Protection Good Condition - Commercia Portable Toilet Removed - Mark Hopkins in to the east side of CE 1 prior 12/6/21. Mark Hopkins remo Portable Toilet Removed - Mark Hopkins an was placed on site prior to the	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-v See Rainwood Rd SWPPP Map al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti to the 11/11/21 inspection. Marved the portable to illet prior to the On Site d Steve Minino removed the poi	5/27/2021 Instruction entrance prior to the 5/17/22 insp g/12/2022 If of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior to the inspection of 4/3/2023 If on prior to the inspection of 4/3/2023 If a prior to the inspection of the inspection. 2/6/2023 If a prior to the inspection.	Active the inspection on Removed ection. Active e basin to the south Removed removed the fuel to r to the inspection of Pending in 6/20/23. Pending in 6/20/23. Pending in 6/20/23. Removed on 9/27/21. Portable table toilet prior to to	No h of Rainwood prior ank from the site prior on 9/26/22. No No No No No No A A A A A A A A A A A A A
Current Condition: CE 2 Current Condition: D 1 Current Condition: EM 1 - 2 Current Condition: FT 1 Current Condition: IP 1 - 2 Current Condition: IP 3 - 4 Current Condition: IP 5 Current Condition: PT 01 Current Condition: PT 01 Current Condition:	Removed - Mark Hopkins pa Construction Entrance Good Condition - 85% effecti Diversion Ditch Removed - Mark Hopkins ret Erosion Control Matting Good Condition - Bluffs Pavi to the inspection on 9/12/22. Fuel Tank Removed - JBG installed the to the inspection on12/6/21. Inlet Protection Good Condition - Commercia Portable Toilet Removed - Mark Hopkins remo Portable Toilet Removed - Mark Hopkins an was placed on site prior to th 4/10/23.	Southwest corner ved the construction entrance p Northeast corner ive - Mark Hopkins installed a co South of SB 4 moved the diversion during pavi See Rainwood Rd SWPPP Map ng seeded and matted the ROW On site e fuel tank on site prior to the ins Mark Hopkins placed a double-w See Rainwood Rd SWPPP Map al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Along Hibbs st al Seeding installed inlet protecti Aljacent to CE 2 stalled and secured a portable to to the 11/11/21 inspection. Marved the portable toilet prior to the On Site d Steve Minino removed the pole inspection on 2/06/23. Mark H	5/27/2021 construction entrance prior to the 5/17/22 insp grior to the 5/17/22 insp g/12/2022 / of Rainwood Road and the spection on 11/22/21. JBG walled fuel tank on site prior walled fuel tank on site prior to the inspection of 4/3/2023 In prior to the inspection of 4/3/2023 In prior to the inspection of the inspection. 2/6/2023 Intable toilet prior to the inspection to the inspection of the inspection of the inspection.	Active Details a control of the cont	No h of Rainwood prior ank from the site prior on 9/26/22. No No No No No No A portable toilet e inspection on

Current Condition:	Good Condition - Storm Cor	tractor installed riprap at the ou	tiali tilat is under Rainwood	a Road prior to irispi	ection on 4/17/23	
RR 3	Riprap	F5	4/17/2023	Active	No	
Current Condition:	Good Condition - Storm Contractor installed riprap at the inlet outfall prior to inspection on 4/17/23.					
SF 1	Silt Fence	East edge of site	5/27/2021	Active	No	
Current Condition:	Good Condition - Mark Hopkins installed prior to the inspection on 5/27/21. Commercial Seeding extended the silt fence we along the basin prior to the inspection on 9/27/21. Mark Hopkins repaired the silt fence prior to the inspection on 12/6/21. M. Hopkins reinstalled the silt fence where removed on the western side of SB 4 prior to the inspection on 9/26/22. Due to pavi as of the 3/20/23 inspection, silt fence reinstallation along the drainage ditch is no longer recommended. An unknown contractor installed EM where the SF was damaged prior to the inspection on 5/23/23. Commercial Seeding repaired the sil fence prior to the inspection on 6/13/23.					
SF 2	Silt Fence	Southern Perimeter	5/27/2021	Active	No	
Current Condition:	Good Condition - Mark Hopkins installed the silt fence prior to the inspection on 5/27/21. Silt fence was previously identified a part of SF 1. Commercial Seeding repaired parts of the silt fence prior to the inspection on 6/13/23. Silt fence is down in area that is being regularly used as an access point for the site near the pond as of the inspection on 6/27/23. E&A inspector will monitor.					
SF 01 - 05	Silt Fence	See Rainwood Rd SWPPP Map	6/14/2022	Active	No	
Current Condition:	Good Condition - Bluffs Paving and Japp Bros installed SF 1, SF 2, and SF 5 around the disturbed area for the Rainwood Roproject prior to the 6/14/22 inspection. E&A inspector will monitor for installation of SF 3 and SF 4.					
STR	Street Cleaning	Entire Site	3/6/2023	Active	No	
Current Condition:	Good Condition - Commercia	al Seeding cleaned the streets p	rior to the inspection on 6/2	27/23.		
SWPPP Sign	Signs	1 sign on site	8/19/2008	Active	No	
Current Condition:	Good Condition - E&A inspec	ctor installed the SWPPP sign of	n 8/19/08 at 156th and Ber	nnington Blvd		
Certification Statement:	direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is,	, that this document and all attar cordance with a system designe ated the information submitted. I stem or those persons directly re to the best of my knowledge an ificant penalties for submitting far r knowing violations.	ed to assure that qualified p Based on my inquiry of the esponsible for gathering the d belief, true, accurate, and	personnel person or e information, d complete. I		
	En Carla					