E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	Manager			gineering Answe	
Inspector: Shaun McGuire		E&A - P2021.3	21.000		Stage
		Morgan Ridge CSW-202207264			
Project Name:		4/20/2			
For Week Ending:	Southwort corpor of Kor			aton NE (Douglas	
Project Location:	Southwest corner of Kempten Creek Drive and 156th Street - Bennington, NE (Douglas County)				68007
Grading:	95%				
Sanitary Sewer:	50%				
Storm Sewer:	1%				
Paving:	0%				
Seeding:	50%				
Utilities:	0%				
Overall Development:	5%				
	Amount in tenths	Data in an estad	Weather Canditions	Time	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Week 1
Sunday:	0.00"				Week
Monday	0.01"	1			
Tuesday	0.26"				
Wednesday	0.00"				
Thursday	0.09"	4/18/2024	Overcast 56/37	12:15 PM	
Friday Saturday	0.00"				
Saturday	0.00				
Complaints: Construction Sequencing: Which portion(s) (i.e. drainage last 14 days? Grading the site (4/20/23). Sanita Which portion(s) (i.e. drainage	ary began (3/14/24).		_		
Grading the site (4/20/23). Sanita		grading, cartinon	k, or ground disturbance	Solication in the he	.xt 14 days:
What temporary or permanent		n this section are b	eing implemented?		
Existing vegetation (4/20/23). No					
Checklist Questions:					
Are receiving waters adjacent to the pro	oject free of any significant signs of er	osion or sediment that w	ould be associated with the con	struction activity?	
Yes Create Corrective Action?					
N/A					
Have disturbed areas been seeded or o Yes	therwise stabilized as required? List in	active portions of the pr	oject and if stabilization measur	e are adequate or needeo	I to prevent erosion.
Create Corrective Action?					
N/A					
Are waste materials (concrete, construct	ction material, hazardous, etc.) being n	nanaged properly?			
Yes					
Create Corrective Action? N/A					
Are construction entrances and adjacen	nt streets being maintained adequately	?			
Create Corrective Action? No, See BMP section.					
Is dust associated with the construction	n activity adequately controlled on the	site?			
Yes Create Corrective Action?					
N/A					
Comments:					
Comments:					
The site was active during the mo	ost recent inspection.				

	(Date):						
naintenance is needed ir	the BMP section.						
Unique Name	Туре	Location	Projected Install Date	Status	Maintenanc		
CE 1	Construction Entrance	00-23	4/20/2023	Active	Yes		
Current Condition:	Fair Condition - 30% Effect				5/23 inspection. Ruf		
	Grading added more rock to	b the construction entra	ince prior to the 8/17/23 in	spection.			
	Construction entrance should	Construction entrance should have more rock added and be lengthened.					
			, , , , , , , , , , , , , , , , , , ,				
	Ruff Grading and Hubbell H			ot done as of last i	nspection. Ruff Grad		
D 1	Hubbell Homes were remin Diversion	BB-4	6/29/2023	Activo	No		
Current Condition:	Good Condition - Ruff Grad			Active	No		
D 2	Diversion	R-5 to Z-4	7/27/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Gradin	ig installed the diversio	n prior to the 7/27/23 inspe				
	Diversion should be re-defined	ned where impacted.					
	Ruff Grading and Hubbell H	lomes were informed to	complete by 11/16/23 No	ot done as of last i	nspection		
D 3	Diversion	R-5 to S-4		Removed			
Current Condition:	Removed - Diversion no lor		1/16/23 inspection.				
D 4	Diversion	I-9 to R-3	8/10/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Gradin	U	n prior to the 8/10/23 inspe	ection. Ruff Gradin	g re-defined the dive		
	prior to the 11/9/23 inspecti	on.					
	Diversion should be re-defined	ned where impacted					
		and a second second					
	Ruff Grading and Hubbell F	lomes were informed to		ot done as of last i	nspection.		
D 5	Diversion	I-8 to E-8	7/13/2023	Active	No		
Current Condition:	Fair Condition - Ruff Gradin activity by Pruss Excavatior						
	diversion by 11/27/23. Find				is informed to repair		
D 6	Diversion	C-8 to D-8	7/13/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad						
D 7	Diversion	BB-11 to BB-12	9/21/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Gradin	ig installed the diversion	n prior to the 9/21/23 inspe	ection.			
	Diversion should be re-defined.						
		icu.					
	Ruff Grading and Hubbell H			ot done as of last ii	nspection. Ruff Grac		
	Hubbell Homes were remin				r		
D 8	Diversion	BB-18 to BB-20	9/21/2023	Active	No		
Current Condition: D 9	Good Condition - Ruff Grad Diversion	NN-23	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta						
D 10	Diversion	AA-33	9/14/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the diversi	on prior to the 9/14/23 ins	pection. Ruff Gradi	ing re-defined the di		
	prior to the 11/16/23 inspec	tion.					
D 11	Diversion	G-13 to H-13	8/3/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	v			1		
D 12	Diversion	K-14 to H-14		Active			
		ling installed the diversi	8/3/2023	action	No		
Current Condition: FM 1			on prior to the 8/3/23 insp				
EM 1 Current Condition:	Erosion Matting Pending - BMP will be insta	See SWPPP	on prior to the 8/3/23 insp 4/20/2023	Pending	No		
EM 1	Erosion Matting Pending - BMP will be insta Erosion Matting	See SWPPP alled when work begins/ See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending pector will monitor. Pending	No		
EM 1 Current Condition:	Erosion Matting Pending - BMP will be insta	See SWPPP alled when work begins/ See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023	Pending pector will monitor. Pending	No		
EM 1 Current Condition: EM 2 Current Condition: EM 3	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023	Pending pector will monitor. Pending pector will monitor. Active	No No No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th	Pending pector will monitor. Pending pector will monitor. Active ne 8/10/23 inspecti	No No No on.		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023	Pending Dector will monitor. Pending Dector will monitor. Active ne 8/10/23 inspecti Pending	No No No on. No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP alled when work begins/	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp	Pending Dector will monitor. Pending Dector will monitor. Active ne 8/10/23 inspecti Pending Dector will monitor.	No No No on. No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ting installed the erosion See SWPPP alled when work begins/ See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp 9/21/2023	Pending bector will monitor. Pending bector will monitor. Active he 8/10/23 inspecti Pending bector will monitor. Active	No No on. No No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ting installed the erosion See SWPPP alled when work begins/ See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp 9/21/2023	Pending bector will monitor. Pending bector will monitor. Active he 8/10/23 inspecti Pending bector will monitor. Active	No No on. No No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023	Pending pector will monitor. Pending pector will monitor. Active he 8/10/23 inspection Pending pector will monitor. Active e 9/21/23 inspection Active	No No on. No on. No on. No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP ding installed the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023	Pending pector will monitor. Pending pector will monitor. Active e 8/10/23 inspecti Pending pector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection	No           No           on.           No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP fing installed the erosion See SWPPP ding installed the erosion	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th	Pending pector will monitor. Pending pector will monitor. Active e 8/10/23 inspecti Pending pector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection Active e 9/21/23 inspection	No           No           On.           No           On.           No           On.           No           On.           On.           On.           On.           On.           No           On.           No           On.           No           On.           No           On.           No           On.           No           On.		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP ding installed the erosion See SWPPP ding installed the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023	Pending pector will monitor. Pending pector will monitor. Active te 8/10/23 inspecti Pending pector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection Active e 9/21/23 inspection Active	No           No           on.           No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP ding installed the erosion See SWPPP ding installed the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 n control matting prior to th 4/20/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th	Pending pector will monitor. Pending pector will monitor. Active the 8/10/23 inspection Pending pector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection A	No           No           on.           No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 4	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled the erosion See SWPPP and the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 9/21/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023	Pending Dector will monitor. Pending Dector will monitor. Active ne 8/10/23 inspecti Pending Dector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection Active e 9/21/23 inspection Active e 9/21/23 inspection Active	No           No           on.           No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition:	Erosion Matting Pending - BMP will be insta Erosion Matting Pending - BMP will be insta Erosion Matting Good Condition - Ruff Grad Erosion Matting Pending - BMP will be insta Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad Erosion Control Terrace Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled the erosion See SWPPP and the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 9/21/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023	Pending Dector will monitor. Pending Dector will monitor. Active ne 8/10/23 inspecti Pending Dector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection Active e 9/21/23 inspection Active e 9/21/23 inspection Active	No           No           on.           No		
EM 1 Current Condition: EM 2 Current Condition: EM 3 Current Condition: EM 4 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 4 Current Condition: ET 5 Current Condition:	Erosion Matting           Pending - BMP will be insta           Erosion Matting           Pending - BMP will be insta           Erosion Matting           Good Condition - Ruff Grad           Erosion Matting           Pending - BMP will be insta           Erosion Matting           Pending - BMP will be insta           Erosion Control Terrace           Good Condition - Ruff Grad           Erosion Control Terrace           Good Condition - Ruff Grad	See SWPPP alled when work begins/ See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP alled when work begins/ See SWPPP ding installed the erosion See SWPPP	on prior to the 8/3/23 insp 4/20/2023 ends in the area. E&A insp 4/20/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 8/10/2023 ends in the area. E&A insp 9/21/2023 ends in the area. E&A insp 9/21/2023 n control terrace prior to th 9/21/2023 n control terrace prior to th 9/21/2023	Pending pector will monitor. Pending pector will monitor. Active the 8/10/23 inspection Pending pector will monitor. Active e 9/21/23 inspection Active e 9/21/23 inspection A	No           No           on.           No		

Current Condition:	Pending - Ruff Grading ins area prior to the 4/18/24 in				
ET 8	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No
Current Condition:	Good Condition - Ruff Grad				
ET 9	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No
Current Condition:	Good Condition - Ruff Gr	ading installed the erc	sion control terrace pri	1	spection.
FT 1	Fuel Tank	On site		Removed	
Current Condition:	Removed - Ruff Grading re	-	or to the 8/31/23 inspection		
PB 1 Current Condition:	Portable toilet Removed - Ruff Grading re	On site	et prior to the 9/7/23 inch	Removed	
RN 4	Erosion Control Matting		4/18/2024	Pending	No
Current Condition:	Pending - Erosion Contro				
RN 6	Erosion Control Matting	West of SB B	4/18/2024	Pending	No
Current Condition:	Pending - Erosion Contro			ea is complete.	
SB A	Sediment Basin	AA-4	4/20/2023	Pending	Yes
Current Condition:	<ul> <li>Fair Condition - 55% Filled - Ruff Grading began shaping the basin prior to the 6/8/23 inspection. Ruff Grading was in process of installing the riser and outflow pipe during the 11/2/23 inspection. Ruff Grading installed the riser and outflow pipe prior to the 11/16/23 inspection.</li> <li>1.) Basin should be installed per SWPPP (Baffle, de-watering holes on riser).</li> <li>2.) Basin should be cleaned out.</li> </ul>				
	1.) Ruff Grading was inform 6/1/23, 7/14/23, 8/4/23, 8/1 2.) Contractor will be bired	0/23, 10/5/23, 10/19/23	3, 11/10/23	ast inspection. Ruff	Grading was reminded
SB B	2.) Contractor will be hired Sediment Basin	R-4	4/20/2023	Active	Yes
Current Condition:	Fair Condition - 55% Filled - Ruff Grading began shaping the basin prior to the 6/8/23 inspection. Ruff Grading installed the riser and outflow pipe prior to the 11/2/23 inspection. 1.) Basin should be installed per SWPPP (Baffle). 2.) Basin should be cleaned out.				
	1.) Ruff Grading was inform 6/1/23, 7/14/23, 8/4/23, 8/1 2.) Contractor will be hired	0/23, 10/5/23, 10/19/23	3, 11/10/23	ast inspection. Ruff (	Grading was reminded
SB C	Sediment Basin	D-8	4/20/2023	Active	Yes
	<ul> <li>2.) Basin should be cleaned out.</li> <li>1.) Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded 6/1/23, 7/14/23, 8/4/23, 8/10/23, 10/5/23, 10/19/23, 11/10/23</li> <li>2.) Contractor will be hired to clean the basin out in the Spring.</li> </ul>				
SB D	2.) Contractor will be hired Sediment Basin	HH-32 to NN-29	4/20/2023	Pending	Yes
Current Condition:	Pending - The basin will be prior to the 12/21/23 inspect Basin should be installed p Ruff Grading and Hubbell H Ruff Grading and Hubbell H	installed as part of infr tion. er SWPPP. tomes were informed to	astructure development.	Ruff Grading began	excavation on the basi
SF 1	Silt Fence	Western Perimeter	4/20/2023	Active	Yes
Current Condition:	<ul> <li>Fair Condition - Ruff Grading installed a portion of the silt fence was installed on the west side of the site prior to the 4/20/23 inspection. Ruff Grading installed the remainder of the silt fence prior to the 5/4/23 inspection. Ruff Grading maintained the silt fence prior to the 8/31/23 inspection. A portion of the silt fence was removed for grading activity by Pruss Excavation for the Hagen Hills East property to the west prior to the 11/23/23 inspection. Re-installation not recommended.</li> <li>Silt fence should be cleaned out and repaired.</li> <li>Ruff Grading was informed to complete by 10/12/23. Not done as of last inspection. Ruff Grading and Hubbell Homes</li> </ul>				
	were reminded on 10/19/23	3, 11/10/23, 3/15/24 Southeastern	5/4/2023		
SF 2 Current Condition:	Silt Fence Good Condition - Ruff Grad the silt fence prior to the 8/	• • • •	of the silt fence prior to the		•
05-	o:: =	Southeastern	5/4/2023		
SF 3 Current Condition:	Silt Fence Good Condition - Ruff Grac prior to the 8/31/23 inspect	•	l nce prior to the 5/4/23 insp		•
SF 4	Silt Fence	Eastern Perimeter	5/4/2023	Active	No
Current Condition:	Good Condition - Ruff Grad prior to the 8/31/23 inspect Ruff Grading and Hubbell H	ling installed the silt fen ion. Ruff Grading and H	ice prior to the 5/4/23 insp lubbell Homes cleaned of	pection. Ruff Gradir ut the silt fence prior	ng maintained the silt fe

SF 5	Silt Fence	Northeastern Perimeter	5/4/2023	Active	Yes	
Current Condition:	Fair Condition - Ruff Gradi					
	prior to the 8/31/23 inspection. Ruff Grading extended the silt fence along Kempten Creek Drive prior to the 8/31/23					
	inspection. Ruff Grading and Hubbell Homes cleaned out the silt fence and added an additional row of silt fence prior to					
	the 10/10/23 inspection. Ruff Grading cleaned out the silt fence prior to the 11/9/23 inspection.					
	Silt fence should be repaired/reinstalled.					
	Ruff Grading and Hubbell H	Homes were informed to	complete by 3/21/24. No	ot done as of last ins	pection.	
SF 6	Silt Fence	Northern Perimeter	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	alled when grading begir	ns/ends in the area. E&A	inspector will monit	or.	
		Northeastern	8/31/2023			
SF 7	Silt Fence	Perimeter	8/31/2023	Active	Yes	
Current Condition:	Fair Condition - Ruff Gradi				d Hubbell Homes repa	
	the silt fence and added ar	additional row of silt fer	nce prior to the 10/10/23	inspection.		
	Silt fence should be cleane	ed out and repaired.				
	Ruff Grading was informed		<ol> <li>Not done as of last ins</li> </ol>	pection. Ruff Gradin	ig and Hubbell Homes	
	were reminded on 11/10/23		2/2/2222			
ST A	Sediment Trap	H-13	8/3/2023	Active	No	
Current Condition:	Good Condition - 3% Filled - Ruff Grading began shaping the sediment trap prior to the 7/27/23 inspection. Ruff Gradin					
	installed the sediment trap					
MS 1	Material Storage	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Materials will be					
WO 1	Concrete Washout	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Concrete will be					
WS 1	Waste Storage	On Site	4/20/2023	Pending	No	
Current Condition:	Pending - Waste will be sto			Anting	<u> </u>	
STR Current Conditions	Streets	N 156th Street	4/20/2023	Active	Yes	
Current Condition:	Fair Condition - The streets were free of track out as of the 4/20/23 inspection. Streets were partially cleaned prior to the 4/20/23 inspection.					
	8/17/23 inspection.					
	Streets should be cleaned.					
	Ruff Grading was informed to complete by 8/11/23. Not done as of last inspection. Ruff Grading and Hubbell Homes w					
	reminded on 10/5/23. 10/1					
SWPPP Sign	SWPPP Notification Sign	On Site	5/11/2023	Active	No	
Current Condition:	Good Condition - E&A insp	ector installed the SWP	PP sign during the 5/11/2	23 inspection.		
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my					
	direction or supervision in accordance with a system designed to assure that qualified personnel					
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or					
	persons who manage the system or those persons directly responsible for gathering the information,					
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I					
	am aware that there are significant penalties for submitting false information including the possibility					
	of fines and imprisonment	for knowing violations."				
	Sm Msgin				Cato Sul	