E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E.	&A- P2011.160.006				
Inspector: Ethan Anderson					Stage	
Project Name:	1	1				
For Week Ending:		4/27/2024			68048	
Project Location:	211 S 23	211 S 23RD ST - Plattsmouth, NE (Cass County)				
Grading:	75%	I	1		1	
Sanitary Sewer:	100%					
Storm Sewer:	80%					
Paving:	45%					
Seeding:	0%					
Utilities:	30%					
Overall Development:	45%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
					Week	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"	4/24/2024	Sunny 71/46	12:45 PM		
Thursday:	0.09"				10:35 - 11:55	
Friday:	0.63"				00:15 - 17:55	
Saturday:	0.11"				15:35 - 16:55	
	T.					
Complaints:	None					

Construction Sequencing:

hich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23) Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23). PCSMP basin riser installation begins (11/1/23)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of (11/23/2022). Removal of concrete at entrance (11/30/22). Retaining wall installation active. Ground disturbance and earthwork related to footings active during inspection (1/11/23). Some grading and concrete work related to apartment construction active (2/01/23). Electrical installation begins (4/5/23). Grading and soil placement at the entrance (6/7/23). Storm sewer installation begins (9/20/23). PCSMP basin riser installation begins

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/23/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

No. See BMP and Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
1.) Site was getive during the inspection

ings / Corrective Actions	spection. (Date):							
ings / Corrective Actions								
ome maintenance in BMP	Section.							
	lld be stabilized with seed and matting. Calab				of last inspection.			
bretto Building Group was	reminded on 5/24/23, 6/21/23, 7/20/23, 8/16/	<mark>23, 9/14/23, 10/19/23, 11/2</mark> /	<mark>/23, 12/7/23, 1/31/24, 3/8/</mark>	24, 4/4/24				
		T		ı				
Unique Name	Type	Location	Projected Install Date	Status	Maintenance			
CE 01	Construction Entrance	North East Corner		Removed				
Current Condition: EM 1	Removed - Calabretto Building Group pa		orior to the inspection on 4		Vaa			
Current Condition:	Erosion Control Mat Pending -	EM 1	11/2/2023	Pending	Yes			
Current Condition.	T Griding -							
	Erosion Matting should be installed when work is complete in the area.							
	Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was remind							
	on 12/7/23, 1/31/24, 3/8/24, 4/4/24	to complete by 11/8/23. Not	t done as of last inspection	n. Calabretto Buildin	g Group was remir			
EM 2	Erosion Control Mat	EM 2	11/2/2023	Pending	Yes			
Current Condition:	Pending -			1 2112				
	Erosion Matting should be installed when	work is complete in the are	ea.					
	Calabretto Building Group was informed	to complete by 11/8/23 Not	t done as of last inspection	n Calabretto Buildin	g Group was remir			
	on 12/7/23, 1/31/24, 3/8/24, 4/4/24	10 complete by 1 1/0/20. 110	t done de el laet mopeetion	n. Galabiotto Ballali	g Croup was rollin			
EM 3	Erosion Control Mat	EM 3	11/2/2023	Pending	Yes			
Current Condition:	Pending -							
	Fracion Matting about the installed when work is complete in the							
	Erosion Matting should be installed when work is complete in the area.							
	Calabretto Building Group was informed	to complete by 11/8/23. Not	t done as of last inspection	n. Calabretto Buildin	g Group was remir			
	on 12/7/23, 1/31/24, 3/8/24, 4/4/24							
EM 4	Erosion Control Mat	EM 4	11/2/2023	Pending	Yes			
Current Condition:	Pending -							
	Erosion Matting should be installed when work is complete in the area.							
	ŭ	· ·						
	Calabretto Building Group was informed	to complete by 11/8/23. Not	t done as of last inspection	n. Calabretto Buildin	g Group was remir			
EM 5	on 12/7/23, 1/31/24, 3/8/24, 4/4/24 Erosion Control Mat	EM 5	11/2/2023	Dandina	Yes			
Current Condition:	Pending -	□ □ □ IVI 3	11/2/2023	Pending	res			
	renuing -							
	Erosion Matting should be installed when	work is complete in the are	ea.					
	Calabratta Building Crave was informed	to commiste by 44/0/02. Not		- Calabaatta Duildia	- C			
	Calabretto Building Group was informed on 12/7/23, 1/31/24, 3/8/24, 4/4/24	to complete by 11/6/25. Not	done as of last inspection	n. Calabiello Bullulii	g Group was remii			
EM 6	Erosion Control Mat	EM 6	11/2/2023	Pending	Yes			
Current Condition:	Pending -							
	Erosion Matting should be installed when	Erosion Matting should be installed when work is complete in the area.						
	Calabretto Building Group was informed to complete by 11/8/23. Not done as of last inspection. Calabretto Building Group was remin							
	on 12/7/23, 1/31/24, 3/8/24, 4/4/24	, , ,	<u> </u>		3 - 1			
FT X	Fuel Tank	On site		Removed				
	Removed - Calabretto Building Group rei	moved the fuel tank prior to						
Current Condition:	Fuel Topk	On cito	3/7/2024		No			
FT 1	Fuel Tank Good Condition - Calabretto Building Gro	On site	3/7/2024 able fuel tanks prior to the	Active inspection on 3/6/2	No 4.			
	Fuel Tank Good Condition - Calabretto Building Gro Inlet Protection							
FT 1 Current Condition:	Good Condition - Calabretto Building Gro	oup re-installed the two porta	able fuel tanks prior to the	inspection on 3/6/2	4.			
FT 1 Current Condition: IF 1-3	Good Condition - Calabretto Building Gro Inlet Protection Pending -	bup re-installed the two portal S 22nd St and 1st Ave	able fuel tanks prior to the	inspection on 3/6/2	4.			
FT 1 Current Condition: IF 1-3	Good Condition - Calabretto Building Gro Inlet Protection	bup re-installed the two portal S 22nd St and 1st Ave	able fuel tanks prior to the	inspection on 3/6/2	4.			
FT 1 Current Condition: IF 1-3	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the	bup re-installed the two portals S 22nd St and 1st Ave	able fuel tanks prior to the 10/18/2023	inspection on 3/6/2- Pending	4. Yes			
FT 1 Current Condition: IF 1-3 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending -	bup re-installed the two portals S 22nd St and 1st Ave e street inlets.	able fuel tanks prior to the 10/18/2023	inspection on 3/6/2- Pending	4. Yes			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 12/7/23, 1/31/24, 3 Material Storage	e street inlets. to complete by 10/25/23. No. 1/25/24, 4/4/24 Near CE 01	ot done as of last inspection 11/23/2022	inspection on 3/6/2- Pending on. Calabretto Buildi Active	ng Group was			
FT 1 Current Condition: IF 1-3 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 1/2/1/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Gro	e street inlets. to complete by 10/25/23. No. 1/8/24, 4/4/24 Near CE 01 up re-installed the two ports s 22nd St and 1st Ave e street inlets.	ot done as of last inspection 11/23/2022 ials on site. A waste stora	on. Calabretto Buildi Active ge container was ins	ng Group was No stalled near the			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 12/7/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Groconstruction entrance (2/8/23). Lumber a	e street inlets. to complete by 10/25/23. No. 1/8/24, 4/4/24 Near CE 01 up re-installed the two ports s 22nd St and 1st Ave e street inlets.	ot done as of last inspection 11/23/2022 ials on site. A waste stora	on. Calabretto Buildi Active ge container was ins	ng Group was No stalled near the			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 12/7/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Groconstruction entrance (2/8/23). Lumber a lumber storage on site (3/29/23).	e street inlets. to complete by 10/25/23. No. 18/24, 4/4/24 Near CE 01 pup is storing building mater and other construction mate	ot done as of last inspection 11/23/2022 ials on site. A waste stora	on. Calabretto Buildi Active ge container was insignated storage are	ng Group was No stalled near the as (3/22/23). Addit			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Groconstruction entrance (2/8/23). Lumber a lumber storage on site (3/29/23). Portable Bathroom	e street inlets. to complete by 10/25/23. No Novar CE 01 Near CE 01 Near CE 01 Near CE 01	ot done as of last inspection 11/23/2022 ials on site. A waste storal pricals moved on site in des	on. Calabretto Buildi Active ge container was insignated storage are Active	ng Group was No stalled near the as (3/22/23). Addit			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 12/7/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Groconstruction entrance (2/8/23). Lumber a lumber storage on site (3/29/23).	e street inlets. to complete by 10/25/23. No. 1/25/24, 4/4/24 Near CE 01 Near CE 01 Near CE 01 P staked down the portable	ot done as of last inspection in the street of the street	on. Calabretto Buildi Active ge container was insignated storage are Active	ng Group was No stalled near the as (3/22/23). Addit			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 12/7/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Groconstruction entrance (2/8/23). Lumber storage on site (3/29/23). Portable Bathroom Fair Condition - Calabretto Building Group was a construction on the construction of the c	e street inlets. to complete by 10/25/23. No. 1/25/24, 4/4/24 Near CE 01 Near CE 01 Near CE 01 P staked down the portable	ot done as of last inspection in the street of the street	on. Calabretto Buildi Active ge container was insignated storage are Active	ng Group was No stalled near the as (3/22/23). Addit			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 1/21/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Group was informed in the storage of the storage on site (3/29/23). Lumber storage on site (3/29/23). Portable Bathroom Fair Condition - Calabretto Building Group	e street inlets. to complete by 10/25/23. No. 1/25/24, 4/4/24 Near CE 01 Near CE 01 Near CE 01 P staked down the portable	ot done as of last inspection in the street of the street	on. Calabretto Buildi Active ge container was insignated storage are Active	ng Group was No stalled near the as (3/22/23). Addit			
FT 1 Current Condition: IF 1-3 Current Condition: MS 01 Current Condition:	Good Condition - Calabretto Building Gro Inlet Protection Pending - Inlet protection should be installed on the Calabretto Building Group was informed reminded on 11/2/23, 12/7/23, 1/31/24, 3 Material Storage Good Condition - Calabretto Building Groconstruction entrance (2/8/23). Lumber storage on site (3/29/23). Portable Bathroom Fair Condition - Calabretto Building Group was a construction on the construction of the c	e street inlets. to complete by 10/25/23. No. 18/24, 4/4/24 Near CE 01 pup is storing building mater and other construction mate Near CE 01 p staked down the portable ior to the inspection on 6/28	ot done as of last inspection 11/23/2022 ials on site. A waste stora arrials moved on site in des 11/30/2022 toilet prior to the 12/21/22 1/23.	on. Calabretto Buildi Active ge container was insignated storage are Active	ng Group was No stalled near the as (3/22/23). Addit Yes etto Building Group			

RN 1 - RN 6	Inlet Protection	RN 1 - RN 6	4/26/2023	Pending	Yes			
Current Condition:	Pending - The inlet filter will be installed		J		5 - 1			
	inlets 5 and 6 prior to the inspection on	10/18/23. Calabretto Building	Group was in the proces	ss of installing the inle	ets during the			
	inspection on 10/25/23.							
	Inlet protection should be installed.							
	Calabretto Building Group was informed	d to complete by 10/25/23. No	ot done as of last inspect	ion. Calabretto Buildii	ng Group was			
	reminded on 11/2/23, 12/7/23, 1/31/24,		· ·					
RN 7 - RN 12	Inlet Protection	Near RN 6	4/26/2023	Pending	Yes			
Current Condition:	Pending - The inlet filter will be installed				ding Group was in the			
	process of installing the inlets during the		9					
	p							
	Inlet protection should be installed.							
	mot protoston should be metalled.							
	Calabretto Building Group was informed	d to complete by 11/8/23 Not	done as of last inspection	n Calabretto Ruilding	g Group was reminde			
	on 12/7/23, 1/31/24, 3/8/24, 4/4/24	a to complete by 1 1/0/20. 140	done as of last inspection	ii. Odlabi cito Dalidii i	g Oroup was reminde			
RN 13 - RN 18	Inlet Protection	Near RN 6	4/26/2023	Pending	Yes			
Current Condition:	Pending - The inlet filter will be installed							
Current Condition:			The liner is at or below g	rade. Calabiello bull	uling Group was in the			
	process of installing the inlets during the	e inspection on 10/25/25.						
	to take a series of an all and the first of the							
	Inlet protection should be installed.							
	Outstand Dutilian Outstand informati	d to a complete bas 44/0/00 No.		O a la la contra de la Destitution				
	Calabretto Building Group was informed	a to complete by 11/8/23. Not	done as of last inspection	n. Calabretto Bullding	g Group was reminde			
DM 4	on 12/7/23, 1/31/24, 3/8/24, 4/4/24	1 5144	4/00/0000	D 10.	V.			
RM 1	Erosion Control Mat	RM 1	4/26/2023	Pending	Yes			
Current Condition:	Pending -							
	Erosion Matting should be installed.							
	Calabretto Building Group was informed				Group was reminded			
	on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9	9/14/23, 10/19/23, 11/2/23, 12	2/7/23, 1/31/24, 3/8/24, 4/	4/24				
RM 2	Erosion Control Mat	RM 2	4/26/2023	Pending	Yes			
Current Condition:	Pending -		•					
	Erosion Matting should be installed.							
	Calabretto Building Group was informed	d to complete by 5/3/23. Not	done as of last inspection	. Calabretto Building	Group was reminded			
	on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9							
RM 3	Erosion Control Mat	RM 3		Removed				
Current Condition:	Removed - Erosion matting is no longe		/PPP as of the inspection		l.			
ST 01	Silt Trap	South end of site	4/19/2023	Active	Yes			
Current Condition:	Fair Condition - Calabretto Building Gro							
Current Condition:				in Calabiotic Ballani	ig Group mus in ans			
	process of installing the PCSMP riser a	process of installing the PCSMP riser and outfall during the inspection on 11/1/23.						
	process of installing the PCSMP riser a	nd oddaii ddinig the inspectio						
	process of installing the PCSMP riser a The area around and in the basin shou							
	The area around and in the basin shou	ld be repaired and stabilized.		n, Calabretto Building	g Group was reminde			
	The area around and in the basin shou Calabretto Building Group was informed	ld be repaired and stabilized.	done as of last inspection		g Group was reminde			
ST 02	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8	ld be repaired and stabilized. d to complete by 4/26/23. No: 3/14/23, 10/19/23, 11/2/23, 12	done as of last inspectio 2/7/23, 1/31/24, 3/8/24, 4/	4/24				
ST 02	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Silt Trap	Id be repaired and stabilized. d to complete by 4/26/23. No: 3/14/23, 10/19/23, 11/2/23, 12 East perimeter	done as of last inspection 2/7/23, 1/31/24, 3/8/24, 4/19/2023	/4/24 Active	Yes			
ST 02 Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group	Id be repaired and stabilized. d to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter bup installed silt fence prior to	t done as of last inspection 27/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/	/4/24 Active	Yes			
	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Silt Trap	Id be repaired and stabilized. d to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter bup installed silt fence prior to	t done as of last inspection 27/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/	/4/24 Active	Yes			
	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group or Calabretto Building Group was informed on 5/24/23, 8/16/23	Id be repaired and stabilized. d to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter bup installed silt fence prior to nd outfall during the inspection	t done as of last inspection 27/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/	/4/24 Active	Yes			
	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group	Id be repaired and stabilized. d to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter bup installed silt fence prior to nd outfall during the inspection	t done as of last inspection 27/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/	/4/24 Active	Yes			
	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group or call of the PCSMP riser and the area around and in the basin/silt transport of the statement of the process of installing the PCSMP riser and the process of th	Id be repaired and stabilized. d to complete by 4/26/23. No: 0/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to nd outfall during the inspection	done as of last inspection 2/7/23, 1/31/24, 3/8/24, 4/19/2023 the inspection on 11/23/2 in on 11/1/23.	/4/24 Active 22. Calabretto Buildin	Yes g Group was in the			
	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was installing the PCSMP riser at the area around and in the basin/silt trace. Calabretto Building Group was informed.	Id be repaired and stabilized. d to complete by 4/26/23. Noi 3/14/23, 10/19/23, 11/2/23, 12 East perimeter bup installed silt fence prior to nd outfall during the inspection ap should be stabilized. d to complete by 4/26/23. Noi	t done as of last inspection 2/7/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/2 in on 11/1/23.	4/24 Active 22. Calabretto Buildin	Yes g Group was in the			
Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was installing the PCSMP riser a The area around and in the basin/silt trace Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9	Id be repaired and stabilized. Id to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to nd outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12	done as of last inspectic 27/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/2 on on 11/1/23.	14/24 Active 22. Calabretto Buildin n. Calabretto Buildin 14/24	Yes g Group was in the			
Current Condition: SF 01	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group coess of installing the PCSMP riser a The area around and in the basin/silt trace Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Fence	Id be repaired and stabilized. d to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter sup installed silt fence prior to nd outfall during the inspection ap should be stabilized. d to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter	t done as of last inspectic 27/23, 1/31/24, 3/8/24, 4/ 1 4/19/2023 the inspection on 11/23/20 on on 11/1/23.	A/24 Active 22. Calabretto Building n. Calabretto Building 4/24 Active	Yes g Group was in the			
Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was installing the PCSMP riser a The area around and in the basin/silt trace Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9	Id be repaired and stabilized. d to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter sup installed silt fence prior to nd outfall during the inspection ap should be stabilized. d to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter	t done as of last inspectic 27/23, 1/31/24, 3/8/24, 4/ 1 4/19/2023 the inspection on 11/23/20 on on 11/1/23.	A/24 Active 22. Calabretto Building n. Calabretto Building 4/24 Active	Yes g Group was in the			
Current Condition: SF 01	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group coess of installing the PCSMP riser at The area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Fair Condition - Calabretto Building Group	Id be repaired and stabilized. Id to complete by 4/26/23. Notal 23, 10/19/23, 11/2/23, 12 East perimeter our installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Notal 23, 10/19/23, 11/2/23, 12 East perimeter our installed silt fence prior to to purple stabilized.	done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/2023 the inspection on 11/23/3 in on 11/1/23. done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/9/2022 the inspection on 11/23/3/4	A/24 Active 22. Calabretto Building n. Calabretto Building 4/24 Active	Yes g Group was in the			
Current Condition: SF 01	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group coess of installing the PCSMP riser a The area around and in the basin/silt trace Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Fence	Id be repaired and stabilized. Id to complete by 4/26/23. Notal 23, 10/19/23, 11/2/23, 12 East perimeter our installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Notal 23, 10/19/23, 11/2/23, 12 East perimeter our installed silt fence prior to to purple stabilized.	done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/2023 the inspection on 11/23/3 in on 11/1/23. done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/9/2022 the inspection on 11/23/3/4	A/24 Active 22. Calabretto Building n. Calabretto Building 4/24 Active	Yes g Group was in the			
Current Condition: SF 01	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group rocess of installing the PCSMP riser at The area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 The silt fence needs to be repaired, extending the silt fence needs to be repaired.	Id be repaired and stabilized. Id to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to nd outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Not 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to teended and reinstalled along to	t done as of last inspectic 12/7/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/2 on on 11/1/23. t done as of last inspectic 12/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/2 the eastern perimeter.	A/24 Active 22. Calabretto Building 24. Calabretto Building 24. Calabretto Building 24. Active 22.	Yes g Group was in the g Group was remind Yes			
Current Condition: SF 01	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group coess of installing the PCSMP riser at the area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed to the silt fence needs to be repaired, extended to be repaired, extended to the silt fence meeds to be repaired, extended to the silt fence meeds to be repaired, extended to the silt fence meeds to be repaired, extended to the silt fence meeds to be repaired, extended to the silt fence meeds to be repaired, extended to the silt fence meeds to be repaired.	Id be repaired and stabilized. Id to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to and outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to ended and reinstalled along the discomplete by 11/30/22. Not appear of the complete by 11/30/22.	t done as of last inspectic 12/7/23, 1/31/24, 3/8/24, 4/9/2023 the inspection on 11/23/24 on on 11/1/23. 12 done as of last inspectic 12/7/23, 1/31/24, 3/8/24, 4/9/9/2022 12 the inspection on 11/23/24 on on on on one of last inspection on on one of last inspection on on one of last inspection one	A/24 Active 22. Calabretto Building 24. Active 24. Active 22.	Yes g Group was in the g Group was remind Yes			
SF 01 Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was installing the PCSMP riser at the area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed in the silt fence needs to be repaired, extended to be repaired, extended to be suilding Group was informed in the silt fence needs to be repaired, extended to 2/23/23, 4/21/23, 5/24/23, 8/21/23, 8/21/23,	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect	A/24 Active 22. Calabretto Building Active Active 22. Active 22. Active 22.	Yes g Group was in the g Group was remind Yes ng Group was 8/24, 4/4/24			
SF 01 Current Condition: SF 02	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group of installing the PCSMP riser at the area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed to the silt fence needs to be repaired, extended on 2/23/23, 4/21/23, 5/24/23, Silt Fence	Id be repaired and stabilized. Id to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to and outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Not 3/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to ended and reinstalled along the discomplete by 11/30/22. Not appear of the complete by 11/30/22.	t done as of last inspectic 12/7/23, 1/31/24, 3/8/24, 4/9/2023 the inspection on 11/23/24 on on 11/1/23. 12 done as of last inspectic 12/7/23, 1/31/24, 3/8/24, 4/9/9/2022 12 the inspection on 11/23/24 on on on on one of last inspection on on one of last inspection on on one of last inspection one	A/24 Active 22. Calabretto Building 24. Active 24. Active 22.	Yes g Group was in the g Group was remind Yes			
SF 01 Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was installing the PCSMP riser at the area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed in the silt fence needs to be repaired, extended to be repaired, extended to be suilding Group was informed in the silt fence needs to be repaired, extended to 2/23/23, 4/21/23, 5/24/23, 8/21/23, 8/21/23,	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect	A/24 Active 22. Calabretto Building Active Active 22. Active 22. Active 22.	Yes g Group was in the g Group was remind Yes ng Group was			
SF 01 Current Condition: SF 02	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 9 Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending -	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect	A/24 Active 22. Calabretto Building Active Active 22. Active 22. Active 22.	Yes g Group was in the Yes ng Group was reminde			
SF 01 Current Condition: SF 02	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group of installing the PCSMP riser at the area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed to the silt fence needs to be repaired, extended on 2/23/23, 4/21/23, 5/24/23, Silt Fence	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect	A/24 Active 22. Calabretto Building Active Active 22. Active 22. Active 22.	Yes g Group was in the g Group was reminde Yes ng Group was 8/24, 4/4/24			
SF 01 Current Condition: SF 02	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 9 Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending -	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect	A/24 Active 22. Calabretto Building Active Active 22. Active 22. Active 22.	Yes g Group was in the g Group was reminde Yes ng Group was 8/24, 4/4/24			
SF 01 Current Condition: SF 02	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 9 Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending -	Id be repaired and stabilized. Id to complete by 4/26/23. No 0/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. No 0/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to the ended and reinstalled along the document of the complete by 11/30/22. No 0/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022	A/24 Active 22. Calabretto Building Active Active 22. Active 22. Active 22. Active 22. Active 22. Active 23. Pending	Yes g Group was in the Yes g Group was reminde Yes g Group was g Group was g Group was g Group was			
SF 01 Current Condition: SF 02	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group or installing the PCSMP riser at The area around and in the basin/silt trace. Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 9 Silt Fence peeds to be repaired, extended on 2/23/23, 4/21/23, 5/24/23, 9 Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed the silt fence should be installed.	Id be repaired and stabilized. Id to complete by 4/26/23. No: 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to nd outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. No: 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to ended and reinstalled along to d to complete by 11/30/22. No: 6/21/23, 7/20/23, 8/16/23, 9/ Eastern Slope	t done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. It done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/2022 the inspection on 11/23/2 the eastern perimeter. 1/2/3, 10/19/23, 11/2/23 1/2/1/2022	A/24 Active 22. Calabretto Building A/24 Active 22.	Yes g Group was remind Yes ng Group was sa/24, 4/4/24 Yes			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 9 Silt Fence Pending - Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 9 Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, 5/24/23, 4/21/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/24/23, 5/	Id be repaired and stabilized. Id to complete by 4/26/23. Notal 2/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Notal 2/14/23, 10/19/23, 11/2/23, 12 East perimeter outprinted installed silt fence prior to ended and reinstalled along the distribution of the complete by 11/30/22. Notal 2/12/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 9	t done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/2023 the inspection on 11/23/3 in on 11/1/23. It done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/9/2022 the inspection on 11/23/3 the eastern perimeter. 1/4/23, 10/19/23, 11/2/23 1/2/11/2022 1/2/2022 1/2/2023 1/2/2024 1/2/2023 1/2/2024 1/2/2023 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024 1/2/2024	A/24 Active 22. Calabretto Building A/24 Active 22.	Yes g Group was remind Yes ng Group was sa/24, 4/4/24 Yes ng Group was g Group was			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group common simulation of installing the PCSMP riser at the area around and in the basin/silt trace. The area around and in the basin/silt trace around and in the basin/silt trace. The area around and in the basin/silt trace. The area around and in the basin/silt trace. Silt Fence are silt fence. Fair Condition - Calabretto Building Group was informed to the silt fence needs to be repaired, ext. Calabretto Building Group was informed in the silt fence. Pending - Silt Fence. Silt fence should be installed. Calabretto Building Group was informed in the silt fence should be installed. Calabretto Building Group was informed in the silt fence should be installed. Calabretto Building Group was informed in the silt fence should be installed.	Id be repaired and stabilized. Id to complete by 4/26/23. Notability and the complete by 4/26/23, 10/19/23, 11/2/23, 12/	t done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/2023 the inspection on 11/23/3 in on 11/1/23. t done as of last inspectic 1/7/23, 1/31/24, 3/8/24, 4/19/9/2022 the inspection on 11/23/3 the eastern perimeter. 1/4/23, 10/19/23, 11/2/23 1/2/1/2022 tot done as of last inspectic 1/4/23, 10/19/23, 11/2/23 10/31/2022	A/24 Active 22. Calabretto Building 4/24 Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 25. Active 26. Active 27. Active 28. Active 29. Active 20. Active 20. Active	Yes g Group was remind Yes ng Group was 8/24, 4/4/24 Yes ng Group was 8/24, 4/4/24 Yes			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed in 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed in 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed in 2/23/23, 4/21/23, 5/24/23, Silt Fence	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/1	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 on on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 ort done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022	Active 22. Calabretto Building Active 22. Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 25. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20. Active 21. Active 22. Active 23. Active 24. Active 25. Active	Yes Ig Group was remind Yes Ing Group was remind Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 8 Silt Trap Fair Condition - Calabretto Building Group common simulation of installing the PCSMP riser at the area around and in the basin/silt trace. The area around and in the basin/silt trace around and in the basin/silt trace. The area around and in the basin/silt trace. The area around and in the basin/silt trace. Silt Fence are silt fence. Fair Condition - Calabretto Building Group was informed to the silt fence needs to be repaired, ext. Calabretto Building Group was informed in the silt fence. Pending - Silt Fence. Silt fence should be installed. Calabretto Building Group was informed in the silt fence should be installed. Calabretto Building Group was informed in the silt fence should be installed. Calabretto Building Group was informed in the silt fence should be installed.	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/1	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 on on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 ort done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022	Active 22. Calabretto Building Active 22. Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 25. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20. Active 21. Active 22. Active 23. Active 24. Active 25. Active	Yes Ig Group was remind Yes Ing Group was remind Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group of installing the PCSMP riser at the area around and in the basin/silt transparent of the silt fence on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed eminded on 2/23/23, 4/21/23, 5/24/23, Streets Fair Condition - Trackout was observed street prior to the inspection on 6/14/23	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/1	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 on on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 ort done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022	Active 22. Calabretto Building Active 22. Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 25. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20. Active 21. Active 22. Active 23. Active 24. Active 25. Active	Yes Ig Group was remind Yes Ing Group was remind Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed in 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed in 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed in 2/23/23, 4/21/23, 5/24/23, Silt Fence	Id be repaired and stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to not outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. No 9/14/23, 10/19/23, 11/2/23, 12 East perimeter pup installed silt fence prior to the ended and reinstalled along the did to complete by 11/30/22. No 9/14/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/23, 9/16/21/23, 7/20/23, 8/16/23, 9/1	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 on on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 ort done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022	Active 22. Calabretto Building Active 22. Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 25. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20. Active 21. Active 22. Active 23. Active 24. Active 25. Active	Yes Ig Group was in the Yes Ing Group was reminde Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Silt Trap Fair Condition - Calabretto Building Group composes of installing the PCSMP riser at the area around and in the basin/silt trace. Silt Fence. Fair Condition - Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Silt Fence. Pending - Silt fence should be installed. Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Streets. Fair Condition - Trackout was observed street prior to the inspection on 6/14/23. Streets should be cleaned.	Id be repaired and stabilized. Id to complete by 4/26/23. Not 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Not 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to ended and reinstalled along the did to complete by 11/30/22. Not 2/12/23, 7/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/20/23,	t done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/3 in on 11/1/23. t done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/3 he eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 of done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022 ection on 4/19/23, Calab vas cleaning the streets desired.	A/24 Active 22. Calabretto Building 4/24 Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20.	Yes Ig Group was in the Yes Ing Group was reminde Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group of installing the PCSMP riser at the area around and in the basin/silt transparent of the silt fence on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Fence Fair Condition - Calabretto Building Group was informed on 2/23/23, 4/21/23, 5/24/23, Silt Fence Pending - Silt fence should be installed. Calabretto Building Group was informed eminded on 2/23/23, 4/21/23, 5/24/23, Streets Fair Condition - Trackout was observed street prior to the inspection on 6/14/23	Id be repaired and stabilized. Id to complete by 4/26/23. Not 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Not 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to ended and reinstalled along the did to complete by 11/30/22. Not 2/12/23, 7/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/20/23,	t done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/3 in on 11/1/23. t done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/3 he eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 of done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022 ection on 4/19/23, Calab vas cleaning the streets desired.	A/24 Active 22. Calabretto Building 4/24 Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20.	Yes Ig Group was reminde Yes Ing Group was reminde Yes Ing Group was 8/24, 4/4/24 Yes Ing Group was 8/24, 4/4/24 Yes Ing Group was 8/24, 4/4/24			
SF 01 Current Condition: SF 02 Current Condition: STR Current Condition:	The area around and in the basin should calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, 9 Silt Trap Fair Condition - Calabretto Building Group of installing the PCSMP riser at the area around and in the basin/silt trace. The area around and in the basin/silt t	Id be repaired and stabilized. Id to complete by 4/26/23. No 0/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to not outfall during the inspectic ap should be stabilized. Id to complete by 4/26/23. No 0/14/23, 10/19/23, 11/2/23, 12 East perimeter out installed silt fence prior to tended and reinstalled along the distribution of the complete by 11/30/22. No 0/14/23, 7/20/23, 8/16/23, 9/20/23, 7/20/23, 8/16/23, 9/20/23, 7/20/23, 8/16/23, 9/20/23, 8/20/23,	done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 4/19/2023 the inspection on 11/23/2 in on 11/1/23. done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4, 9/9/2022 the inspection on 11/23/2 the eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 of done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022 ection on 4/19/23. Calab vas cleaning the streets of	A/24 Active 22. Calabretto Building Active Active Active Active 22. Active Ac	Yes g Group was in the Yes g Group was reminde Yes ng Group was 8/24, 4/4/24 Yes ng Group was 8/24, 4/4/24 Yes cleaned the entrance on 2/7/24.			
SF 01 Current Condition: SF 02 Current Condition:	The area around and in the basin shou Calabretto Building Group was informed on 5/24/23, 6/21/23, 7/20/23, 8/16/23, \$ Silt Trap Fair Condition - Calabretto Building Group composes of installing the PCSMP riser at the area around and in the basin/silt trace. Silt Fence. Fair Condition - Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Silt Fence. Pending - Silt fence should be installed. Calabretto Building Group was informed reminded on 2/23/23, 4/21/23, 5/24/23, Streets. Fair Condition - Trackout was observed street prior to the inspection on 6/14/23. Streets should be cleaned.	Id be repaired and stabilized. Id to complete by 4/26/23. Not 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to not outfall during the inspection ap should be stabilized. Id to complete by 4/26/23. Not 2/14/23, 10/19/23, 11/2/23, 12 East perimeter oup installed silt fence prior to ended and reinstalled along the did to complete by 11/30/22. Not 2/12/23, 7/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/16/23, 9/20/23, 8/20/23,	t done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 4/19/2023 the inspection on 11/23/3 in on 11/1/23. t done as of last inspectic 2/7/23, 1/31/24, 3/8/24, 4/ 9/9/2022 the inspection on 11/23/3 he eastern perimeter. of done as of last inspect 14/23, 10/19/23, 11/2/23 12/1/2022 of done as of last inspect 14/23, 10/19/23, 11/2/23 10/31/2022 ection on 4/19/23, Calab vas cleaning the streets desired.	A/24 Active 22. Calabretto Building 4/24 Active 22. Active 22. Active 22. Active 22. Active 23. Active 24. Active 26. Active 27. Active 28. Active 29. Active 29. Active 20. Active 20. Active 20.	Yes Ig Group was remind Yes Ing Group was remind Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24 Yes Ing Group was 18/24, 4/4/24			

Current Condition:	Good Condition - E&A inspector installed the SWPPP sign on the north east corner of the site during the inspection on 12/7/22. E&A					
	inspector reinstalled the SWPPP sign near the entrance of the site during the 1/4/23 inspection. E&A inspector reinstalled the SWPPP					
	sign near the entrance of the site during the 11/22/23 inspection.					
WO 01	Concrete Washout	On site	12/1/2022	Pending	Yes	
Current Condition:	Pending - Calabretto Building Group paved around the drainage area prior to the inspection. 1.) Concrete waste related to construction on the north central portion of the site should be cleaned up and removed. 2.) A concrete washout should be installed to contain any washouts.					
	1.) Calabretto Building Group was inform Calabretto Building Group was reminded 1/31/24, 3/8/24, 4/4/24 2.) Calabretto Building Group was inform Calabretto Building Group was reminded 1/31/24, 3/8/24, 4/4/24	d on 2/23/23, 4/21/23, 5/24/2 ned to complete by 1/25/23 o	3, 6/21/23, 7/20/23, 8/16, r as weather conditions a	/23, 9/14/23, 10/19/23 allow. Not done as of la	, 11/2/23, 12/7/23, ast inspection.	
WS 01	Waste Storage Area	On site	12/7/2022	Active	No	
Current Condition:	Good Condition - Calabretto Building Groonstruction entrance (2/8/23).	oup is storing building materi	als on site. A waste stora	ige container was inst	alled near the	
WT 01	Wattle	North East Corner		Removed		
Current Condition:	Removed - Calabretto Building Group pa on 11/2/23.	aved the area above the drai	nage and connected it to	existing storm inlets p	orior to the inspection	
Certification Statement	"I certify, under penalty of law, that this d with a system designed to assure that q inquiry of the person or persons who ma information submitted is, to the best of n penalties for submitting false information	ualified personnel properly ga nage the system or those pe ny knowledge and belief, true	athered and evaluated the ersons directly responsible, accurate, and complete	e information submitte e for gathering the info e. I am aware that ther	ed. Based on my ormation, the	
nspector Signature:	En Carles			Reviewed By:	Sito Sol	