E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



www.cacg.com			E & A CONSULTING GROUP, INC.		
Zachary A. Jilek, CPESC, C Environmental Services Do		Engineering Answers			
Environmental Services De	ері. мападег	E&A- P2	2020.056.003		,
Inspector: Luke Antholz		20,7,12			Stage
		Ds Transportat	ion Trucking Termina	al	
Project Name:			9263 -38898	~ .	1
•			10/2021		51501
For Week Ending: Project Location:	Southwest of S 20t		nue in Council Bluffs, IA (Po	ttawattamia County)	31301
r roject Location.	Journwest of 5 250	in oti eet and 21st Ave	nue in Council Bluins, IA (1 C	ttawattanne county)	
Grading:	70%				
Sanitary Sewer:	0%				
Storm Sewer: Paving:	0%				
Seeding:	0%				+
Utilities:	0%				
Overall Development:	3%				
	1	1		1	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
	0.000				Week
Sunday	0.00"				
Monday Tuesday	0.00"	07/06/21	Moethy Claudy 00/70	2:40 DM	
	0.46"	07/06/21	Mostly Cloudy 90/72	2:10 PM	
Wednesday	0.00"				_
Thursday Friday	0.03"				-
Saturday	1.31"				
					-1
	None				
Complaints:					
Construction Sequencing:					
		orary or permanent cessati	on of grading, earthwork, or ground	disturbance in the last 14 day	/s?
Rough grading began on site	e (6/29/21).				
NAME:		the continued of the second	41-4	4 dec-20	
Rough grading began on site		ling, earthwork, or ground (disturbance scheduled in the next 1	4 days?	
Trough grading began on site	C (O/ZO/ZT).				
	abilization measures listed in this	section are being impleme	nted?		
Existing vegetation (6/29/21)).				
Charlist Overtions					
Checklist Questions:					
Are receiving waters adiac	ent to the project free of a	nv significant signs o	f erosion or sediment that we	ould be associated with	the construction activity?
Yes					
Create Corrective Action?					
N/A					
Have disturbed areas been	seeded or otherwise stab	ilized as required? Lis	st inactive portions of the pro	ject and if stabilization	measure are adequate or
needed to prevent erosion		<u> </u>			
Yes Create Corrective Action?					
N/A					
	rete, construction material	, hazardous, etc.) beir	ng managed properly?		
Yes Create Corrective Action?					
N/A					
Ave construction outside	a and adjacent storets but	a majutaje - 1 - 1 - 1 - 1			
Are construction entrance:	s and adjacent streets beir	ig maintained adequa	tery?		
Create Corrective Action?					
No - See BMP Section					
le dust associated with the	construction activity adec	ruately controlled on	the site?		
Yes	- construction activity duet	quality controlled Off			<u> </u>
Create Corrective Action?					
N/A					

Comments:
Comments:
1.) Site was active for rough grading during the last inspection.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 01	Construction Entrance	J3	7/13/2021	Pending	Yes			
Current Condition:	Pending -							
	The construction entrance should be installed.							
	Rich Engdahl and Drummond Crews were informed to complete by 7/13/21.							
CW 01	Concrete Washout	On Site	8/29/2021	Pending	No			
Current Condition:		Il be installed once paving/						
IP 01	Inlet Protection	F13	8/29/2021	Pending	No			
Current Condition: IP 02	Inlet Protection	rill be installed once the inte	et is installed and the inlet is 6/29/2021	s at or below grade. Active	No			
Current Condition:								
Current Condition.	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at time. E&A inspector will continue to monitor.							
IP 03	Inlet Protection	F2	6/29/2021	Active	No			
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at							
	time. E&A inspector will continue to monitor.							
IP 04	Inlet Protection	M4	8/29/2021	Pending	No			
Current Condition:			et is installed and the inlet is					
IP 05	Inlet Protection	P3	6/29/2021	Active	No			
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at time. E&A inspector will continue to monitor.							
IP 06	<u>'</u>	P2	6/00/0004	A ativo	T No			
Current Condition:	Inlet Protection		6/29/2021	Active	No mondation is peeded a			
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at time. E&A inspector will continue to monitor.							
IP 07	Inlet Protection	Q4	8/29/2021	Pending	No			
Current Condition:			et is installed and the inlet is		110			
IP 08	Inlet Protection	U4	8/29/2021	Pending	No			
Current Condition:		ill be installed once the inle	et is installed and the inlet is		-			
IP 09	Inlet Protection	X3	6/29/2021	Active	No			
Current Condition:	· · · · · · · · · · · · · · · · · · ·		enue. Due to the location o	f the inlet no BMP recom	mendation is needed a			
	time. E&A inspector will co							
IP 10	Inlet Protection	X2	6/29/2021	Active	No			
Current Condition:			enue. Due to the location of	t the inlet no BMP recomi	mendation is needed a			
IP 11	time. E&A inspector will co	Y6	8/29/2021	Pending	No			
Current Condition:			et is installed and the inlet is		INO			
IP 12	Inlet Protection	Y7	8/29/2021	Pending	No			
Current Condition:		ill be installed once the inle	et is installed and the inlet is					
IP 13	Inlet Protection	Y8	8/29/2021	Pending	No			
Current Condition:	Pending - The inlet filter w	ill be installed once the inle	et is installed and the inlet is	at or below grade.				
IP 14	Inlet Protection	Y11	8/29/2021	Pending	No			
Current Condition:			et is installed and the inlet is		1			
PB 01	Portable toilet	On Site	7/6/2021	Active	No			
Current Condition:	Good Condition - Rich Engdahl installed/secured a portable toilet adjacent to CE 01 prior to the inspection on 7/6/21.							
SF 01 - SF 06	Silt Fence	G3 to B15	6/29/2021	Active	No			
Current Condition:			F 06 prior to the inspection		110			
SF 07 - SF 12	Silt Fence	B16 to P12	6/29/2021	Active	No			
Current Condition:			F 12 prior to the inspection		-1			
SF 13 - SF 17	Silt Fence	S12 to Z5	6/29/2021	Active	No			
Current Condition:			F 17 prior to the inspection					
SF 18 - SF 22	Silt Fence	Z3 to K3	6/29/2021	Active	No			
Current Condition:			F 22 prior to the inspection		T			
STR	Streets	On Site	6/29/2021	Active	No			
Current Condition: SWPPP Sign 01	Good Condition - No majo		7/6/0004	Dondina	Vac			
Current Condition:	SWPPP Signs Pending -	Adjacent to CE 1	7/6/2021	Pending	Yes			
Current Condition:	, storing							
	SWPPP sign should be installed.							
	erri i eigi eriodia de riotarioa.							
	The E&A inspector will install the SWPPP sign when the sign is received from the sign shop. Not done as of last inspection.							
			<u> </u>	J 1133 33770 W				
	Lule Orthaly				- ·			
	and windly			Reviewed By:	Et Su			