E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services D	Dept. Manager			Engineering	Answers
		E&A- P2	020.056.003		
Inspector: Alex Brown					Stage
Project Name:	5Ds Transportation Trucking Terminal IA - 39263 - 38898				1
For Week Ending:		11/13/2021			
Project Location:	Southwest of S 29th Street and 21st Avenue in Council Bluffs, IA (Pottawattamie County)				
Grading:	98%	,			
Sanitary Sewer:	70%	<mark>)</mark>			
Storm Sewer:	70%	<mark>)</mark>			
Paving:	70%	•			
Seeding:	0%	)			
Utilities:	25%	)			
Overall Development:	30%	) <u> </u>			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday	0.00"				
Monday	0.00"				
Tuesday	0.00"	11/9/2021	Sunny 63/38	8:35 AM	
Wednesday	0.34"		_		
Thursday	0.00"				
Friday	0.00"				
Saturday	0.21"				
-	•	•	•	•	
Complaints:	None				
Construction Sequencing					•
iwnich portion(s) (i.e. drainage b	asins) of the site have had a temp	orary or permanent cessation	on of graging, earthwork, or gro	und disturbance in the last 14 days	7

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/29/21).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

**Create Corrective Action?** 

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

**Create Corrective Action?** 

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

No, see BMP section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No, see BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

1		
ı	N/A	
1	,,	

# Comments:

- 1.) Site was active for building construction and sewer installation during the last inspection.
  2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21.

  Findings / Corrective Actions (Date):
  Findings / Corrective Actions (Date):
  1.) Some maintenance is required in the BMP section.

Unique Name CE 01	Type Construction Entrance	Location J3	Projected Install Date	Status Removed	Maintenance
Current Condition:		removed the construction e	entrance prior to the inspec		ļ
CE 02	Construction Entrance	Z7	10/19/2021	Active	Yes
Current Condition:			ed the construction entrance		
	More rock should be adde		Not done as of last inspecti	on.	
CW 01	Concrete Washout	On Site	8/10/2021	Active	Yes
Current Condition:	cleaned up the concrete we Rich Engdahl installed a concrete washout should	aste from around the site a concrete washout west of the be cleaned out and concre	y concrete washouts on site and installed a third concret e former CE 01 prior to the te waste should be removed.  Not done as of last inspections of the concrete waste should be removed.	e washout on site prior to inspection on 10/26/21.  d from the eastern side of	the inspection on 9/1
			the inercetion on 9/10/21		
Current Condition: IP 01	Inlet Protection	cneck was regraded prior t F13	o the inspection on 8/10/21 8/29/2021	Pending	No
Current Condition:			t is installed and the inlet is		INO
IP 02	Inlet Protection	F3	6/29/2021	Active	No
Current Condition:			enue. Due to the location of		
one ochanion.	time. E&A inspector will co				
IP 03	Inlet Protection	F2	6/29/2021	Active	No
Current Condition:	Active - This is an existing time. E&A inspector will co		enue. Due to the location of	f the inlet no BMP recomm	nendation is needed a
IP 04	Inlet Protection	M4	8/29/2021	Pending	No
Current Condition:	1 0 0	stalled the inlet prior to the . E&A inspector will continu	inspection on 10/26/21. Due to monitor.	ue to the area being paved	, inlet protection is no
IP 05	Inlet Protection	P3	6/29/2021	Active	No
Current Condition:		inlet located off of 21st Av	enue. Due to the location o		nendation is needed
IP 06	Inlet Protection	P2	6/29/2021	Active	No
Current Condition:			enue. Due to the location o		
IP 07	Inlet Protection	Q4	10/5/2021	Pending	No
Current Condition:		stalled the inlet prior to the . E&A inspector will continu	inspection on 10/05/21. Due to monitor.	ue to the area being paved	, inlet protection is no
IP 08	Inlet Protection	U4	10/5/2021	Active	No
Current Condition:			inlet protection prior to the		110
IP 09	Inlet Protection	X3	6/29/2021	Active	No
Current Condition:	Active - This is an existing time. E&A inspector will co		enue. Due to the location o	f the inlet no BMP recomn	nendation is needed a
IP 10	Inlet Protection	X2	6/29/2021	Active	No
Current Condition:	time. E&A inspector will co	ontinue to monitor.	enue. Due to the location o		
IP 11	Inlet Protection		10/5/2021	Active	No
Current Condition: IP 12		gdahl installed the inlet and Y7	l inlet protection prior to the		N <sub>0</sub>
Current Condition:	Inlet Protection Good Condition - Rich End		10/5/2021 I inlet protection prior to the	Active	No
IP 13	Inlet Protection	Y8	10/5/2021	Active	No
Current Condition:			inlet protection prior to the		
IP 14	Inlet Protection	Y11	10/5/2021	Active	No
Current Condition:		gdahl installed the inlet and	inlet protection prior to the		
PB 01	Portable toilet	On Site	7/6/2021	Active	No
Current Condition:			ortable toilet adjacent to CE		
SF 01 - SF 06 Current Condition:	Silt Fence G3 to B15 G/29/2021 Active Yes  Fair Condition - Rich Engdahl installed SF 01 to SF 06 prior to the inspection on 6/29/21. The city inspector pre-approved remove of SF 3-6 on 9/23/21. SF 3 and 4 were removed prior to the inspection on 10/05/21. Due to city approval and the grade in the area reinstallation will not be recommended. SF 6 was damaged prior to the inspection on 10/05/21. Due to the grade in the area and planned removal of silt fence, repairs will not be recommended at this time. E&A inspector will monitor.				
	The remaining section of S	ce, repairs will not be reco SF 6 on the west side of the d to complete by 11/2/21. I	e basin can be removed.		

SF 07 - SF 12	Silt Fence	B16 to P12	6/29/2021	Active	Yes	
Current Condition:	Fair Condition - Rich Engdahl installed SF 07 to SF 12 prior to the inspection on 6/29/21. Rich Engdahl was observed actively					
		SF 12 was damaged durin				
		where damaged by utility v				
		n prior to the inspection on				
		informed the E&A inspector				
	to these constraints and completion of paving in the area, the recommendation has been modified, but the same reminder dates					
	apply.					
		out where full in multiple loo			sinded on 7/29/21 9/4/21	
	8/10/21, 8/26/21, 10/21/21		Not dolle as of last ilispect	ion. Nich Enguani was fem	iiilueu 011 7/20/21, 0/4/21,	
SF 13 - SF 17	Silt Fence	S12 to Z5	6/29/2021	Active	Yes	
Current Condition:		dahl installed SF 13 to SF				
		constraints prevent SF 13				
		ndation has been modified,				
	was removed during sev	ver installation prior to th	e inspection on 11/8/21.	Due to active work in the	area, reinstallation is not	
		ne. E&A inspector will co			·	
		·				
	SF 14 should be repaired	where damaged, or can be	removed.			
		•				
	Rich Engdahl was informe	ed to complete by 8/10/21. I	Not done as of last inspect	<mark>ion. Rich Engdahl was rem</mark>	inded on 8/10/21, 8/26/21,	
	10/21/21, 10/27/21					
SF 18 - SF 22	Silt Fence	Z3 to K3	6/29/2021	Active	No	
Current Condition:	Good Condition - Rich Er	ngdahl installed SF 18 to SF	22 prior to the inspection	on 6/29/21. Rich Engdahl	reinstalled/repaired the silt	
	fence where damaged by	utility work prior to the insp	ection on 9/14/21. Rich En	igdahl removed a small por	tion of SF 18 prior to the	
	inspection on 10/19/21. The	ne area is flat and vegetate	d, so reinstallation is not re	ecommended at this time. I	E&A inspector will continue	
	to monitor.					
STR	Streets	On Site	6/29/2021	Active	No	
Current Condition:	Good Condition - Rich En	gdahl cleaned up the track	out on 21st Ave. prior to the	e inspection on 9/7/21. Ric	h Engdahl cleaned up	
	trackout around CE 1 prior to the inspection on 10/12/21. Rick Engdahl cleaned up trackout around CE 02 prior to the inspection on					
	11/2/21.					
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	8/3/2021	Active	No	
Current Condition:	Good Condition - The E&A	A inspector installed the SV	VPPP sign adjacent to CE	01 during the inspection or	n 8/3/21.	
	10					
	182			G	to See	
Inspector Signature:				Reviewed By:		