E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

	Ds Transportati IA - 39 5/2	020.056.003 on Trucking Term 263 - 38898 28/2022	inal	Stage 1		
	IA - 39 5/2	263 - 38898	inal			
	IA - 39 5/2	263 - 38898	inal	1		
	IA - 39 5/2	263 - 38898		ı		
Southwest of S 29th	5/2			1		
Southwest of S 29th				51501		
	Southwest of S 29th Street and 21st Avenue in Council Bluffs, IA (Pottawattamie County)					
100%						
100 /0						
Amount in tenths	Date inspected	Weather Conditions	Time			
				Wee		
0.00"						
0.00"						
0.72"	5/24/2022	Cloudy 61	10:00 AM			
1.11"		_				
0.01"						
0.00"						
0.00"						
-		<u> </u>	-			
None						
0 0 0 0	0.00" 0.00" 0.72" 1.11" 0.01" 0.00"	100% 100% 100% 100% 100% 100% 100% 100%	100% 100% 100% 100% 100% 100% 100% 100%	100% 100% 100% 100% 100% 100% 100% Date inspected Weather Conditions Time Double inspected Cloudy 61 10:00 AM 1.11" 1.11" 1.00" 1.00"		

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12/22). Fine grading (4/26/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21). Grading along the northern perimeter ROW (3/1/22). Grading ceased (3/8/22). Minor excavation for sprinkler system (4/12/22). Fine grading (4/26/22).

Existing vegetation (6/29/21). Seeding / matting PCSMP basin (5/10/22). Sodding throughout the site (5/17/22)

Checklist Questions

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Yes Create Corrective Action?

Comments:

- 1.) Site was active during the last inspection.
- 2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21. Rich Engdahl seeded / matted the basin prior to the 5/10/22 inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP section.
- 2.) Rich Engdahl seeded / matted the basin prior to the 5/10/22 inspection. Rich Engdahl sodded the remainder of the site prior to the 5/17/22 inspection. E&A inspector will continue to monitor for vegetative growth in the PCSMP basin.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 01	Construction Entrance	J3		Removed	
Current Condition:		paved the entrance prior to	the inspection on 12/21/21		!
CE 02	Construction Entrance	Z7	110 110p000011 011 12,2 1,2 1	Removed	
Current Condition:		paved the construction enti	ranco prior to the inspection		
CW 01	Concrete Washout	On Site	I	Removed	
Current Condition:		removed the concrete was	acut prior to the increation		
			lout prior to the inspection		1
D 01	Diversion Check	Z6 to Z8		Removed	
Current Condition:		check was regraded prior t			
IP 01	Inlet Protection	F13	8/29/2021	Active	No No
Current Condition:		alled the inlet prior to the in . E&A inspector will continu		to the area being paved,	nlet protection is not
IP 02	Inlet Protection	F3	6/29/2021	Active	No
Current Condition:	Good Condition - This is a	n existing inlet located off	of 21st Avenue. Rich Engda	ahl installed inlet protection	n prior to the 3/22/22
	Good Condition - This is an existing inlet located off of 21st Avenue. Rich Engdahl installed inlet protection prior to the 3/22/22 inspection.				
IP 03	Inlet Protection	F2	6/29/2021	Active	No
Current Condition:		inlet located off of 21st Av			
Jurient Condition.	time. E&A inspector will co		ende. Due to the location c	i the injectio bivii Tecomi	nendation is needed t
IP 04	Inlet Protection	M4	8/29/2021	Active	No
Current Condition:		alled the inlet prior to the in			No plot protection is not
surrent Condition:		. E&A inspector will continu		to the area being paved, i	niet protection is not
IP 05	Inlet Protection	P3	6/29/2021	Active	No
Current Condition:	Good Condition - This is a inspection.	n existing inlet located off of	of 21st Avenue. Rich Engda	ahl installed inlet protectio	n prior to the 3/22/22
IP 06	Inlet Protection	P2	6/29/2021	Active	No
Current Condition:		inlet located off of 21st Av			
Juli Cili Collultion.	time. E&A inspector will co		ondo. Duo to the lecation o	Tallo IIIIot IIIo Bivii 1000IIII	nonadion lo nocaca i
IP 07	Inlet Protection	Q4	10/5/2021	Active	No
Current Condition:		alled the inlet prior to the in			
Jurient Condition.		. E&A inspector will continu	•	to the area being paved,	filet protection is not
ID 00		<u> </u>			
IP 08	Inlet Protection	U4	10/5/2021	Active	No
Current Condition:		gdahl installed the inlet and			
IP 09	Inlet Protection	X3	6/29/2021	Active	No
Current Condition:		n existing inlet located off of	of 21st Avenue. Rich Enga	ani installed inlet protectio	n prior to the 3/22/22
	inspection.				
IP 10	Inlet Protection	X2	6/29/2021	Active	No
Current Condition:		inlet located off of 21st Av	enue. Due to the location o	of the inlet no BMP recomr	nendation is needed
	time. E&A inspector will co			-	
IP 11	Inlet Protection	Y6	10/5/2021	Active	No
Current Condition:		gdahl installed the inlet and			
IP 12	Inlet Protection	Y7	10/5/2021	Active	No
Current Condition:		alled the inlet and inlet prot ection on 11/23/21. Due to nonitor			
IP 13	Inlet Protection	Y8	10/5/2021	Active	No
Current Condition:		alled the inlet and inlet prot			
aon condition		ection on 11/23/21. Due to			
IP 14	Inlet Protection	Y11	10/5/2021	Active	No
Current Condition:	Good Condition - Rich Eng	gdahl installed the inlet and	inlet protection prior to the	inspection on 10/05/21.	
PB 01	Portable toilet	On Site		Removed	
Current Condition:		removed the portable toilet	prior to the 5/17/22 inspec		
SF 01 - SF 06	Silt Fence	G3 to B15		Removed	
Current Condition:	Removed - The city inspe 10/05/21. Rich Engdahl re	ctor pre-approved removal moved the remaining secti al in this area for sprinkler	on of SF 6 prior to the insp	and 4 were removed pricection on 11/30/21. As of	11/30/21, the City has
SF 07 - SF 12	Silt Fence	B16 to P12		Removed	

SF 13 - SF 17	Silt Fence	S12 to Z5		Removed				
Current Condition:	Removed - As of 11/30/21	, the City has approved silt	fence removal in this area	. Rich Engdahl removed S	F 13 and SF 14 prior to			
	the inspection on 12/7/21. Rich Engdahl removed SF 15 - 17 prior to the inspection on 3/8/22.							
SF 18 - SF 22	Silt Fence	Z3 to K3		Removed				
Current Condition:	Removed - Rich Engdahl removed the silt fence posts from SF 18 - 22 prior to the inspection on 12/14/21. Rich Engdahl removed							
	the trenched silt fence fabric prior to the inspection on 3/1/22.							
STR	Streets	On Site	6/29/2021	Active	No			
Current Condition:	Good Condition - Rich Engdahl cleaned up the trackout on 21st Ave. prior to the inspection on 9/7/21. Rich Engdahl cleaned up							
	trackout around CE 1 prior to the inspection on 10/12/21. Rick Engdahl cleaned up trackout around CE 02 prior to the inspection 11/2/21. Minor sedimentation was observed around CE 1 during the 12/14/21 inspection. Rich Engdahl cleaned up the sedimen							
	around CE 1 prior to the 1	2/28/21 inspection. Rich Er	ngdahl cleaned 21st Avenu	e prior to the 3/22/22 inspe	ection.			
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	8/3/2021	Active	No			
Current Condition:	Good Condition - The E&A inspector installed the SWPPP sign adjacent to CE 01 during the inspection on 8/3/21. The E&A							
	inspector reinstalled the SWPPP sign during the 2/1/22 inspection. Rich Engdahl relocated the SWPPP sign S 21st Avenu							
	anticipation of fine grading	/ sodding prior to the 4/26	/22 inspection.					
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in							
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted.							
	Based on my inquiry of the	person or persons who m	erson or persons who manage the system or those persons directly responsible for gathering the					
	information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violation							
/	1							
l Man				Q.	- Su			
Inspector Signature:				Reviewed By:				