E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

|  |   | E&A- P2017.2   | 258.000             |          |        |  |  |
|--|---|--|---------------------|----------|--------|--|--|
| Inspector: Alex Brown                                | : Alex Brown                              |  |                     |          |        |  |  |
| Project Name:  | CSW-2                                     |  | 1                   |          |        |  |  |
| For Week Ending:                                     |   | 2/12/2022  |                     |          |        |  |  |
| Project Location:                                    | 120th Str                                 | 120th Street and Schram Road, Papillion, NE (Sarpy County) |                     |          |        |  |  |
| Grading:   | 97%                                       |  |                     |          |        |  |  |
| Sanitary Sewer:                                      | 96%                                       |  |                     |          |        |  |  |
| Storm Sewer:   | 96%                                       |  |                     |          |        |  |  |
| Paving:  | 96%                                       |  |                     |          |        |  |  |
| Seeding:   | 50%                                       |  |                     |          |        |  |  |
| Utilities:   | 90%                                       |  |                     |          |        |  |  |
| Overall Development:                                 | 48%                                       |  |                     |          |        |  |  |
| RAIN FALL AMOUNTS                                    | Amount in tenths                          | Data increased   | Weather Conditions  | T:       |        |  |  |
| RAIN FALL AMOUNTS                                    | Amount in tentils                         | Date inspected   | Weather Conditions  | Time     | Week 1 |  |  |
|  |   | 4  | <u> </u>            |          | Week   |  |  |
| Sunday:  | 0.00"                                     |  | l l                 |          |        |  |  |
| Sunday:<br>Monday                                    | 0.00"                                     |  |                     |          |        |  |  |
| Monday   | 0.00"                                     |  |                     |          |        |  |  |
|  |   | 2/9/2022   | Partly Cloudy 49/28 | 12:00 PM |        |  |  |
| Monday<br>Tuesday                                    | 0.00"<br>0.00"                            | 2/9/2022   | Partly Cloudy 49/28 | 12:00 PM |        |  |  |
| Monday<br>Tuesday<br>Wednesday                       | 0.00"<br>0.00"<br>0.00"                   | 2/9/2022   | Partiy Cloudy 49/28 | 12:00 PM |        |  |  |
| Monday<br>Tuesday<br>Wednesday<br>Thursday           | 0.00"<br>0.00"<br>0.00"<br>0.02"          | 2/9/2022   | Partly Cloudy 49/28 | 12:00 PM |        |  |  |
| Monday<br>Tuesday<br>Wednesday<br>Thursday<br>Friday | 0.00"<br>0.00"<br>0.00"<br>0.02"<br>0.22" | 2/9/2022   | Partly Cloudy 49/28 | 12:00 PM |        |  |  |
| Monday<br>Tuesday<br>Wednesday<br>Thursday<br>Friday | 0.00"<br>0.00"<br>0.00"<br>0.02"<br>0.22" | 2/9/2022   | Partly Cloudy 49/28 | 12:00 PM |        |  |  |

# Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/18) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/18). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/19). Stockpiling in the western portion of Dev 2 (4/24/19). Grading has begun in the western portion of Dev 2 (5/9/19). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/19). Stripping/Grading in northeastern portion of Dev 2 (6/27/19) Minor regrading/excavation in DEV 3 -School (7/31/19). Excavation in Dev 3 and Dev 4 for sanitary installation (08/08/19). Trenching in Dev 4 for utility installation (09/04/19). Grading has temporarily ceased throughout the site (10/11/19). Excavation near SB 4 for basin installation (10/22/19). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/19). Stripping/grading in DEV A (10/31/19). Disking occurring in Dev 4 (11/7/19). Sanitary installation in Dev 2/3 (11/7/19). Grading in Dev 5 and Dev A for basin excavation (11/14/19). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/19). Grading in Dev 4 (12/12/19). Grading has temporarily ceased due to winter conditions (1/23/20). Grading has resumed (4/27/20); Backfilling of curbs for paving underway (10/21/200). Excavation on Lot 110 (12/22/20). Grading on eastern side of Dev 2 (1/12/21). Grading in Dev A, and northern portion of Dev 2 (2/23/21). Excavation by 124th st and Gold Coast Rd (3/4/21). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/21). Utilities were put in the southwest corner of the site (4/21/21). Grading in SW corner of site by Calabretto Building Group (9/8/21).

## Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/18) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/18). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/19). Stockpiling in the western portion of Dev 2 (4/24/19). Grading has begun in the western portion of Dev 2 (5/9/19). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/19). Stripping/Grading in northeastern portion of Dev 2 (6/27/19) Minor regrading/excavation in DEV 3 -School (7/31/19). Excavation in Dev 3 and Dev 4 for sanitary installation (08/08/19). Trenching in Dev 4 for utility installation (09/04/19). Grading has temporarily ceased throughout the site (10/11/19). Grading has resumed for basin installation (10/16/19) Grading has resumed throughout the site (10/22/19). Excavation near SB 4 for basin installation (10/22/19). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/19). Stripping/grading in DEV A (10/31/19). Disking occurring in Dev 4 (11/7/19). Sanitary installation in Dev 2/3 (11/7/19). Grading in Dev 5 and Dev A for basin excavation (11/14/19). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/19). Grading in Dev A (12/12/19). Grading has temporarily ceased due to winter conditions (1/23/20). Grading has resumed (4/27/20); Backfilling of curbs for paving underway (10/21/20). Excavation on Lot 110 (12/22/20). Grading on eastern side of Dev 2 (1/12/21). Grading in Dev A, and northern portion of Dev 2 (2/23/21). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/21). Utilities were put in the southwest corner of the site (4/21/21). Grading in SW corner of site by Calabretto Building Group (9/8/21).

## What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/18). EM 1 partially installed (09/30/19). DEJ seeded the central drainage around the future S. 124th St., the slope in the northeastern quadrant of the site (6/16/20); school site was sodded (12/9/20). ROW seeding began (6/2/21). Matting of the slope west of S 120th entrance (8/25/21).

## Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

No, See BMP Section (SB 5)

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

# No, See Findings Section

# Create Corrective Action? No, See BMP and Findings Section

Create Corrective Action?
No, See BMP Section

Is dust associated with the construction

Yes

N/A

#### Comments

#### Comments:

- 1) Site was active for home construction during the last inspection.
- 2) Ashbury Hills Self Storage (CSW-202105789) is active on Lot 166 of the Ashbury Hills development as of 9/13/21.

# Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) E&A will monitor the removal of the inlet filters around the school project with the site stabilization. E&A inspector received an email from Tyson Smith with Lamp Rynearson 1/11/21 that they did not recommend putting inlet filters around the school. GPCS was informed to remove the inlet filters by 3/11/21. GPCS removed 5 inlet filters prior to the 3/24/21 inspection. As of 4/9/21 there are two inlet filters left by the school, E&A inspector will continue to monitor. GPCS was reminded on 4/30/21, 5/4/21, 5/6/21, 5/11/2021, 5/19/21, 5/30/21, 6/25/21, 7/14/21, 8/13/21, 9/10/21, 9/30/21. Peter Katt, Gene Graves, and Commercial Seeding were reminded on 10/14/21, 11/3/21
- 3) Disturbed areas throughout the site should be stabilized. Silt fences should be installed on various lot corners throughout the site until the areas are stabilized. GPCS was informed to complete by 3/22/21. Not done as of last inspection. GPCS was reminded on 4/12/21, 4/16/21, 4/30/21, 5/4/21, 5/6/21, 5/11/21, 5/19/21, 5/30/21, 6/25/21, 7/14/21, 8/13/21, 9/10/21. Plans to stabilize disturbed areas were sent to Commercial Seeding on 10/1/21. Peter Katt, Gene Graves, and Commercial Seeding were reminded on 10/14/21, 11/3/21. Graves Development was reminded on 12/6/21.
- 4) Concrete waste should be removed where spot dumping has taken place. Peter Katt, Gene Graves, and Great Plains Contractor Services were informed to complete by 4/28/21. Not done as of the last inspection. GPCS was reminded on 4/30/21, 5/4/21, 5/6/21, 5/11/21, 5/19/21, 5/30/21, 6/25/21, 7/14/21, 8/13/21, 9/10/21, 9/30/21. Peter Katt, Gene Graves, and Commercial Seeding were reminded on 10/14/21, 11/3/21

| Unique Name        | Туре   | Location  | Projected Install Date          | Status               | Maintenance                          |  |  |  |
|--------------------|--|---|---------------------------------|----------------------|--------------------------------------|--|--|--|
| A 1                | Area Inlet Protection  | R 16  |                                 | Removed              |                                      |  |  |  |
| Current Condition: | Removed - Silt fence around  | Removed - Silt fence around the inlet will not be recommended as of 4/16/21 due to inlet leading to a sediment basin. |                                 |                      |                                      |  |  |  |
| B 1                |  | North side of site (west of   |                                 |                      |                                      |  |  |  |
|                    | Temporary Berm   | SB 2)   |                                 | Removed              |                                      |  |  |  |
| Current Condition: | Removed - DEJ Grading rem  | Removed - DEJ Grading removed the temporary berm during the excavation of SB 5 prior to inspection on 11/14/19.       |                                 |                      |                                      |  |  |  |
| B 2                | Temporary Berm   | Southwest side of site (NE of SB 5)   |                                 | Removed              |                                      |  |  |  |
| Current Condition: |  |   | ection on 12/18/19. The her     |                      | L<br>at this time. E&A will monitor. |  |  |  |
| ourion condition.  | Tromovou BEO Grading rom   | oved the benne prior to mope  | 500011 011 12, 10, 10. THE BOI  | ino are not necaca   | at the time. Last will memor.        |  |  |  |
|                    | Stabilized Construction  |   |                                 |                      | I                                    |  |  |  |
| CE 1               | Entrance   | Schram Road (W27)   |                                 | Removed              |                                      |  |  |  |
| Current Condition: | Removed - The construction of  | entrance is no longer necess  | ary as it is removed and no     | longer in use due to | o the Schram Road Improvements       |  |  |  |
|                    | project grading reaching the a   | rea as of the inspection on 8   | 3/18/20.                        |                      |                                      |  |  |  |
| CE 2               | Stabilized Construction  | Cobrom Dood (AA27)  |                                 | Removed              |                                      |  |  |  |
|                    | Entrance   | Schram Road (AA27)  |                                 |                      |                                      |  |  |  |
| Current Condition: |  |   |                                 |                      | construction. Since this BMP is      |  |  |  |
|                    | associated with the school pro   | pject, E&A will no longer insp  | ect its effectiveness as of the | ne 10/11/19 inspect  | ion.                                 |  |  |  |
| CE 3               | Stabilized Construction  | Schram Road (O27)   |                                 | Removed              |                                      |  |  |  |
|                    | Entrance   | , ,   |                                 |                      |                                      |  |  |  |
| Current Condition: |  |   |                                 |                      | n on 9/24/20. Reinstallation is not  |  |  |  |
|                    | necessary due to grading for tinspection on 9/24/20.   | ine Scram Road Improveme  | nts (114th to 132nd Street)     | project reaching the | e entrance location prior to the     |  |  |  |
|                    | inspection on 9/24/20.   |   |                                 |                      |                                      |  |  |  |
| CW 1               | Concrete Washout   | North of SB 4   |                                 | Removed              |                                      |  |  |  |
| Current Condition: | Removed- Tab Construction r  | emoved the washout pit prio   | r to 11/18/20                   |                      |                                      |  |  |  |
| CW 2               | Concrete Washout   | Outlot A-South 124th  | 5/19/2021                       | Active               | No                                   |  |  |  |
| CW Z               | Concrete Washout   | Street & Horizon Street   | 3/19/2021                       | Active               | NO                                   |  |  |  |
| Current Condition: | Good Condition- GPCS install   | ed the washout pit prior to th  | e inspection on 5/19/21.        |                      |                                      |  |  |  |
| D 1                | Temporary Diversion Ditch  | (BB8-BB15)  |                                 | Removed              |                                      |  |  |  |
| Current Condition: | Removed - The majority of the  | e diversion was graded out p  | rior to the inspection on 9/2   | 4/20. Reinstallation | does not appear necessary at this    |  |  |  |
|                    | time due to establishment of v   |   |                                 |                      | ,,                                   |  |  |  |
| D 2                | Temporary Diversion Ditch  | (Q1-V2)   |                                 | Removed              |                                      |  |  |  |
|                    | ' '  | ( ,   | 0/07/02 :                       |                      |                                      |  |  |  |
| Current Condition: |  | o longer necessary as of the  | inspection on 8/27/20 due t     | to paving of S. 123r | d Avenue, which will divert water    |  |  |  |
|                    | via curb inlets to the basin.  |   |                                 |                      |                                      |  |  |  |
| D 3                | Temporary Diversion Ditch  | (C20-C26)   | 8/27/2020                       | Active               | No                                   |  |  |  |
| Current Condition: | Good Condition - DEJ installed the diversion prior to the inspection on 8/27/20. Commercial Seeding redefined the diversion prior to the |   |                                 |                      |                                      |  |  |  |
|                    | inspection on 11/11/21.  |   |                                 |                      |                                      |  |  |  |
| D 4                | Temporary Diversion Ditch  | (BB21-BB25)   |                                 | Removed              |                                      |  |  |  |
| Current Condition: | Removed- Due to pavement   | ,   | diversion ditch was remove      | d as of 10/21/2020   | L                                    |  |  |  |
|                    | ·  |   |                                 |                      | Ι                                    |  |  |  |
| D 5                | Temporary Diversion Ditch  | (X2-BB6)  | 8/27/2020                       | Pending              | No                                   |  |  |  |

|  | Pending - Perimeter silt fence diversion is not recommended  |  |  | ment as of the 7/10  | 21 inspection. Installing the  |
|--|--|--|--|--|--|
| D 6  | Temporary Diversion Ditch  | (V27-AA27)   |  | Removed  |  |
| Current Condition:   | Removed - The diversion will location as well as the start of  | not be necessary as of the in  |  |  | detation in part of the intended der of the intended location.   |
| D 7  | Temporary Diversion Ditch  | (E28-P28)  | 8/27/2020  | Active   | No   |
| Current Condition:   | Good Condition - DEJ installe 6/15/21.   | d the diversion prior to the in  | spection on 8/27/20. DEJ re  | edefined the diversi   | on prior to the inspection on  |
| D 8  | Temporary Diversion Ditch  | (B8-B13)   | 8/27/2020  | Active   | No   |
| Current Condition:   | Good Condition - DEJ installe 5/19/21.   | d the diversion prior to the in  | spection on 8/27/20. GPCS  | redefined the diver  | sion prior to the inspection on  |
| D 9  | Temporary Diversion Ditch  | (C3-E2)  |  | Removed  |  |
| Current Condition:   | Removed- Due to pavement of  | operations and school work,  | diversion ditch was remove   | d as of 10/21/2020   |  |
| EM 1   | Erosion Control Matting  | (CC20-CC27)  | 9/30/2019  | Active   | No   |
| Current Condition:   | Good Condition - Erosion con installation during future inspe  |  |  |  |  |
| EM 2   | Erosion Control Matting  | B5   | 11/15/2018   | Pending  | No   |
| Current Condition:   | Pending - Will be installed who  | en grading of area is comple   | te.  | -  | •  |
| EM 3   | Erosion Control Matting  | D3   | 11/15/2018   | Pending  | No   |
| Current Condition:   | Pending - Will be installed who  |  | te.  |  |  |
| ET 1   | Erosion Control Terrace  | C 12-21  |  | Removed  |  |
| Current Condition:   | Removed - The erosion contr  | ol terrace has been removed  | and replaced with D-3 and  | D-8 as of the inspe  | ection on 8/27/20.   |
| FT 1   | Fuel Tanks   | O23  |  | Removed  |  |
| Current Condition:   | Removed - Roth Enterprises   | removed the fuel tank prior to   | o the inspection on 5/26/20.   |  |  |
| Lot 1  | Individual Lot   | Lot 1  | 3/24/2021  | Active   | No   |
| Current Condition:   | Active - Ideal Designs began behind the lot, E&A inspector   |  |  | The lot is relatively  | flat and there is a vegetated area   |
| Lot 4  | Individual Lot   | Lot 4  |  | Removed  |  |
| Current Condition:   | Removed - Belt Construction  | sodded the lot prior to the in   | spection on 11/16/21.  |  |  |
| Lot 5  | Individual Lot   | Lot 5  |  | Removed  |  |
| Current Condition:   | Removed - Peter Young sodd   | ded the lot prior to the inspec  | tion on 11/16/21.  | -  |  |
| Lot 6  | Individual Lot   | Lot 6  |  | Removed  |  |
| Current Condition:   | Removed - Belt Construction  |  |  |  |  |
| Lot 19 Current Condition:  | Individual Lot   | Lot 19   | 9/13/2021  | Active   | No  Noved the dirt piles from the ROW  |
| Current Condition.   | prior to the 9/22/21 inspection recommended at this time. El   | n. The front of the lot is down  | grade of the street, and the   |  |  |
| Lot 26<br>Current Condition:   | Individual Lot   | Lot 26   | 7/6/2021   | Active   | Yes d in the ROW during the 7/6/21   |
|  | inspection. Timeless Homes r<br>piles prior to the inspection or   | removed the concrete waste   |  |  | imeless Homes removed the dirt   |
|  |  | ed to complete by 7/17/21. N   | ot done as of last inspection  | n. Timeless Homes  | was reminded on 7/29/21, 8/11/21   |
| Lot 29   |  | ed to complete by 7/17/21. N   |  | n. Timeless Homes  | was reminded on 7/29/21, 8/11/21   |
| Lot 29<br>Current Condition:   | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 1ndividual Lot Active - Colony Custom Home Colony Homes removed the co   | d to complete by 7/17/21. N<br>12/16/21, 1/25/22<br>Lot 29<br>es began excavating the lot p<br>dirt piles prior to the 1/24/21 i   | 12/15/2021<br>prior to the 12/15/21 inspectinspection. The front of the I  | Active ion. Dirt piles were  |  |
| Current Condition:   | Timeless Homes was informe<br>9/10/21, 10/15/21, 11/12/21,<br>Individual Lot<br>Active - Colony Custom Home<br>Colony Homes removed the cono BMPs are recommended a  | d to complete by 7/17/21. N<br>12/16/21, 1/25/22<br>Lot 29<br>es began excavating the lot l<br>dirt piles prior to the 1/24/21 i<br>at this time. E&A inspector w  | 12/15/2021<br>prior to the 12/15/21 inspect<br>inspection. The front of the I<br>ill continue to monitor.  | Active<br>ion. Dirt piles were<br>ot is mostly flat and  | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  |
|  | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 1 Individual Lot Active - Colony Custom Home Colony Homes removed the cono BMPs are recommended a Individual Lot Active - Legacy Homes began 10/25/21 inspection. Legacy H   | ed to complete by 7/17/21. N 12/16/21, 1/25/22  Lot 29 es began excavating the lot pridit piles prior to the 1/24/21 is at this time. E&A inspector w  Lot 35 n excavating the lot prior to to thomes removed the dirt piles   | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Di s prior to the 11/11/21 inspe  | Active ion. Dirt piles were ot is mostly flat and Active irt piles were obser ction. Lot is mostly   | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is   |
| Current Condition:  Lot 35  Current Condition:   | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, Individual Lot Active - Colony Custom Home Colony Homes removed the cono BMPs are recommended a Individual Lot Active - Legacy Homes began 10/25/21 inspection. Legacy I surrounded by vegetation, so  | d to complete by 7/17/21. Note 12/16/21, 1/25/22  Lot 29 es began excavating the lot prior to the 1/24/21 is at this time. E&A inspector with the second of  | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Di s prior to the 11/11/21 inspe  | Active ion. Dirt piles were ot is mostly flat and Active irt piles were obser ction. Lot is mostly will continue to mo   | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is   |
| Current Condition:  Lot 35  Current Condition:  Lot 110  | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 1 Individual Lot Active - Colony Custom Home Colony Homes removed the cono BMPs are recommended a Individual Lot Active - Legacy Homes began 10/25/21 inspection. Legacy H   | d to complete by 7/17/21. Note 12/16/21, 1/25/22  Lot 29 es began excavating the lot prior to the 1/24/21 at this time. E&A inspector with this time. E&A inspector with the complete service of the c | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I inspection to monitor.  10/25/2021 he inspection on 6/22/21. Di s prior to the 11/11/21 inspect at this time. E&A inspector  | Active ion. Dirt piles were ot is mostly flat and Active irt piles were obser ction. Lot is mostly   | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is   |
| Current Condition:  Lot 35  Current Condition:  Lot 110  Current Condition:  | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 1ndividual Lot Active - Colony Custom Home Colony Homes removed the cono BMPs are recommended a Individual Lot Active - Legacy Homes began 10/25/21 inspection. Legacy homes was removed by vegetation, so Individual Lot Removed - Legacy Homes so  | d to complete by 7/17/21. Note 12/16/21, 1/25/22  Lot 29 es began excavating the lot prior to the 1/24/21 at this time. E&A inspector with the second to the | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Di s prior to the 11/11/21 inspe d at this time. E&A inspector  pection on 11/16/21.  | Active ion. Dirt piles were ot is mostly flat and Active irt piles were obser ction. Lot is mostly will continue to mo Removed   | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is nitor.  |
| Current Condition:  Lot 35  Current Condition:  Lot 110  | Timeless Homes was informed 9/10/21, 10/15/21, 11/12/21, | d to complete by 7/17/21. N 12/16/21, 1/25/22  Lot 29 es began excavating the lot light piles prior to the 1/24/21 at this time. E&A inspector w  Lot 35 n excavating the lot prior to the mes removed the dirt piles no BMPs are recommended Lot 110  ddded the lot prior to the insp  Lot 111  Lot 111  nes Omaha LLC began cons   | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Disprior to the 11/11/21 inspect at this time. E&A inspector  | Active ion. Dirt piles were ot is mostly flat and Active irt piles were obser ction. Lot is mostly will continue to mo Removed Active  | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is nitor.  No  |
| Current Condition:  Lot 35 Current Condition:  Lot 110 Current Condition:  Lot 111 Current Condition:                                      | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 1 Individual Lot Active - Colony Custom Home Colony Homes removed the cono BMPs are recommended a Individual Lot Active - Legacy Homes began 10/25/21 inspection. Legacy Homes varrounded by vegetation, so Individual Lot Removed - Legacy Homes so Individual Lot Good Condition - Legacy Hombehind the lot prior to the 1/15  | d to complete by 7/17/21. No. 12/16/21, 1/25/22  Lot 29 es began excavating the lot properties of the 1/24/21 is at this time. E&A inspector was been excavating the lot prior to the 1/24/21 is at this time. E&A inspector was been excavating the lot prior to the form of the dirt piles on BMPs are recommended but 110 bedded the lot prior to the inspection. Lot 111 mes Omaha LLC began conspection. E&A inspection.  | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Disprior to the 11/11/21 inspect at this time. E&A inspector  12/22/2020 etruction on 11/16/21.  12/22/2020 etruction prior to inspection or or will continue to monitor.   | Active ion. Dirt piles were ot is mostly flat and Active int piles were obser- ction. Lot is mostly will continue to mo Removed  Active on 12/22/20. Legacy  | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is nitor.  No v Homes placed straw wattles   |
| Current Condition:  Lot 35 Current Condition:  Lot 110 Current Condition:  Lot 111   | Timeless Homes was informed 9/10/21, 10/15/21, 11/12/21, 1 Individual Lot Active - Colony Custom Home Colony Homes removed the conor BMPs are recommended a Individual Lot Active - Legacy Homes began 10/25/21 inspection. Legacy Homes was undividual Lot Removed - Legacy Homes so Individual Lot Removed - Legacy Homes so Individual Lot Good Condition - Legacy Homes behind the lot prior to the 1/15 Individual Lot  | d to complete by 7/17/21. Note 12/16/21, 1/25/22  Lot 29 es began excavating the lot property of the 1/24/21 is at this time. E&A inspector who is a considerable of the lot prior to the 1/24/21 is at this time. E&A inspector who is a considerable of the lot prior to the one and the lot prior to the lot prior to the lot 110 odded the lot prior to the inspection. E&A inspection. E&A inspection. E&A inspection. E&A inspection. Lot 112 and lot 111 for more informatical considerable.  | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Disprior to the 11/11/21 inspect at this time. E&A inspector example.  12/22/2020 pection on 11/16/21.  12/22/2020 pertruction prior to inspection or will continue to monitor.  4/29/2021 attion as of 4/29/21. Legacy I  | Active ion. Dirt piles were ot is mostly flat and Active int piles were obser- ction. Lot is mostly will continue to mo Removed  Active on 12/22/20. Legacy Active Homes repaired the  | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so  No ved in the ROW during the flat, and rear of the lot is nitor.  No  |
| Current Condition:  Lot 35 Current Condition:  Lot 110 Current Condition:  Lot 111 Current Condition:  Lot 112 Current Condition:          | Timeless Homes was informed 9/10/21, 10/15/21, 11/12/21, | d to complete by 7/17/21. No. 12/16/21, 1/25/22  Lot 29 es began excavating the lot properties of the 1/24/21 at this time. E&A inspector with the second of | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Disprior to the 11/11/21 inspect at this time. E&A inspector  2 the inspection on 11/16/21.  12/22/2020 pection on 11/16/21.  12/22/2020 pertruction prior to inspection cor will continue to monitor.  4/29/2021 attion as of 4/29/21. Legacy It thes prior to the inspection of  | Active ion. Dirt piles were ot is mostly flat and Active irt piles were obser ction. Lot is mostly will continue to mo Removed  Active In 12/22/20. Legacy Active Homes repaired the In 10/13/21.                              | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so No ved in the ROW during the flat, and rear of the lot is nitor.  No v Homes placed straw wattles No v wattles prior to the inspection on  |
| Current Condition:  Lot 35 Current Condition:  Lot 110 Current Condition:  Lot 111 Current Condition:  Lot 111 Current Condition:          | Timeless Homes was informed 9/10/21, 10/15/21, 11/12/21, | d to complete by 7/17/21. No 12/16/21, 1/25/22  Lot 29 es began excavating the lot properties of the 1/24/21 at this time. E&A inspector with the second of  | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Disprior to the 11/11/21 inspect at this time. E&A inspector lead to the 12/22/2020 pection on 11/16/21.  12/22/2020 struction prior to inspection or will continue to monitor.  4/29/2021 ation as of 4/29/21. Legacy I tles prior to the inspection of 4/29/2021   | Active ion. Dirt piles were ot is mostly flat and Active int piles were obser- ction. Lot is mostly will continue to mo Removed  Active In 12/22/20. Legacy Active Homes repaired the In 10/13/21. Active                      | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so No ved in the ROW during the flat, and rear of the lot is nitor.  No v Homes placed straw wattles  |
| Current Condition:  Lot 35 Current Condition:  Lot 110 Current Condition:  Lot 111 Current Condition:  Lot 112 Current Condition:  Lot 131 | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 11/2/21, 1 | de to complete by 7/17/21. No. 12/16/21, 1/25/22  Lot 29 es began excavating the lot prior to the 1/24/21 at this time. E&A inspector was began excavating the lot prior to the second the dirt piles on excavating the lot prior to the Homes removed the dirt piles no BMPs are recommended.  Lot 110  began consumer to the lot prior to the inspector of the lot prior to the lot 112 and lot 111 for more informated and extended the wat lot 131 es excavated the lot prior to 10/19/21 inspection.  | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Dispection to the 11/11/21 inspect at this time. E&A inspector  12/22/2020 prior to the 11/16/21.  12/22/2020 prior to inspection of the inspection of 4/29/2021 prior to the inspection of 4/29/2021 prior to the inspection of 4/29/2021 prior to the inspection of 4/29/2021  | Active ion. Dirt piles were ot is mostly flat and Active int piles were obser ction. Lot is mostly will continue to mo Removed  Active on 12/22/20. Legacy Active Homes repaired the n 10/13/21.  Active aned up the concre    | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so No ved in the ROW during the flat, and rear of the lot is nitor.  No ved the lot is No ved in the ROW during the flat, and rear of the lot is nitor.  No ver wattles prior to the inspection on  Yes ver waste and installed silt fence on |
| Current Condition:  Lot 35 Current Condition:  Lot 110 Current Condition:  Lot 111 Current Condition:  Lot 112 Current Condition:  Lot 131 | Timeless Homes was informe 9/10/21, 10/15/21, 11/12/21, 11/2/21, 11/ | do to complete by 7/17/21. Note 12/16/21, 1/25/22  Lot 29 es began excavating the lot prior to the 1/24/21 at this time. E&A inspector with this time. E&A inspector with the dirt piles of the  | 12/15/2021 prior to the 12/15/21 inspect inspection. The front of the I inspection. The front of the I ill continue to monitor.  10/25/2021 he inspection on 6/22/21. Disprior to the 11/11/21 inspect at this time. E&A inspector example of the III/16/21.  12/22/2020 pection on 11/16/21.  12/22/2020 pection prior to inspection of or will continue to monitor.  4/29/2021 petition as of 4/29/21. Legacy I tles prior to the inspection of the Inspec | Active ion. Dirt piles were ot is mostly flat and Active int piles were obser- ction. Lot is mostly will continue to mo Removed  Active In 12/22/20. Legacy Active Homes repaired the In 10/13/21. Active In and up the concre | No observed in the ROW on 12/15/21 the rear of the lot is vegetated, so No ved in the ROW during the flat, and rear of the lot is nitor.  No ved the lot is No ved in the ROW during the flat, and rear of the lot is nitor.  No ver wattles prior to the inspection on  Yes ver waste and installed silt fence on |

| Current Condition: | Panding This let is inactive f   | or construction Loggov Hon                 | and disturbed the let during    | homo building octiviti  | ios on adiacent lete prior to the   |  |  |
|--------------------|--|--|---------------------------------|-------------------------|---|--|--|
| Current Condition. | Pending - This lot is inactive for construction. Legacy Homes disturbed the lot during home-building activities on adjacent lots prior to the 10/28/21 inspection.   |  |                                 |                         |   |  |  |
|                    | Silt fence should be extended or wattles should be installed across the front of the lot.  |  |                                 |                         |   |  |  |
|                    | Legacy Homes was informed 1/27/22  | to complete by 11/4/21. Not                | done as of last inspection.     | Legacy Homes was        | reminded on 12/2/21, 12/23/21,  |  |  |
| Lot 133            | Individual Lot   | Lot 133                                    | 4/29/2021                       | Active                  | Yes   |  |  |
| Current Condition: | Fair Condition - Legacy Hom  | es excavated the lot prior to              | 4/29/21. Legacy Homes ins       | talled a portable toile | et on the lot prior to the inspection                                     |  |  |
|                    | Fair Condition - Legacy Homes excavated the lot prior to 4/29/21. Legacy Homes installed a portable toilet on the lot prior to the inspection on 8/25/21. Legacy Homes installed silt fence on the front of the lot prior to the 10/19/21 inspection.  1.) Silt fence should be extended or wattles should be installed across all non-paved areas along the front of the lot. |  |                                 |                         |   |  |  |
|                    | <ul><li>2.) The portable toilet across</li><li>1.) Legacy Homes was inform</li></ul>   |  |                                 | on. Legacy Homes w      | ras reminded on 12/2/21,  |  |  |
|                    | 12/23/21, 1/27/22<br>2.) Legacy Homes was inform   | ned to complete by 12/29/21                | . Not done as of last inspec    | tion. Legacy Homes      | was reminded on 1/27/22   |  |  |
| Lot 134            | Individual Lot   | Lot 134                                    | 4/29/2021                       | Active                  | Yes   |  |  |
| Current Condition: | Fair Condition - Legacy Hom 10/19/21 inspection.  Silt fence should be extended  | or wattles should be installe              | ed across all non-paved area    | as along the front of t | the lot.  |  |  |
|                    | Legacy Homes was informed 1/27/22  | to complete by 11/4/21. Not                | done as of last inspection.     | Legacy Homes was        | reminded on 12/2/21, 12/23/21,  |  |  |
| Lot 135            | Individual Lot   | Lot 135                                    | 10/28/2021                      | Pending                 | Yes   |  |  |
| Current Condition: | Pending - This lot is inactive f   | or construction. Legacy Hon                | nes disturbed the lot during    | home-building activiti  | ies on adjacent lots prior to the   |  |  |
|                    | 10/28/21 inspection.  Silt fence should be extended  | or wattles should be installe              | ed across the front of the lot. |                         |   |  |  |
|                    | Legacy Homes was informed 1/27/22  | to complete by 11/4/21. Not                | done as of last inspection.     | Legacy Homes was        | reminded on 12/2/21, 12/23/21,  |  |  |
| Lot 136            | Individual Lot   | Lot 136                                    | 6/22/2021                       | Pending                 | Yes   |  |  |
| Current Condition: | Pending - Legacy Homes beg   | an excavating the lot prior to             | the inspection on 6/22/21.      |                         |   |  |  |
|                    | Silt fence is needed in the front of the lot.  |  |                                 |                         |   |  |  |
|                    | Legacy Homes was informed 8/11/21, 9/10/21, 10/15/21, 10   |  |                                 | Legacy Homes was        | reminded on 7/23/21, 7/29/21,   |  |  |
| Lot 137            | Individual Lot   | Lot 137                                    | 6/30/2021                       | Pending                 | Yes   |  |  |
| Current Condition: | Pending - Legacy Homes beg<br>Silt fence is needed in the from<br>Legacy Homes was informed<br>8/11/21, 9/10/21, 10/15/21, 10  | nt of the lot. to complete by 7/14/21. Not | done as of last inspection.     | Legacy Homes was        | reminded on 7/23/21, 7/29/21,   |  |  |
| Lot 139            | Individual Lot   | Lot 139                                    | 7/7/2021                        | Active                  | No  |  |  |
| Current Condition: | Active - This lot is inactive for  |  | 1/1/2021                        | Active                  | INO   |  |  |
|                    |  | ı  | 1 0/00/0004                     |                         |   |  |  |
| Lot 154            | Individual Lot   | Lot 154                                    | 6/22/2021                       | Active                  | No  |  |  |
| Current Condition: | inspection. The front of the lo  | t is mostly flat, so no BMPs a             | are recommended at this tin     |                         | ed in the ROW during the 6/22/21<br>Il continue to monitor. Legacy        |  |  |
| Lot 159            | Individual Lot   | Lot 159                                    | 7/21/2021                       | Pending                 | Yes   |  |  |
| Current Condition: | Pending - Legacy Homes began excavating the lot prior to the inspection on 7/21/21.  1.) Silt fence should be installed along the front of the lot. 2.) Silt fence should be installed in the rear of the lot.  1.) Legacy Homes was informed to complete by 10/20/21. Not done as of last inspection. Legacy Homes was reminded on 10/29/21, 12/2/21, 12/23/21, 1/27/22       |  |                                 |                         |   |  |  |
|                    | 2.) Legacy Homes was inform  | ned to complete by 12/29/21                | . Not done as of last inspec    | tion. Legacy Homes      | was reminded on 1/27/22   |  |  |
| Lot 5, Replat 1    | Individual Lot   | Lot 5, Replat 1                            | 12/29/2021                      | Active                  | No  |  |  |
| Current Condition: |  |  |                                 | /21. Dirt piles were o  | bserved in the ROW on 12/29/21.   |  |  |
| Lot 6, Replat 1    | Epcon removed the dirt piles Individual Lot  | from the ROW prior to the in               | 12/22/2021                      | Active                  | No  |  |  |
| Current Condition: |  |  |                                 |                         | ar of the lot are mostly flat, so no                                      |  |  |
|                    | BMPs are recommended at the  | his time. E&A inspector will o             | continue to monitor.            |                         | ·<br>   |  |  |
| Lot 7, Replat 1    | Individual Lot   | Lot 7, Replat 1                            | 12/22/2021                      | Active                  | No  |  |  |
| Current Condition: | BMPs are recommended at the  | his time. E&A inspector will o             | continue to monitor.            | //21. I he front and re | ar of the lot are mostly flat, so no                                      |  |  |
| Lot 8, Replat 1    | Individual Lot   | Lot 8, Replat 1                            | 12/29/2021                      | Active                  | No  |  |  |
| Current Condition: | Active - Epcon Communities BMPs are recommended at the   |  |                                 | /21. The front and re   | ar of the lot are mostly flat, so no                                      |  |  |
| Lot 9, Replat 1    | Individual Lot   | Lot 9, Replat 1                            | 12/29/2021                      | Active                  | No  |  |  |
| Current Condition: |  |  |                                 |                         | ng inlet on Horizon Street prior to<br>nended at this time. E&A inspector |  |  |

| Lot 10, Replat 1                     | Individual Lot  | Lot 10, Replat 1   | 12/29/2021  | Active   | No   |
|--------------------------------------|---|--|---|--|--|
| Current Condition:                   |   |  |   |  | observed in the ROW on 12/29/21.   |
|                                      | Epcon removed the dirt piles  | · · · · · · · · · · · · · · · · · · ·  | ·   | 1  |  |
| Lot 11, Replat 1  Current Condition: | Individual Lot  | Lot 11, Replat 1   | 8/9/2021  | Active   | Yes ter Homes installed silt fence and   |
|                                      | wattles along the front and sic curb inlet prior to the inspecti installed three geocurves ove Coast Rd) prior to the inspecti inspection on 9/13/21. Bridge repositioned the wattles and protection on the east side of north side of the lot during sic stabilized. E&A inspector will toilet and removed the remainmonitor. Bridgewater Home  1.) Inlet protection on the wes 2.) Inlet protection on the eas 3.) The portable toilet on the  1.) Bridgewater Homes was in 11/24/21, 1/20/22 2.) Bridgewater Homes was in 11/20/22 | des of the lot prior to the inspon on 8/17/21. Bridgewater in a existing curb inlets around tion on 9/8/21. Bridgewater in water Homes cleaned out are cleaned out the inlet protection of the 1/1/21. Bridgewater in the water Homes cleaned out are cleaned out the inlet protection of the 1/2/21 and the inlet protection of the 1/2/21 and the inlet protection of the 1/2/21 and | pection on 8/17/21. Bridgew, installed a portable toilet on individual of the lot (east side of \$123 domes relocated the portable difference of the silt fence prior prior to the 10/19/21 inspection. Bridgewall 7/21 inspection. Bridgewall vibration of the 10/19/21 inspection. Sidewalk vibration as new for sodding prior to the 12/10 pilet prior to the 2/9/22 inspection. Sidewall vibration as new for sodding prior to the 2/9/22 inspection. Sidewall vibration in the 2/9/ | ater Homes installed the lot prior to the interest was a fired Ave, west side of the toilet and cleaned or to the 9/22/21 insection. Bridgewater ter Homes removed will act as a temporacessary. Bridgewate 5/21 inspection. E8 pection.  Rd should be clean pection. Bridgewater the should be clean pection. | d inlet protection on an existing ispection on 8/31/21. Bridgewater if 123rd Ave, and south side of Gold tout the inlet protection prior to the spection. Bridgewater Homes Homes cleaned out the inlet a portion of silt fence along the my berm until the lot can be er Homes re-secured the portable A inspector will continue to ed out. |
|                                      | 3.) Bridgewater Homes was   | s informed to complete by  | 2/16/22.  |  |  |
| Lot 12, Replat 1                     | Individual Lot  | Lot 12, Replat 1   | 8/9/2021  | Active   | No   |
| Current Condition:                   | along the front and sides of the prior to the inspection on 8/11 wattles along the front of the lot prior to the inspection on 9 Bridgewater Homes removed along the front of the lot prior   | r Homes began excavating the lot prior to the inspection of the inspection of the inspection of the inspection on the inspection on the inspection on the inspection on the inspection of the silt fence from the front to the 12/7/21 inspection. Signature of the inspection of the insp | The lot prior to the inspection on 8/17/21. Bridgewater Hotocated the portable toilet to 8/31/21. Bridgewater reposientstalled silt fence along the for the lot prior to the 10/28/dewalk will act as a temporatecessary. Bridgewater Hore  | on 8/9/21. Bridgew<br>mes installed and so<br>Lot 11, Replat 1, re<br>tioned and resecure<br>e front of the lot pric<br>21 inspection. Bridg<br>ary berm until the lo<br>nes removed the re  | ewater Homes installed sidewalk<br>t can be stabilized. E&A inspector<br>maining silt fence in preparation for   |
| Lot 16, Replat 1                     | Individual Lot  | Lot 16, Replat 1   | 8/9/2021  | Active   | No   |
| Current Condition:                   | Active - Bridgewater Homes front and sides of the lot prior inspection on 11/11/21. Bridg   | began excavating the lot price<br>to the inspection on 8/17/21<br>ewater Homes removed the   | or to the inspection on 8/9/2<br>. Bridgewater Homes remo<br>remaining silt fence during  | Bridgewater Hom<br>ved some silt fence<br>sidewalk installation  | es installed silt fence along the for driveway paving prior to the prior to the inspection on 12/15/21. or and recommend reinstallation as   |
| Lot 17, Replat 1                     | Individual Lot  | Lot 17, Replat 1   | 8/2/2021  | Active   | Yes  |
| Current Condition:                   | the front and sides of the lot p<br>the inspection on 8/17/21. Bri<br>installed wattles along the rea<br>paving prior to the inspection   | prior to the inspection on 8/17 dgewater Homes cleaned ou ar of the lot prior to the inspection 11/16/21. Bridgewater Homes during sidewalk installation are in place in the rear of the es installed inlet protection of the lot should be secured.   | 7/21. Bridgewater Homes in<br>ut and repaired the silt fence<br>ction on 11/11/21. Bridgewa<br>omes repaired the silt fence<br>prior to the inspection on 1:<br>e lot. E&A inspector will con<br>over an existing inlet on Hori   | stalled and secured:<br>prior to the 9/22/2*<br>ter Homes remove:<br>prior to the inspect<br>2/15/21. Sidewalk w<br>tinue to monitor and<br>zon Street prior to t  | vill act as a temporary berm until the<br>I recommend reinstallation as  |
| PB 1                                 | Portable Bathroom   | Site   |   | Removed  |  |
| Current Condition:                   | Removed - Kersten Construc  |  |   |  |  |
| PB 2 Current Condition:              | Portable Bathroom   | Site   | 1/27/2021   | Active   | No tion on 1/27/21, portable toilet is   |
|                                      | secured. Legacy Homes mov   | red the PB away from the cu  | rb prior to 5/10/21.  | i piloi to tile ilispec  | ation on 1/2//21, portable toller is   |
| SB 1                                 | Sediment Basin  | B5   | 11/14/2019  | Active   | Yes  |
| Current Condition:                   | still missing the outlet structu<br>as of the 11/22/19 inspection<br>riser and outlet pipe prior to the   | re, inlets, and the baffle. The DEJ Grading partially instal he inspection on 7/21/20. Grunterprises began cleaning or the inspection on 9/8/21.   | outlet pipe was installed pr<br>led the riser prior to inspect<br>eat Plains Contractor Servic<br>ut the basin prior to the insp  | ior to inspection on<br>ion on 12/12/19. DE<br>les installed rip rap<br>lection on 8/17/21. I  | us of the last inspection, the basin is 11/22/19. The riser is not in place is J closed the gaps between the below the outfall prior to the Roth finished cleaning out the basin   |
|                                      |   |  |   | EJ was reminded or   | 7/9/21, 8/13/21, 8/26/21, 9/10/21,   |
| SB 2                                 | 10/29/21. Graves Developme<br>Sediment Basin  | ent was reminded on 12/6/21 V5   | 8/19/2019   | Activo   | No   |
| 3D Z                                 | Sedifferit Dasiff   | l vo   | 0/13/2019   | Active   | No   |

| Current Condition: | gaps between the riser and outle  | 1/19. E&A will monitor through the right are gaps between the right pipe prior to the inspection to the basin, inspections the basin, inspections that the basin, inspections in the basin, inspections are reconstructed. | ugh completion of installation<br>ser and outlet pipe that need<br>on on 7/21/20. DEJ installer<br>stalled dewatering holes and  | on. DEJ Grading ins<br>d closed as of the 1<br>d rip rap below the o<br>d the eastern baffle   | talled a riser in the basin prior to 2/27/19 inspection. DEJ closed the outfall prior to the inspection on prior to the inspection on 5/19/21.                   |
|--------------------|---|--|--|--|--|
| SB 3               | Sediment Basin  | AA17   | 11/15/2018   | Active   | No   |
|                    |   |  |  |  |  |
| Current Condition: | Good Condition - 6% Filled - Bas<br>11/28/18, however, excavation/s<br>9/11/19 inspection. DEJ Grading<br>inspection on 12/12/19. DEJ inst<br>inspection on 8/13/20. Roth bega                                      | shaping of the basin was n<br>rebuilt the berm of the ba<br>alled a riser in the basin p   | ot complete. E&A will monit<br>usin prior to inspection on 10<br>rior to the inspection on 7/2   | or. Excavation of th<br>0/16/19. The outlet p<br>1/20. DEJ installed   | ne basin is complete as of the<br>pipe was installed prior to<br>rip rap below the outfall prior to the  |
| SB 4               | Sediment Basin  | AA26   | 11/15/2018   | Active   | No   |
| Current Condition: |   |  |  |  | n was complete as of inspection or   |
|                    |   | pipe was installed prior to i<br>te inspection on 8/13/20. To<br>cessary. Roth Enterprises<br>rises installed the baffle p   | nspection on 11/27/19. DE<br>he outfall is connected to the<br>began cleaning out the bas<br>fior to the 10/25/21 inspection   | J installed a perman<br>ne riser pipe as of th<br>in prior to the 10/19<br>on. Sediment at the   | nent riser in the basin and rip rap<br>ne inspection on 8/13/20, therefore<br>1/21 inspection. E&A inspector will<br>outfall was washed away by                  |
| SB 5               | Sediment Basin  | C28  | 11/14/2019   | Active   | Yes  |
| Current Condition: | still missing the outlet structure, in the basin prior to the inspection of Contractor Services installed rip the baffle prior to the inspection of The dewatering holes lower than DEJ, Peter Katt, Gene Graves, a | inlets, and the baffle. The<br>on 7/21/20, therefore a silt<br>rap below the outfall prior<br>on 10/25/21.<br>2.58 feet from the riser c<br>and Great Plains Contract  | outlet pipe was installed pri-<br>ifence wrap around the outleto the inspection on 8/07/20<br>rest should be plugged.  | or to inspection on<br>let pipe is no longer<br>D. Roth Enterprises<br>to complete by 8/05   | necessary. Great Plains cleaned out the basin and installed  |
|                    | · ·   | h Enterprises was reminde  |  |  | 1. DEJ was reminded on 10/29/21.   |
| SF 1               | Silt Fence  | BB 20-BB14   |  | Removed  |  |
| Current Condition: | Removed - SF 1 *(SF 1.3) was it southeast corner of the site, incluinspection on 4/22/20. As of the southeastern perimeter of the sit monitor. E&A inspector removed  | uding the undermined port<br>inspection on 7/29/20, veg<br>te that reinstallation of the   | ion by the outfall of the basi<br>getation has become sufficien<br>removed silt fence is no lor  | in and the multiple f<br>ently established on  | ull spots, was removed prior to the the slope located along the  |
| SF 2               | Silt Fence  | BB 14 - Gold Coast Rd  | 11/28/2018   | Active   | No   |
| Current Condition: | Services installed the remainder side of Gold Coast Road prior to 2 outfall. The full portion of silt fe  | of the silt fence prior to in<br>the inspection on 8/19/20<br>ence south of the future loo<br>nce was removed due to g<br>Contractor Services repa<br>the silt fence south of Gol  | spection on 7/31/19. Great b. Great Plains Contractor S Great Plains Coast Road v grading on eastern perimete ired and reinstalled new silt d Coast Road to SB 3 prior                                     | Plains Contractor S<br>ervices closed the g<br>vas removed to allo<br>er from Lake Vista I<br>fence above SB 3 (                           | Orive to Gold Coast Road prior to (C) outfall prior to 5/10/21.  |
|                    |   | 0.110 (8) 884  | 4.4/00/0040  |  |  |
| SF 3               |   | Gold Coast Rd - BB 1   | 11/28/2018   | Active   | No No  |
| Current Condition: | Services installed the remainder side of Gold Coast Road prior to 2 outfall, cleaned out some of the cleaned out the silt fence where future location of Gold Coast Roadue to grading on eastern perime             | of the silt fence prior to in<br>the inspection on 8/19/20<br>e full portions of silt fence<br>full on the north side of the<br>ad was removed to allow:<br>eter from Gold Coast Roa<br>a along the northeast corne        | spection on 7/31/19. Great I. Great Plains Contractor S on the northeastern perime e site prior to the inspection access for sewer work prior d to the northeast corner of er of the site prior to the 11/ | Plains Contractor S<br>ervices closed the<br>ter of the site (addit<br>on 9/09/20. The ful<br>to the inspection o<br>the site prior to 1/1 | I portion of silt fence south of the n 9/24/20. Silt fence was removed   |
| SF 4               | Silt Fence  | BB 1 - 120th St  | 11/28/2018   | Active   | No   |
| Current Condition: | Good Condition - A portion of SF<br>Services installed the remainder<br>full portions of silt fence on the n  | F 4 (SF 1.2) was installed of the silt fence prior to in ortheastern perimeter of the to the inspection on 9/09/S installed silt fence on the  | by Double D Excavating prices<br>spection on 7/31/19. Great<br>the site (additional cleanout of<br>20. Great Plains Contractor<br>e east side of 120th Street,   | or to inspection on a Plains Contractor S still required), and c r Services repaired and backfilled the s                                  | 11/28/18. Great Plains Contractor<br>fervices cleaned out some of the<br>cleaned out the silt fence where full<br>and reinstalled new silt fence in the          |
| SF 5               | Silt Fence  | 120th St - S 123rd Ave   | 11/7/2019  | Active   | No   |
| Current Condition: | Good Condition - (SF 1.1) Great<br>South 123rd Avenue; and east si<br>snow removal prior to inspection  | t Plains Contractor Servicide of South 120th Street on 12/30/20. Silt fence will fence on the west silt fence on the west silt fence on the desired and e  | es repaired the silt fence an<br>prior to 11/10/20. Silt fence<br>as removed between 123rd<br>side of 120th Street prior to<br>extended the silt fence on th   | dreinstalled the silt<br>going north/south n<br>ave and S 120th S<br>5/19/21. GPCS clea<br>e west side of 120th                            | t fence on east and west sides of orth of S 124th Street damaged by treet due to grading prior to aned out the silt fence on the west h street prior to 8/25/21. |

| SF 6                    | Silt Fence   | S 123rd Ave - S 125th St  |  | Removed                |  |  |  |
|-------------------------|--|---|--|------------------------|--|--|--|
| Current Condition:      | 123rd Avenue; and east side  | of South 120th Street prior to<br>tion on 12/30/20. Great Plains                          | o 11/10/2020. Silt fence goir<br>s Contractor Services remo                | ng north/south north   | on east and west sides of South of S 124th Street damaged by rior to the 4/21/21 inspection. E&A     |  |  |
| SF 7                    | Silt Fence   | S 125th St - A 5  | 11/7/2019  | Active                 | No   |  |  |
| Current Condition:      | Good Condition - (SF 1.1) Great Plains Contractor Services repaired the silt fence and reinstalled the silt fence on east and west sides of South 123rd Avenue; and east side of South 120th Street prior to 11/10/2020. Silt fence going north/south north of S 124th Street damaged by snow removal prior to inspection on 12/30/20. GPCS removed a portion of the silt fence north of SB 1 prior to the inspection on 6/15/21. Commercial seeding repaired and reinstalled the silt fence around S 125th street and north of SB 1 prior to the 11/11/21 inspection.   |   |  |                        |  |  |  |
| SF 8                    | Silt Fence   | B 24 - K 28   | 7/18/2019  | Active                 | No   |  |  |
| Current Condition:      | Good Condition - (SF 1.5) - D<br>County Department of Roads<br>4/30/2021. Commercial Seed  | until road project is complete  | ed. E&A removed that sect  | ion of silt fence fron | D7 will be maintained by Sarpy<br>n the maintenance plan as of                                       |  |  |
| SF 9                    | Silt Fence   | A 9 - A 12  | 11/7/2019  | Active                 | No   |  |  |
| Current Condition:      | Good Condition - (SF 2) Great Plains Contractor Services repaired the silt fence where full (still needs cleaned out), backfilled the undermined portions north of the full portion, and backfilled/trenched-in the portion south of the full portion prior to the inspection on 7/15/20. Great Plains Contractor Services cleaned out and repaired the silt fence where full and trenched-in the silt fence where the bottom of the rur was exposed in several areas (some still need trenched-in) prior to the inspection on 9/09/20. Great Plains Contractor Services repaired/cleaned out the silt fence prior to the 4/21/21 inspection. Great Plains Contractor Services repaired/cleaned out the silt fence prior to the 5/10/21 inspection. Commercial Seeding cleaned out and repaired the silt fence prior to the 11/11/21 inspection. |   |  |                        |  |  |  |
| STR                     | Streets  | Site  | 11/8/2018  | Active                 | Yes  |  |  |
| Current Condition:      | off S 120th Street prior to the  | 11/11/21 inspection. Legacy<br>e 11/23/21 inspection. Peter<br>Homes lots should be clean | Homes cleaned the streets Katt / Graves Development ed daily or as needed. | prior to the 11/11/2   | ion. Commercial Seeding cleaned<br>21 inspection. Bridgewater Homes<br>athern entrances prior to the |  |  |
| SWPPP Sign              | Misc./Other  | Schram Road (W27) and S<br>120th Street (P1)  | 11/19/2018   | Active                 | No   |  |  |
| Current Condition:      | Good Condition - E&A inspector installed the SWPPP sign at S 124th Street and Schram Road during inspection on 11/19/18. E&A inspector installed the SWPPP sign at S 120th Street at the north end of the site during the inspection on 6/9/21.  |   |  |                        |  |  |  |
| Certification Statement | "I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."  |   |  |                        |  |  |  |
| Inspector Signature:    |  |   |  | Reviewed By:           | Hatte Vann   |  |  |