E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A- P2017.	258.000					
Inspector: Alex Brown					Stage			
Project Name:	CSW-2	l	1					
For Week Ending:		8/6/2022						
Project Location:	120th St	reet and Schram Road,	Papillion, NE (Sarpy County)				
Grading:	97%							
Sanitary Sewer:	96%							
Storm Sewer:	96%							
Paving:	96%							
Seeding:	90%							
Utilities:	90%							
Overall Development:	48%							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time				
					Week '			
Sunday:	0.00"							
Monday:	0.00"							
Tuesday:	0.00"							
Wednesday:	0.02"	8/3/2022	Mostly Cloudy 94/73	10:50 AM				
Thursday:	0.00"							
Friday:	0.00"							
Saturday:	0.00"							
Complaints:								
	1							

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/18) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/18). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/19). Stockpiling in the western portion of Dev 2 (4/24/19). Grading has begun in the western portion of Dev 2 (5/9/19). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/19). Stripping/Grading in northeastern portion of Dev 2 (6/27/19) Minor regrading/excavation in DEV 3 -School (7/31/19). Excavation in Dev 3 and Dev 4 for sanitary installation (08/08/19). Trenching in Dev 4 for utility installation (09/04/19). Grading has temporarily ceased throughout the site (10/11/19). Excavation near SB 4 for basin installation (10/22/19). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/19). Stripping/grading in DEV A (10/31/19). Disking occurring in Dev 4 (11/7/19). Sanitary installation in Dev 2/3 (11/7/19). Grading in Dev 5 and Dev A for basin excavation (11/14/19). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/19). Grading in Dev 4 (12/12/19). Grading has temporarily ceased due to winter conditions (1/23/20). Grading has resumed (4/27/20); Backfilling of curbs for paving underway (10/21/200). Excavation no Lot 110 (12/22/20). Grading on eastern side of Dev 2 (1/12/21). Grading in Dev A, and northern portion of Dev 2 (2/23/21). Excavation by 124th st and Gold Coast Rd (3/4/21). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/21). Utilities were put in the southwest corner of the site (4/21/21). Grading in SW corner of site by Calabretto Building Group (9/8/21). Ground disturbance for sewer installation around Outlot L (7/27/22.)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/18) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/18). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/19). Stockpiling in the western portion of Dev 2 (4/24/19). Grading has begun in the western portion of Dev 2 (5/9/19). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/19). Stripping/Grading in northeastern portion of Dev 2 (6/27/19) Minor regrading/excavation in DEV 3 -School (7/31/19). Excavation in Dev 3 and Dev 4 for sanitary installation (08/08/19). Trenching in Dev 4 for utility installation (09/04/19). Grading has temporarily ceased throughout the site (10/11/19). Grading has resumed for basin installation (10/16/19) Grading has resumed throughout the site (10/22/19). Excavation near SB 4 for basin installation (10/22/19). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/19). Stripping/grading in DEV A (10/31/19). Disking occurring in Dev 4 (11/7/19). Sanitary installation in Dev 2/3 (11/7/19). Grading in Dev 5 and Dev A for basin excavation (11/14/19). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/19). Grading in Dev 4 (12/12/19). Grading has temporarily ceased due to winter conditions (1/23/20). Grading has resumed (4/27/20); Backfilling of curbs for paving underway (10/21/20). Excavation on Lot 110 (12/22/20). Grading on eastern side of Dev 2 (1/12/21). Grading in Dev A, and northern portion of Dev 2 (2/23/21). Excavation by 124th st and Gold Coast Rd (3/4/21). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/21). Utilities were put in the southwest corner of the site (4/21/21). Grading in SW corner of site by Calabretto Building Group (9/8/21). Ground disturbance for sewer installation around Outlot L (7/27/22.)

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/18). EM 1 partially installed (09/30/19). DEJ seeded the central drainage around the future S. 124th St., the slope in the northeastern quadrant of the site (6/16/20); school site was sodded (12/9/20). ROW seeding began (6/2/21). Matting of the slope west of S 120th entrance (8/25/21). Seeding / matting Outlots F, G, H, and ROW overseeding (4/1/22).

Checklist Questions:

CHECKIST QUESTIONS.

Are precising waters adjacent to the project free of any significant signs of excession or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?
N/A
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
No No
Create Corrective Action?
No, See BMP Section
Are construction entrances and adjacent streets being maintained adequately?
No .
Create Corrective Action?
No, See BMP Section
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Commenter

- 1) Site was active for home construction and storm sewer installation during the last inspection.
- 2) Ashbury Hills Self Storage (CSW-202105789) is active on Lot 166 of the Ashbury Hills development as of 9/13/21

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) E&A will monitor the removal of the inlet filters around the school project with the site stabilization. E&A inspector received an email from Tyson Smith with Lamp Rynearson 1/11/21 that they did not recommend putting inlet filters around the school. GPCS was informed to remove the inlet filters by 3/11/21. GPCS removed 5 inlet filters prior to the 3/24/21 inspection. As of 4/9/21 there are two inlet filters left by the school, E&A inspector will continue to monitor. GPCS was reminded on 4/30/21, 5/4/21, 5/6/21, 5/11/2021, 5/19/21, 5/30/21, 6/25/21, 7/14/21, 8/13/21, 9/10/21, 9/30/21. Peter Katt, Gene Graves, and Commercial Seeding were reminded on 10/14/21, 11/3/21
- 3) Commercial Seeding seeded / matted Outlots F, G, and H, and overseeded disturbed areas throughout the development prior to the 4/1/22 inspection. E&A inspector will continue to monitor for growth. Seeded areas are well vegetated as of the 8/3/22 inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
A 1	Area Inlet Protection	R 16		Removed				
Current Condition:	Removed - Silt fence around	Removed - Silt fence around the inlet will not be recommended as of 4/16/21 due to inlet leading to a sediment basin.						
B 1		North side of site (west of						
ВТ	Temporary Berm	SB 2)		Removed				
Current Condition:	Removed - DEJ Grading rem			prior to inspection of	on 11/14/19.			
B 2	Temporary Berm	Southwest side of site (NE of SB 5)		Removed				
Current Condition:	Removed - DEJ Grading rem		Lection on 12/18/19. The her		Lat this time F&A will monitor			
	Tromovod BLO Grading rom	oved the benne phot to mop	000011 011 12/10/10: 1110 001	nio dio not nocaca	at this time. East will mornion.			
	Stabilized Construction							
CE 1	Entrance	Schram Road (W27)		Removed				
Current Condition:	Removed - The construction			longer in use due to	the Schram Road Improven			
	project grading reaching the a	area as of the inspection on 8	3/18/20.					
CE 2	Stabilized Construction	Schram Road (AA27)		Removed				
Current Condition:	Entrance	, ,			tti Ci thi- DMD			
Current Condition:	Removed - Prairie Constructi							
	Stabilized Construction	T	T	10 10/11/10 IIISPECI	I			
CE 3	Entrance	Schram Road (O27)		Removed				
Current Condition:	Removed - Graham Construc	tion removed the entrance to	prep the area for paving p	rior to the inspection	n on 9/24/20. Reinstallation is			
	necessary due to grading for							
	inspection on 9/24/20.							
CW 1	Concrete Washout	North of SB 4		Removed				
	D 1710 1 "	1.0 1						
Current Condition:	Removed- Lab Construction I	removed the washout pit price	or to 11/18/20					
		removed the washout pit price Outlot A-South 124th	1	A 12				
Current Condition: CW 2	Concrete Washout		5/19/2021	Active	No			
	Concrete Washout Good Condition- GPCS instal	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the	5/19/2021 ne inspection on 5/19/21. Su	dbeck Homes clear	l ned out the washout and clea			
CW 2	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the to the washout prior to the ins	5/19/2021 ne inspection on 5/19/21. Su	dbeck Homes clear	l ned out the washout and clea			
CW 2	Concrete Washout Good Condition- GPCS instal	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the to the washout prior to the ins	5/19/2021 ne inspection on 5/19/21. Su	dbeck Homes clear	l ned out the washout and clea			
CW 2 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the to the washout prior to the ins	5/19/2021 ne inspection on 5/19/21. Su	dbeck Homes clear	l ned out the washout and clea			
CW 2 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/ Temporary Diversion Ditch Removed - The majority of the	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the the washout prior to the ins 22. (BB8-BB15) e diversion was graded out p	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck	dbeck Homes clear Homes installed a l Removed	led out the washout and clea berm along the front of the w			
CW 2 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the the washout prior to the ins 22. (BB8-BB15) e diversion was graded out p	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck	dbeck Homes clear Homes installed a l Removed	led out the washout and clea berm along the front of the w			
CW 2 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/ Temporary Diversion Ditch Removed - The majority of the	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the the washout prior to the ins 22. (BB8-BB15) e diversion was graded out p	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck	dbeck Homes clear Homes installed a l Removed	led out the washout and clea berm along the front of the wa			
CW 2 Current Condition: D 1 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the time due to establishment of the control of th	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection (BB8-BB15) e diversion was graded out provegetation in the upstream a	5/19/2021 ne inspection on 5/19/21. Su pection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea.	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation	ned out the washout and clea berm along the front of the washington, and the washingto			
CW 2 Current Condition: D 1 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the state of the	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection (BB8-BB15) e diversion was graded out provegetation in the upstream a	5/19/2021 ne inspection on 5/19/21. Su pection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea.	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation	ned out the washout and clea berm along the front of the washington, and the washingto			
CW 2 Current Condition: D 1 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the majority Diversion Ditch Removed - The diversion is not be a concrete with the diversion is not concrete washingtoned.	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection (BB8-BB15) e diversion was graded out provegetation in the upstream a	5/19/2021 ne inspection on 5/19/21. Su pection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea.	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation	ned out the washout and clea berm along the front of the was does not appear necessary a			
CW 2 Current Condition: D 1 Current Condition: D 2 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of time due	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection of the washout prior to the insection (BB8-BB15) e diversion was graded out provegetation in the upstream a (Q1-V2) o longer necessary as of the	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea. sinspection on 8/27/20 due 1	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation Removed o paving of S. 123r	does not appear necessary and Avenue, which will divert was			
CW 2 Current Condition: D 1 Current Condition: D 2 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of th	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection of the washout prior to the insection (BB8-BB15) e diversion was graded out provegetation in the upstream a (Q1-V2) o longer necessary as of the	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea. sinspection on 8/27/20 due 1	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation Removed o paving of S. 123r	does not appear necessary and Avenue, which will divert was			
CW 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the time due to establish time due to establis	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection of the section of the sec	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea. sinspection on 8/27/20 due 1	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation Removed o paving of S. 123r Active lercial Seeding rede	deed out the washout and clea berm along the front of the w does not appear necessary d Avenue, which will divert w			
CW 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the of the washout prior to the insection of the section of the sec	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea. inspection on 8/27/20 due to 8/27/2020 spection on 8/27/20. Comm	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation Removed o paving of S. 123r Active ercial Seeding rede	does not appear necessary and Avenue, which will divert was			
CW 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the diversion Ditch Removed - The diversion Ditch Good Condition - DEJ installe inspection on 11/11/21. Temporary Diversion Ditch Removed - Due to pavement of the properties of the time diversion of time diversion of the t	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the othe washout prior to the ins 22. (BB8-BB15) e diversion was graded out pregetation in the upstream a (Q1-V2) o longer necessary as of the (C20-C26) d the diversion prior to the ins (BB21-BB25) operations and school work,	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea. sinspection on 8/27/20 due to 8/27/2020 sspection on 8/27/20. Communication of the superior of the inspection on 8/27/20.	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation Removed o paving of S. 123r Active ercial Seeding rede	does not appear necessary a			
CW 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition:	Concrete Washout Good Condition- GPCS instal up concrete waste adjacent to prior to the inspection on 3/7/. Temporary Diversion Ditch Removed - The majority of the time due to establishment of the	Outlot A-South 124th Street & Horizon Street led the washout pit prior to the othe washout prior to the insection of the washout prior to the programma of the washout prior of the insection of the i	5/19/2021 ne inspection on 5/19/21. Supection on 3/7/22. Sudbeck prior to the inspection on 9/2 rea. le inspection on 8/27/20 due to 8/27/2020 repection on 8/27/20. Communication of the inspection on 8/27/20.	dbeck Homes clear Homes installed a l Removed 4/20. Reinstallation Removed to paving of S. 123r Active tercial Seeding redection Removed d as of 10/21/2020 Pending	ned out the washout and clea berm along the front of the washout and clea berm along the front of the washout and clea to be the washout and clea to be washout and clea to be washout and clea washout and clea to be washout and clea to be washout and clea washout and clea to be washout and clea to			

D 6	Temporary Diversion Ditch	(V27-AA27)		Removed	
Current Condition:	Removed - The diversion will	, ,	nspection on 7/29/20 due to	stabilization by ve	getation in part of the intend
	location as well as the start of				
D 7	Temporary Diversion Ditch	(E28-P28)	8/27/2020	Active	No
Current Condition:	Good Condition - DEJ installer 6/15/21.	d the diversion prior to the in	spection on 8/27/20. DEJ r	edefined the divers	sion prior to the inspection or
D 8	Temporary Diversion Ditch	(B8-B13)	8/27/2020	Active	No
Current Condition:	Good Condition - DEJ installe	, ,			
	5/19/21.		Γ	T	
D 9	Temporary Diversion Ditch	(C3-E2)	di	Removed	
Current Condition:	Removed- Due to pavement of				
EM 1 Current Condition:	Erosion Control Matting Good Condition - Erosion con	(CC20-CC27)	9/30/2019	Active	No will manitor for completion of
Current Condition.	installation during future inspe				
EM 2	Erosion Control Matting	B5	11/15/2018	Pending	No
Current Condition:	Pending - Will be installed who				
EM 3	Erosion Control Matting	D3	11/15/2018	Pending	No
Current Condition: ET 1	Pending - Will be installed who Erosion Control Terrace	en grading of area is comple C 12-21	rte.	Removed	T
Current Condition:	Removed - The erosion control		L d and replaced with D-3 and		_L pection on 8/27/20.
FT 1	Fuel Tanks	O23	<u>'</u>	Removed	T
Current Condition:	Removed - Roth Enterprises i		the inspection on 5/26/20		
FT X	Fuel Tank	Site	7/27/2022	Active	No
Current Condition:	Good Condition - An unidentifi				
Lot 1	Individual Lot	Lot 1		Removed	
Current Condition:	Removed - Ideal Designs sod	· · · · · · · · · · · · · · · · · · ·	22 inspection.		
Lot 4	Individual Lot	Lot 4	1. 11/10/01	Removed	
Current Condition:	Removed - Belt Construction	· · · · · · · · · · · · · · · · · · ·	spection on 11/16/21.	T	
Lot 5 Current Condition:	Individual Lot Removed - Peter Young sodd	Lot 5	tion on 11/16/21	Removed	
	Individual Lot	Lot 6	uon on 11/16/21.	Damayad	T
Lot 6 Current Condition:	Removed - Belt Construction		1/11/21 inspection.	Removed	
Lot 10	Individual Lot	Lot 10	6/21/2022	Active	No
Current Condition:	Active - JC Custom Build beg		the inspection on 6/21/22.	Due to vegetation	surrounding the lot, no BMP
1 144	recommended at this time. E&		4/07/0000	T	
Lot 11 Current Condition:	Individual Lot Good Condition - The homeov	Lot 1	4/27/2022	Active	re observed in the ROW on
	The homeowner removed the lot prior to the inspection on 6.	dirt piles from the ROW price			
Lot 17	Individual Lot	Lot 17	5/18/2022	Active	No
Current Condition:	Active - Timeless Homes beg active foundation work, remov				
Lot 19	Individual Lot	Lot 19		Removed	
Current Condition:	Removed - Belt Construction	· · · · · · · · · · · · · · · · · · ·	18/22 inspection.		Т
Lot 26 Current Condition:	Individual Lot Removed - Timeless Homes	Lot 26	spection on 6/21/22	Removed	
Lot 27	Individual Lot	Lot 27	5/18/2022	Active	No
Current Condition:	Active - Timeless Homes beg	an excavating the lot prior to		rt piles were obse	erved in the ROW on 8/3/22
	to active sewer hook-up, re		d at this time. E&A inspec		to monitor.
Lot 29 Current Condition:	Individual Lot Removed - Colony Custom He	Lot 29	the inspection on 6/20/22	Removed	
Lot 32	Individual Lot	Lot 32	3/7/2022	Active	No
Current Condition:	Active - Belt Construction beg				
	Construction removed the dirt	piles prior to the 4/1/22 insp	ection. The front of the lot i	s mostly flat and th	ne rear of the lot is vegetated
	BMPs are recommended at the Sidewalk will act as a temporary				the state of the s
Lot 35	Individual Lot	Lot 35	10/25/2021	Active	No
Current Condition:	Active - Legacy Homes begar	n excavating the lot prior to t	he inspection on 6/22/21. D	irt piles were obse	rved in the ROW during the
	10/25/21 inspection. Legacy F				
Lot 44	surrounded by vegetation, so Individual Lot	Lot 44	4/1/2022	Active	No
Current Condition:	Active - Frasier-Martis Archite				
	Frasier-Martis removed the di			,	
Lot 45	Individual Lot	Lot 45	7/14/2022	Active	No
	Active - Belt Construction beg		the 7/14/22 inspection. Dir		
Current Condition:		nd the rear of the lot is veget	ated, so no BMPs are reco	nmended at this tir	me. E&A inspector will moni
Current Condition:	dirt pile removal.	Lot 47	4/7/0000	Λς4:	T 81-
		Lot 47	4/7/2022	Active	No observed in the ROW on 4/7

Current Condition:	Good Condition - This lot i			Services installed	silt fence along the northeast
Lot 90	Individual Lot	Lot 90	8/3/2022	Active	No
Current Condition:				Services installed	silt fence along the northeast
	corner of the lot prior to the				
Lot 111	Individual Lot	Lot 111	1. 14/40/04	Removed	
Current Condition:	Removed - Legacy Homes so	· · · · · · · · · · · · · · · · · · ·		A -4i	N-
Lot 112 Current Condition:	Individual Lot	Lot 112	4/29/2021	Active	No r to the inspection on 6/15/21.
ouren conduct.		nd extended the wattles prior			nstalled silt fence on the northeast
Lot 114	Individual Lot	Lot 114	7/27/2022	Active	No
Current Condition:	Good Condition - This lot is in 7/27/22 inspection.	nactive for construction. Lega	cy Homes installed silt fenc	e along the south si	de and rear of the lot prior to the
Lot 115	Individual Lot	Lot 115	7/27/2022	Active	No
Current Condition:	Good Condition - This lot is in inspection.	nactive for construction. Lega	cy Homes installed silt fenc	e along the rear of t	he lot prior to the 7/27/22
Lot 116	Individual Lot	Lot 116	7/27/2022	Active	No
Current Condition:	Good Condition - This lot is in inspection.	nactive for construction. Lega	cy Homes installed silt fenc	e along the rear of t	he lot prior to the 7/27/22
Lot 120	Individual Lot	Lot 120	8/3/2022	Active	No
Current Condition:	corner of the lot prior to the	e 8/3/22 inspection.			silt fence along the southeast
Lot 126	Individual Lot	Lot 126	Syst Plains Contractor	Active	No
Current Condition:	corner of the lot prior to the		. Great Flains Contractor !	Services installed	silt fence along the northeast
Lot 131	Individual Lot	Lot 131		Removed	
Current Condition:	Removed - Legacy Homes so	odded the lot prior to the insp	ection on 7/27/22.		
Lot 132	Individual Lot	Lot 132	10/28/2021	Pending	Yes
Current Condition:	Pending - This lot is inactive f	f <mark>or construction. Legacy Hom</mark>	es disturbed the lot during h	nome-building activit	ties on adjacent lots prior to the
	10/28/21 inspection.				
	Silt fence should be extended	or wattles should be installed	d across the front of the lot.		
	Legacy Homes was informed 1/27/22, 3/3/22, 4/7/22, 5/20/3		done as of last inspection. I	Legacy Homes was	reminded on 12/2/21, 12/23/21,
Lot 133	Individual Lot	Lot 133		Removed	
Current Condition:	Removed - Legacy Homes so		ection on 7/27/22.		
Lot 134 Current Condition:	Individual Lot Removed - Legacy Homes so	Lot 134	oction on 7/27/22	Removed	
Lot 135	Individual Lot	Lot 135	10/28/2021	Active	No
Current Condition:					ing activities on adjacent lots prior
	to the 10/28/21 inspection. Le				
Lot 136	Individual Lot	Lot 136	6/22/2021	Active	No
Current Condition:	the front corner of the lot p	rior to the 8/3/22 inspection	n.	6/22/21. Legacy Ho	omes installed silt fence along
Lot 137	Individual Lot	Lot 137	6/30/2021	Active	No No
Current Condition:	the front corner of the lot p			b/30/21. Legacy Ho	omes installed silt fence along
Lot 139	Individual Lot	Lot 139	7/7/2021	Active	No
Current Condition:					ence along the northeast corner
	of the lot prior to the 8/3/22				
Lot 140	Individual Lot	Lot 140	8/3/2022	Active	No
Current Condition:	corner of the lot prior to the	e 8/3/22 inspection.			silt fence along the southeast
Lot 147	Individual Lot	Lot 147	8/3/2022	Active	No
Current Condition:	corner of the lot prior to the	e 8/3/22 inspection.			silt fence along the northwest
Lot 153	Individual Lot	Lot 153	8/3/2022	Active	No
Current Condition:	Cood Condition Till	a impositive for the state of	Crook Diction Continued	Complete to the total of the tot	
	Good Condition - This lot i	e 8/3/22 inspection.			·
Lot 154	corner of the lot prior to the Individual Lot	e 8/3/22 inspection. Lot 154	6/22/2021	Active	No
Lot 154 Current Condition:	corner of the lot prior to the Individual Lot Good Condition - Legacy Ho the front corners of the lot	e 8/3/22 inspection. Lot 154 prior to the 8/3/22 inspection	6/22/2021 of prior to the inspection on on.	Active 6/22/21. Legacy Ho	No omes installed silt fence along
Lot 154 Current Condition: Lot 159	corner of the lot prior to the Individual Lot Good Condition - Legacy Ho the front corners of the lot Individual Lot	E 8/3/22 inspection. Lot 154 person began excavating the logorous to the 8/3/22 inspection Lot 159	6/22/2021 ot prior to the inspection on on. 7/21/2021	Active 6/22/21. Legacy Ho	No omes installed silt fence along No
Lot 154 Current Condition:	corner of the lot prior to the Individual Lot Good Condition - Legacy Hothe front corners of the lot Individual Lot Good Condition - Legacy Hothe	E 8/3/22 inspection. Lot 154 prior to the 8/3/22 inspection Lot 159 priors began excavating the logarithms and the second se	6/22/2021 ot prior to the inspection on on. 7/21/2021 ot prior to the inspection on	Active 6/22/21. Legacy Ho	No omes installed silt fence along
Lot 154 Current Condition: Lot 159	corner of the lot prior to the Individual Lot Good Condition - Legacy Ho the front corners of the lot Individual Lot	E 8/3/22 inspection. Lot 154 prior to the 8/3/22 inspection Lot 159 priors began excavating the logarithms and the second se	6/22/2021 ot prior to the inspection on on. 7/21/2021 ot prior to the inspection on	Active 6/22/21. Legacy Ho	No omes installed silt fence along No
Lot 154 Current Condition: Lot 159 Current Condition:	corner of the lot prior to the Individual Lot Good Condition - Legacy Hother front corners of the lot Individual Lot Good Condition - Legacy Hother front corners of the lot Individual Lot Individual Lot Active - An unidentified but flat, so no BMPs are recommended.	Lot 154 Comes began excavating the legarity to the 8/3/22 inspection Lot 159 Comes began excavating the legarity to the 8/3/22 inspection Lot 159 Comes began excavating the legarity to the 8/3/22 inspection Lot 3, Replat 1 Idder began excavating the	6/22/2021 ot prior to the inspection on on. 7/21/2021 ot prior to the inspection on on. 8/3/2022 lot prior to the inspection	Active 6/22/21. Legacy Ho Active 7/21/21. Legacy Ho Active on 8/3/22. The from	No pmes installed silt fence along No pmes installed silt fence along
Lot 154 Current Condition: Lot 159 Current Condition: Lot 3, Replat 1	corner of the lot prior to the Individual Lot Good Condition - Legacy Hother front corners of the lot Individual Lot Good Condition - Legacy Hother front corners of the lot Individual Lot Active - An unidentified bui	Lot 154 Comes began excavating the legarity to the 8/3/22 inspection Lot 159 Comes began excavating the legarity to the 8/3/22 inspection Lot 159 Comes began excavating the legarity to the 8/3/22 inspection Lot 3, Replat 1 Idder began excavating the	6/22/2021 ot prior to the inspection on on. 7/21/2021 ot prior to the inspection on on. 8/3/2022 lot prior to the inspection	Active 6/22/21. Legacy Ho Active 7/21/21. Legacy Ho Active on 8/3/22. The from	No omes installed silt fence along No omes installed silt fence along No No nt and rear of the lot are mostly

Lot 6, Replat 1	Individual Lot	Lot 6, Replat 1	12/22/2021	Active	No		
Current Condition:					front and rear of the lot are most		
					aced a portable toilet prior to 3/7/2		
	inspection, but did not acknow	owledge ownership until 3/14/2	22. THI Builders secured the	ne portable toilet prid	or to the 4/14/22 inspection.		
		T = =	1	1	1		
Lot 7, Replat 1	Individual Lot	Lot 7, Replat 1	12/22/2021	Active	No No		
Current Condition:		this time. E&A inspector will o		2/21. The front and	rear of the lot are mostly flat, so		
Lato Danieto		· · · · · · · · · · · · · · · · · · ·		A -45	l N-		
Lot 8, Replat 1 Current Condition:	Individual Lot	Lot 8, Replat 1	12/29/2021	Active	rear of the lot are mostly flat, so		
Current Condition.		this time. E&A inspector will of		19/21. The front and	rear or the lot are mostly flat, so		
Let 0. Penlet 1	Individual Lot	Lot 9, Replat 1	12/29/2021	Active	Yes		
Lot 9, Replat 1 Current Condition:					ing inlet on Horizon Street prior t		
Current Condition.					nmended at this time. E&A inspe		
					reet prior to the inspection on		
			n on Horizon Street is ass	igned to THI Builder	s as of 3/7/22, but removal will b		
	the responsibility of Bridgew	ater Homes.					
	The inlet protection should b	o cloaned out					
	The linet protection should b	le cleaned out.					
	THI Builders was informed to	o complete by 3/14/22. Not do	one as of last inspection. T	HI Builders was rem	ninded on 4/15/22, 5/28/22 , 8/5/2		
			·				
Lot 10, Replat 1	Individual Lot	Lot 10, Replat 1	12/29/2021	Active	Yes		
Current Condition:			e lot prior to the inspection	on 12/29/21. THI B	uilders installed wattles on the ea		
	side of the lot prior to the 7/8	3/22 inspection.					
	The inlet costs stiers about I	1					
	The inlet protection should b	e cleaned out.					
	THI Builders was informed to	o complete by 6/2/22. Not dor	ne as of last inspection. Th	II Builders was ren	ninded on 8/5/22		
Lot 11, Replat 1	Individual Lot	Lot 11, Replat 1		Removed			
Current Condition:		mes sodded the lot prior to the	5/18/22 inspection	rtomovou			
Lot 12, Replat 1	Individual Lot	Lot 12, Replat 1	T	Removed	T		
Current Condition:		mes sodded the lot prior to the	5/19/22 increation	Removed			
		· · · · · · · · · · · · · · · · · · ·		1	T		
Lot 13, Replat 1	Individual Lot	Lot 13, Replat 1	7/8/2022	Active	No		
Current Condition:		er Homes has been using the prior to the 7/8/22 inspection.	lot for their job trailer. Brid	gewater Homes soc	dded part of the lot and installed		
				1	T		
Lot 14, Replat 1	Individual Lot	Lot 14, Replat 1	7/18/2022	Active	No		
Current Condition:	inspection.	inactive for construction. Brido	gewater Homes Installed w	attles in the rear of	the lot prior to the 7/18/22		
		1	T/40/0000	1	1		
Lot 15, Replat 1	Individual Lot	Lot 15, Replat 1	7/18/2022	Active	No No		
Current Condition:	inspection.	inactive for construction. Brido	gewater Homes installed w	attles in the rear of	the lot prior to the 7/18/22		
1 (40 D 1)4	· ·	1 140 D 114	I	T 5 .	1		
Lot 16, Replat 1	Individual Lot	Lot 16, Replat 1	7/0/00 :	Removed			
Current Condition:		mes sodded the lot prior to the	e 7/8/22 inspection.		1		
Lot 17, Replat 1	Individual Lot	Lot 17, Replat 1		Removed			
Current Condition:		mes sodded the lot prior to the		_			
Lot 44, Replat 1	Individual Lot	Lot 4, Replat 1	8/3/2022	Active	No		
Current Condition:			. Great Plains Contracto	r Services installed	d silt fence along the east cor		
	of the lot prior to the 8/3/2						
PB 1	Portable Bathroom	Site		Removed			
Current Condition:		ction removed the portable to	ilet prior to the 4/21/21 ins	· _			
PB 2	Portable Bathroom	Site		Removed			
Current Condition:	0 7	removed the portable toilet pri					
PB X	Portable Bathroom	Site	7/27/2022	Active	No No		
Current Condition:		tified builder secured a portab			_		
SB 1	Sediment Basin	B5	11/14/2019	Active	Yes		
Current Condition:					As of the last inspection, the bas		
					i 11/22/19. The riser is not in pla EJ closed the gaps between the		
		the inspection on 7/21/20. Gre					
					Roth finished cleaning out the b		
	and installing the baffle prior to the inspection on 9/8/21.						
	The basin isn't draining corre	ectly and a new riser with the	correct dimensions should	pe installed.			
	DE L Grading was informed in	to complete by 6/16/21. Not d	one as of last inspection. I	El was reminded o	on 7/9/21, 8/13/21, 8/26/21, 9/10		
			· · · · · · · · · · · · · · · · · · ·		ector on 2/23/22 that the new rise		
		uled for delivery by 3/4/22. E&					
SB 2	Sediment Basin	V5	8/19/2019	Active	No		
Current Condition:					in the process of excavating the		
					stalled a riser in the basin prior t		
					12/27/19 inspection. DEJ closed		
					outfall prior to the inspection on		
					e prior to the inspection on 5/19/ . E&A inspector painted cleanou		
	mark on 6/18/21.	u mataneu unt bannes and dev	valering notes prior to the	mapection on 6/8/21	. Lan inspector painted deanot		
		· · · · -		1	· · ·		
SB 3	Sediment Basin	AA17	11/15/2018	Active	No		

Current Condition:	9/11/19 inspection. DEJ Grad inspection on 12/12/19. DEJ i	on/shaping of the basin was n ding rebuilt the berm of the ba installed a riser in the basin p	ot complete. E&A will monit usin prior to inspection on 10 rior to the inspection on 7/2	tor. Excavation of th 0/16/19. The outlet p 1/20. DEJ installed	e basin is complete as of the
SB 4	Sediment Basin	AA26	11/15/2018	Active	No
Current Condition:	Good Condition - 7% Filled - I 11/19/18, however, no riser s 11/14/19 inspection. The outle below the basin outfall prior to	Basin was being excavated of tructure has been installed as et pipe was installed prior to to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pit 10/28/21 inspection. Roth El	uring inspection on 11/15/1 s of last inspection. The out nspection on 11/27/19. DE. he outfall is connected to the began cleaning out the bas rior to the 10/25/21 inspectinterprises completed the re	8. Basin excavation fall of the basin was J installed a permanner riser pipe as of the in prior to the 10/19 on. Sediment at the maining SWPPP ite	ent riser in the basin and rip rap ne inspection on 8/13/20, therefore 1/21 inspection. E&A inspector will outfall was washed away by
SB 5	Sediment Basin	C28	11/14/2019	Active	Yes
Current Condition:					s of the last inspection, the basin is
	the basin prior to the inspectic Contractor Services installed the baffle prior to the inspection inspector will continue to more than the dewatering holes lower the DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde	on on 7/21/20, therefore a silt rip rap below the outfall prior on 10/25/21. An unidentification. han 2.58 feet from the riser case, and Great Plains Contract don 8/20/20. DEJ, Peter Kat Roth Enterprises was reminded.	rest should be plugged. or Services were informed to, Gene Graves, and Great to, Gene Graves, and Great to the output to the inspection on Services were informed to, Gene Graves, and Great to the output to the o	let pipe is no longer 0. Roth Enterprises ng the inlet pipe prior to complete by 8/05 Plains Contractor S	cleaned out the basin and installed r to the 4/20/22 inspection. E&A
SF 1	Silt Fence	BB 20-BB14		Removed	
Current Condition:	Removed - SF 1 *(SF 1.3) was outheast corner of the site, inspection on 4/22/20. As of t	as installed by Double D Excancluding the undermined portule inspection on 7/29/20, vegosite that reinstallation of the	ion by the outfall of the bas getation has become suffici- removed silt fence is no lor	n 11/28/18. The silt in and the multiple f ently established on	fence east of the slope in the ull spots, was removed prior to the the slope located along the e E&A inspector will continue to
SF 2	Silt Fence	BB 14 - Gold Coast Rd	11/28/2018	Active	Yes
	2 outfall. The full portion of sil the inspection on 9/24/20. Silf 1/12/21 inspection. Great Pla Commercial Seeding reinstall fence will be recommended to 1.) The silt fence should be re 2.) The silt fence should be re	It fence south of the future loc t fence was removed due to g ins Contractor Services repa led the silt fence south of Gol to homebuilders at the lot level epaired where fallen. epaired where fallen in an add the informed to complete by 5/2	eation of Gold Coast Road of grading on eastern perimeterized and reinstalled new silt of Coast Road to SB 3 prior all as necessary. ditional location. 5/22. Not done as of last in	vas removed to allo er from Lake Vista E fence above SB 3 (to the 11/11/21 ins	gap in the silt fence east of the SB w access for sewer work prior to Drive to Gold Coast Road prior to C) outfall prior to 5/10/21. pection. Missing portions of silt
SF 3 Current Condition:	Services installed the remaind side of Gold Coast Road prion 2 outfall, cleaned out some of cleaned out the silt fence whe future location of Gold Coast due to grading on eastern per	der of the silt fence prior to in r to the inspection on 8/19/20 f the full portions of silt fence ere full on the north side of the Road was removed to allow in rimeter from Gold Coast Roance along the northeast corne	spection on 7/31/19. Great I. Great Plains Contractor S on the northeastern perime e site prior to the inspection access for sewer work prior d to the northeast corner of er of the site prior to the 11/	Plains Contractor S ervices closed the ofter of the site (addition 9/09/20. The full to the inspection of the site prior to 1/1	No. 11/28/18. Great Plains Contractor services installed silt fence on either gap in the silt fence east of the SB ional cleanout still required), and I portion of silt fence south of the n 9/24/20. Silt fence was removed 2/21 inspection. Commercial issing portions of silt fence will be
SF 4	Silt Fence	BB 1 - 120th St	11/28/2018	Active	No
Current Condition:	OIL I CILCE	25 1 - 120ttl Ot	11/20/2010	, AOUVE	110
	Services installed the remaind full portions of silt fence on the on the north side of the site p NE corner prior to 5/10/21. G	der of the silt fence prior to in the northeastern perimeter of t trior to the inspection on 9/09/ PCS installed silt fence on the g cleaned out and repaired th	spection on 7/31/19. Great he site (additional cleanout /20. Great Plains Contracto e east side of 120th Street,	Plains Contractor S still required), and o r Services repaired and backfilled the s	11/28/18. Great Plains Contractor ervices cleaned out some of the eleaned out the silt fence where full and reinstalled new silt fence in the silt fence north of SB 2, prior to eat Plains Contractor Services
SF 5	Services installed the remaind full portions of silt fence on th on the north side of the site p NE corner prior to 5/10/21. G 6/15/21. Commercial Seeding repaired the silt fence prior	der of the silt fence prior to in e northeastern perimeter of t rior to the inspection on 9/09/ PCS installed silt fence on the g cleaned out and repaired the to the 8/3/22 inspection.	spection on 7/31/19. Great he site (additional cleanout '20. Great Plains Contracto e east side of 120th Street, e silt fence prior to the 11/1	Plains Contractor S still required), and or r Services repaired and backfilled the s 1/21 inspection. Gree	ervices cleaned out some of the leaned out the silt fence where full and reinstalled new silt fence in the litt fence north of SB 2, prior to eat Plains Contractor Services
SF 5 Current Condition:	Services installed the remaind full portions of silt fence on the on the north side of the site p NE corner prior to 5/10/21. G 6/15/21. Commercial Seeding repaired the silt fence prior Silt Fence Good Condition - (SF 1.1) G South 123rd Avenue; and eas snow removal prior to inspect 1/1/2/21 Inspection. GPCS inside of 120th Street prior to 6	der of the silt fence prior to in e northeastern perimeter of it rior to the inspection on 9/09/PCS installed silt fence on the g cleaned out and repaired the to the 8/3/22 inspection. 120th St - S 123rd Ave great Plains Contractor Services side of South 120th Street tion on 12/30/20. Silt fence we stalled silt fence on the west sout and repaired the silt fence out and repaired the silt fence out and repaired the silt fence out and repaired the silt fence.	spection on 7/31/19. Great the site (additional cleanout (20. Great Plains Contract) e east side of 120th Street, e silt fence prior to the 11/1 11/7/2019 tes repaired the silt fence al prior to 11/10/20. Silt fence as removed between 123rd side of 120th Street prior to extended the silt fence on the e around S 120th street an	Plains Contractor Still required), and or reverses repaired and backfilled the still repaired and backfilled the still repaired and seat the still repair to the still	ervices cleaned out some of the eleaned out the silt fence where full and reinstalled new silt fence in the silt fence north of SB 2, prior to eat Plains Contractor Services No t fence on east and west sides of orth of S 124th Street damaged by treet due to grading prior to aned out the silt fence on the west in street prior to 8/25/21.

Current Condition:	123rd Avenue; and east side snow removal prior to inspec	of South 120th Street prior to	11/10/2020. Silt fence goi Contractor Services remo	ng north/south north o	n east and west sides of South f S 124th Street damaged by or to the 4/21/21 inspection. E&A
SF 7	Silt Fence	S 125th St - A 5	11/7/2019	Active	No
Current Condition:	South 123rd Avenue; and early snow removal prior to instructional seeding repaire	st side of South 120th Street pection on 12/30/20. GPCS re	prior to 11/10/2020. Silt fer moved a portion of the silt around S 125th street and	nce going north/south r fence north of SB 1 pr I north of SB 1 prior to	ence on east and west sides of north of S 124th Street damaged rior to the inspection on 6/15/21. the 11/11/21 inspection. Great
Current Condition:	Good Condition - (SF 1.5) - I County Department of Roads	Due to Schram Road Improve s until road project is complet ding repaired the silt fence pri	ments, damaged silt fence ed. E&A removed that sec	south of SB E and D7 tion of silt fence from t	will be maintained by Sarpy
SF 9	Silt Fence	A 9 - A 12	11/7/2019	Active	Yes
	exposed in several areas (so out the silt fence prior to the inspection. Commercial See The silt fence should be repa	4/21/21 inspection. Great Pla ding cleaned out and repaired aired where fallen.	or to the inspection on 9/09 ns Contractor Services rep the silt fence prior to the 1	/20. Great Plains Cont paired/cleaned out the 1/11/21 inspection.	he bottom of the run was tractor Services repaired/cleane silt fence prior to the 5/10/21
STR	Streets	Site	11/8/2018	Active	Yes
Current Condition:	streets prior to the 7/14/22 in Streets around active Legac	spection. y Homes lots should be clean to complete by 1/25/22. Not	ed daily or as needed.		eminded on 3/3/22, 4/7/22,
SWPPP Sign	Misc./Other	Schram Road (W27) and S 120th Street (P1)	11/19/2018	Active	No
Current Condition:	inspector installed the SWPF	ctor installed the SWPPP sign PP sign at S 120th Street at the	e north end of the site duri	ng the inspection on 6	ection on 11/19/18. E&A /9/21. The SWPPP sign on S 120th Street during the 4/1/22
Certification Statement	system designed to assure to person or persons who mand to the best of my knowledge	hat qualified personnel proper age the system or those perso	ly gathered and evaluated ons directly responsible for d complete. I am aware tha	the information submit gathering the informat tt there are significant	supervision in accordance with a ted. Based on my inquiry of the tion, the information submitted is penalties for submitting false
Sta	4				Post Sil