E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A- P2017.	258.000		·		
Inspector: Joe Manning					Stage		
Project Name:	CSW-2	1					
For Week Ending:		3/4/2023					
Project Location:	120th Str	120th Street and Schram Road, Papillion, NE (Sarpy County)					
Grading:	97%						
Sanitary Sewer:	96%						
Storm Sewer:	96%						
Paving:	96%						
Seeding:	90%						
Utilities:	90%						
Overall Development:	48%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Time		
Sunday:	0.25"				Weel		
Monday:	0.12"						
Tuesday:	0.00"				+		
Wednesday:	0.00"						
Thursday:	0.00"	3/2/2023	Sunny 43	2:40 PM			
Friday:	0.00"	0.2.2020					
Saturday:	0.00"						
Complaints:	None						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/2018) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/2018). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/2019). Stockpiling in the western portion of Dev 2 (4/24/2019). Grading has begun in the western portion of Dev 2 (5/9/2019). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/2019). Stripping/Grading in northeastern portion of Dev 2 (6/27/2019) Minor regrading/excavation in DEV 3 -School (7/31/2019). Excavation in Dev 3 and Dev 4 for sanitary installation (8/08/2019). Trenching in Dev 4 for utility installation (9/04/2019). Grading has temporarily ceased throughout the site (10/11/2019). Grading has resumed for basin installation (10/16/2019) Grading has resumed throughout the site (10/22/2019). Excavation near SB 4 for basin installation (10/22/2019). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/2019). Stripping/grading in DEV A (10/31/2019). Disking occurring in Dev 4 (11/7/2019). Sanitary installation in Dev 2/3 (11/7/2019). Grading in Dev 5 and Dev A for basin excavation (11/14/2019). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/2019). Grading in Dev A (12/12/2019). Grading has temporarily ceased due to winter conditions (11/23/2020). Grading has resumed (4/27/2020); Backfilling of curbs for paving underway (10/21/2020). Excavation on Lot 110 (12/22/2020). Grading on eastern side of Dev 2 (1/12/2021). Excavation by 124th st and Gold Coast Rd (3/4/2021). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/2021). Utilities were put in the southwest corner of the site (4/21/2021). Grading in SW corner of site by Calabretto Building Group (9/8/2021). Ground disturbance for sewer installation around Outlot L (7/27/2022). Ground disturbance west of SB 4 for sewer installation (10/19/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site: Grading commenced (11/8/2018) Grading has begun in Drainage Areas Dev. 2, Dev. 3, and Dev. 4 (11/15/2018). Grading has temporarily ceased due to winter conditions. Minor grading/regrading W of SB 3 to redirect water flowing off site to east (4/13/219). Stockpiling in the western portion of Dev 2 (4/24/2019). Grading has begun in the western portion of Dev 2 (5/9/2019). Stripping/Grading in southern portion of Dev A and throughout Dev 5 (6/13/2019). Stripping/Grading in northeastern portion of Dev 2 (6/27/2019) Minor regrading/excavation in DEV 3 -School (7/31/2019). Excavation in Dev 3 and Dev 4 for sanitary installation (8/08/2019). Trenching in Dev 4 for utility installation (9/04/2019). Grading has temporarily ceased throughout the site (10/11/2019). Grading has resumed for basin installation (10/16/2019) Grading has resumed throughout the site (10/22/2019). Excavation near SB 4 for basin installation (10/22/2019). Excavation along the northern perimeter of the site near 120th St for sanitary tie-in (10/31/2019). Stripping/grading in DEV A (10/31/2019). Disking occurring in Dev 4 (11/7/2019). Sanitary installation in Dev 2/3 (11/7/2019). Grading in Dev 5 and Dev A for basin excavation (11/14/2019). Fine grading in Dev 4 and Dev 3 in preparation for paving (11/14/2019). Grading in Dev A (12/12/2019). Grading has temporarily ceased due to winter conditions (11/23/2020). Grading has resumed (4/27/2020); Backfilling of curbs for paving underway (10/21/2020). Excavation on Lot 110 (12/22/2020). Grading on eastern side of Dev 2 (1/12/2021). Excavation by 124th st and Gold Coast Rd (3/4/2021). Excavation by 125th and Edward St, and sidewalk pavement near east end of Gold Coast Rd (3/10/2021). Utilities were put in the southwest corner of the site (4/21/2021). Grading in SW corner of site by Calabretto Building Group (9/8/2021). Ground disturbance for sewer installation (10/19/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/2018). EM 1 partially installed (9/30/2019). DEJ seeded the central drainage around the future S. 124th St., the slope in the northeastern quadrant of the site (6/16/2020); school site was sodded (12/9/2020). ROW seeding began (6/2/2021). Matting of the slope west of S 120th entrance (8/25/2021). Seeding/matting Outlots F, G, H, and ROW overseeding (4/1/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No - See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes
Create Corrective Action?
N/A
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
No No
Create Corrective Action?
No - See BMP Section.
Are construction entrances and adjacent streets being maintained adequately?
No.

Create Corrective Action?
No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Comments:

Comments:

- 1) Site was active for home construction and sewer installation during the last inspection.
- 2) Ashbury Hills Self Storage (CSW-202105789) is active on Lot 166 of the Ashbury Hills development as of 9/13/21.

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) E&A will monitor the removal of the inlet filters around the school project with the site stabilization. E&A inspector received an email from Tyson Smith with Lamp Rynearson 1/11/21 that they did not recommend putting inlet filters around the school. GPCS was informed to remove the inlet filters by 3/11/21. GPCS removed 5 inlet filters prior to the 3/24/21 inspection. As of 4/9/21 there are two inlet filters left by the school, E&A inspector will continue to monitor. GPCS was reminded on 4/30/21, 5/4/21, 5/6/21, 5/11/2021, 5/19/21, 5/30/21, 6/25/21, 7/14/21, 8/13/21, 9/10/21, 9/30/21. Peter Katt, Gene Graves, and Commercial Seeding were reminded on 10/14/21, 11/3/21, 12/08/22, 1/20/23
- 3) Trackout was observed on Horizon Street, S 124th Avenue, and S 125th Street where construction vehicles for the storm sewer installation in the west portion of the site have been accessing the area during the inspection on 2/02/23. Trackout should be cleaned up, and construction entrances should be installed or access restricted in these areas. The construction observer was contacted to inform the contractor to complete as weather conditions allow. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
A 1	Area Inlet Protection	R 16		Removed			
Current Condition:	Removed - Silt fence around the inlet will not be recommended as of 4/16/21 due to inlet leading to a sediment basin.						
B 1	Temporary Berm	North side of site (west of SB 2)		Removed			
Current Condition:	Removed - DEJ Grading rem	oved the temporary berm du	ring the excavation of SB 5	prior to inspection of	on 11/14/19.		
B 2	Temporary Berm	Southwest side of site (NE of SB 5)		Removed			
Current Condition:	Removed - DEJ Grading rem	oved the berms prior to insp	ection on 12/18/19. The ber	ms are not needed	at this time. E&A will monitor.		
CE 1	Stabilized Construction Entrance	Schram Road (W27)		Removed			
Current Condition:	project grading reaching the			longer in use due to	o the Schram Road Improvements		
CE 2	Stabilized Construction Entrance	Schram Road (AA27)		Removed			
Current Condition:	associated with the school pr				construction. Since this BMP is ion.		
CE 3	Stabilized Construction Entrance	Schram Road (O27)		Removed			
Current Condition:					n on 9/24/20. Reinstallation is not e entrance location prior to the		
CE 4	Stabilized Construction Entrance	Schram Road (W27)	11/16/2022	Active	No		
Current Condition:	Good Condition - 85% effective	ve - The sewer contractor ins	stalled a construction entran	ce prior to the inspe	ection on 11/16/22.		
CW 1	Concrete Washout	North of SB 4		Removed			
Current Condition:	Removed- Tab Construction	removed the washout pit pric	r to 11/18/20		•		
CW 2	Concrete Washout	Outlot A-South 124th Street & Horizon Street	5/19/2021	Active	No		
Current Condition:		o the washout prior to the ins			ned out the washout and cleaned berm along the front of the washout		
D 1	Temporary Diversion Ditch	(BB8-BB15)		Removed			
Current Condition:	Removed - The majority of the time due to establishment of			4/20. Reinstallation	does not appear necessary at this		
D 2	Temporary Diversion Ditch	(Q1-V2)		Removed			
Current Condition:	Removed - The diversion is rivia curb inlets to the basin.	o longer necessary as of the	inspection on 8/27/20 due	to paving of S. 123r	d Avenue, which will divert water		
D 3	Temporary Diversion Ditch	(C20-C26)	8/27/2020	Active	No		
Current Condition:	Good Condition - DEJ installe inspection on 11/11/21.	d the diversion prior to the in	spection on 8/27/20. Comm	nercial Seeding rede	efined the diversion prior to the		
D 4	Temporary Diversion Ditch	(BB21-BB25)		Removed			
Current Condition:	Removed- Due to pavement	operations and school work,	diversion ditch was remove	d as of 10/21/2020.			
D 5	Temporary Diversion Ditch	(X2-BB6)	8/27/2020	Pending	No		

Current Condition:	Pending - Perimeter silt fence diversion is not recommended			none as of the 1710	orz i inspection. Installing the
D 6	Temporary Diversion Ditch	(V27-AA27)	will continue to monitor.	Removed	
Current Condition:			l nspection on 7/29/20 due to		getation in part of the intended
	location as well as the start of				
D 7	Temporary Diversion Ditch	(E28-P28)	8/27/2020	Active	No
Current Condition:	Good Condition - DEJ installe				
	6/15/21.	•	•		
D 8	Temporary Diversion Ditch	(B8-B13)	8/27/2020	Active	No
Current Condition:	Good Condition - DEJ installe	d the diversion prior to the in	spection on 8/27/20. GPCS	redefined the dive	ersion prior to the inspection on
	5/19/21.				
D 9	Temporary Diversion Ditch	(C3-E2)		Removed	
Current Condition:	Removed- Due to pavement			d as of 10/21/2020).
EM 1	Erosion Control Matting	(CC20-CC27)	9/30/2019	Active	No
Current Condition:	Good Condition - Erosion con				
514.0	installation during future inspe				
EM 2 Current Condition:	Erosion Control Matting Pending - Will be installed wh	B5	11/15/2018	Pending	No
EM 3		D3	11/15/2018	Ponding	No
Current Condition:	Erosion Control Matting Pending - Will be installed wh			Pending	NO
ET 1	Erosion Control Terrace	C 12-21		Removed	
Current Condition:	Removed - The erosion contr		I and replaced with D-3 and		ection on 8/27/20.
FT 1	Fuel Tanks	O23	<u>'</u>	Removed	1
Current Condition:	Removed - Roth Enterprises		the inspection on 5/26/20	Removed	1
FT X	Fuel Tank	Site	2/23/2023	Active	No
Current Condition:					sewer contractor placed a double
	walled fuel tank on site prior to		,		
Lot 1	Individual Lot	Lot 1		Removed	
Current Condition:	Removed - Ideal Designs soc	ded the lot prior to the 5/18/2	22 inspection.	•	
Lot 7	Individual Lot	Lot 7	10/27/2022	Active	Yes
Current Condition:	Active - Al Belt began excava				
	inspection, however, due to a	ctive excavation. Al Belt Con	struction cleaned the street	prior to the inspec	tion on 11/16/22.
	The street in front of the lot sh	hould be cleaned			
	The street in front of the lot si	iodid be clearied.			
	Al Belt Construction was infor	med to complete by 12/30/2	2. Not done as of the last in	spection.	
Lot 8	Al Belt Construction was infor	med to complete by 12/30/2:	2. Not done as of the last in	spection. Active	Yes
Lot 8 Current Condition:	Individual Lot Active - Baranko Homes bega	Lot 8 an excavating the lot prior to	9/27/2022 the inspection on 9/27/22. T	Active	of the lot are mostly flat, so no
	Individual Lot Active - Baranko Homes bega BMPs are recommended at the	Lot 8 an excavating the lot prior to his time. E&A inspector will n	9/27/2022 the inspection on 9/27/22. I nonitor. A dirt pile was obse	Active The front and rear or red in the ROW, I	of the lot are mostly flat, so no however Baranko Homes was
	Individual Lot Active - Baranko Homes bega	Lot 8 an excavating the lot prior to his time. E&A inspector will n	9/27/2022 the inspection on 9/27/22. I nonitor. A dirt pile was obse	Active The front and rear or red in the ROW, I	of the lot are mostly flat, so no however Baranko Homes was
	Individual Lot Active - Baranko Homes bega BMPs are recommended at the actively excavating during the	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara	9/27/2022 the inspection on 9/27/22. I nonitor. A dirt pile was obse	Active The front and rear or red in the ROW, I	of the lot are mostly flat, so no however Baranko Homes was
	Individual Lot Active - Baranko Homes bega BMPs are recommended at the	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara	9/27/2022 the inspection on 9/27/22. I nonitor. A dirt pile was obse	Active The front and rear or red in the ROW, I	of the lot are mostly flat, so no however Baranko Homes was
	Individual Lot Active - Baranko Homes bega BMPs are recommended at the actively excavating during the	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara hould be cleaned.	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection of the dispersion of the inspection of the inspect	Active The front and rear or rved in the ROW, In the ROW, In the interpretation of the i	of the lot are mostly flat, so no however Baranko Homes was
	Individual Lot Active - Baranko Homes bega BMPs are recommended at the actively excavating during the The street in front of the lot st	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara hould be cleaned.	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection of the dispersion of the inspection of the inspect	Active The front and rear or rved in the ROW, In the ROW, In the interpretation of the i	of the lot are mostly flat, so no however Baranko Homes was
	Individual Lot Active - Baranko Homes bega BMPs are recommended at the actively excavating during the The street in front of the lot st	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara hould be cleaned.	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection of the dispersion of the inspection of the inspect	Active The front and rear or rved in the ROW, In the ROW, In the interpretation of the i	of the lot are mostly flat, so no however Baranko Homes was
Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot she Baranko Homes was informed Individual Lot Active - JC Custom Build beg	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. N Lot 10 an excavating the lot prior to	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection of the inspection of the last inspection of the last inspection of the last inspection of the inspection	Active The front and rear orved in the ROW, Interpreted in the rear or the interpreted in the rear or the interpreted in the in	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22.
Current Condition: Lot 10 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot standard Homes was informed and the Individual Lot Active - JC Custom Build begrecommended at this time. Exception is a second support of the Individual Lot Active - JC Custom Build begrecommended at this time. Exception is a second support of the Individual Lot Active - JC Custom Build begrecommended at this time.	Lot 8 an excavating the lot prior to his time. E&A inspector will n inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. N Lot 10 an excavating the lot prior to &A inspector will monitor.	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/2022 the inspection on 6/21/22.	Active The front and rear or rved in the ROW, in the prior to the in ction. Active Due to vegetation s	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will
Current Condition: Lot 10 Current Condition: Lot 11	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Ed	Lot 8 an excavating the lot prior to his time. E&A inspector will in hispection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. N Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/2022 the inspection on 6/21/22. 4/27/2022	Active The front and rear or rved in the ROW, I rt pile prior to the in action. Active Due to vegetation active Active	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will
Current Condition: Lot 10 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build begrecommended at this time. Exception of the lot o	Lot 8 an excavating the lot prior to his time. E&A inspector will in inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. N Lot 10 lan excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection of the last inspection of the last inspection on 6/21/22. The inspection on 6/21/22 of prior to the 4/27/22 inspec	Active The front and rear or rved in the ROW, Interpreted in the ROW, Interpre	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will be observed in the ROW on 4/27/27
Current Condition: Lot 10 Current Condition: Lot 11	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot standard to the Individual Lot Active - JC Custom Build begrecommended at this time. Except Individual Lot Good Condition - The homeous The homeowner removed the	Lot 8 an excavating the lot prior to his time. E&A inspector will in his inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. N Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection of the last inspection of the last inspection on 6/21/22. The inspection on 6/21/22 of prior to the 4/27/22 inspec	Active The front and rear or rved in the ROW, Interpreted in the ROW, Interpre	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2
Lot 10 Current Condition: Lot 11 Current Condition: Lot 11 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Ed Individual Lot Good Condition - The homeof The homeowner removed the lot prior to the inspection on 6	Lot 8 an excavating the lot prior to his time. E&A inspector will in inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. No Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot of the lot prior to the dirt piles from the ROW prior 1/29/22.	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/2022 the inspection on 6/21/22. 4/27/2022 of prior to the 4/27/22 inspection. The inspection on 7/20/20 inspection.	Active The front and rear or rved in the ROW, Interpreted in the ROW, Interpre	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of
Lot 10 Current Condition: Lot 11 Current Condition: Lot 11 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot shadow in the Individual Lot Active - JC Custom Build beg recommended at this time. Experience of Good Condition - The homeous The homeowner removed the lot prior to the inspection on 6	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot prior to the l	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. 4/27/2022 the inspection on 6/21/22. 4/27/2022 to trior to the 4/27/22 inspection. The first of the 5/3/22 inspection. The inspection of 5/3/22 inspection. The first of the 5/3/22 inspection. The first of the 5/3/22 inspection. The first of the 5/3/22 inspection. The inspection of the 5/3/22 inspection. The first of the first	Active The front and rear or rved in the ROW, Int pile prior to the pile prior to th	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/2 stalled silt fence along the rear of
Lot 10 Current Condition: Lot 11 Current Condition: Lot 11 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot of Baranko Homes was informed at the Individual Lot Active - JC Custom Build beg recommended at this time. Evaluation in the Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homeomer Individual Lot Good Condition - Timeless Homeomer Individual Lot	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot of the lot prior to the lot of lot o	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/2022 the inspection on 6/21/22. 4/27/2022 the inspection on 6/21/22 inspection to the 5/3/22 inspection. The first of the 5/18/2022 of prior to the 5/18/2021 inspection.	Active The front and rear or rved in the ROW, in the prior to the interpretation. Active Due to vegetation active. Active Cition. Dirt piles were The homeowner inserting. Active ection. Dirt piles were the homeowner inserting.	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No eo observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on
Lot 10 Current Condition: Lot 11 Current Condition: Lot 11 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot of Baranko Homes was informed at the Individual Lot Active - JC Custom Build beg recommended at this time. Evaluation in the Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homeomer Individual Lot Good Condition - Timeless Homeomer Individual Lot	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot of the lot prior to the lot of lot o	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/2022 the inspection on 6/21/22. 4/27/2022 the inspection on 6/21/22 inspection to the 5/3/22 inspection. The first of the 5/18/2022 of prior to the 5/18/2021 inspection.	Active The front and rear or rved in the ROW, in the prior to the interpretation. Active Due to vegetation active color. Dirt piles were the homeowner insumed the prior to the interpretation. Dirt piles were color.	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on
Lot 10 Current Condition: Lot 11 Current Condition: Lot 11 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Exication in the homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes Ho	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot of the lot prior to the lot of lot o	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/2022 the inspection on 6/21/22. 4/27/2022 the inspection on 6/21/22 inspection to the 5/3/22 inspection. The first of the 5/18/2022 of prior to the 5/18/2021 inspection.	Active The front and rear or rved in the ROW, in the prior to the interpretation. Active Due to vegetation active color. Dirt piles were the homeowner insumed the prior to the interpretation. Dirt piles were color.	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No eo observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition:	Individual Lot Active - Baranko Homes beging BMPs are recommended at the actively excavating during the The street in front of the lot shadow the shadow the street in front of the lot shadow the	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara nould be cleaned. d to complete by 12/30/22. Note that the lot prior to the lo	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22 at prior to the 4/27/22 inspection on 6/21/22 inspection to the 5/3/22 inspection. The first of the 5/18/22 inspection on 8/16/22. Timestation on 8/16/22. Timestation on 8/16/22.	Active The front and rear or yed in the ROW, In the prior to the in the ROW, In the prior to the in the prior to the in the ROW, In the prior to the in the prior to the in the ROW, In th	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No eo observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 19 Current Condition: Lot 26	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot street in front Build beg recommended at this time. Experience in front from the front of the inspection on 6 and front in front i	Lot 8 an excavating the lot prior to his time. E&A inspector will no inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. No lan excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to 10 dependent of the lot of lot of the lot of lot	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 or to the 5/3/22 inspection. The first of the 5/3/22 inspection. The first on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection.	Active The front and rear or yed in the ROW, In the prior to the in the ROW, In the prior to the in the prior to the in the ROW, In the prior to the in the prior to the in the ROW, In th	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No ee observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximination of the lot prior to the inspection on 6 Individual Lot Good Condition - The homeound the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes ren to the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes	Lot 8 an excavating the lot prior to his time. E&A inspector will no inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. No land excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to 12/20/22. Lot 1 where began excavating the lot dirt piles from the ROW prior 12/20/22. Lot 17 comes began excavating the lot prior to the 12/20/22. Lot 19 sodded the lot prior to the 5/2 based details and the lot prior to the incomplete in the lot 26/20/20.	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. Interpretation on 6/21/22. 4/27/2022 the inspection on 6/21/22 inspection. The 5/3/22 inspection. The 5/18/2022 of prior to the 5/18/22 inspection on 8/16/22. Time 18/22 inspection. 18/22 inspection.	Active The front and rear or rved in the ROW, in the prior to the interpretation. Active Due to vegetation and Active Compared to the prior to the interpretation. Dirt piles were the homeowner insurance action. Dirt piles were less Homes section. Removed Removed	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 26 Current Condition: Lot 25	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximple the lot prior to the inspection on 60 Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 60 Individual Lot Good Condition - Timeless Homes removed the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot	Lot 8 an excavating the lot prior to his time. E&A inspector will no inspection on 10/6/22. Bara mould be cleaned. d to complete by 12/30/22. No least the lot prior to least the lot prior lot least the lot prior lot least le	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. 4/27/2022 the inspection on 6/21/22 inspection to the 5/3/22 inspection. The first of the 5/3/22 inspection on 8/16/22. Time inspection on 8/16/22. Time inspection. 18/22 inspection. 18/22 inspection. 5/18/2022 11/16/2022	Active The front and rear or yed in the ROW, in the prior to the interpretation. Active Due to vegetation and Active Lition. Dirt piles were holders Homeowner insured the home	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot of Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Existing the street in front of the lot of the inspection on 6 Individual Lot Good Condition - Timeless Homes rent of the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde	Lot 8 an excavating the lot prior to his time. E&A inspector will no inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. No least the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior to the lot prior began excavating the lot prior began excav	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. 10 done as of the last inspection on 6/21/22. 10 done as of the last inspection on 6/21/22. 11/18/2022 12 of prior to the 4/27/22 inspection on 6/21/22. Times inspection on 8/16/22. Times inspection on 8/16/22. Times inspection on 6/21/22. 11/16/2022	Active The front and rear or yed in the ROW, In the prior to the information of the infor	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/stalled silt fence along the rear of No sere observed in the ROW on ured a portable toilet on the lot pri
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 26 Current Condition: Lot 25	Individual Lot Active - Baranko Homes beging BMPs are recommended at the actively excavating during the The street in front of the lot street in front of th	Lot 8 an excavating the lot prior to his time. E&A inspector will no inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. No land excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (1/29/22). Lot 17 omes began excavating the lot noved the dirt pile prior to the lot 26 sodded the lot prior to the 5/ Lot 26 sodded the lot prior to the inspector will move the inspector of the lot prior to the inspector of the lot prior to the inspector of the lot prior to the lot prior to the inspector of the lot prior to	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection. The spection on 8/16/22. Time 18/22 inspection. The spection on 6/21/22. Time 18/22 inspection.	Active The front and rear or rved in the ROW, Int pile prior to the pile prior t	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/2 stalled silt fence along the rear of No re observed in the ROW on ured a portable toilet on the lot prince as observed in the ROW; however the ROW prior to the inspection
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 26 Current Condition: Lot 25	Individual Lot Active - Baranko Homes beging BMPs are recommended at the actively excavating during the The street in front of the lot street in front of th	Lot 8 an excavating the lot prior to his time. E&A inspector will no inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. No land excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (1/29/22). Lot 17 omes began excavating the lot noved the dirt pile prior to the lot 26 sodded the lot prior to the 5/ Lot 26 sodded the lot prior to the inspector will move the inspector of the lot prior to the inspector of the lot prior to the inspector of the lot prior to the lot prior to the inspector of the lot prior to	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection. The spection on 8/16/22. Time 18/22 inspection. The spection on 6/21/22. Time 18/22 inspection.	Active The front and rear or rved in the ROW, Int pile prior to the pile prior t	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/2 stalled silt fence along the rear of No re observed in the ROW on ured a portable toilet on the lot prince as observed in the ROW; however the ROW prior to the inspection
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 26 Current Condition: Lot 25	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Extended the lot prior to the inspection on 60 Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 60 Individual Lot Good Condition - Timeless Homes removed - Timeless Homes removed - Belt Construction Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builded the builder was actively excav 12/01/22. Due to the grade of as necessary.	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot prior to the l	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection. The spection on 8/16/22. Time 18/22 inspection. The spection on 6/21/22. Time 18/22 inspection.	Active The front and rear or rved in the ROW, Int pile prior to the pile prior t	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/2 stalled silt fence along the rear of No re observed in the ROW on ured a portable toilet on the lot prince as observed in the ROW; however the ROW prior to the inspection
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 26 Current Condition: Lot 25	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximination of the lot precommended at this time. Eximination of the lot prior to the inspection on 6 Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes rent to the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excav 12/01/22. Due to the grade of	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot prior to the l	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection. The spection on 8/16/22. Time 18/22 inspection. The spection on 6/21/22. Time 18/22 inspection.	Active The front and rear or rved in the ROW, Int pile prior to the pile prior t	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/2 stalled silt fence along the rear of No re observed in the ROW on ured a portable toilet on the lot prince as observed in the ROW; however the ROW prior to the inspection
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 26 Current Condition: Lot 25	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximination of the lot provided in the lot prior to the inspection on 6 Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes rent to the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excav 12/01/22. Due to the grade of as necessary. The streets along the lot should	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot prior to 8A inspector will monitor. Lot 10 an excavating the lot prior to 8A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (1/29/22). Lot 17 omes began excavating the lot prior to the lot prior to the sodded the lot prior to the 5/2 began excavating the lot prior to the sodded the lot prior to the included by the lot prior to the included by the lot prior to the lot prior by the lot prior to the lot prior by the lot prior	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection to the 5/3/22 inspection. The first of the first on 8/16/22. The inspection on 8/16/22. The inspection on 8/16/22. The inspection on 8/16/22. The inspection on 6/21/22. The inspection on 11/16/2022 inspection. The builder removemended at this time. Each	Active The front and rear or rved in the ROW, in the R	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No ee observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot prince as observed in the ROW, however the ROW prior to the inspection nitor and make recommendations
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot prior to the inspection on 6 and in front of the inspection on 6 and front of the lot street in front of	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. d to complete by 12/30/22. Note that the lot prior to the second will monitor. Lot 10 an excavating the lot prior to the second will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior to the second will monitor. Lot 17 comes began excavating the lot prior to the line will be completed by 12/29/22. Lot 17 comes began excavating the lot prior to the second will be completed by 12/29/22. Lot 19 sodded the lot prior to the included by 13/29/22 began excavating the lot prior to the included by 14/16/22 instance of the lot BMPs will not be recorded by 14/16/22 instance of the lot BMPs will not be recorded by 14/16/22 instance of the lot builder as soon a second will be cleaned. Int to the lot builder as soon a	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. In the inspection on 6/21/22. 4/27/2022 the inspection on 6/21/22 inspection. The 5/3/22 inspection. The 5/18/202 of prior to the 5/3/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. 11/16/2022 in to the inspection on 11/1/2022 in the inspection on 11/1/2/2022 in the inspection on 3/2/2/2 in	Active The front and rear or rved in the ROW, Interpreted in the Rowell Active Active Active Active Active Cition. Dirt piles we release Homes sect Removed Removed Removed Active 16/22. A dirt pile we red the dirt pile from A inspector will more A inspector will more Active response to the result of the result	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will No re observed in the ROW on 4/27/stalled silt fence along the rear of No re observed in the ROW on ured a portable toilet on the lot price. Yes as observed in the ROW; however in the ROW prior to the inspection nitor and make recommendations.
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximination of the lot precommended at this time. Eximination of the lot prior to the inspection on 6 Individual Lot Good Condition - The homeous the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes ren to the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excav 12/01/22. Due to the grade of as necessary. The streets along the lot should recommendations will be ser Individual Lot	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara hould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (29/22). Lot 17 comes began excavating the lot prior to the file prior to	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. In the inspection on 6/21/22. The inspection on 6/21/22 of prior to the 4/27/22 inspection. The 5/3/22 inspection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. 11/16/2022 ior to the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection. The builder removement of the inspection on 11/1/29 inspection.	Active The front and rear or rved in the ROW, in the prior to the information of the info	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will no e observed in the ROW on 4/27/2 stalled silt fence along the rear of no lot no l
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot of the Individual Lot Active - JC Custom Build beg recommended at this time. Earlie Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes removed - Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excavation 12/01/22. Due to the grade of as necessary. The streets along the lot should Recommendations will be serviced in Individual Lot Active - Timeless Homes beg	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara mould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot prior to dirt piles from the ROW prior 1/29/22. Lot 17 comes began excavating the lot prior to the dirt pile prior to the 5/29/22. Lot 19 sodded the lot prior to the 5/20/25 and 25/25 and 25/25 arbitrary to the inspector will monitor. Lot 26 sodded the lot prior to the inspector will be lot prior to the inspector will be lot prior to the lot began excavating the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot prior to the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot prior to the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot pr	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection to the 4/27/22 inspection or to the 5/3/22 inspection. The spection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. The spection on 6/21/22. The spection on 6/21/22. The spection on 11/2 inspection. The builder removemended at this time. East of the single sidentified. Not done as of 5/18/2022 of the 5/18/202 inspection. Direction. Directio	Active The front and rear arred in the ROW, in the prior to the interpretation. Active Due to vegetation and the prior to the interpretation. Dirt piles were cition. Active the last inspector will more the last inspector. Active tiples were observed in the front piles were cition. Active tiples were observed in the prior to the prio	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri Yes as observed in the ROW; however the ROW prior to the inspection nitor and make recommendations are the ROW on 8/3/22. Due to the ROW on 8/3/22.
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot of the Individual Lot Active - JC Custom Build beg recommended at this time. Earlie Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes removed - Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excavation 12/01/22. Due to the grade of as necessary. The streets along the lot should Recommendations will be serviced in Individual Lot Active - Timeless Homes beg	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara mould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot prior to dirt piles from the ROW prior 1/29/22. Lot 17 comes began excavating the lot prior to the dirt pile prior to the 5/29/22. Lot 19 sodded the lot prior to the 5/20/25 and 25/25 and 25/25 arbitrary to the inspector will monitor. Lot 26 sodded the lot prior to the inspector will be lot prior to the inspector will be lot prior to the lot began excavating the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot prior to the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot prior to the lot prior to the lot builder as soon at Lot 27 pan excavating the lot prior to the lot pr	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection to the 4/27/22 inspection or to the 5/3/22 inspection. The spection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. The spection on 6/21/22. The spection on 6/21/22. The spection on 11/2 inspection. The builder removemended at this time. East of the single sidentified. Not done as of 5/18/2022 of the 5/18/202 inspection. Direction. Directio	Active The front and rear arred in the ROW, in the prior to the interpretation. Active Due to vegetation and the prior to the interpretation. Dirt piles were cition. Active the last inspector will more the last inspector. Active tiples were observed in the front piles were cition. Active tiples were observed in the prior to the prio	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri Yes as observed in the ROW; however the ROW prior to the inspection nitor and make recommendations are the ROW on 8/3/22. Due to the ROW on 8/3/22.
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot street in front of the inspection on 6 and in front of the inspection on 6 and front of the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excavance in front of the street i	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara mould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (1/29/22). Lot 17 omes began excavating the lot prior to the dirt pile prior to the lot 26 sodded the lot prior to the inspector will monitor. Lot 29 sodded the lot prior to the inspector will prior to the inspector will be prior to the inspector will be a sound to the lot BMPs will not be recorded to the lot builder as soon at Lot 27 Jan excavating the lot prior to tall is not recommended at this	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection to the 4/27/22 inspection or to the 5/3/22 inspection. The spection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. The spection on 6/21/22. The spection on 6/21/22. The spection on 11/2 inspection. The builder removemended at this time. East of the single sidentified. Not done as of 5/18/2022 of the 5/18/202 inspection. Direction. Directio	Active The front and rear or red in the ROW, Introduced in the Introduced in	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri Yes as observed in the ROW; however the ROW prior to the inspection nitor and make recommendations are the ROW on 8/3/22. Due to the ROW on 8/3/22.
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at the actively excavating during the The street in front of the lot of the Individual Lot Active - JC Custom Build beg recommended at this time. Earlie Individual Lot Good Condition - The homeon The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes removed - Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excavation 12/01/22. Due to the grade of as necessary. The streets along the lot should Recommendations will be serviced in Individual Lot Active - Timeless Homes beg	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara mould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (29/22). Lot 17 comes began excavating the lot prior to the fire prior prior prior to the fire prior prior prior prior prior prior to the fire prior pr	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection of the 5/3/22 inspection. The 5/3/22 inspection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. Time 18/22 inspection on 11/1/2022 inspection. The builder removement of the inspection on 11/1/2022 inspection. The builder removement of 5/18/2022 inspection. Direction in 18/22 inspection.	Active The front and rear arred in the ROW, in the prior to the interpretation. Active Due to vegetation and the prior to the interpretation. Dirt piles were cition. Active the last inspector will more the last inspector. Active tiples were observed in the front piles were cition. Active tiples were observed in the prior to the prio	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri Yes as observed in the ROW; however the ROW prior to the inspection nitor and make recommendations are the ROW on 8/3/22. Due to the ROW on 8/3/22.
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot st Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximited in the lot of green and the lot prior to the inspection on 6 Individual Lot Good Condition - The homeous the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes rent to the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excav 12/01/22. Due to the grade of as necessary. The streets along the lot shound individual Lot Active - Timeless Homes begantive sewer hook-up, removed Individual Lot	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara mould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot dirt piles from the ROW prior (29/22). Lot 17 comes began excavating the lot prior to the fire prior prior prior to the fire prior prior prior prior prior prior to the fire prior pr	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection of the 5/3/22 inspection. The 5/3/22 inspection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. Time 18/22 inspection on 11/1/2022 inspection. The builder removement of the inspection on 11/1/2022 inspection. The builder removement of 5/18/2022 inspection. Direction in 18/22 inspection.	Active The front and rear or red in the ROW, Introduced in the Introduced in	of the lot are mostly flat, so no however Baranko Homes was aspection on 10/27/22. No surrounding the lot, no BMPs will No e observed in the ROW on 4/27/2 stalled silt fence along the rear of No ere observed in the ROW on ured a portable toilet on the lot pri Yes as observed in the ROW; however in the ROW prior to the inspection nitor and make recommendations over the ROW on 8/3/22. Due to the ROW on 8/3/22. Due to the ROW on 8/3/22. Due to the the ROW on 8/3/22.
Lot 10 Current Condition: Lot 11 Current Condition: Lot 17 Current Condition: Lot 19 Current Condition: Lot 26 Current Condition: Lot 25 Current Condition: Lot 27 Current Condition:	Individual Lot Active - Baranko Homes begs BMPs are recommended at it actively excavating during the The street in front of the lot si Baranko Homes was informed Individual Lot Active - JC Custom Build beg recommended at this time. Eximited in the lot provided in the lot prior to the inspection on 6 Individual Lot Good Condition - The homeous The homeowner removed the lot prior to the inspection on 6 Individual Lot Good Condition - Timeless Homes rent to the inspection on 8/24/22. Individual Lot Removed - Belt Construction Individual Lot Removed - Timeless Homes Individual Lot Active - An unidentified builde the builder was actively excav 12/01/22. Due to the grade of as necessary. The streets along the lot should be serviced in the lot service in the lot servic	Lot 8 an excavating the lot prior to his time. E&A inspector will not inspection on 10/6/22. Bara anould be cleaned. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 10 an excavating the lot prior to &A inspector will monitor. Lot 1 where began excavating the lot prior to dritr piles from the ROW prior 1/29/22. Lot 17 comes began excavating the lot prior to the first pile prior to the 1/29/22. Lot 19 sodded the lot prior to the 5/ Lot 26 sodded the lot prior to the inspector will prior to the inspector will prior to the 1/16/22 inspector w	9/27/2022 the inspection on 9/27/22. The inspection on 9/27/22. The inspection on 9/27/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22. The inspection on 6/21/22 inspection to the 4/27/22 inspection on the 5/3/22 inspection. The state of the first of the 5/3/22 inspection on 8/16/22. Time 18/22 inspection on 8/16/22. Time 18/22 inspection on 6/21/22. The state of the inspection on 11/2 inspection. The builder removemented at this time. Each of the first of the first of the first of the first of the inspection. Direction. The builder removemented at this time. Each of the first of the fi	Active The front and rear or yed in the ROW, in the RO	of the lot are mostly flat, so no however Baranko Homes was inspection on 10/27/22. No surrounding the lot, no BMPs will lot be observed in the ROW on 4/27/2 stalled silt fence along the rear of the lot price observed in the ROW on ured a portable toilet on the lot price as observed in the ROW, however the ROW prior to the inspection nitor and make recommendations

Comment Constitions	Damayad The hamasumar /	Ma Davishandar\ aaddad th	a lat and alasmad the atract	prior to the inequest	ion on 0/12/22
Current Condition:	Removed - The homeowner (, , , , , , , , , , , , , , , , , , , ,			
Lot 44 Current Condition:	Individual Lot	Lot 44	4/1/2022	Pending	Yes ved in the ROW on 4/1/22. KRT
Current Condition:	Construction removed the dirt				
	inspection on 11/16/22.	plies prior to the 4/14/22 life	spection. RRT Construction	cleaned the street i	if from or the lot prior to the
	inspection on 11/10/22.				
	Silt fence or straw wattles sho	ould be installed along the fro	ont of the lot.		
		3			
	KRT Construction was inform	ed to complete by 11/16/22.	Not done as of the last insp	ection.	
Lot 45	Individual Lot	Lot 45	7/14/2022	Pending	Yes
Current Condition:					rved in the ROW on 7/14/22. Belt
Surront Sommeron.	Construction removed the dirt			p 11 0.10 0.200.	100 111 1110 110 11
	1.) Silt fence or straw wattles	should be installed along the	front of the lot.		
	2.) The street in front of the lo	ot should be cleaned.			
	,	rmed to complete by 8/31/22	2. Not done as of the last ins	spection. Belt Const	ruction was reminded on 11/09/22,
	12/30/22	rmed to complete by 9/25/25	Not done so of the last inc	naction Balt Const	rustion was reminded on 11/00/22
	12/30/22	inled to complete by 6/25/22	. Not done as of the last ins	spection. Beit Const	ruction was reminded on 11/09/22,
Lot 47		1 -4 47	4/7/0000	A -45	NI-
Current Condition:	Individual Lot	Lot 47	4/7/2022	Active	No bserved in the ROW on 4/7/22.
Current Condition:					rear of the lot is vegetated, so no
	BMPs are recommended at the				
		g,			
Lot 58	Individual Lot	Lot 58	8/3/2022	Active	No
Current Condition:					e along the northeast and southeast
Carrent Condition.	corners of the lot prior to the 8		Sommador Gorvice		and more discounted southeast
Lot 70	Individual Lot	Lot 70	8/3/2022	Active	No
Current Condition:					e along the southeast corner of the
ourient condition.	lot prior to the 8/3/22 inspection		aa.iio Contidutoi Col Vice		a.c.,g are countries contor of the
Lot 90	Individual Lot	Lot 90	8/3/2022	Active	No
Current Condition:					e along the northeast corner of the
Current Condition.	lot prior to the 8/3/22 inspection		at I lains Contractor Service	s ilistalled slit lefte	s along the northeast comer of the
Lot 112	Individual Lot	Lot 112	4/29/2021	Activo	Vac
Current Condition:	Fair Condition - See lot 111 for			Active	Yes
Current Condition.					installed silt fence on the northeast
	corner of the lot prior to the 7/				
	· ·	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 1		
	The silt fence should be repai	red or removed.			
	Legacy Homes was informed	to complete by 12/15/22. No	ot done as of the last inspec	tion.	
Lot 114	Individual Lot	Lot 114	7/27/2022	Active	No
Current Condition:		active for construction. Lega	cy Homes installed silt fenc	e along the south s	ide and rear of the lot prior to the
1 1445	7/27/22 inspection.	1 1445	7/07/0000	A (:	
Lot 115 Current Condition:	Individual Lot Good Condition - This lot is in	Lot 115	7/27/2022	Active	No
Current Condition:	inspection.	lactive for construction, Lega	cy nomes installed silt lend	e along the real of	the lot prior to the 7/27/22
Lot 116	Individual Lot	Lot 116	7/27/2022	Active	No
Current Condition:	Good Condition - This lot is in				
Current Condition.	inspection.	active for construction, Lega	cy Homes installed silt ferio	c along the real of	the lot phot to the 1/21/22
1 1 100		1 1 100	0/0/0000	A (:	
Lot 120	Individual Lot	Lot 120	8/3/2022	Active	No No
Current Condition:	lot prior to the 8/3/22 inspection		at Fiailis Contractor Service	s ilistailed siit tence	e along the southeast corner of the
1 1 100	<u> </u>		0/0/0000		
Lot 126	Individual Lot	Lot 126	8/3/2022	Active	No
Current Condition:	Good Condition - This lot is in lot prior to the 8/3/22 inspection		at Flains Contractor Service	s installed silt tence	e along the northeast corner of the
	<u> </u>		T		
Lot 131	Individual Lot	Lot 131	, = 10=10¢	Removed	
Current Condition:	Removed - Legacy Homes so		I	l	
Lot 132	Individual Lot	Lot 132	10/28/2021	Active	Yes
Current Condition:		ctive for construction. Legac	y Homes disturbed the lot d	uring home-building	activities on adjacent lots prior to
	the 10/28/21 inspection.				
	Silt fence should be extended	or wattles should be installe	d across the front of the lot	and repaired where	damaged
	Circ remes emeals 20 ementes	or manage endang pe mename		and ropanion miloro	aumagou.
	Legacy Homes was informed	to complete by 11/4/21. Not	done as of last inspection.	Legacy Homes was	reminded on 12/2/21, 12/23/21,
	1/27/22, 3/3/22, 4/7/22, 5/20/2	22, 7/15/22, 9/09/22, 12/08/2	2		
Lot 133	Individual Lot	Lot 133		Removed	
Current Condition:	Removed - Legacy Homes so	odded the lot prior to the insp	ection on 7/27/22.		
Lot 134	Individual Lot	Lot 134		Removed	
Current Condition:	Removed - Legacy Homes so	odded the lot prior to the insp	ection on 7/27/22.		
Lot 135	Individual Lot	Lot 135	10/28/2021	Active	No
Current Condition:					ng activities on adjacent lots prior to
	the 10/28/21 inspection. Lega	cy Homes installed silt fence	along the front corner of the	e lot prior to the 8/3	3/22 inspection.
Lot 136	Individual Lot	Lot 136	6/22/2021	Active	No
Current Condition:			prior to the inspection on 6	/22/21. Legacy Hon	nes installed silt fence along the
	front corner of the lot prior to	the 8/3/22 inspection.			
Lot 137	Individual Lot	Lot 137	6/30/2021	Active	No

Current Condition:			t prior to the inspection on	6/30/21. Legacy Hor	mes installed silt fence along the
Lot 139	front corner of the lot prior to Individual Lot	Lot 139	7/7/2021	Active	Yes
Current Condition:	Fair Condition - This lot is ina	ctive for construction. Great	Plains Contractor Services	installed silt fence a	along the northeast corner of the lot
	prior to the 8/3/22 inspection.	The silt fence was partially of	damaged during the inspec	tion on 11/16/22.	
	Repair or remove silt fence.				
	Crayon Dayalanment was int	formed to complete by 19/15	/22 Not done as of the lost	inenection Crayes	Davidenment was reminded on
	1/20/23	offiled to complete by 12/15/	122. Not dolle as of the last	inspection. Graves	Development was reminded on
Lot 140	Individual Lot	Lot 140	8/3/2022	Active	Yes
Current Condition:	Fair Condition - This lot is in lot prior to the 8/3/22 inspect		Plains Contractor Services	s installed silt fence	along the southeast corner of the
	lot phor to the 0/0/22 mapeet	On.			
	Repair or remove silt fence.				
	Graves Development was inf	ormed to complete by 12/15/	/22. Not done as of the last	inspection. Graves	Development was reminded on
	1/20/23				
Lot 147 Current Condition:	Individual Lot	Lot 147	8/3/2022	Active	No e along the northwest corner of the
Current Condition:	lot prior to the 8/3/22 inspect		at Fiairis Contractor Servic	es iristalled slit lerici	e along the northwest corner of the
Lot 153	Individual Lot	Lot 153	8/3/2022	Active	No
Current Condition:			at Plains Contractor Servic	es installed silt fence	e along the northwest corner of the
1. (454	lot prior to the 8/3/22 inspect		0/00/0004	1	
Lot 154 Current Condition:	Individual Lot	Lot 154	6/22/2021	Active 6/22/21 Legacy Hor	No Mes installed silt fence along the
Current Contaition:	front corners of the lot prior to		t phot to the hispection on	o, zz, z i. Legacy Hui	moo motalica ont leffee along the
Lot 159	Individual Lot	Lot 159	7/21/2021	Active	No
Current Condition:	Good Condition - Legacy Hor	nes began excavating the lo			mes installed silt fence along the
1.10.5.111	front corners of the lot prior to		1 0/0/0000	1	
Lot 3, Replat 1 Current Condition:	Individual Lot	Lot 3, Replat 1	8/3/2022	Active 3/22 The front and re	ear of the lot are mostly flat, so no
Current Condition.					uilder removed the dirt piles from
	the ROW prior to the inspect	1			
Lot 5, Replat 1	Individual Lot	Lot 5, Replat 1		Removed	
Current Condition: Lot 6, Replat 1	Removed - THI Builders sod	Lot 6, Replat 1	12/22/2021	Active	No
Current Condition:					Builders placed a portable toilet
	prior to 3/7/22 inspection, but	did not acknowledge owners alled silt fence along the north	ship until 3/14/22. THI Build n side of the lot prior to the	lers secured the por inspection on 9/19/2	rtable toilet prior to the 4/14/22 22. THI Builders sodded the lot prior
Lot 7, Replat 1	Individual Lot	Lot 7, Replat 1	12/22/2021	Active	No
Current Condition:					Builders installed silt fence along the
	north side of the lot prior to the in place during the inspection	ne inspection on 9/19/22. THI on 10/06/22.	Builders sodded the lot pri	ior to the inspection	on 10/06/22. The silt fence was still
Lot 8, Replat 1	Individual Lot	Lot 8, Replat 1	12/29/2021	Active	No Builders installed silt fence clong the
Current Condition:	north side of the lot prior to the	ne inspection on 9/19/22.		_	Builders installed silt fence along the
Lot 9, Replat 1 Current Condition:	Individual Lot	Lot 9, Replat 1	12/29/2021	Active	No Sting inlet on Horizon Street prior to
current condition.	the inspection on 12/29/21. E	ridgewater Homes installed i ensibility for the inlet protectio	inlet protection over an exis in on Horizon Street is assi	sting inlet on Horizon gned to THI Builders	n Street prior to the inspection on s as of 3/7/22, but removal will be
Lot 10, Replat 1	Individual Lot	Lot 10, Replat 1	12/29/2021	Active	No
Current Condition:					Builders installed wattles on the east of the lot prior to the inspection on
Lot 11, Replat 1	Individual Lot	Lot 11, Replat 1		Removed	
Current Condition:	Removed - Bridgewater Hom		e 5/18/22 inspection.		
Lot 12, Replat 1	Individual Lot	Lot 12, Replat 1	F/49/00 i	Removed	
Current Condition: Lot 13, Replat 1	Removed - Bridgewater Hom Individual Lot	Lot 13, Replat 1	5/18/22 inspection. 7/8/2022	Active	No
Current Condition:					Ided part of the lot and installed
	wattles in the rear of the lot p				<u> </u>
Lot 14, Replat 1	Individual Lot	Lot 14, Replat 1	7/18/2022	Active	No
Current Condition:	Good Condition - This lot is in inspection.	nactive for construction. Brido	gewater Homes installed w	attles in the rear of t	the lot prior to the 7/18/22
Lot 15, Replat 1	Individual Lot	Lot 15, Replat 1	7/18/2022	Active	No
Current Condition:	Good Condition - This lot is in inspection.	nactive for construction. Brido	gewater Homes installed w	attles in the rear of t	the lot prior to the 7/18/22
Lot 16, Replat 1	Individual Lot	Lot 16, Replat 1	7/0/00: "	Removed	
Current Condition:	Removed - Bridgewater Hom		e 7/8/22 inspection.	Domested	
Lot 17, Replat 1 Current Condition:	Individual Lot Removed - Bridgewater Hom	Lot 17, Replat 1	1 7/8/22 inspection.	Removed	
Lot 44, Replat 1	Individual Lot	Lot 4, Replat 1	8/3/2022	Active	No

Current Condition:	Good Condition - This lot is i prior to the 8/3/22 inspection.	nactive for construction. Grea	at Plains Contractor Service	es installed silt fenc	e along the east corner of the lot
PB 1	Portable Bathroom	Site		Removed	
Current Condition:	Removed - Kersten Construc		let prior to the 4/21/21 inspe		-
PB 2	Portable Bathroom	Site		Removed	
Current Condition:	Removed - Legacy Homes re		or to the 4/1/22 inspection	rtomovou	L
				1 A C	
PB X	Portable Bathroom	Site	2/2/2023	Active	No No
Current Condition:			tollet prior to the inspection	on 10/2//22. The s	torm sewer contractor secured a
	portable toilet on site prior to	· ·		1	
SB 1	Sediment Basin	B5	11/14/2019	Active	Yes
Current Condition:					As of the last inspection, the basin is
					11/22/19. The riser is not in place
					J closed the gaps between the
	riser and outlet pipe prior to t				
			ut the basin prior to the insp	ection on 8/17/21. I	Roth finished cleaning out the basin
	and installing the baffle prior	to the inspection on 9/8/21.			
	-	and the second			
	The basin isn't draining corre	city and a new riser with the t	correct diffierisions should b	e installed.	
	DE I Crading was informed to	s complete by 6/16/21. Not do	one as of last inspection. Di	E Lwas reminded of	n 7/9/21, 8/13/21, 8/26/21, 9/10/21,
					ctor on 2/23/22 that the new riser
		ed for delivery by 3/4/22. E&/			
			-		1
SB 2	Sediment Basin	V5	8/19/2019	Active	No
Current Condition:					in the process of excavating the
					stalled a riser in the basin prior to
					12/27/19 inspection. DEJ closed the
					outfall prior to the inspection on
					prior to the inspection on 5/19/21.
		installed dirt baffles and dew	atering holes prior to the in	spection on 6/9/21.	E&A inspector painted cleanout
	mark on 6/18/21.	T			
SB 3	Sediment Basin	AA17	11/15/2018	Active	No
Current Condition:					had begun as of inspection on
		, •	•		ne basin is complete as of the
	9/11/19 inspection. DEJ Grad				
					rip rap below the outfall prior to the
	inspection on 8/13/20. Roth b	egan cleanout prior to the ins	spection on 6/9/21. Roth ins	talled a dirt baffle p	prior to the inspection on 6/16/21.
SB 4	Sediment Basin	AA26	11/15/2018	Active	No
Current Condition:	Good Condition - 7% Filled -	Basin was being excavated d	luring inspection on 11/15/1	8. Basin excavatio	n was complete as of inspection on
	11/10/18 however no riser s				
	1 17 13/10, HOWEVEL, HO HISEL 3	tructure has been installed as	s of last inspection. The out	fall of the basin was	s partially installed as of the
	11/14/19 inspection. The outl	et pipe was installed prior to i	inspection on 11/27/19. DE	J installed a permar	nent riser in the basin and rip rap
	11/14/19 inspection. The outl below the basin outfall prior to	et pipe was installed prior to i the inspection on 8/13/20. T	inspection on 11/27/19. DE The outfall is connected to the	J installed a permar ne riser pipe as of t	nent riser in the basin and rip rap he inspection on 8/13/20, therefore
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer	et pipe was installed prior to i o the inspection on 8/13/20. T necessary. Roth Enterprises	nspection on 11/27/19. DE The outfall is connected to the began cleaning out the bas	J installed a perman ne riser pipe as of t sin prior to the 10/19	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle p	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspecti	J installed a perman ne riser pipe as of the in prior to the 10/19 on. Sediment at the	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pit to 10/28/21 inspection. Roth El	inspection on 11/27/19. DE, the outfall is connected to the began cleaning out the base rior to the 10/25/21 inspectinterprises completed the re	J installed a perman ne riser pipe as of the in prior to the 10/19 on. Sediment at the maining SWPPP ito	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pit to 10/28/21 inspection. Roth El	inspection on 11/27/19. DE, the outfall is connected to the began cleaning out the base rior to the 10/25/21 inspectinterprises completed the re	J installed a perman ne riser pipe as of the in prior to the 10/19 on. Sediment at the maining SWPPP ito	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by
SR 5	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector	et pipe was installed prior to i to the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth El or painted the cleanout mark of the control of the cleanout mark of the cle	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basior to the 10/25/21 inspectinterprises completed the reduring the 4/1/22 inspection	J installed a permaner riser pipe as of the inprior to the 10/19 on. Sediment at the maining SWPPP ite.	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21
SB 5	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspecto	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pi 10/28/21 inspection. Roth E or painted the cleanout mark of	Inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bar- ior to the 10/25/21 inspection therprises completed the re- during the 4/1/22 inspection	J installed a perman ne riser pipe as of t in prior to the 10/15 on. Sediment at the maining SWPPP ito	nent riser in the basin and rip rap the inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will be outfall was washed away by tems prior to the 11/16/21
SB 5 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspectors Sediment Basin Fair Condition - 10% Filled - I	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavation	Inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basirior to the 10/25/21 inspection therprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspection	J installed a permaner riser pipe as of the finding service of the	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will coutfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - It to inspection on 11/22/19. DE	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pi 10/28/21 inspection. Roth E or painted the cleanout mark of C28 DEJ Grading began excavation Installed a riser in the basin	Inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspense prior to the inspection on the basin prior to the basin	J installed a permai ne riser pipe as of t in prior to the 10/15 on. Sediment at the maining SWPPP it Active action on 11/14/19. 7/21/20, therefore a	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior is sit fence wrap around the outlet
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary.	et pipe was installed prior to i to the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavation J installed a riser in the basin Great Plains Contractor Servi	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basinor to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension prior to the inspection on the basin prior to the inspection on the prior to the inspection on the inspection on the prior to the pri	J installed a permaner iser pipe as of the 10/15 on. Sediment at the maining SWPPP ite. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the terminal of the section of the country of the country of the outfall prior to the section of the country of the	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the basin selection on 11/22/19. Depipe is no longer necessary.	et pipe was installed prior to i to the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavation EJ installed a riser in the basin Great Plains Contractor Services in and installed the baffle p	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basinor to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension prior to the inspection on the basin prior to the inspection on the prior to the inspection on the inspection on the prior to the pri	J installed a permaner iser pipe as of the 10/15 on. Sediment at the maining SWPPP ite. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the terminal of the section of the country of the country of the outfall prior to the section of the country of the	nent riser in the basin and rip rap he inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior is sit fence wrap around the outlet
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary.	et pipe was installed prior to i to the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavation EJ installed a riser in the basin Great Plains Contractor Services in and installed the baffle p	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basinor to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension prior to the inspection on the basin prior to the inspection on the prior to the inspection on the inspection on the prior to the pri	J installed a permaner iser pipe as of the 10/15 on. Sediment at the maining SWPPP ite. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the terminal of the section of the country of the country of the outfall prior to the section of the country of the	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth
	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - It to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth El or painted the cleanout mark of C28 DEJ Grading began excavation J installed a riser in the basis Great Plains Contractor Servi assin and installed the baffle pi inspection.	Inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension of the basin prior to inspension of the inspection on 10/25/2019 or to the inspection or 10/25/2019 or to th	J installed a permaner iser pipe as of the 10/15 on. Sediment at the maining SWPPP ite. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the terminal of the section of the country of the country of the outfall prior to the section of the country of the	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the basin selection on 11/22/19. Depipe is no longer necessary.	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth El or painted the cleanout mark of C28 DEJ Grading began excavation J installed a riser in the basis Great Plains Contractor Servivasin and installed the baffle pi inspection.	Inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension of the basin prior to inspension of the inspection on 10/25/2019 or to the inspection or 10/25/2019 or to th	J installed a permaner iser pipe as of the 10/15 on. Sediment at the maining SWPPP ite. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the terminal of the section of the country of the country of the outfall prior to the section of the country of the	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to	et pipe was installed prior to i to the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavatio J installed a riser in the basin Great Plains Contractor Services in and installed the baffle pi inspection.	Inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 In of the basin prior to inspension prior to the inspection on 10 inspect	J installed a permaner iser pipe as of the 10/15 on. Sediment at the maining SWPPP it. Active Ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 1/25/21. An unidentification of the section of the section of the section of the outfall prior to the section of t	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior is lit fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave.	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Enterprises erprises installed the baffle pit 10/28/21 inspection. Roth Elbar painted the cleanout mark of the cle	Inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basiner to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspection on the prior to the inspection on 10 or the inspection or 10 o	J installed a permaner riser pipe as of to in prior to the 10/15 on. Sediment at the maining SWPPP it. Active action on 11/14/19. 7/21/20, therefore a the outfall prior to the 1/25/21. An unidentification complete by 8/05	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminded.	et pipe was installed prior to i to the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle pi 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavation Great Plains Contractor Services asin and installed the baffle pi inspection. han 2.58 feet from the riser of the services, and Great Plains Contractor d on 8/20/20. DEJ, Peter Kat	Inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the began cleaning out the began cleaning out the price of the 10/25/21 inspection of the 10/25/21 inspection of the 4/1/22 inspection of the basin prior to inspection on the prior to the inspection on on the inspection on 10 or the inspection or 10 or the inspec	J installed a permane riser pipe as of to in prior to the 10/15 on. Sediment at the maining SWPPP it. Active action on 11/14/19. 7/21/20, therefore at the outfall prior to the 1/25/21. An unidential to complete by 8/05 Plains Contractor \$	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet pie inspection on 8/07/20. Roth field contractor began installing the
	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21.	et pipe was installed prior to i to the inspection on 8/13/20. T o the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle p i 10/28/21 inspection. Roth E or painted the cleanout mark of C28 DEJ Grading began excavation Great Plains Contractor Services and installed the baffle p inspection. han 2.58 feet from the riser of d on 8/20/20. DEJ, Peter Kat Roth Enterprises was reminded	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension prior to the inspection on the inspection on 10 inspect	J installed a permane riser pipe as of to in prior to the 10/15 on. Sediment at the maining SWPPP it. Active action on 11/14/19. 7/21/20, therefore at the outfall prior to the 1/25/21. An unidential to complete by 8/05 Plains Contractor \$	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. DE pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. E2/23/22. Graves Development	et pipe was installed prior to i to the inspection on 8/13/20. T o the inspection on 8/13/20. T necessary. Roth Enterprises erprises installed the baffle p i 10/28/21 inspection. Roth E or painted the cleanout mark of C28 DEJ Grading began excavation Great Plains Contractor Services in and installed the baffle p inspection. han 2.58 feet from the riser of d on 8/20/20. DEJ, Peter Kat Roth Enterprises was remindent twas reminded on 12/6/21, 8	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension prior to the inspection on the inspection on 10 inspect	J installed a permainer riser pipe as of the riser	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet pie inspection on 8/07/20. Roth field contractor began installing the
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminded 10/30/20, 01/15/21, 3/5/21. E2/23/22. Graves Developments	et pipe was installed prior to i to the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavatio J installed a riser in the basis Great Plains Contractor Services and installed the baffle pi inspection. han 2.58 feet from the riser of d on 8/20/20. DEJ, Peter Kat Roth Enterprises was reminde to was reminded on 12/6/21, s BB 20-BB14	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspension prior to the inspection on the inspection on 10 inspect	J installed a permaner riser pipe as of the riser pipe as the r	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sitt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the 5/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21,
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - It to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminded 10/30/20, 01/15/21, 3/5/21. F/2/23/22. Graves Development Silt Fence Removed - SF 1 *(SF 1.3) was reminded Removed - SF 1 *(SF 1.3) was removed - SF 1 *(SF 1	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pi to 10/28/21 inspection. Roth Ei or painted the cleanout mark of C28 DEJ Grading began excavation Great Plains Contractor Services in and installed the baffle pi inspection. The contractor Services and Great Plains Contractor Services in and installed the baffle pi inspection. The contractor Services and Great Plains Contract d on 8/20/20. DEJ, Peter Kat d on 8/20/20. DEJ, Peter Kat and Teterprises was reminde to twas reminded on 12/6/21, § BB 20-BB14 as installed by Double D Excavations and Services and Great Plains Contract by BB 20-BB14 as installed by Double D Excavations and Great Plains Contract by BB 20-BB14 as installed by Double D Excavations Descriptions Description	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 and of the basin prior to inspension prior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas installed rip rap below brior to the inspection on 10 ideas in 14/21, 15/14/21, 17/9/20/22, 12/08/22, 1/20/23 ideas in 14/21, 15/14/21, 17/9/20/22, 1/20/23 ideas idea in 14/21, 15/14/21, 17/9/20/22, 1/20/23 ideas idea in 14/21, 15/14/21, 17/9/20/22, 1/20/23 ideas idea idea idea idea idea idea idea idea	J installed a permaner iser pipe as of the service of the 10/15 on. Sediment at the maining SWPPP lite. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/15/21. An unidentification complete by 8/05/21, 8/10/21, 9/10/2 Removed 11/28/18. The silt.	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. fence east of the slope in the
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. If 2/23/22. Graves Development Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, if	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pit 10/28/21 inspection. Roth Eior painted the cleanout mark of the properties of the proper	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basing to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 and of the basing prior to the inspection on of the basing prior to the inspection on the inspection on 10 prior to 11/2/19/19/19/22, 12/08/22, 1/20/23 prior to 11/29/29/29, 12/08/22, 1/20/23 prior to inspection outling prior to inspection outling the basing prior to inspection outling the basing prior to the basing prior	J installed a permaner iser pipe as of to the 10/15 on. Sediment at the maining SWPPP it. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 25/21. An unidentification of the complete by 8/05 Plains Contractor \$21, 8/10/21, 9/10/2 Removed 11/28/18. The silt in and the multiple is	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will be outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior is silt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, if ence east of the slope in the full spots, was removed prior to the
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. Fe/2/3/22. Graves Developmer Silt Fence Removed - SF 1 * (SF 1.3) was southeast corner of the site, inspection on 4/22/20. As of the salt of the salt inspection on 4/22/20. As of the salt is silt for the site, inspection on 4/22/20. As of the salt is silt for the site, inspection on 4/22/20. As of the salt is silt for the salt inspection on 4/22/20. As of the salt is silt for the salt inspection on 4/22/20. As of the salt is salt for the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20.	et pipe was installed prior to i o the inspection on 8/13/20. To the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pie 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the proper	Inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspend prior to the inspection on its installed rip rap below for the inspection on 10 inspection inspection on 10 inspection in	J installed a permaner iser pipe as of the serior of the 10/15 on. Sediment at the maining SWPPP it. Active section on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification complete by 8/05 Plains Contractor \$21, 8/10/21, 9/10/2 Removed In 11/28/18. The silt in and the multiple iently established or	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet re inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, a fence east of the slope in the full spots, was removed prior to the in the slope located along the
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. Fe/2/3/22. Graves Developmer Silt Fence Removed - SF 1 * (SF 1.3) was southeast corner of the site, inspection on 4/22/20. As of the salt of the salt inspection on 4/22/20. As of the salt is silt for the site, inspection on 4/22/20. As of the salt is silt for the site, inspection on 4/22/20. As of the salt is silt for the salt inspection on 4/22/20. As of the salt is silt for the salt inspection on 4/22/20. As of the salt is salt for the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20.	et pipe was installed prior to i o the inspection on 8/13/20. To the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pie 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the proper	Inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspend prior to the inspection on its installed rip rap below for the inspection on 10 inspection inspection on 10 inspection in	J installed a permaner iser pipe as of the serior of the 10/15 on. Sediment at the maining SWPPP it. Active section on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification complete by 8/05 Plains Contractor \$21, 8/10/21, 9/10/2 Removed In 11/28/18. The silt in and the multiple iently established or	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior is the face wrap around the outlet is einspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, if ence east of the slope in the full spots, was removed prior to the
Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. Fe/2/3/22. Graves Developmer Silt Fence Removed - SF 1 * (SF 1.3) was southeast corner of the site, inspection on 4/22/20. As of the salt of the salt inspection on 4/22/20. As of the salt is silt for the site, inspection on 4/22/20. As of the salt is silt for the site, inspection on 4/22/20. As of the salt is silt for the salt inspection on 4/22/20. As of the salt is silt for the salt inspection on 4/22/20. As of the salt is salt for the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20. As of the salt inspection on 4/22/20.	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pie 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on 11/14/2019 on of the basin prior to inspension prior to the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas in 11 ideas in 1	J installed a permaner iser pipe as of the serior of the 10/15 on. Sediment at the maining SWPPP it. Active section on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification complete by 8/05 Plains Contractor \$21, 8/10/21, 9/10/2 Removed In 11/28/18. The silt in and the multiple iently established or	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet re inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, a fence east of the slope in the full spots, was removed prior to the in the slope located along the
Current Condition:	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. If 2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, it inspection on 4/22/20. As of the southeastern perimeter of the	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pie 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on 11/14/2019 on of the basin prior to inspension prior to the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas in 11 ideas in 1	J installed a permaner iser pipe as of the serior of the 10/15 on. Sediment at the maining SWPPP it. Active section on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification complete by 8/05 Plains Contractor \$21, 8/10/21, 9/10/2 Removed In 11/28/18. The silt in and the multiple iently established or	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet re inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, a fence east of the slope in the full spots, was removed prior to the in the slope located along the
Current Condition: SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminded 10/30/20, 01/15/21, 3/5/21. E2/23/22. Graves Development Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, i inspection on 4/22/20. As of the monitor. E&A inspector remo	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Enterprises erprises installed the baffle pit 10/28/21 inspection. Roth Eight painted the cleanout mark of the cleanout mar	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on 11/14/2019 on of the basin prior to inspense in prior to the inspection on 10/14/20 inspection o	J installed a permaner iser pipe as of the reserving prior to the 10/15 on. Sediment at the maining SWPPP it. Active Section on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/15/21. An unidentification complete by 8/05/21, 8/10/21, 9/10/2 Removed In 11/28/18. The silt in and the multiple tently established or noger necessary. The	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sitt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, or fence east of the slope in the full spots, was removed prior to the in the slope located along the e E&A inspector will continue to
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. If 2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, it inspection on 4/22/20. As of the southeastern perimeter of the monitor. E&A inspector remo	et pipe was installed prior to i o the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Element of the basic price of the contract o	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 11/14/2018 11/14/2018 11/14/2018 11/14/2018 11/14/2018 11/14/2018 11/14/2018	J installed a permaner iser pipe as of the riser pi	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sit fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, if ence east of the slope in the full spots, was removed prior to the a the slope located along the e E&A inspector will continue to
SF 1 Current Condition:	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. Fe/2/3/22. Graves Developmer Silt Fence Removed - SF 1 * (SF 1.3) was southeast corner of the site, inspection on 4/22/20. As of the southeast corner of the site, inspection on 5/20 in Silt Fence Fair Condition - A portion of Services installed the remain	et pipe was installed prior to in the inspection on 8/13/20. The inspection on 8/13/20. The inspection on 8/13/20. The inspection of the inspection. Roth Element of 10/28/21 installed a riser in the basing Great Plains Contractor Services and installed the baffler inspection. The inspection of 12/6/21, 8 and Great Plains Contractor do n 8/20/20. DEJ, Peter Kat Roth Enterprises was reminded to 12/6/21, 8 as installed by Double D Excanciluding the undermined portion on 7/29/20, veg exite that reinstallation of the ved SF 1 as of 4/29/21 due to BB 14 - Gold Coast Rd BB 14 - Gold Coast Rd BB 14 - Gold Coast Rd Great Plains Installed by Ger of the silt fence prior to in	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the bas rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection 11/14/2019 on of the basin prior to inspend prior to the inspection on the inspection on the inspection on the inspection on 10 or set in the inspection on 11/28/2018 or set in the inspection on 7/31/19. Great in the inspection on 7/31/19. Great	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active section on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/15/21. An unidentification of 11/28/18. The silt in and the multiple entity established or neer necessary. The Active to inspection on 11/Plains Contractor Section 11/28/18.	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet re inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, a fence east of the slope in the full spots, was removed prior to the real the slope located along the e E&A inspector will continue to Yes 1/28/18. Great Plains Contractor Services installed silt fence on either services were reminded on the contractor services installed silt fence on either services in servic
SF 1 Current Condition:	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. If 2/23/22. Graves Development Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, it inspection on 4/22/20. As of the southeast corner of the site, it inspection on 4/22/20. As of the southeast corner of the site, it inspection on 4/22/20. As of the southeastern perimeter of the monitor. E&A inspector remosit Fence Fair Condition - A portion of Services installed the remains side of Gold Coast Road priores.	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pie 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the bas rior to the 10/25/21 inspection to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on the basin prior to inspense prior to the basin prior to inspense prior to the inspection on the inspection on the inspection on 10 inspense prior to the inspection on 3/14/21, 5/14/21, 7/9/19/09/22, 12/08/22, 1/20/23 inspection on 10 inspection on 2 inspection on 2 inspection on 11/28/2018 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signature in 11/28/20 inspection in 11/28/20 inspection on 7/31/19. Great Plains Contractor Signat	J installed a permaner iser pipe as of the inprior to the 10/15 on. Sediment at the maining SWPPP it. Active Active action on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification of the complete by 8/05. Plains Contractors 21, 8/10/21, 9/10/2 Removed n 11/28/18. The silt in and the multiple the entity established or orgen necessary. The Active to inspection on 1. Plains Contractors 21, 12/20, 12/20, 13/20,	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silf fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, if ence east of the slope in the full spots, was removed prior to the he the slope located along the e E&A inspector will continue to Yes Yes 1/28/18. Great Plains Contractor
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. It 2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, in inspection on 4/22/20. As of the southeast corner of the site, in spection. E&A inspector remound in the silt of southeastern perimeter of the monitor. E&A inspector remound is graves and the remain side of Gold Coast Road prio 2 outfall. The full portion of silt of the side of Gold Coast Road prio 2 outfall. The full portion of silts.	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Eight painted the cleanout mark of the state of painted the cleanout mark of the state of the stat	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection of the basin prior to inspection of the basin prior to the inspection on the inspection on 10 inspection on 20 inspecti	J installed a permaner iser pipe as of the inprior to the 10/15 on. Sediment at the maining SWPPP it. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/15/21. An unidentification of 11/28/18. The sitting in and the multiple tently established or nger necessary. The Active to inspection on 11/28/18. The sitting and the multiple tently established or nger necessary. The Active to inspection on 11/28/18. The sitting and the multiple tently established or nger necessary. The Active to inspection on 11/28/18. The sitting and the multiple tently established or nger necessary. The Active to inspection on 11/28/18. The sitting and the multiple tently established or nger necessary. The Active to inspection on 11/28/18. The sitting and the multiple tently established or nger necessary. The Active to inspection on 11/28/18/18/18/18/18/18/18/18/18/18/18/18/18	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 8/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sitt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, if ence east of the slope in the full spots, was removed prior to the in the slope located along the e E&A inspector will continue to Yes 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence cast of the SB ow access for sewer work prior to
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. De pipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminded 10/30/20, 01/15/21, 3/5/21. F 2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, i inspection on 4/22/20. As of to southeastern perimeter of the monitor. E&A inspector remo Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prio 2 outfall. The full portion of sithe inspection on 9/24/20. Silt the inspection on 9/24/20.	et pipe was installed prior to it of the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Enterprises erprises installed the baffle pit 10/28/21 inspection. Roth Eight propriets and installed the cleanout mark of the propriets of the cleanout mark of the cleanout mark of the propriets of the cleanout mark of the propriets of the cleanout mark of the cleanout mark of the propriets of the cleanout mark of the cleanout m	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection of the basin prior to inspension of the basin prior to inspension of the basin prior to inspension of the basin prior to the inspection on the inspection on 10 incest installed rip rap below the prior to the inspection on 10 incest installed rip rap below the prior to the inspection on 10 incest installed rip rap below the prior to the inspection on 10 incest installed rip rap below the inspection on 10 incest installed rip rap below the inspection on 10 incest installed rip rap below the inspection on 10 incest installed rip rap below the inspection on 3/14/21, 5/14/21, 7/9/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/3/	J installed a permaner iser pipe as of the inprior to the 10/15 on. Sediment at the maining SWPPP little. Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 25/21. An unidentification of 11/28/18. The siltle in and the multiple tently established or inger necessary. The lattice of inspection on 11/28/18. The siltle in and the multiple tently established or inger necessary. The lattice of the inspection on 11/28/18. The siltle in and the multiple tently established or inger necessary. The lattice of the inspection on 11/28/18. The siltle in and the multiple tently established or inger necessary. The lattice of the inspection on 11/28/18. The siltle in and the multiple tently established or inger necessary. The lattice of the inspection on 11/28/18. The siltle in and the multiple tently established or inger necessary. The lattice of the inspection of 11/28/18/18/18/18/18/18/18/18/18/18/18/18/18	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sitt fence wrap around the outlet he inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, or fence east of the slope in the full spots, was removed prior to the in the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB ow access for sewer work prior to Drive to Gold Coast Road prior to
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to the lower	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on the basin prior to inspend prior to the inspection on the basin prior to the inspection on 10 or services were informed to the inspection on 10 or services were informed to the inspection on 3/14/21, 5/14/21, 7/9/20/22, 12/08/22, 1/20/23 or services were informed to the inspection on 10 or services were informed to the inspection on 1/1/28/2013 or services were informed to the inspection on 1/1/28/2013 or services were informed to the basing the inspection on 1/1/28/2018 or services were informed to the basing the inspection on 1/1/28/2018 or services were informed to the basing the inspection on 1/1/28/2018 or services were informed to the basing the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection on 1/1/28/2018 or services were informed to the inspection or 1/1/28/2018 or services were informed to the inspection or serv	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active section on 11/14/19, 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification of 11/28/18. The silt in and the multiple sently established or necessary. The Active to inspection on 11/28/18. The silt in and the multiple sently established or necessary. The Active to inspection on 11/28/18. The silt in and the multiple sently established or necessary. The Active to inspection on 11/28/18. The silt in and the multiple sently established or necessary. The Active to inspection on 11/28/18. The silt in and the multiple sently established or necessary. The Active to inspection on 11/28/18. The silt in and the multiple sently established or necessary. The Active the inspection on 11/28/18/18/18/18/18/18/18/18/18/18/18/18/18	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior is silt fence wrap around the outlet re inspection on 8/07/20. Roth fied contractor began installing the field contractor began installing the Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was removed prior to the full spots, was removed prior to the field spots access for sever work prior to Drive to Gold Coast Road prior to (C) outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. E/2/33/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, i inspection on 4/22/20. As of the southeast corner of the site, i inspection on Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prior 2 outfall. The full portion of silthe inspection on 9/24/20. Silthe inspection on 9/24/20. Silthe inspection on 9/24/20. Silthe inspection on Great Pla Commercial Seeding reinstalled commercial Seeding reinst	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Enterprises erprises installed the cleanout mark of the properties of the	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the bas rior to the 10/25/21 inspection to the 10/25/21 inspection the second prior to the 10/25/21 inspection the second prior to the second prior to the prior to the inspection on the second prior to the inspection on the second prior to the inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 10 inspection on 10 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 10 inspection on 10 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active Active	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20. In DEJ was reminded on 10/29/21, if ence east of the slope in the full spots, was removed prior to the note the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB was access for sewer work prior to Drive to Gold Coast Road prior to CO outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. E/2/3/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, i inspection on 4/22/20. As of the southeast corner of the site, i inspection on 4/22/20. As of the southeast corner of the site, inspection on 4/22/20. As of the southeastern perimeter of the monitor. E&A inspector remo Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prio 2 outfall. The full portion of silt the inspection on 9/24/20. Sil 1/12/21 inspection. Great Pla Commercial Seeding reinstal fence will be recommended to	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Enterprises erprises installed the cleanout mark of the properties of the	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the bas rior to the 10/25/21 inspection to the 10/25/21 inspection the second prior to the 10/25/21 inspection the second prior to the second prior to the prior to the inspection on the second prior to the inspection on the second prior to the inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 10 inspection on 10 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 10 inspection on 10 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active Active	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was removed prior to the note the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB was access for sewer work prior to Drive to Gold Coast Road prior to CO outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. E/2/33/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, i inspection on 4/22/20. As of the southeast corner of the site, i inspection on Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prior 2 outfall. The full portion of silthe inspection on 9/24/20. Silthe inspection on 9/24/20. Silthe inspection on 9/24/20. Silthe inspection on Great Pla Commercial Seeding reinstalled commercial Seeding reinst	et pipe was installed prior to i to the inspection on 8/13/20. To the inspection on 8/13/20. To the inspection. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Enterprises erprises installed the cleanout mark of the properties of the	nspection on 11/27/19. DE. The outfall is connected to the began cleaning out the bas rior to the 10/25/21 inspection to the 10/25/21 inspection the second prior to the 10/25/21 inspection the second prior to the second prior to the prior to the inspection on the second prior to the inspection on the second prior to the inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 10 inspection on 10 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 11/28/2018 inspection on 10 inspection on 10 inspection on 10 inspection on 10 inspection on 11/28/2018 inspection on 11/28/2	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active Active	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was removed prior to the note the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB was access for sewer work prior to Drive to Gold Coast Road prior to CO outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to the dewatering holes lower to the single prior to the 4/20/22. The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. Fe/2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, inspection on 4/22/20. As of the southeastern perimeter of the monitor. E&A inspector remoins Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prior 2 outfall. The full portion of silt he inspection on 9/24/20. Silt 1/12/21 inspection. Great Pla Commercial Seeding reinstal fence will be recommended to no 9/19/22.	et pipe was installed prior to in the inspection on 8/13/20. To the inspection. Roth Elip painted the cleanout mark of the properties of t	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on the basin prior to inspection on the basin prior to the inspection on 3/14/21, 5/14/21, 7/9/20/22, 12/08/22, 1/20/23 availing prior to inspection on the bast getation has become sufficing removed silf fence is no lor to established vegetation. 11/28/2018 In Double D Excavating prior is pection on 7/31/19. Great Desired and reinstalled new silt does the control of Gold Coast Road to SB 3 prior of an ancessary. Graves Desired and reinstalled new silt as necessary.	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active Active	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was removed prior to the note the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB was access for sewer work prior to Drive to Gold Coast Road prior to CO outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. E/2/3/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the site, i inspection on 4/22/20. As of the southeast corner of the site, i inspection on 4/22/20. As of the southeast corner of the site, inspection on 4/22/20. As of the southeastern perimeter of the monitor. E&A inspector remo Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prio 2 outfall. The full portion of silt the inspection on 9/24/20. Sil 1/12/21 inspection. Great Pla Commercial Seeding reinstal fence will be recommended to	et pipe was installed prior to in the inspection on 8/13/20. To the inspection. Roth Elip painted the cleanout mark of the properties of t	inspection on 11/27/19. DE, The outfall is connected to the began cleaning out the bastrior to the 10/25/21 inspection to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on the basin prior to inspection on the basin prior to the inspection on 3/14/21, 5/14/21, 7/9/20/22, 12/08/22, 1/20/23 availing prior to inspection on the bast getation has become sufficing removed silf fence is no lor to established vegetation. 11/28/2018 In Double D Excavating prior is pection on 7/31/19. Great Desired and reinstalled new silt does the control of Gold Coast Road to SB 3 prior of as an ecessary. Graves Desired and reinstalled new silt as necessary.	J installed a permaner iser pipe as of the property of the 10/15 on. Sediment at the maining SWPPP it. Active Active	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was removed prior to the note the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB was access for sewer work prior to Drive to Gold Coast Road prior to CO outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. If 2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) we southeast corner of the site, it inspection on 4/22/20. As of the southeast corner of the site, it inspection on 4/22/20. As of the southeast corner of the monitor. E&A inspector remose Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prior 2 outfall. The full portion of silt the inspection on 9/24/20. Silt 1/12/21 inspection. Great Place Commercial Seeding reinstal fence will be recommended to on 9/19/22. The silt fence should be trend	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the cleanout mark of the properties of	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on 11/14/2019 on of the basin prior to inspense prior to the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for spection of 3/14/21, 5/14/21, 7/9/9/09/22, 12/08/22, 1/20/23 ideas in 11/28/2018 in 11	J installed a permaner iser pipe as of the inprior to the 10/15 on. Sediment at the maining SWPPP it. Active Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification of the complete by 8/05 Plains Contractor State outfall prior to the complete by 8/05 Plains Contractor State outfall prior to the number of the complete by 8/05 Plains Contractor State of the complete by 8/05 Plains Plains Contractor State of th	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sit fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was reminded o
SF 1 Current Condition:	11/14/19 inspection. The outlibelow the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth entinatural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - Ito inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22 The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminded 10/30/20, 01/15/21, 3/5/21. E2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) was southeast corner of the sile, inspection on 4/22/20. As of the southeast corner of the sile, inspection on 4/22/20. As of the monitor. E&A inspector remosite Fair Condition - A portion of Services installed the remainside of Gold Coast Road prior 2 outfall. The full portion of silthe inspection on 9/24/20. Silf 1/12/21 inspection. Great Pla Commercial Seeding reinstal fence will be recommended to no 9/19/22. The silt fence should be trend.	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the cleanout mark of the properties of	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on 11/14/2019 on of the basin prior to inspense prior to the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for spection of 3/14/21, 5/14/21, 7/9/9/09/22, 12/08/22, 1/20/23 ideas in 11/28/2018 in 11	J installed a permaner iser pipe as of the inprior to the 10/15 on. Sediment at the maining SWPPP it. Active Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification of the complete by 8/05 Plains Contractor State outfall prior to the complete by 8/05 Plains Contractor State outfall prior to the number of the complete by 8/05 Plains Contractor State of the complete by 8/05 Plains Plains Contractor State of th	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a silt fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the 6/20. Not done as of the last Services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was removed prior to the note the slope located along the e E&A inspector will continue to 1/28/18. Great Plains Contractor Services installed silt fence on either gap in the silt fence east of the SB was access for sewer work prior to Drive to Gold Coast Road prior to CO outfall prior to 5/10/21.
SF 1 Current Condition:	11/14/19 inspection. The outl below the basin outfall prior to a silt fence wrap is no longer continue to monitor. Roth ent natural processes prior to the inspection. The E&A inspector. Sediment Basin Fair Condition - 10% Filled - I to inspection on 11/22/19. Depipe is no longer necessary. Enterprises cleaned out the binlet pipe prior to the 4/20/22. The dewatering holes lower to DEJ, Peter Katt, Gene Grave inspection. DEJ was reminde 10/30/20, 01/15/21, 3/5/21. If 2/23/22. Graves Developmer Silt Fence Removed - SF 1 *(SF 1.3) we southeast corner of the site, it inspection on 4/22/20. As of the southeast corner of the site, it inspection on 4/22/20. As of the southeast corner of the monitor. E&A inspector remose Silt Fence Fair Condition - A portion of Services installed the remain side of Gold Coast Road prior 2 outfall. The full portion of silt the inspection on 9/24/20. Silt 1/12/21 inspection. Great Place Commercial Seeding reinstal fence will be recommended to on 9/19/22. The silt fence should be trend	et pipe was installed prior to i o the inspection on 8/13/20. To necessary. Roth Enterprises erprises installed the baffle pipe 10/28/21 inspection. Roth Eight painted the cleanout mark of the properties of the cleanout mark of the properties of	inspection on 11/27/19. DE. The outfall is connected to the began cleaning out the basin rior to the 10/25/21 inspection terprises completed the reduring the 4/1/22 inspection on 11/14/2019 on of the basin prior to inspense prior to the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for the inspection on 10 ideas installed rip rap below for spection of 3/14/21, 5/14/21, 7/9/9/09/22, 12/08/22, 1/20/23 ideas in 11/28/2018 in 11	J installed a permaner iser pipe as of the inprior to the 10/15 on. Sediment at the maining SWPPP it. Active Active ection on 11/14/19. 7/21/20, therefore at the outfall prior to the 10/25/21. An unidentification of the complete by 8/05 Plains Contractor State outfall prior to the complete by 8/05 Plains Contractor State outfall prior to the number of the complete by 8/05 Plains Contractor State of the complete by 8/05 Plains Plains Contractor State of th	nent riser in the basin and rip raphe inspection on 8/13/20, therefore 9/21 inspection. E&A inspector will e outfall was washed away by ems prior to the 11/16/21 Yes The outlet pipe was installed prior a sit fence wrap around the outlet ne inspection on 8/07/20. Roth fied contractor began installing the services were reminded on 9/25/20, 1. DEJ was reminded on 10/29/21, 1. DEJ was reminded o

Current Condition:	Services installed the remain side of Gold Coast Road pric 2 outfall, cleaned out some or cleaned out the silt fence whit future location of Gold Coast due to grading on eastern pe Seeding reinstalled the silt fe	der of the silt fence prior to ins or to the inspection on 8/19/20. if the full portions of silt fence o ere full on the north side of the Road was removed to allow a virimeter from Gold Coast Road	pection on 7/31/19. Great Great Plains Contractor S in the northeastern perime site prior to the inspection coess for sewer work prio to the northeast corner of of the site prior to the 11/	Plains Contractor S Services closed the e ster of the site (addit on 9/09/20. The ful r to the inspection of f the site prior to 1/1	11/28/18. Great Plains Contractor fervices installed silt fence on either gap in the silt fence east of the SB ional cleanout still required), and I portion of silt fence south of the n 9/24/20. Silt fence was removed 2/21 inspection. Commercial issing portions of silt fence will be
Current Condition:	Services installed the remain full portions of silt fence on the on the north side of the site p NE corner prior to 5/10/21. G	der of the silt fence prior to ins ne northeastern perimeter of the prior to the inspection on 9/09/2 EPCS installed silt fence on the g cleaned out and repaired the	pection on 7/31/19. Great e site (additional cleanout 0. Great Plains Contracto east side of 120th Street,	Plains Contractor S still required), and or r Services repaired and backfilled the s	11/28/18. Great Plains Contractor increises cleaned out some of the cleaned out the silt fence where full and reinstalled new silt fence in the ilt fence north of SB 2, prior to eat Plains Contractor Services
SF 5	Silt Fence	120th St - S 123rd Ave	11/7/2019	Active	No
Current Condition:	South 123rd Avenue; and ea snow removal prior to inspec 1/12/21 Inspection. GPCS in side of 120th Street prior to 6 Commercial seeding cleanec Street prior to the 11/11/21 in	st side of South 120th Street p tion on 12/30/20. Silt fence was stalled silt fence on the west si 6/15/21. GPCS repaired and ex	rior to 11/10/20. Silt fence or removed between 123rd de of 120th Street prior to tended the silt fence on the around S 120th Street ar ctor Services repaired the	going north/south n d ave and S 120th S 5/19/21. GPCS clea ne west side of 120th and reinstalled silt fen silt fence prior to th	aned out the silt fence on the west h street prior to 8/25/21. ce around S 123rd and S 125th e 8/3/22 inspection. Graves
SF 6	Silt Fence	S 123rd Ave - S 125th St		Removed	
Current Condition:	Removed- (SF 1.1) Great Plant 123rd Avenue; and east side	ains Contractor Services repair of South 120th Street prior to	11/10/2020. Silt fence goi	talled the silt fence ng north/south north	I on east and west sides of South of S 124th Street damaged by rior to the 4/21/21 inspection. E&A
		of 4/29/2021 due to established		wed the silt terioe p	nor to the 4/21/21 mapection. Earl
SF 7	Silt Fence	S 125th St - A 5	11/7/2019	Active	No
Current Condition:					fence on east and west sides of
	South 123rd Avenue; and ea by snow removal prior to insp Commercial seeding repaired	st side of South 120th Street projection on 12/30/20. GPCS ren	rior to 11/10/2020. Silt fen noved a portion of the silt around S 125th street and	ce going north/soutl fence north of SB 1	n north of S 124th Street damaged prior to the inspection on 6/15/21. to the 11/11/21 inspection. Great
SF 8	Silt Fence	B 24 - K 28	7/18/2019	Active	Yes
SF 9 Current Condition:	Silt Fence Fair Condition - (SF 2) Great portions north of the full porti Contractor Services cleaned exposed in several areas (sc out the silt fence prior to the inspection. Commercial Seed The silt fence should be repa	A 9 - A 12 Plains Contractor Services repon, and backfilled/trenched-in tout and repaired the silt fence me still need trenched-in) prior 4/21/21 inspection. Great Plain ding cleaned out and repaired the titred where fallen. formed to complete by 5/25/22.	11/7/2019 saired the silt fence where the portion south of the full where full and trenched-into the inspection on 9/09 is Contractor Services represent fence prior to the 1	Active full (still needs cleat portion prior to the in the silt fence where (20. Great Plains Colaired/cleaned out th 1/11/21 inspection.	Yes ned out), backfilled the undermined inspection on 7/15/20. Great Plains
272	21		1.1/0/00.10	1	
STR Current Condition:	Streets Fair Condition Peter Katt / (Site	11/8/2018	Active	Yes
Current Condition:	streets prior to the 7/14/22 in Streets around active Legacy Legacy Homes was informed 5/20/22, 7/15/22, 9/09/22, 12	spection. y Homes lots should be cleaned to complete by 1/25/22. Not de t/08/22	d daily or as needed.		<u> </u>
SWPPP Sign	Misc./Other	Schram Road (W27) and S 120th Street (P1)	11/19/2018	Active	No
Current Condition:	inspector installed the SWPF	ctor installed the SWPPP sign a PP sign at S 120th Street at the	north end of the site during	ng the inspection on	S pection on 11/19/18. E&A 6/9/21. The SWPPP sign on S S 120th Street during the 4/1/22
Certification Statement	system designed to assure to person or persons who mana to the best of my knowledge	hat qualified personnel properly age the system or those persor	gathered and evaluated is directly responsible for complete. I am aware that	the information subn gathering the inform	or supervision in accordance with a nitted. Based on my inquiry of the lation, the information submitted is, at penalties for submitting false

	Je lin	Ports Sur
Inspector Signature:		Reviewed By: