	E&A	- P2008.207.000						
Inspector: Zach Jilek, CPESC, CISEC			•	Stage				
Project Name:	Bell Brook 2							
For Week Ending:		6/28/2008						
Grading: Sanitary Sewer:	100% 100%							
Storm Sewer:	100%							
Paving:	100%							
Seeding:	100%							
Utilities:	100%							
Overall Development:	45%							
DAIN FALL AMOUNTO	A	I						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		Week 1				
Sunday:	0.12"			WCCK 1				
Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	1.19"	06/20/08						
Friday Saturday	0.08" 0.19"	06/20/08						
Caturday	0.13			Week 2				
Sunday:	0.00"							
Monday	0.00"							
Tuesday	1.07"	00/05/00						
Wednesday Thursday	0.00" 0.48"	06/25/08						
Friday	0.57"	06/27/08						
Saturday	0.02"	06/28/08						
,		1	I.					
Complaints:	None							
		I	1					
Construction Sequencing:								
Which portion(s) (i.e. drainage basins) of the site	have had a tempo	rary or permanent cessation	n of grading, earthwork, o	r ground disturbance in the last				
14 days?								
Entire Site; grading completed and site se	eeded prior to 4/2	2008.						
Which portion(s) (i.e. drainage basins) of the site	do not have gradi	ng, earthwork, or ground di	sturbance scheduled in th	ne next 14 days? :				
Faire Oiles and in a second standard and aile		2000						
Entire Site; grading completed and site se	eeded prior to 4/2	2008.						
What temporary or permanent stabilization meas	sures listed in this	section are being implemen	ted?					
Existing Vegetation (4/2008)								
Comments:								
Comments:								
Home construction is the only activity on	site.							
Findings / Corrective Actions (Date):								
Findings / Corrective Actions (Date): 1) Varies lot level silt fence is down/dama was directed to complete maintenance by	•	•		•				
aware of overdue maintenance and was reminded to complete ASAP. This was not completed as of last inspection.								
2) Erosion rills in outlot south of the club house and erosion in outlot northeast of closed sediment basin #9 needs to be repaired								
and area needs to be seeded and matted. Bryan with Groundworks was directed to complete maintenance by 5/2/08. As of								
inspection on 6/5/08 maintenance was not complete. Groundworks is aware of overdue maintenance and was reminded to complete ASAP. This was not completed as of last inspection.								
3) Straw wattle at the bottom of the slope along Harrison Street is damaged and needs to be removed. Erosion rills also need to								
be repaired and slope needs to seeded and matted. Bryan with Groundworks was directed to complete maintenance by 5/2/08.								
As of inspections on 5/21 and 5/23 maintenance was not completed. As of inspection on 5/30/08 maintenance was not complete. 4) Washout south of closed basin #1 needs cleaned out. Groundwork's was requested to have this completed by 7/4/08. 5) Some maintenance is required in the RMP section.								
5) Some maintenance is required in the BMP section.								

		Projected Install			
Unique Name	Type	Location	Date	Status	Maintance

	Sediment	N41d00m00s				
SB 1	Basin	W96d00m00s		Removed		
Current Condition:	Removed					
	Sediment	N41d00m00s				
SB 2	Basin	W96d00m00s		Removed		
Current Condition:	Removed		*			
	Sediment	N41d00m00s				
SB 3	Basin	W96d00m00s	In Place	Active	Yes	
Current Condition:	Good Condition					
	Outlet pipe is damaged and needs to be repaired. Rip rap needs to be added at outlet pipe.					
	As of inspection	on 6/5/08 maintenanc	e was not complete. G	roundworks is aware of ove	rdue maintenance	
	and was reminded to complete ASAP. This was not completed as of last inspection.					
	Sediment	N41d00m00s				
SB 4	Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition				-	
	Sediment	N41d00m00s				
SB 5	Basin	W96d00m00s		Removed		
Current Condition:	Removed					
	Sediment	N41d00m00s				
SB 6	Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition					
Carrone Condition.	Sediment	N41d00m00s				
SB 7	Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition		11111400	710.110	110	
Garrone Gorialdoni	Sediment	N41d00m00s				
SB 8	Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition					
	Sediment	N41d00m00s			·	
SB 9	Basin	W96d00m00s		Removed		
Current Condition:	Removed					
		N41d00m00s				
SF 1	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Completely Removed					
	_	N41d00m00s				
STR	Streets	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition	 No majors signs of tra 	ack off.	. 1		
nspector Signature: Zadrung	k. Jildc		Reviewed By:	Zochany L. Jilek		