


E&A- P2008.207.000			
Inspector: Phillip Dechant			Stage
Project Name:	Bell Brook		2
For Week Ending:	9/13/2008		
Grading:	100%		
Sanitary Sewer:	100%		
Storm Sewer:	100%		
Paving:	100%		
Seeding:	100%		
Utilities:	100%		
Overall Development:	50%		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	
			Week 1
Sunday:	0.00"		
Monday	0.00"		
Tuesday	0.00"		
Wednesday	1.17"		
Thursday	0.00"	08/28/08	
Friday	0.00"		
Saturday	0.00"		
			Week 2/3
Sunday:	0.00"; 0.00"		
Monday	0.00"; 0.40"		
Tuesday	0.06"; 0.00"	None; 09/09/08	
Wednesday	0.00"; 0.00"	9/3/2008; 09/10/08	
Thursday	0.00"; 1.29"		
Friday	0.03"; 0.27"	None; 09/12/08	
Saturday	0.08"; 0.01"		
Complaints:	None		
Construction Sequencing:	Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?		
	Entire Site; grading completed and site seeded prior to 4/2008.		
	Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :		
	Entire Site; grading completed and site seeded prior to 4/2008.		
	What temporary or permanent stabilization measures listed in this section are being implemented?		
	Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08)		
Comments:			
Comments:	Home construction is the only activity on site.		
Findings / Corrective Actions (Date):			
Findings / Corrective Actions (Date):	1) No maintenance is required in the BMP section.		

Unique Name	Type	Location	Projected Install Date	Status	Maintance
SB 1	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 18% Filled Outlet pipe was damaged and repaired and Rip rap was added at outlet pipe prior to inspection on 8-19-08 by Commercial Seeding.				
SB 4	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No

Current Condition:	Good Condition- 23% Filled				
SB 5	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 6	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 16% Filled				
SB 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 17% Filled The large erosion rills and the washout that exposed the OPPD lines have been backfilled, and the outlet pipe was repaired prior to inspection on 8-19-08 by Commercial Seeding.				
SB 8	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 12% Filled				
SB 9	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SF 1	Silt Fence	N41d00m00s W96d00m00s	In Place	Removed	
Current Condition:	Removed due to dense vegetation				
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- No major signs of track off.				
SWPPP Sign	Signs	2 signs	8-19-08	Active	No
Current Condition:	Good Condition: RD sign installed 201st and Harrison				
Inspector Signature:			Reviewed By: 