


E&A- P2008.207.000			
Inspector: Phillip Dechant			Stage
Project Name:	Bell Brook		2
For Week Ending:	10/25/2008		
Grading:	100%		
Sanitary Sewer:	100%		
Storm Sewer:	100%		
Paving:	100%		
Seeding:	100%		
Utilities:	100%		
Overall Development:	50%		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	
			Week 1
Sunday:	0.00"		
Monday	1.27"		
Tuesday	0.46"	10/14/08	
Wednesday	0.28"	10/15/08	
Thursday	0.00"		
Friday	0.06"		
Saturday	0.00"		
			Week 2/3
Sunday:	0.00"		
Monday	0.00"		
Tuesday	0.31"		
Wednesday	1.18"		
Thursday	0.13"	10/23/08	
Friday	0.11"	10/24/08	
Saturday	0.00"		
Complaints:	None		
Construction Sequencing:			
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?			
Entire Site; grading completed and site seeded prior to 4/2008.			
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :			
Entire Site; grading completed and site seeded prior to 4/2008.			
What temporary or permanent stabilization measures listed in this section are being implemented?			
Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08) Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08)			
Comments:			
Home construction is the only activity on site. The site is in overall good condition.			
Findings / Corrective Actions (Date):			
Findings / Corrective Actions (Date):			
1) No maintenance is required in the BMP section.			

Unique Name	Type	Location	Projected Install Date	Status	Maintance
SB 1	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 19% Filled Outlet pipe was repaired and Rip rap added prior to inspection on 8-19-08 by Commercial Seeding.				
SB 4	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No

Current Condition:	Good Condition- 24% Filled				
SB 5	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 6	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 17% Filled				
SB 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 18% Filled The large erosion rills and the washout that exposed the OPPD lines have been backfilled, and the outlet pipe was repaired prior to inspection on 8-19-08 by Commercial Seeding.				
SB 8	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 13% Filled				
SB 9	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SF 1	Silt Fence	N41d00m00s W96d00m00s	In Place	Removed	
Current Condition:	Removed due to dense vegetation				
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- No major signs of track off.				
SWPPP Sign	Signs	2 signs	8-19-08	Active	No
Current Condition:	Good Condition: RD signs installed 201st and Harrison, 199th and Harrison				
Inspector Signature:			Reviewed By: 