E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

**Engineering Answers** 

<b>Environmental Services Dept.</b>	. Manager		Engin	eering Answers		
		E&A- P2015.7	717.002			
Inspector: Matt Vanicek				Stage		
		Bennine	gton Storage			
Project Name:			-	2		
•		CSW-201701311				
For Week Ending:		5/13/2017				
Project Location:	12	616 N. 156th Street, Be	ennington, NE (Douglas County)	68007		
Grading:		0%		1		
Sanitary Sewer:		0%				
Storm Sewer:	1	0%				
Paving:		0%				
Seeding:		0%				
Utilities:		0%				
Overall Development:		0%				
		970				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
TAIN I ALL AMOUNTO	7 tillodile ili tollalo	Date inspected	Weather Conditions	Week		
Sunday:	0.00"			Week		
Monday	0.00"					
Tuesday	0.15"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.40"	04/28/17	44/36 Rain			
Saturday	0.02"					
				Week		
Sunday:	0.97"					
Monday	0.05"	5/1/2017	54/35 Rain			
Tuesday	0.00"					
Wednesday	0.12"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
				Week		
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday 	0.65"	05/10/17	63/55 Tstorm			
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"			<u>l</u>		
	None					
	None					
Complaints:						
Construction Sequencing:	<u> </u>		1	L		
	s) of the site have had a tempo	rary or permanent cessation	of grading, earthwork, or ground disturband	e in the last 14 days?		
			7	•		
Entire Site scheduled for gradin	ng in the next 2 weeks (4/28	3/17).				
-	·	·				
Which portion(s) (i.e. drainage basin	s) of the site do not have gradi	ng, earthwork, or ground dis	sturbance scheduled in the next 14 days? :			
Entire Site scheduled for gradin	$\frac{1}{1}$ the next $\frac{1}{2}$ weeks (4/28)	3/17).				
<u> </u>						
What temporary or permanent stabili	ization measures listed in this s	section are being implement	ed?			
Existing Vegetation (4/28/17).						
SUMMARY QUESTIONS:						
Are approved entrances and adjacen	t streets being maintained adec	quately?				

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

**CHECKLIST QUESTIONS:** 

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Site was idle during the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance required in BMP Section

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE1	Construction Entrance	N. 156th Street	5/5/2017	Pending	No		
Current Condition:	Pending - To be installed once construction begins.						
CW 1	Concrete Washout	On Site	7/5/2017	Pending	No		
Current Condition:		lled once concrete wo					
D 1	Diversion	West side of site	5/5/2017	Pending	No		
Current Condition:	Pending - To be insta	lled once grading begi					
D 2	Diversion	East of SB 1	5/5/2017	Pending	No		
Current Condition:		lled once grading begi					
D 3	Diversion	South side of site	5/5/2017	Pending	No		
Current Condition: D 4		lled once grading begi		Donding	No		
	Diversion	North of SB 2	5/5/2017	Pending	NO		
Current Condition:	Erosion Control	lled once grading begi	ns in the area.				
EC 1	Transition Matting	Outfall of SB 2	8/5/2017	Pending	No		
Current Condition:		lled once outfall is cor		renamy	110		
Current Condition.	Erosion Control	died office outlant is con	isti ucteu.				
EC 2	Transition Matting	Outfall of SB 1	8/5/2017	Pending	No		
Current Condition:		lled once outfall is cor		9			
	Erosion Control						
EM 1	Matting	SE corner of site	9/5/2017	Pending	No		
Current Condition:		lled after grading is co	mplete in the area.				
	Erosion Control						
EM 2	Matting	South side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be insta	lled after grading is co	mplete in the area.				
<b>511.0</b>	Erosion Control		0/5/00/45				
EM 3	Matting	SW corner of site	9/5/2017	Pending	No		
Current Condition:	Erosion Control	lled after grading is co	mplete in the area.				
EM 4	Matting	West side of site	9/5/2017	Pending	No		
Current Condition:		lled after grading is co		1 chang	140		
Current Condition.	Erosion Control	grading is co	implete in the drea.				
EM 5	Matting	NW corner of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be insta	lled after grading is co	mplete in the area.	<u>_</u>			
	Erosion Control						
EM 6	Matting	North side of site	9/5/2017	Pending	No		
Current Condition:		lled after grading is co	mplete in the area.				
	Erosion Control						
EM 7	Matting	North side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be insta	lled after grading is co	mplete in the area.				
EM 0	Erosion Control	Foot side of site	0/5/0047	Donalina	Na		
EM 8	Matting  Panding To be inste	East side of site	9/5/2017	Pending	No		
Current Condition:	rending - 10 be insta	lled after grading is co	implete in the area.				
IP 1	Inlet Protection	Bioretention Basin B	8/5/2017	Pending	No		
Current Condition:		lled once inlet is const		Tonaing	140		
Surront Sonation.	i chang To be illata	SE corner of	. actour				
IP 2	Inlet Protection	buildings	8/5/2017	Pending	No		
Current Condition:		lled once inlet is const					
IP 3	Inlet Protection	<b>Bioretention Basin A</b>	8/5/2017	Pending	No		
Current Condition:		lled once inlet is const					
IP 4	Inlet Protection	South of buildings	8/5/2017	Pending	No		
Current Condition:	Pending - To be insta	lled once inlet is const	tructed.	<u> </u>			
		SW corner of	0/2/00/42				
IP 5	Inlet Protection	buildings	8/5/2017	Pending	No		
Current Condition:	Pending - To be insta	lled once inlet is const	tructed.				

IP 6	Inlet Protection	West of CE 1	8/5/2017	Pending	No			
Current Condition:	Pending - To be installed once inlet is constructed.							
IP 7	Inlet Protection	Near CE 1	8/5/2017	Pending	No			
Current Condition:	Pending - To be installed once inlet is constructed.							
IP 8	Inlet Protection	SE corner of site	8/5/2017	Pending	No			
Current Condition:	Pending - To be installed once surrounding area is disturbed.							
SF 1	Silt Fence	All sides of site	4/28/2017	Active	No			
Current Condition:		Good Condition - Commercial Seeding installed the silt fence prior to the inspection on 4/28/17.						
SF 2	Silt Fence	East side of site	4/28/2017	Active	No			
Current Condition:	Good Condition - Co	Good Condition - Commercial Seeding installed the silt fence prior to the inspection on 4/28/17.						
SB 1	Sediment Basin	SW corner of the site	5/5/2017	Pending	No			
Current Condition:	Pending - To be insta	Pending - To be installed once grading begins in the area.						
SB 2	Sediment Basin	SE corner of the site	5/5/2017	Pending	No			
Current Condition:	Pending - To be insta	Pending - To be installed once grading begins in the area.						
ST 1	Sediment Trap	SW corner of the site	5/5/2017	Pending	No			
Current Condition:	Pending - To be insta	Pending - To be installed once grading begins in the area.						
STR	Streets	On Site	4/28/2017	Active	No			
Current Condition:	Good Condition - No	Good Condition - No track out visible.						
SWPPP Sign	SWPPP Sign	N. 156th Street	5/5/2017	Pending	Yes			
Current Condition:	Pending -							
	The SWPPP sign nee	The SWPPP sign needs to be installed.						
	The F&A inspector w	ill install the sign wher	it arrives. Not done a	s of the last inspecti	on			
	The Lan inspector w	in matan the sign when	in annes. Not done a	la or the last mapecu	OII.			
W. Le				7.	2 1/			
Inspector Signature:	Sam			Reviewed By:	Sianoum Sture			
		1		· · · · · · · · · · · · · · · · · · ·				