E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Enaineerina Answers

Environmental Services Dept. Manager Environmental Services Dept. Manager							
		E&A- P2015.7	17.002				
nspector: Matt Vanicek				Stage			
		Benning	gton Storage				
Project Name:			201701311	2			
For Week Ending:		5/27/2017					
Project Location:	11						
Floject Location.		12616 N. 156th Street, Bennington, NE (Douglas County)					
Grading:		25%					
Sanitary Sewer:		0%					
Storm Sewer:		0%					
Paving:		0%					
Seeding:		0%					
Jtilities:		0%					
Overall Development:		0%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions				
				Week			
Sunday:	0.00"						
Monday	0.00"						
Tuesday Mednaeday	0.09"	05/47/47	72/57 Totows				
Wednesday Foursday	0.48" 0.49"	05/17/17	73/57 Tstorm				
Гhursday Friday	1.19"						
Saturday	0.98"						
outui uuy	0.00			Week			
Sunday:	0.00"			vioc.			
Monday	0.00"	5/22/2017	74/51 Tstorm				
Гuesday	0.06"						
Vednesday	0.00"						
Гhursday	0.00"						
-riday	0.00"						
Saturday	0.02"						
	21/2	NVA		Week			
Sunday:	N/A	N/A					
Monday	N/A N/A	N/A N/A					
Гuesday Vednesday	N/A	N/A					
Thursday	N/A	N/A					
Friday	N/A	N/A					
Saturday	N/A	N/A					
	1		+				
	None						
Complaints:							
Professional Control of the Control							
Construction Sequencing:							
Vhich portion(s) (i.e. drainage basins	s) of the site have had a tempo	rary or permanent cessation	of grading, earthwork, or ground disturbance in	the last 14 days?			
Entire Site echedulad for gradin	g in the next 2 weeks (4/2	9/17) Site etripped (5/17	/17)				
Entire Site scheduled for grading	y III IIIE IIEXL Z WEEKS (4/Z	or ir j. one suippeu (5/17	111).				
Which portion(s) (i.e. drainage basins	s) of the site do not have gradi	ng, earthwork, or ground dis	turbance scheduled in the next 14 days? :				
Entire Site scheduled for grading	<u> </u>		-				
grading	5 2.2 2 (1/2	,pp - a (o/ //	,				
Vhat temporary or permanent stabilize	zation measures listed in this	section are being implement	ed?				
Existing Vegetation (4/28/17).							
SUMMARY QUESTIONS:							
Are approved entrances and adjacent	t streets being maintained ade	quately?					

No, See BMP Section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?
Yes

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Site was inactive during the current inspection. Site was stripped prior to the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance required in BMP Section

			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
CE1	Construction Entrance	N. 156th Street	5/5/2017	Pending	Yes		
Current Condition:	Pending -			<u> </u>			
	To thomas						
	A rock entrance needs to be installed.						
	Prairie Construction was informed to complete by 5/24/17. Not done as of the last inspection.						
CW 1	Concrete Washout	On Site	7/5/2017	Pending	No		
Current Condition:	Pending - To be installed						
D 1	Diversion	West side of site	5/5/2017	Pending	No		
Current Condition:	Pending - To be installe				1		
D 2	Diversion	East of SB 1	5/5/2017	Pending	No		
Current Condition:	Pending - To be installe			D din	T NI-		
D 3	Diversion	South side of site	5/5/2017	Pending	No		
Current Condition: D 4	Pending - To be installe Diversion	North of SB 2	In the area. 5/5/2017	Dondina	No		
Current Condition:	Pending - To be installe			Pending	INO		
Current Condition.	Erosion Control	d once grading begins	in the area.				
EC 1	Transition Matting	Outfall of SB 2	8/5/2017	Pending	No		
Current Condition:	Pending - To be installe			Fending	INU		
Current Condition.	Erosion Control	u once outlail is consti	ucieu.		1		
EC 2	Transition Matting	Outfall of SB 1	8/5/2017	Pending	No		
Current Condition:	Pending - To be installed			1 Origing	110		
Guiterit Gorialion.	Erosion Control	a onec oatian is consti	dolou.				
EM 1	Matting	SE corner of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe			9			
Carron Conadon	Erosion Control	a artor graaming to comp	1				
EM 2	Matting	South side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe		olete in the area.	J			
	Erosion Control	<u> </u>					
EM 3	Matting	SW corner of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe	d after grading is comp	olete in the area.	-	•		
	Erosion Control						
EM 4	Matting	West side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe	d after grading is comp	olete in the area.				
	Erosion Control						
EM 5	Matting	NW corner of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe	d after grading is comp	olete in the area.				
	Erosion Control						
EM 6	Matting	North side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe	d after grading is comp	olete in the area.		1		
	Erosion Control		0.5.00.45				
EM 7	Matting	North side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installed after grading is complete in the area.						
E11.0	Erosion Control		0/5/0047	D !!			
EM 8	Matting	East side of site	9/5/2017	Pending	No		
Current Condition:	Pending - To be installe			Dandina	N _a		
IP 1		Bioretention Basin B		Pending	No		
Current Condition:	Pending - To be installe	u once miet is constru	Lieu.		1		
IP 2	Inlet Protection	QE corner of buildings	0/5/2017	Donding	Ma		
Current Condition:		SE corner of buildings		Pending	No		
IP 3	Pending - To be installe Inlet Protection	Bioretention Basin A	8/5/2017	Pending	No		
Current Condition:	Inlet Protection Bioretention Basin A 8/5/2017 Pending No Pending - To be installed once inlet is constructed.						
IP 4	Inlet Protection	South of buildings	8/5/2017	Pending	No		
	ILLICI CIULECIUII	South of bullullus	UIJIZUTI		i INO		

		SW corner of						
IP 5	Inlet Protection	buildings	8/5/2017	Pending	No			
Current Condition:	Pending - To be installed once inlet is constructed.							
IP 6	Inlet Protection	West of CE 1	8/5/2017	Pending	No			
Current Condition:	Pending - To be installed once inlet is constructed.							
IP 7	Inlet Protection	Near CE 1	8/5/2017	Pending	No			
Current Condition:	Pending - To be installed once inlet is constructed.							
IP 8	Inlet Protection	SE corner of site	8/5/2017	Pending	Yes			
Current Condition:	Pending - The inlet protection needs to be installed. Prairie Construction was informed to complete by 5/24/17. Not done as of the last inspection.							
SF 1	Silt Fence	All sides of site	4/28/2017	Active	Yes			
	The silt fence needs to be cleaned out, backfilled, and repaired at the SE corner of the site. Prairie Construction was informed to complete by 5/24/17. Not done as of the last inspection.							
SF 2	Silt Fence	East side of site	4/28/2017	Active	No			
Current Condition:	Good Condition - Commercial Seeding installed the silt fence prior to the inspection on 4/28/17.							
SB 1	Sediment Basin	SW corner of the site	5/5/2017	Pending	No			
Current Condition:	Pending - To be installed once grading begins in the area.							
SB 2	Sediment Basin	SE corner of the site	5/5/2017	Pending	No			
Current Condition:	Pending - To be installed	ed once grading begins	in the area.	•				
ST 1	Sediment Trap	SW corner of the site	5/5/2017	Pending	No			
Current Condition:	Pending - To be installed once grading begins in the area.							
STR	Streets	On Site	4/28/2017	Active	No			
Current Condition:	Good Condition - No track out visible.							
SWPPP Sign	SWPPP Sign	N. 156th Street	5/5/2017	Pending	Yes			
Current Condition:	Pending - The SWPPP sign need							
Inspector Signature:	Van			Reviewed By:	un Sture			