E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. M				Engineering A	nswers
Environmental Services Dept. N	wanager	E&A- P2015	717 000		
Inspector: Josh Ellington		EGA-1 2010	.717.000		Stage
moposton coon Limigton	McGrego	Stage			
Project Name:	McGrego	3			
For Week Ending:					
Project Location:	126	68007			
Grading:	100%			<u> </u>	I
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	90%				
Utilities:	100%				
Overall Development:	95%				
				<u> </u>	1
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Week
Sunday:	0.00"	7/9/2023	Mostly Sunny 81 / 57	2:50 PM	Week
Monday	0.08"	1.3/2020	moon, ourning or ror	2.001 111	
Tuesday	0.00"				
Wednesday	0.54" (06:15 - 10:00)	7/12/2023	Mostly Sunny 82 / 62	11:15 AM	
Thursday	0.00"				
Friday	0.27" (09:30 - 16:00)				
Saturday	0.00"				
					Week
Sunday:	0.07" (08:15 - 09:55)				
Monday	0.16" (07:55 - 08:55)	7/17/2023	Partly cloudy 68	10:00 AM	
Tuesday	0.18" (07:35 - 09:55)				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.31" (03:55)				
	2 221				Week
Sunday:	0.00"	=/0.//0000	Built de la 04	40 40	
Monday	0.19"	7/24/2023	Partly cloudy 81	10:55 AM	
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.03"				
Friday					
Saturday	0.00"				Week
Sunday:	0.00"				VVeek
Monday	1.16" (04:55 - 08:55)	7/31/2023	Mostly sunny 81	2:00 PM	
Tuesday	0.01"				
Wednesday	2.08" (01:55 - 09:55)	8/2/2023	Cloudy 80	2:40 PM	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				- Week
Sunday:	0.08"				Week
Monday:	0.00"				
Tuesday:	0.02"				
Wednesday:	0.10"				
Thursday:	0.00"				
Friday:	0.07"				
Saturday:	0.00"				

Complaints:	None		

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site scheduled for grading in the next 2 weeks (4/28/2017). Site stripped (5/17/2017). Grading was underway (6/05/2017). Grading was completed prior to the inspection on 6/30/2017. Minor grading to be completed at a later time. Grading was active on the southern portion of the site (7/2/2018). The southeast portion of the site grading was completed (7/18/2018). The post construction basins were cleaned out (9/18/2018). The area west of the storage units was graded for new construction (10/9/2018). Major grading complete, minor grading possible at a later date (5/8/2019). ROW along road disturbed by water installation (12/31/2019). Western portion of site disturbed by water installation (5/25/2020). Utility installation along Spruce Street (11/11/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site scheduled for grading in the next 2 weeks (4/28/2017). Site stripped (5/17/2017). Grading was underway (6/05/2017). Grading was completed prior to the inspection on 6/30/2017. Minor grading to be completed at a later time. Grading was active on the southern portion of the site (7/2/2018). The southeast portion of the site grading was completed (7/18/2018). The post construction basins were cleaned out (9/18/2018). The area west of the storage units was graded for new construction (10/9/2018). Major grading complete, minor grading possible at a later date (5/8/2019). ROW along road disturbed by water installation (12/31/2019). Western portion of site disturbed by water installation (5/25/2020). Utility installation along Spruce Street (11/11/2020).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/28/2017). Prairie Construction seeded the site (8/16/2017). Prairie Construction installed erosion control matting on the northeast corner of the site (8/16/2017). Prairie Construction installed erosion control matting on the south, east, and northern borders of the site BMPs EM1-EM5 (8/21/2017). The area north of Building A was seeded and matted (12/13/2017). The area North of Building C was seeded and matted (1/10/2018). The area along the entrance to the old storage units was seeded and matted (2/20/2018). The inside slopes of the sediment basin were seeded and matted (4/18/2019). The slopes to the east and south of the sediment basin were seeded and matted (8/10/2018). The area around CS 1 was seeded (8/15/2018). The area around both post construction basins and all storage units was seeded and matted (9/18/2018). Seeding and matting along the ROW on storage unit lot and ROW along HWY 30 (4/15/2020). Seeding and matting over SB 1 outlet pipe and ROW of N. 156th Street (4/14/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Nο

Create Corrective Action?

No - See BMP Section (SB 1).

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments:

The site was inactive during the most recent inspection. The storage units are open and operating.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance required in BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE1	Construction Entrance	N. 156th Street		Removed	
Current Condition:	Removed - The temporary construction entrance was removed prior to the inspection on 7/16/18.				
CE 2	Construction Entrance	N. 156th Street		Removed	
Current Condition:	Removed - Prairie Construction paved the entrance prior to the inspection on 5/14/18.				
CW 1	Concrete Washout	On Site		Removed	

Current Condition:	Removed - Development level paving appears complete as of 11/6/19. Future concrete work will be handled on a lot by
D 1	lot basis. Diversion North side of Site Removed
Current Condition:	Removed - The diversion has silted in, but due to heavy vegetation is no longer needed as of the inspection on 5/22/18.
D 2	Diversion Courth Feet eite of Cite Demoved
D 2 Current Condition:	Diversion South East site of Site Removed Removed Removed - The diversion has silted in, but due to heavy vegetation is no longer needed as of the inspection on 5/22/18.
Guitent Gondition.	The moved - The diversion has since in, but due to heavy vegetation is no longer needed as of the inspection on 5/22/10.
D 3	Diversion South side of site Removed
Current Condition:	Removed - Due to the storm sewer being installed the diversion is no longer needed as of the inspection on 5/22/18.
D 4	Diversion North of SB 2 Removed
Current Condition:	Removed - Due to the storm sewer being installed the diversion is no longer needed as of the inspection on 4/18/19.
EC 1	Erosion Control Transition Matting Outfall of SB 1 4/14/2022 Active No
Current Condition:	Good Condition - Geoff McGregor installed the Shoremax Transition Mat at the outfall of SB 1 prior to the inspection on 4/14/22.
	Erosion Control
EM 1	Matting SE corner of site 3/26/2018 Active No
Current Condition:	Good Condition - Prairie Construction seeded and matted the slopes around SB 1 prior to inspection on 8/10/18.
EM O	Erosion Control Motting South side of site 9/21/2017 Active
EM 2 Current Condition:	Matting South side of site 8/21/2017 Active No Good Condition - Prairie Construction installed erosion control matting prior to the inspection on 8/21/17.
Current Condition.	Erosion Control
EM 3	Matting SW corner of site 8/21/2017 Active No
Current Condition:	Good Condition - Prairie Construction installed erosion control matting prior to the inspection on 8/21/17.
_	Erosion Control
EM 4	Matting West side of site 8/21/2017 Active No
Current Condition:	Good Condition - Prairie Construction installed erosion control matting prior to the inspection on 8/21/17.
EM 5	Erosion Control Matting NW corner of site 8/16/2016 Active No
Current Condition:	Good Condition - Prairie Construction installed erosion control matting prior to the inspection on 8/21/17.
	Erosion Control
EM 6	Matting North side of site 7/13/2017 Active No
Current Condition:	Good Condition- Prairie Construction installed erosion control matting prior to the inspection on 11/10/18.
EN 7	Erosion Control Alastica State and a faite State Stat
EM 7 Current Condition:	Matting North side of site 7/13/2017 Active No Good Condition - Prairie Construction installed the erosion control matting prior to the inspection on 12/13/17.
Current Condition.	Erosion Control
EM 8	Matting East side of site Removed
Current Condition:	Removed - EM 8 was improperly placed onto the report. It is not present on the SWPPP.
15.4	
IP 1 Current Condition:	Inlet Protection SE corner of buildings Removed Removed - All areas that drain to the inlet are stabilized/paved as of 4/11/19.
Current Condition.	Removed - All aleas that drain to the met are stabilized/paved as 01 4/17/19.
IP 2	Inlet Protection SE corner of buildings Removed
Current Condition:	Removed - All areas that drain to the inlet are stabilized/paved as of 4/11/19.
IP 3	Inlet Protection SE corner of buildings Removed
Current Condition:	Removed - All areas that drain to the inlet are stabilized/paved as of 4/11/19. Inlet Protection South of buildings Removed
Current Condition:	Removed - All areas that drain to the inlet are stabilized/paved as of 4/11/19.
	,
IP 5	Inlet Protection SW corner of buildings Removed
Current Condition:	Removed - All areas that drain to the inlet are stabilized/paved as of 4/11/19.
IP 6	Straw Wattle West of CE 1 Removed Removed - Prairie Construction removed the straw wattle prior to the inspection on 6/2/18.
Current Condition:	Removed - Prairie Construction removed the straw wattle prior to the inspection on 6/2/18. Straw Wattle Near CE 1 5/22/2018 Active No
Current Condition:	Active - Prairie Construction removed the straw wattle in the inlet. The inlet is draining properly and the area is paved as
	of the inspection on 8/15/18. The inspector will continue to monitor.
IP 8	Inlet Protection SE corner of site Removed
Current Condition:	Removed - Geoff McGregor stabilized the area around the inlet prior to the inspection on 4/15/20.
SF 1	Silt Fence All sides of site Removed
Current Condition:	Removed - Geoff McGregor removed the silt fence prior to the inspection on 4/14/22.
SF 2 Current Condition:	Silt Fence East side of site Removed Removed - Prairie Construction removed the remaining portion of silt fence due to the area being seeded and matted
Garrent Condition.	prior to inspection on 8/10/18.
SF 3	Silt Fence Outfall of ST 1 Removed
Current Condition:	Removed - Geoff McGregor removed the silt fence prior to the inspection on 4/14/22. Due to stabilization in the area,
07.1	reinstallation will not be recommended.
SF 4	Silt Fence Outfall of ST 2 Removed

Current Condition:	reinstallation will not be	-	nce prior to the inspection of	on 4/14/22. Due to stabil	ization in the area,	
SF 5	Silt Fence	Outfall of ST 3		Removed		
Current Condition:		egor removed the silt fe	nce prior to the inspection o		ization in the area,	
SF 6	Silt Fence	Outfall of ST 4		Removed		
Current Condition:			nce prior to the inspection o		ization in the area,	
	reinstallation will not be	recommended.				
		East side of site at the				
05.7	0111 5	intersection of 156th				
SF 7 Current Condition:	Silt Fence	and Spruce Streets	to the inequation on 4/14/0	Removed	the area reinstallation	
Current Condition:	Removed - The straw wattle decomposed prior to the inspection on 4/14/22. Due to stabilization in the area, reinstallation will not be recommended.					
SB 1	Sediment Basin	SW corner of the site	5/5/2017	Active	Yes	
Current Condition:						
	Fair Condition - 40% full - Prairie Construction installed the inlet prior to the inspection on 3/24/18. Geoff McGregor backfilled and seeded/matted the erosion over the outfall pipe prior to the inspection on 4/14/22. Geoff McGregor					
	painted the cleanout mark on the riser prior to the 7/17/23 inspection; when weather allows, the E&A inspector					
	will verify the height a	will verify the height and that the extra dewatering holes were patched.				
	4) 71					
		should be painted on the	eriser. oproved height need to be p	patched		
	2.) Several extra dewar	ering noies below the ap	oproved height heed to be p	aicheu.		
	1.) Prairie Construction	and Geoff McGregor we	ere informed to complete by	/ 4/18/19. Not done as o	f the last inspection.	
			6/19, 8/13/19, 10/2/19, 12/6		14/20, 5/28/20,	
			17/22, 7/6/2022, 8/30/22, 1			
		2.) Prairie Construction and Geoff McGregor were informed to complete by 4/18/19. Not done as of the last inspection. Geoff McGregor was reminded on 6/05/19, 7/16/19, 8/13/19, 10/2/19, 12/6/19, 3/21/20, 4/15/20, 5/14/20, 5/28/20,				
			17/22, 7/6/2022, 8/30/22, 1		14/20, 5/26/20,	
	1720/20, 3/11/20, 12/03/	120, 0100121, 0120121, 21	11722, 170/2022, 0/00/22, 1	1/22/22, 0/ 14/20		
SB 2	Sediment Basin	SE corner of the site		Removed		
Current Condition:			I sin is no longer needed prio		I 30/17.	
ST 1	Sediment Trap	NE corner of site	6/30/2017	Active	No	
Current Condition:			on installed the silt trap prio			
			p prior to the 7/17/23 insp		50, 111 55011	
ST 2	Sediment Trap	East corner of site	6/30/2017	Active	No	
Current Condition:	Good Condition - 30% f	filled. Prairie Constructi	on installed the silt trap prior	r to the inspection on 6/3	30/17.	
ST 3	Sediment Trap	SE corner of site	6/30/2017	Active	No	
Current Condition:	Good Condition - 30% f	filled. Prairie Constructi	on installed the silt trap prior	r to the inspection on 6/3	30/17.	
ST 4	Sediment Trap	SE corner of site	6/30/2017	Active	No	
Current Condition:			on installed the silt trap prio	r to the inspection on 6/3	30/17. The silt trap was	
	mistakenly removed fro	· · · · · · · · · · · · · · · · · · ·				
SW 1	Straw Wattle	North of Building C		Removed		
Current Condition:	Removed - Prairie Construction removed the wattles due to seeding and matting of the area as of the inspection on					
	9/25/18.	I	Г	Γ	Г	
SW 2	Straw Wattle	South Side of Building C		Removed		
Current Condition:		_	I attles due to seeding and m		the inspection on	
Current Condition.	9/18/18.	su action removed the w	atties due to seeding and in	latting of the area as of	ine inspection on	
STR	Streets	On Site	4/28/2017	Active	No	
Current Condition:			ned by Geis Inc. prior to the		The intersection of	
			uring the inspection on 4/15			
	inspection on 7/12/21.					
SWPPP Sign	SWPPP Sign	N. 156th Street	6/24/2017	Active	No	
Current Condition:			NPPP sign prior to the inspe			
	.1	•	0 1			
Certification Statement:						
	I certify, under penalty of	of law, that this documer	nt and all attachments were	prepared under my dire	ction or supervision in	
	1		nt and all attachments were hat qualified personnel prop		•	
	accordance with a syste submitted. Based on m	em designed to assure t y inquiry of the person o	hat qualified personnel prop r persons who manage the	perly gathered and evalu system or those person	uated the information s directly responsible	
	accordance with a syste submitted. Based on m for gathering the inform	em designed to assure t y inquiry of the person o ation, the information su	hat qualified personnel proper persons who manage the submitted is, to the best of my	perly gathered and evalus system or those person y knowledge and belief,	uated the information s directly responsible true, accurate, and	
	accordance with a syste submitted. Based on m for gathering the inform complete. I am aware the	em designed to assure to y inquiry of the person of ation, the information sun at there are significant	hat qualified personnel prop r persons who manage the	perly gathered and evalus system or those person y knowledge and belief,	uated the information s directly responsible true, accurate, and	
	accordance with a syste submitted. Based on m for gathering the inform	em designed to assure to y inquiry of the person of ation, the information sun at there are significant	hat qualified personnel proper persons who manage the submitted is, to the best of my	perly gathered and evalus system or those person y knowledge and belief,	uated the information s directly responsible true, accurate, and	
	accordance with a syste submitted. Based on m for gathering the inform complete. I am aware the and imprisonment for ki	em designed to assure to y inquiry of the person of ation, the information sun at there are significant	hat qualified personnel proper persons who manage the submitted is, to the best of my	perly gathered and evalusystem or those person y knowledge and belief, e information including t	uated the information s directly responsible true, accurate, and the possibility of fines	
	accordance with a syste submitted. Based on m for gathering the inform complete. I am aware the	em designed to assure to y inquiry of the person of ation, the information sun at there are significant	hat qualified personnel proper persons who manage the submitted is, to the best of my	perly gathered and evalusystem or those person y knowledge and belief, e information including t	uated the information s directly responsible true, accurate, and	