E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Friday

Saturday

Sunday:

0.00"

0.00"

N/A



**Engineering Answers** 

Week 5

| Environmental Services Dept.   | Manager          |                  |                    |            |        |  |  |
|--|------------------|------------------|--------------------|------------|--------|--|--|
|  |                  | E&A- P2015       | .717.000           |            |        |  |  |
| Inspector: Josh Ellington  |                  |                  |                    |            | Stage  |  |  |
|  | McGre            | egor Brae Subdiv | vision @ 156th &   | Highway 36 |        |  |  |
|  |                  |                  | igton Storage)     | 0 9        | 3      |  |  |
|  |                  | 5                |                    |            |        |  |  |
| Project Name:  |                  | CSW              | -202206443         |            |        |  |  |
| For Week Ending:   |                  |                  |                    |            |        |  |  |
| Project Location:  | 1                | 68007            |                    |            |        |  |  |
| Project Location: 12616 N. 156th Street, Bennington, NE (Douglas County) 68007 |                  |                  |                    |            |        |  |  |
| Grading:   | 10               | 0%               |                    |            |        |  |  |
| Sanitary Sewer:  |                  | 0%               |                    |            |        |  |  |
| Storm Sewer:   |                  | 0%               |                    |            |        |  |  |
| Paving:  |                  | 0%               |                    |            |        |  |  |
| Seeding:   |                  | 0%               |                    |            |        |  |  |
| Utilities:   |                  | 0%               |                    |            |        |  |  |
| Overall Development:   |                  | 5%               |                    |            |        |  |  |
|  | <b>`</b>         | L                | <b>I</b>           | I          | 1      |  |  |
| RAIN FALL AMOUNTS  | Amount in tenths | Date inspected   | Weather Conditions | Time       |        |  |  |
|  |                  |                  |                    |            | Week 1 |  |  |
| Sunday:  | 0.00"            |                  |                    |            |        |  |  |
| Monday   | 0.00"            |                  |                    |            |        |  |  |
| Tuesday  | 0.00"            |                  |                    |            |        |  |  |
| Wednesday  | 0.00"            |                  |                    |            |        |  |  |
| Thursday   | 0.00"            |                  |                    |            |        |  |  |
| Friday   | 0.00"            |                  |                    |            |        |  |  |
| Saturday   | 0.00"            |                  |                    |            |        |  |  |
|  |                  |                  |                    |            | Week 2 |  |  |
| Sunday:  | 0.02"            |                  |                    |            |        |  |  |
| Monday:  | 0.14"            | 11/20/2023       | Cloudy 45          | 11:05 AM   |        |  |  |
| Tuesday:   | 0.00"            |                  |                    |            |        |  |  |
| Wednesday:   | 0.00"            |                  |                    |            |        |  |  |
| Thursday:  | 0.00"            |                  |                    |            |        |  |  |
| Friday:  | 0.00"            |                  |                    |            |        |  |  |
| Saturday:  | 0.00"            |                  |                    |            |        |  |  |
|  |                  |                  |                    |            | Week 3 |  |  |
| Sunday:  | 0.00"            |                  |                    |            |        |  |  |
| Monday   | 0.00"            |                  |                    |            |        |  |  |
| Tuesday  | 0.00"            |                  |                    |            |        |  |  |
| Wednesday  | 0.00"            |                  |                    |            |        |  |  |
| Thursday   | 0.00"            |                  |                    |            |        |  |  |
| Friday   | 0.00"            |                  |                    |            |        |  |  |
| Saturday   | 0.00"            |                  |                    |            |        |  |  |
|  |                  |                  |                    |            |        |  |  |
| Sunday:  | 0.00"            |                  |                    |            |        |  |  |
| Monday   | 0.00"            |                  |                    |            |        |  |  |
| Tuesday  | 0.00"            |                  |                    |            |        |  |  |
| Wednesday  | 0.00"            |                  |                    |            |        |  |  |
| Thursday   | 0.00"            |                  |                    |            |        |  |  |
|  |                  |                  |                    |            | 1      |  |  |

| <b>1</b>   | 1   |  |   |   |   |
|--|---|--|---|---|---|
| Monday   | N/A   |  |   |   |   |
| Tuesday  | N/A   |  |   |   |   |
| Wednesday  | N/A   |  |   |   |   |
| Thursday   | N/A   |  |   |   |   |
| Friday   | N/A   |  |   |   |   |
| Saturday   | N/A   |  |   |   |   |
|  |   |  |   |   |   |
| Complaints:  | None  |  |   |   |   |
|  |   |  |   |   |   |
| Construction Sequencing:   |   |  |   |   |   |
| Which portion(s) (i.e. drainage basins) of the s   | site have had a temporary or  | permanent cessation of gra   | ding, earthwork, or ground distu  | irbance in the last 14 days?  |   |
| Entire site scheduled for grading in the<br>the inspection on 6/30/2017. Minor gra-<br>portion of the site grading was complet<br>graded for new construction (10/9/2018<br>installation (12/31/2019). Western porti<br>Which portion(s) (i.e. drainage basins) of the s | ding to be completed at<br>ted (7/18/2018). The pos<br>3). Major grading completion of site disturbed by v        | a later time. Grading wast construction basins wast construction basins waste, minor grading possil water installation (5/25/2 | as active on the southern po<br>ere cleaned out (9/18/2018)<br>ble at a later date (5/8/2019<br>020). Utility installation alor | ortion of the site (7/2/20)<br>). The area west of the s<br>1). ROW along road dist<br>ng Spruce Street (11/11) | 18). The southeast<br>torage units was<br>urbed by water          |
| Entire site scheduled for grading in the   |   |  |   |   | was completed prior to  |
| the inspection on 6/30/2017. Minor graportion of the site grading was complet graded for new construction (10/9/2018 installation (12/31/2019). Western portion  | ding to be completed at<br>ted (7/18/2018). The pos<br>3). Major grading completion<br>ion of site disturbed by v | a later time. Grading wast construction basins waste, minor grading possil<br>water installation (5/25/2                       | as active on the southern po<br>ere cleaned out (9/18/2018)<br>ble at a later date (5/8/2019                                    | ortion of the site (7/2/20)<br>. The area west of the s<br>.). ROW along road dist                              | 18). The southeast<br>torage units was<br>urbed by water          |
| What temporary or permanent stabilization me   | asures listed in this section   | are being implemented?   |   |   |   |
| of the site (8/16/2017). Prairie Construct<br>The area north of Building A was seed<br>entrance to the old storage units was s<br>to the east and south of the sediment b<br>construction basins and all storage uni<br>(4/15/2020). Seeding and matting over            | ed and matted (12/13/20<br>seeded and matted (2/20<br>pasin were seeded and r<br>ts was seeded and matt           | 017). The area North of I<br>0/2018). The inside slope<br>matted (8/10/2018). The<br>ted (9/18/2018). Seeding                  | Building C was seeded and<br>es of the sediment basin we<br>area around CS 1 was see<br>g and matting along the RO              | matted (1/10/2018). Th<br>ere seeded and matted (<br>eded (8/15/2018). The an                                   | e area along the<br>4/18/2019). The slopes<br>ea around both post |
| Checklist Questions:   |   |  |   |   |   |
| Are receiving waters adjacent to the   | project free of any sig   | inificant signs of grosi   | on or sodiment that would   | h ha associated with th   | a construction  |
| activity?  | project nee of any sig  | initicant signs of erosi   | on or seament that would  |   | le construction   |
| Yes  |   |  |   |   |   |
|  |   |  |   |   |   |
| Create Corrective Action?  |   |  |   |   |   |
| N/A  |   |  |   |   |   |
| Have disturbed areas been seeded of adequate or needed to prevent erosi  |   | as required? List inac   | tive portions of the projec   | ct and if stabilization n   | neasures are  |
| Yes  |   |  |   |   |   |
| Create Corrective Action?  |   |  |   |   |   |
| N/A  |   |  |   |   |   |
|  |   |  |   |   |   |
| Are waste materials (concrete, const   | truction material, haza   | rdous, etc.) being man   | aged properly?  |   |   |
| Yes  |   |  |   |   |   |
| Create Corrective Action?  |   |  |   |   |   |
| N/A  |   |  |   |   |   |
|  |   |  |   |   |   |
| Are construction entrances and adja  | cent streets being ma   | intained adequately?   |   |   |   |
| Yes  | Som areera beilig illd  | mamen avequatery ?   |   |   |   |
| Create Corrective Action?  |   |  |   |   |   |
| N/A  |   |  |   |   |   |
|  |   |  |   |   |   |
|  |   |  |   |   |   |
| Is dust associated with the construct  | tion activity adequate  | y controlled on the site   | e?  |   |   |
| Yes  |   |  |   |   |   |
| Create Corrective Action?  |   |  |   |   |   |
| N/A  |   |  |   |   |   |
|  |   |  |   |   |   |

## Comments:

## Comments:

The site was inactive during the most recent inspection. The storage units are open and operating.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance required in BMP Section.

| Unique Name                | Туре                    | Location                    | Projected Install Date                   | Status                      | Maintenance              |
|----------------------------|-------------------------|-----------------------------|--|-----------------------------|--------------------------|
| CE1                        | Construction Entrance   | N. 156th Street             |  | Removed                     |                          |
| Current Condition:         |                         |                             | e was removed prior to the               |                             |                          |
|                            |                         |                             |  |                             |                          |
| CE 2                       | Construction Entrance   |                             |  | Removed                     |                          |
| Current Condition:         |                         | -                           | ance prior to the inspection             |                             |                          |
| CW 1<br>Current Condition: | Concrete Washout        | On Site                     | complete as of 11/6/19. Fu               | Removed                     | bandlad on a lat by      |
| Current Condition.         | lot basis.              | in level pavilig appears    |  |                             |                          |
| D 1                        | Diversion               | North side of Site          |  | Removed                     |                          |
| Current Condition:         | Removed - The diversion | on has silted in, but due   | to heavy vegetation is no lo             | onger needed as of the      | inspection on 5/22/18.   |
|                            |                         |                             |  |                             |                          |
|                            | <b>D</b>                |                             |  |                             |                          |
| D 2                        | Diversion               | South East site of Site     | ta haavavaatatian is na k                | Removed                     | noncotion on 5/00/40     |
| Current Condition:         | Removed - The diversion | on has silled in, but due   | to heavy vegetation is no lo             | onger needed as of the      | inspection on 5/22/16.   |
| D 3                        | Diversion               | South side of site          |  | Removed                     |                          |
| Current Condition:         |                         |                             | led the diversion is no long             |                             | L<br>Dection on 5/22/18. |
| D 4                        | Diversion               | North of SB 2               |  | Removed                     |                          |
| Current Condition:         | Removed - Due to the    | storm sewer being insta     | led the diversion is no long             | er needed as of the insp    | Dection on 4/18/19.      |
|                            | Erosion Control         |                             |  |                             |                          |
| EC 1                       | Transition Matting      | Outfall of SB 1             | 4/14/2022                                | Active                      | No                       |
| Current Condition:         |                         | f McGregor installed the    | Shoremax Transition Mat a                | it the outfall of SB 1 pric | or to the inspection on  |
|                            | 4/14/22.                |                             |  | 1                           |                          |
| EM 1                       | Erosion Control         | SE corner of site           | 3/26/2018                                | Active                      | No                       |
| Current Condition:         | Matting                 |                             | and matted the slopes arour              |                             | No<br>No 8/10/18         |
| Current Condition.         | Erosion Control         |                             |  |                             |                          |
| EM 2                       | Matting                 | South side of site          | 8/21/2017                                | Active                      | No                       |
| Current Condition:         | Good Condition - Prairi | e Construction installed    | erosion control matting pric             | or to the inspection on 8   | /21/17.                  |
|                            | Erosion Control         |                             |  |                             |                          |
| EM 3                       | Matting                 | SW corner of site           | 8/21/2017                                | Active                      | No                       |
| Current Condition:         |                         | e Construction installed    | erosion control matting pric             | or to the inspection on 8   | /21/17.                  |
| EM 4                       | Erosion Control         | West side of site           | 8/21/2017                                | Active                      | No                       |
| Current Condition:         | Matting                 |                             | erosion control matting pric             |                             |                          |
|                            | Erosion Control         |                             |  |                             |                          |
| EM 5                       | Matting                 | NW corner of site           | 8/16/2016                                | Active                      | No                       |
| Current Condition:         | Good Condition - Prairi | e Construction installed    | erosion control matting pric             | or to the inspection on 8   | /21/17.                  |
|                            | Erosion Control         |                             |  |                             |                          |
| EM 6                       | Matting                 | North side of site          | 7/13/2017                                | Active                      | No                       |
| Current Condition:         |                         | Construction installed      | erosion control matting prior            | r to the inspection on 11   | /10/18.                  |
|                            | Erosion Control         | North state of star         | 7/40/0047                                | A                           | NL.                      |
| EM 7                       | Matting                 | North side of site          | 7/13/2017<br>the erosion control matting | Active                      | No                       |
| Current Condition:         | Erosion Control         |                             |  |                             |                          |
| EM 8                       | Matting                 | East side of site           |  | Removed                     |                          |
| Current Condition:         |                         |                             | ne report. It is not present o           |                             | I                        |
|                            |                         |                             | . ,                                      |                             |                          |
| IP 1                       | Inlet Protection        | SE corner of buildings      |  | Removed                     |                          |
| Current Condition:         | Removed - All areas th  | at drain to the inlet are s | tabilized/paved as of 4/11/              | 19.                         |                          |
|                            |                         | 1                           |  | 1                           | 1                        |
| IP 2                       | Inlet Protection        | SE corner of buildings      |  | Removed                     |                          |

| No<br>e area is paved                                 |
|---|
| e area is paved                                       |
|   |
| led and matted  |
|   |
|   |
|   |
| ion in the area,                                      |
|   |
|   |
| ion in the area,                                      |
|   |
|   |
| ion in the area,                                      |
|   |
|   |
| ion in the area,                                      |
|   |
|   |
|   |
|   |
| area, reinstalla                                      |
|   |
| No  |
| off McGregor  |
| McGregor pair<br>ior to the 7/17/                     |
|   |
| 7   |
| 7.  |
| No  |
| 7. Geoff McGre  |
| No  |
| NO INC  |
| 7   |
| 17.   |
| No  |
| No<br>17.   |
| No<br>17.<br>No                                       |
| No<br>17.   |
| No<br>17.<br>No                                       |
| No<br>17.<br>No<br>17. The silt trap                  |
| No<br>17.<br>No                                       |
| No<br>17.<br>No<br>17. The silt trap                  |
| No<br>17.<br>No<br>17. The silt trap<br>inspection on |
| No<br>17.<br>No<br>17. The silt trap                  |
| e eff   |

| Current Condition: |   | nterior streets were clean<br>s was free of sediment du  |  | •  |   |
|--------------------|---|--|--|--|---|
| SWPPP Sign         | SWPPP Sign  | N. 156th Street  | 6/24/2017  | Active   | No  |
| Current Condition: | Good Condition - The i                            | inspector installed the SW   | PPP sign prior to the insp                             | ection on 9/5/17.                                  |   |
|                    | submitted. Based on m<br>for gathering the inform | tem designed to assure th<br>ny inquiry of the person or<br>nation, the information sub<br>that there are significant p<br>knowing violations. | persons who manage the<br>omitted is, to the best of m | system or those person<br>by knowledge and belief, | s directly responsib<br>true, accurate, and |
|                    |   |  |  |  |   |