E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services De	pt. Manager			cnymeering Ansi	vers
		E&A - P201	9.328.000		
Inspector: Jason Brackett					Stage
		Bridgenor	t Development		e to ge
		• • •			
			228-3910-GP1		1
Project Name:		CSW-2	201701381		
For Week Ending:		10/	10/2020		68136
	SW of Co		S 180th Street, Sarpy Coun	47 NE	
Project Location:	3000100		13 Tooth Street, Sarpy Coun	ty, NE	
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	95%				
Seeding:	75%				
Utilities:	100%				
Overall Development:	60%				
F					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				HCCK
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	10/7/2020	Mostly Sunny 85/51	11:15 AM	
Thursday:	0.00"	10///2020	Wostly Sunny 85/51		
Friday:	0.00"				
Saturday:	0.00"				
outurday.	0.00				
Complaints:	None				
Construction Sequencing:					
	ins) of the site have had a tempo	rary or permanent cessa	tion of grading, earthwork, or grou	nd disturbance in the last	14 days?
Grading in Phase I was comp	leted prior to E&A being hire	ed to conduct SWPP	P inspections (1/3/20).		
	· · ·		· · · ·		
Which portion(s) (i.e. drainage bas	ins) of the site do not have gradi	ng, earthwork, or ground	d disturbance scheduled in the next	t 14 days?	
Grading in Phase I was comp	leted prior to E&A being hire	ed to conduct SWPP	P inspections (1/3/20).		
What temporary or permanent stat					
•	being hired to conduct SWF	PPP inspections (1/3/	20). Trails/sidewalks around	the site were backfilled	d and partially matted
(4/9/2020).					
Checklist Questions:					
· · ·	ne project free of any significant s	signs of erosion or sedin	nent that would be associated with	the construction activity?	
Yes					
Create Corrective Action? N/A					
Have disturbed areas been seeded	or otherwise stabilized as requir	red? List inactive portion	is of the project and if stabilization	measure are adequate or	needed to prevent erosion.
	te were seeded and partially	matted prior to the 4	/27/20 inspection, the inspecto	or will monitor growth.	
Create Corrective Action?					
No, See Findings section.					
Are weete materials (otwotion metarial barrates	a) being menors if an	and and a second s		
Are waste materials (concrete, con	istruction material, hazardous, et	c.) being managed prope	eriy r		
No Create Corrective Action?					
No, See BMPs and Findings	section.				
Jan Start St					
Are construction entrances and ad	ljacent streets being maintained a	adequately?			
No					

Create Corrective Action?

No, See BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action? N/A

1.1,7.1

Comments:

Comments: Site was active for homebuilding during the most recent inspection.

Civil development and some homebuilding was completed prior to E&A being hired to conduct SWPPP inspections on 1/3/20.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

2) All inactive areas of the site that have no planned ground disturbance within 14 days need to be stabilized.

A. Overgraded lots during homebuilding need to be stabilized. *As of 5/18/20 the builders who need to stabilize are Hildy Homes (Lot 18/87), Colony Custom (Lot 73), Belt (Lot 126), Vencil (Lot 95). As of the 6/10/20 inspection, this finding also includes disturbed lots 148-150. All builders were informed to complete by 1/17/20 when weather allows and as-needed. Not done as of the last inspection. All builders were reminded on 5/19/20, 8/5/20. B. Void areas south of Camelback Ave need to be stabilized and erosion at the southwest section of the wetland needs to be repaired and stabilized.

Gene Graves was informed to complete by 6/1/20. Not done as of the last inspection. Gene Graves was reminded on 6/12/20. Void areas along the south of Camelback have been removed as of the 9/9/20 inspection due to active grading of the property to the south.

3) Trash dumpsters on site need to be emptied if they are above the fill line and trash needs to be picked up to prevent trash and debris from blowing around the site. All builders were informed to complete by 2/12/20. Not done as of the last inspection. All builders were reminded on 5/19/20, 6/20/20, 8/5/20.

A. Trash needs to be picked up around the site. Gene Graves was informed to complete by 5/25/20. Not done as of the last inspection. Gene Graves was reminded on 6/12/20.

4) CIR 12854 was received, reviewed, and forwarded to Gene Graves on 9/16/20. CIR findings are inconsistent with E&A inspector's report, see below for current findings.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
AI 1	Area Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 2, to prevent flooding the inlet protection will not be reinstalled.					
AI 2	Area Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 2, to prevent flooding the inlet protection will not be reinstalled.					
AI 3	Area Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - The area inlet inspection.	protection is now includ	ed with the new grading proje	ect to the south of Brid	geport as of the 9/9	
AI 4	Area Inlet Protection	See SWPPP	3/12/2020	Active	No	
Current Condition:			0 inspection. To prevent floo W is recommended in the fine		let protection will be	
AI 5	Area Inlet Protection	See SWPPP	8/12/2020	Active	No	
Current Condition:	Good Condition - The area installed around the inlet p		eeded/matted prior to the 4/23 ection.	3/20 inspection. A silt	fence wrap was	
AI 6	Area Inlet Protection	See SWPPP		Removed		
Current Condition:	Removed - The area arou	nd the inlet was seeded	/matted prior to the 4/23/20 ir	spection.		
	Stabilized Construction	Cornhusker and S				
CE 1	Entrance	181st Street	1/10/2020	Pending	No	
Current Condition:	entrance. The inspector v		unty Road project will start so continue to recommend stree			
	inspection.					
CE 2	Stabilized Construction Entrance	Cornhusker and S 184th Street	1/10/2020	Pending	Yes	
CE 2 Current Condition:	Stabilized Construction Entrance Pending - Commercial Se event that the entrance is The entrance needs to be	184th Street eding closed off the entr improperly used in the f further closed off. *A s ed to complete by 5/25/2	rance prior to the 4/15/20 insp	ack Ave should be ins	ain on this report in	

	began cleaning out the concrete washout prior to the 6/16/20 inspection, the inspector will continue to monitor. Comm Seeding finished cleaning out the washout prior to the 6/19/20 inspection. Gene Graves cleaned out the concrete was
	prior to the 9/22/20 inspection.
	Rock needs to be added to the approach for the concrete washout to prevent trackout when in use.
	Gene Graves was informed to complete by 1/10/20. Not done as of the last inspection. Commercial Seeding was hire complete maintenance on 4/9/20. Commercial Seeding was reminded on 4/24/20, 6/10/20.
IP 1	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 2	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 3	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
IP 4	prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 5	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 6	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 7	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 8	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 9	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 10	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 11	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroun area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 12	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroun area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 13	Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroun
Current Condition:	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 14 Current Condition:	Inlet Protection See SWPPP Removed Removed
	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroun area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 15 Current Condition:	Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surroun
IP 16	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed. Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/12/20 inspection. Inlet drains to a basin and the surrou
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 17 Current Condition:	Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/12/20 inspection. Inlet drains to a basin and the surrou
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 18	Inlet Protection See SWPPP Removed Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled. See SW 3.
IP 19 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to SB 1, to
Carrent Condition.	prevent flooding the inlet protection will not be reinstalled. See SW 3.

Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S prevent flooding the inlet protection will not be reinstalled.	JD 4, 10
IP 21	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 4, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 22 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S See SWPPP	P 4 to
Current Condition.	prevent flooding the inlet protection will not be reinstalled.	56 4, 10
IP 23	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 4, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 24	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S prevent flooding the inlet protection will not be reinstalled.	5B 4, to
IP 25	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 4, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 26	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 4, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 27 Current Condition:	Inlet Protection See SWPPP Removed Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S See SWPPP	BA to
Current Condition.	prevent flooding the inlet protection will not be reinstalled.	, io
IP 28	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 4, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 29	Inlet Protection See SWPPP 1/3/2020 Active	No
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding mair inlet protection prior to the 4/23/20 inspection.	itained the
IP 30	Inlet Protection See SWPP 1/3/2020 Active	No
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding mair	-
	inlet protection prior to the 4/23/20 inspection.	
IP 31	Inlet Protection See SWPPP 1/3/2020 Active	No
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding main	
IP 32	inlet protection prior to the 4/23/20 inspection. Sudbeck cleaned out the inlet protection prior to the 8/5/20 ins Inlet Protection See SWPPP 1/3/2020 Active	No
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding mair	
Current Contation.	inlet protection prior to the 4/23/20 inspection. Sudbeck cleaned out the inlet protection prior to the 8/5/20 inspection.	
IP 33	Inlet Protection See SWPPP 1/3/2020 Active	No
Current Condition:	Good Condition - Curb inlet protection was installed prior to the 1/3/20 inspection. Commercial Seeding mair	
	inlet protection prior to the 4/23/20 inspection. Sudbeck cleaned out the inlet protection prior to the 8/5/20 ins	spection.
IP 34	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S prevent flooding the inlet protection will not be reinstalled.	SB 5, 10
IP 35	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 5, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 36	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 5, to
IP 37	prevent flooding the inlet protection will not be reinstalled. Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 5 to
	prevent flooding the inlet protection will not be reinstalled.	
IP 38	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 5, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 39	Inlet Protection See SWPPP Removed	
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S	SB 5, to
	prevent flooding the inlet protection will not be reinstalled.	
IP 40	Inlet Protection See SWPPP Removed Removed	BE to
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to S prevent flooding the inlet protection will not be reinstalled.	DD D, TO
IP 41		
Current Condition:	Inlet Protection See SWPPP Removed Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the	e surroun
C C C C C C C C C C C C C C C C C C C	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.	

Current Condition:		•	prior to the 8/5/20 inspectio		asin and the surround
	area is relatively stabilize	-	lushing of the storm sewer w	vill occur as needed.	-
IP 43	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - IP 43 drains to		on is needed at this time.	1	
IP 44	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - IP 44 drains to				
IP 45	Inlet Protection	See SWPPP	8/5/2020	Active	No
Current Condition:			ections prior to the 8/5/20 ins		
Lot 1 Replat 1	Individual Lot	Lot 1 Replat 1		Removed	
Current Condition:	Removed - PHI sodded th) inspection.		
Lot 1	Individual Lot	Lot 1		Removed	
Current Condition:			ortable toilet and sodded t		
Lot 1 Replat 2	Individual Lot	Lot 1 Replat 2	8/20/2020	Active	No
Current Condition:		-	avation of the pool area prio		ction. SF 4 is in plac
			eplat 2 as of the 8/20/20 insp		
Lot 8	Individual Lot	Lot 8		Removed	
Current Condition:			rior to the 9/22/20 inspection		
Lot 8 Replat 1	Individual Lot	Lot 8 Replat 1	2/5/2020	Active	No
Current Condition:			n the lot prior to the 2/5/20 in	nspection. Fools Inc. i	installed silt fence in
	rear of the lot prior to the		1	1	
Lot 18	Individual Lot	Lot 18		Removed	
Current Condition:	Removed - Hildy Homes	sodded the lot prior to th	e 5/13/20 inspection.		
Lot 27	Individual Lot	Lot 27	1/3/2020	Active	Yes
Current Condition:	Fair Condition - Mercury	Contractors began const	ruction on the lot prior to the	1/3/20 inspection. N	Nercury Contractors
			ed. *Straw wattles would als	o be adequate sedim	ent control for the no
	side of the lot along the b	asin.	ed. *Straw wattles would als		
	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v	asin. nce should be installed i vere informed to comple 10, 9/17/20.		ent off-site discharge, of the last inspection.	or the lot should be Mercury was remin
	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20.	asin. nce should be installed i vere informed to comple 10, 9/17/20. vere informed to comple	n the front of the lot to preve te by 1/10/20. Not done as o	ent off-site discharge, of the last inspection. of the last inspection.	or the lot should be Mercury was remin
Lot 34	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot	asin. nce should be installed i vere informed to comple 10, 9/17/20. vere informed to comple Lot 34	n the front of the lot to preve te by 1/10/20. Not done as a te by 6/17/20. Not done as a	ent off-site discharge, of the last inspection.	or the lot should be Mercury was remin
Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde	asin. nce should be installed i vere informed to comple 0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2	n the front of the lot to preve te by 1/10/20. Not done as o te by 6/17/20. Not done as o /20 inspection.	of the last inspection. of the last inspection. of the last inspection.	or the lot should be Mercury was remin Mercury was remin
Current Condition: Lot 51	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot	asin. nce should be installed i vere informed to comple 0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51	n the front of the lot to preve te by 1/10/20. Not done as t te by 6/17/20. Not done as t /20 inspection. 4/27/2020	of the last inspection. of the last inspection. of the last inspection. Removed Active	or the lot should be Mercury was remin Mercury was remin
Current Condition: Lot 51 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for so next regular inspection.	asin. nce should be installed i vere informed to comple 0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to od prior to the 9/30/20 in	n the front of the lot to preve te by 1/10/20. Not done as o te by 6/17/20. Not done as o /20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance G ecommend reinstalla	or the lot should be Mercury was remin Mercury was remin
Current Condition: Lot 51 Current Condition: Lot 59	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodd Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for su next regular inspection.	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot pri to the curb inlet prior to od prior to the 9/30/20 in Lot 59	n the front of the lot to preve te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance 0	or the lot should be Mercury was remin Mercury was remin Mercury was remin No silt fence in the front Group removed the s
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for su next regular inspection. Individual Lot Removed - Hildy Homes	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the	n the front of the lot to preve te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance (recommend reinstalla Removed	or the lot should be Mercury was remin Mercury was remin Mercury was remin No silt fence in the front Group removed the s
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors w on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors w on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for sinext regular inspection. Individual Lot Removed - Hildy Homes Individual Lot	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60	n the front of the lot to prevent te by 1/10/20. Not done as of te by 6/17/20. Not done as of /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance G ecommend reinstalla	or the lot should be Mercury was remin Mercury was remin Mercury was remin No silt fence in the front Group removed the s
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors w on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors w on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for sinext regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 sodded the lot prior to the	n the front of the lot to prevent te by 1/10/20. Not done as of te by 6/17/20. Not done as of /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection.	ont off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance G recommend reinstalla Removed Removed	or the lot should be Mercury was remin Mercury was remin
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for so next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot	asin. nce should be installed i vere informed to comple 10, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to Lot 64	n the front of the lot to prevente by 1/10/20. Not done as the by 6/17/20. Not done as a function of the by 6/17/20. Not done as a function of the 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will respection, the inspector will respect to a substant of the 7/1/20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance (recommend reinstalla Removed	or the lot should be Mercury was remin Mercury was remin
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for so next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot	asin. nce should be installed i vere informed to comple 10, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to Lot 64 s sodded the lot prior to	n the front of the lot to prevent te by 1/10/20. Not done as of te by 6/17/20. Not done as of /20 inspection. /20 inspection. /20 inspection. Lan /20 inspection. Lan /20 inspection. Lan /20 inspection. Lan /20 inspection. //20 inspection. ///20 inspection. ///20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance C recommend reinstalla Removed Removed	or the lot should be Mercury was remin Mercury was remin Mercury was remin No silt fence in the front Group removed the s tion if not sodded by
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 64 Current Condition: Lot 66	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot	asin. nce should be installed i vere informed to comple 10, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to Lot 64 s sodded the lot prior to Lot 66	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. /20 inspection.	of the last inspection. of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance C recommend reinstalla Removed Removed Removed Active	or the lot should be Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mo
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for so next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to Lot 64 s sodded the lot prior to Lot 66 tter Homes began const ear of the lot prior to the	n the front of the lot to prevent te by 1/10/20. Not done as of te by 6/17/20. Not done as of te by 6/17/20. Not done as of //20 inspection. //20 inspection. Lan //20 inspection. Lan //20 inspection. Lan //20 //20 //20 //20 //20 //20 //20 //2	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance C recommend reinstalla Removed Removed Removed Active 6/1/20 inspection. P	or the lot should be Mercury was remin Mercury was remin Mercury was remin No silt fence in the front Group removed the s tion if not sodded by
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition: Lot 66 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to o prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to Lot 64 s sodded the lot prior to Lot 66 tter Homes began const ear of the lot prior to the Lot 67	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. /20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance O recommend reinstalla Removed Removed Removed 6/1/20 inspection. P	or the lot should be Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mo silt fence in the front Soup removed the state in the front soup removed the soup removed th
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to to the curb inlet prior to the sodded the lot prior to the Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to Lot 66 tter Homes began const ear of the lot prior to the Lot 67 entified builder began existed ear of the lot prior to the Lot 67	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a //20 inspection. //20 inspection. //20 inspection. //20 inspection. //20 inspection. //20 inspection. //20 inspection. ///20 inspection. ////20 inspection. ////20 inspection. ////20 inspection. ////20 inspection. ////20 inspection. /////20 inspection. /////20 inspection. /////20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance O recommend reinstalla Removed Removed Removed 6/1/20 inspection. P	or the lot should be Mercury was remin Mercury was remin Mercury was remin I I I Soup removed the stion if not sodded by I I I I I No Pacesetter Homes No
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition: Lot 67 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to to the curb inlet prior to the sodded the lot prior to the Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to Lot 66 tter Homes began const ear of the lot prior to the Lot 67 entified builder began existed ear of the lot prior to the Lot 67	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a //20 inspection. //20 inspection. //20 inspection. //20 inspection. //20 inspection. //20 inspection. //20 inspection. ///20 inspection. ////20 inspection. ////20 inspection. ////20 inspection. ////20 inspection. ////20 inspection. /////20 inspection. /////20 inspection. /////20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance O recommend reinstalla Removed Removed Removed 6/1/20 inspection. P	or the lot should be Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mo silt fence in the front Soup removed the state in the front soup removed the soup removed th
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition: Lot 67 Current Condition: Lot 67 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r Individual Lot	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to the Lot 66 tter Homes began const ear of the lot prior to the Lot 67 entified builder began ex- ear of the lot prior to the Lot 70	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection. the 7/1/20 inspection. 6/1/2020 ruction on the lot prior to the 6/10/20 inspection. 7/1/2020 xcavation of the lot prior to the 7/1/20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance G recommend reinstalla Removed Removed Removed Active 6/1/20 inspection. P Active ne 7/1/20 inspection.	or the lot should be Mercury was remine Mercury was remine Mercury was remine Mercury was remine Mercury was remine Mo silt fence in the front Sroup removed the s tion if not sodded by
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition: Lot 67 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r	asin. nce should be installed i vere informed to comple (0, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to the curb inlet prior to od prior to the 9/30/20 in Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to the Lot 66 tter Homes began const ear of the lot prior to the Lot 67 entified builder began ex- ear of the lot prior to the Lot 70	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection. the 7/1/20 inspection. 6/1/2020 ruction on the lot prior to the 6/10/20 inspection. 7/1/2020 xcavation of the lot prior to the 7/1/20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance G recommend reinstalla Removed Removed Removed Active 6/1/20 inspection. P Active ne 7/1/20 inspection.	or the lot should be Mercury was remine Mercury was remine Mercury was remine Mercury was remine Mercury was remine Mo silt fence in the front Sroup removed the s tion if not sodded by
Current Condition: Lot 51 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 64 Current Condition: Lot 66 Current Condition: Lot 67 Current Condition: Lot 70 Current Condition:	side of the lot along the b 2.) Straw wattles or silt fe sodded. 1.) Mercury Contractors v on 3/6/20, 5/19/20, 6/11/2 2.) Mercury Contractors v on 9/17/20. Individual Lot Removed - McCaul sodde Individual Lot Active - Landmark began corner of the lot adjacent fence in preparation for si- next regular inspection. Individual Lot Removed - Hildy Homes Individual Lot Removed - Kavan Homes Individual Lot Removed - Kavan Homes Individual Lot Good Condition - Pacese installed silt fence in the r Individual Lot Good Condition - An unid installed silt fence in the r Individual Lot Removed - Kavan Homes Individual Lot	asin. nce should be installed i vere informed to comple 10, 9/17/20. vere informed to comple Lot 34 ed the lot prior to the 9/2 Lot 51 excavation of the lot prior to to the curb inlet prior to the Act 59 sodded the lot prior to the Lot 59 sodded the lot prior to the Lot 60 s sodded the lot prior to the Lot 64 s sodded the lot prior to the Lot 66 tter Homes began const ear of the lot prior to the Lot 67 entified builder began ex- ear of the lot prior to the Lot 70 s sodded the lot prior to the Lot 70 s sodded the lot prior to the Lot 70 s sodded the lot prior to the Lot 73	n the front of the lot to prevent te by 1/10/20. Not done as a te by 6/17/20. Not done as a /20 inspection. 4/27/2020 or to the 4/27/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection. Lan ispection, the inspector will r e 8/20/20 inspection. the 7/1/20 inspection. 6/1/2020 ruction on the lot prior to the 6/10/20 inspection. 7/1/2020 xcavation of the lot prior to the 7/1/20 inspection.	ent off-site discharge, of the last inspection. of the last inspection. Removed Active Landmark installed s dmark Performance O recommend reinstallad Removed Removed Active e 6/1/20 inspection. P Active ne 7/1/20 inspection. Removed Removed	or the lot should be Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mercury was remin Mo silt fence in the front Soup removed the state in the front soup removed the soup removed th

	Pending - Nielsen Custom installed silt fence in the re for installation of the retain	ear of the lot prior to the	ion of the lot prior to the 4/23 4/23/20 inspection. Nielsen 6/20 inspection.	3/20 inspection. Nielsen removed the silt fence	Custom Homes in the rear of the lo
	1.) The portable toilet nee 2.) Silt fence needs to be r		om the curb inlet. e of the retaining wall below t	the disturbed ground.	
	on 9/17/20.		plete by 6/8/20. Not done as plete by 9/23/20. Not done a		lielsen was reminc
Lot 82	Individual Lot	Lot 82	7/23/2020	Active	No
Current Condition:	the lot prior to the 8/12/20 installation of the retaining	inspection, the silt fence g wall, the inspector will r	rior to the 7/23/20 inspectior e is not behind all of the grou monitor. Landmark Perform 0 inspection, the inspector w	and disturbance to make ance Group removed th	e room for the e silt fence for
Lot 86	Individual Lot	Lot 86	7/23/2020	Active	No
Current Condition:	adequate perimeter protect		n on the lot prior to the 7/23/ spection and will now be att	ributed to Hildy Homes.	ting SF 4 in the are
Lot 87	Individual Lot	Lot 87		Removed	
Current Condition:	Removed - Hildy Homes s	-	-	· · ·	
Lot 89	Individual Lot	Lot 89	7/23/2020	Active	No
Current Condition:	the lot, maintenance to the	e silt fence in the area w	n on the lot prior to the 7/23/2 rill be recommended to Hildy	Homes as of the 7/23/2	0 inspection.
Lot 91	Individual Lot	Lot 91	4/1/2020	Active	No
Current Condition:	SF 4 in the rear, any new	maintenance to SF 4 in	construction on the lot prior the area will be sent to Adva	intage Development as	
Lot 93	Individual Lot	Lot 93		Removed	
Current Condition:			r to the 9/22/20 inspection.	A ative	Na
Lot 94 Current Condition:	Individual Lot	Lot 94	1/3/2020 n the lot prior to the 1/3/20 ir	Active	No stalled silt force in
Lot 95	of the lot prior to the 4/27/ the 9/16/20 inspection, the Individual Lot		mage to the silt fence in the	front corner of the lot war	as observed durin
Current Condition:	Removed - Vencil sodded	the lot prior to the 4/23/	20 inspection.	•	
Lot 100	Individual Lot	Lot 100	9/30/2020	Active	No
Current Condition:			e lot prior to the 9/30/20 insp onitor for removal and the in		observed in the R
Lot 119 Current Condition:	Individual Lot	Lot 119	2/18/2020 on the lot prior to the 2/18/2	Active	Yes
	fence along the rear and r 1.) Silt fence or straw watt	ear corners of the lot an	lot, street cleaning will be re id cleaned the sidewalk prior		
	 3.) The sidewalk needs to 1.) Ideal was informed to a 9/17/20. 2.) Ideal was informed to a 	ar of the lot is damaged/ be cleaned. complete by 4/8/20. Not complete by 6/17/20. Not	d along the sidewalk. /undermined and needs to be t done as of the last inspection of done as of the last inspect of done as of the last inspect	on. Ideal was reminded	on 5/19/20, 6/11/2
Lot 126	 3.) The sidewalk needs to 1.) Ideal was informed to a 9/17/20. 2.) Ideal was informed to a 3.) Ideal was informed to a Individual Lot 	ar of the lot is damaged/ be cleaned. complete by 4/8/20. Not complete by 6/17/20. Not complete by 9/17/20. Not Lot 126	undermined and needs to be t done as of the last inspection of done as of the last inspect of done as of the last inspect	on. Ideal was reminded	on 5/19/20, 6/11/2
Current Condition: Lot 128	 3.) The sidewalk needs to 1.) Ideal was informed to o 9/17/20. 2.) Ideal was informed to o 3.) Ideal was informed to o Individual Lot Removed - Belt Construct Individual Lot 	ar of the lot is damaged/ be cleaned. complete by 4/8/20. Not complete by 6/17/20. Not complete by 9/17/20. Not Lot 126 tion sodded the lot prior Lot 128	undermined and needs to be t done as of the last inspection of done as of the last inspect of done as of the last inspect to the 5/6/20 inspection.	on. Ideal was reminded tion. Ideal was reminde	on 5/19/20, 6/11/2
Current Condition: Lot 128 Current Condition:	 3.) The sidewalk needs to 1.) Ideal was informed to a 9/17/20. 2.) Ideal was informed to a 3.) Ideal was informed to a 3.) Ideal was informed to a Individual Lot Removed - Belt Construct Individual Lot Removed - Belt Construct Removed - Belt Construct 	ar of the lot is damaged/ be cleaned. complete by 4/8/20. Not complete by 6/17/20. Not complete by 9/17/20. Not Lot 126 tion sodded the lot prior Lot 128 tion sodded the lot prior	undermined and needs to be t done as of the last inspection of done as of the last inspect of done as of the last inspect to the 5/6/20 inspection.	on. Ideal was reminded ion. Ideal was reminded ion. Removed Removed	on 5/19/20, 6/11/2 d on 9/17/20.
Current Condition: Lot 128	 3.) The sidewalk needs to 1.) Ideal was informed to a 9/17/20. 2.) Ideal was informed to a 3.) Ideal was informed to a 3.) Ideal was informed to a 1.1 dividual Lot Removed - Belt Construct Individual Lot Removed - Belt Construct Individual Lot Removed - Belt Construct Individual Lot SF 4 in the rear, any new inspection. The silt fence 	ar of the lot is damaged/ be cleaned. complete by 4/8/20. Not complete by 6/17/20. Not complete by 9/17/20. Not Lot 126 Lot 128 tion sodded the lot prior Lot 131 onstruction builder begat maintenance to SF 4 in 1 in the rear of the lot was as of the 9/16/20 inspect	/undermined and needs to be t done as of the last inspection of done as of the last inspect of done as of the last inspect of done as of the last inspect to the 5/6/20 inspection. 4/23/2020 n excavation of the lot prior f the area will be sent to the b s maintained prior to the 9/16 ion. Carder Construction m	on. Ideal was reminded tion. Ideal was reminded tion. Removed Removed Active o the 4/23/20 inspectior uilder when identified as 5/20 inspection. Wattles	on 5/19/20, 6/11/2 d on 9/17/20. <u>Yes</u> 1. The lot backs u s of the 4/23/20 s do not appear
Current Condition: Lot 128 Current Condition: Lot 131	 3.) The sidewalk needs to 1.) Ideal was informed to a 9/17/20. 2.) Ideal was informed to a 3.) Ideal was informed to a 3.) Ideal was informed to a 1.1 Ideal was informed to a 3.) Ideal was informed to a 4.) Ideal was informed to a 5.) Ideal was informed to a 5.) Ideal was informed to a 6.) Ideal was informed to a 7.) Ideal was informed to a	ar of the lot is damaged/ be cleaned. complete by 4/8/20. Not complete by 6/17/20. Not complete by 9/17/20. Not Lot 126 tion sodded the lot prior Lot 128 tion sodded the lot prior Lot 131 onstruction builder began maintenance to SF 4 in in the rear of the lot was as of the 9/16/20 inspect tion, the portable toilet s the the rear of the lot and ds to be secured.	Aundermined and needs to be to done as of the last inspection of done as of the last inspection of done as of the last inspect of done as of the last inspect to the 5/6/20 inspection. 4/23/2020 n excavation of the lot prior to the area will be sent to the b s maintained prior to the 9/16 ion. Carder Construction mo- still needs to be patched.	on. Ideal was reminded tion. Ideal was reminded tion. Removed Removed Active o the 4/23/20 inspectior uilder when identified as 5/20 inspection. Wattles	on 5/19/20, 6/11/ d on 9/17/20. <u>Yes</u> 1. The lot backs u s of the 4/23/20 s do not appear

Lot 134	Individual Lot	Lot 134	0/5/00 in an a sti	Removed	
Current Condition:	Removed - Silverthorn so		8/5/20 inspection.		
Lot 135	Individual Lot	Lot 135		Removed	
Current Condition:	Removed - Landmark soc			1	
Lot 137	Individual Lot	Lot 137	5/6/2020	Active	Yes
Current Condition:	Fair Condition - HBC Hor	nes began construction (on the lot and installed silt fe	ence in the rear prior to	the 5/6/20 inspec
	2.) The portable toilet nee 1.) HBC was informed to a	ds to be moved 50 feet complete by 6/17/20. No	cleaned out/repaired and ex from the nearest inlet. of done as of the last inspect done as of the last inspection	tion. HBC was remind	ed on 7/30/20, 9/1
	Oo dina ant Daain		4/0/0000	Antina	
SB 1 (Pond 5)	Sediment Basin	See SWPPP	1/3/2020	Active	Yes
Current Condition:	Basin is full and needs to	be cleaned out.	ed prior to the 1/3/20 inspect		iser.
SB 2 (Pond 4)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspec		
		See SWPPP	1/3/2020	Active	No
SB 3 (Pond 3)	Sediment Basin				
Current Condition:			ed prior to the 1/3/20 inspec 20 inspection, the plug is wo		riser. A plug was
SB 4 (Pond 2)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 43% fille	ed - The basin was insta	lled prior to the 1/3/20 inspe	ction with a permanen	t riser.
SB 5 (Pond 1)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 43% fille	ed - The basin was insta	lled prior to the 1/3/20 inspe	ction with a permanent	riser.
SF 1 Current Condition:	Silt fence	See SWPPP	fence prior to the 4/23/20 in	Removed	
SF 2	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		
SF 3	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		ng silt fence will b
	associated with Lot 64.				
SF 4	Silt fence	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - Silt fenc	e was installed around t	he wetlands and drainagewa	ays prior to the 1/3/20 i	nspection.
SF 5	Silt fence	See SWPPP		Removed	
Current Condition: SF 6	Removed - Commercial S Silt fence	Seeding removed the silt See SWPPP	fence prior to the 4/15/20 in	spection. Removed	
Current Condition:			fence prior to the 4/15/20 in		
SF 7	Silt fence	See SWPPP		Removed	
Current Condition:			new grading project to the s	south of Bridgeport as	of the 9/9/20 inspe
SF 8	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Silt fence was		/20 inspection.	•	
SF 9	Silt fence	See SWPPP		Removed	
Current Condition: SF 10	Removed - Commercial S Silt fence	Seeding removed the silt See SWPPP	fence prior to the 4/15/20 in	spection. Removed	
Current Condition:	Removed - Commercial S		fence prior to the 4/15/20 in		
SF 11	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Commercial S	Seeding removed the silt	fence prior to the 4/15/20 in		
SF 12	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		
SF 13	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in	spection.	
SF 14 Current Condition:	Silt fence Removed - The silt fence	See SWPPP is now included with the	new grading project to the s	Removed south of Bridgeport as	of the 9/9/20 inspe
014/4	0/2011/0/10/2011		4/0/0000	0 - 1 0 - 1 0 - 1	, Ni-
SW 1	Straw Wattles	See SWPPP	1/3/2020	Active	No
Current Condition:			the SW corner of Lot 39 pric		
SW 2 Current Condition:	Straw Wattles Good Condition - Straw w	See SWPPP attles were installed at t	4/9/2020 he base of the slope west of	Active SB 3 where matted pr	No ior to the 4/9/20
	inspection.	0.0000000			
0	Straw Wattles	See SWPPP	4/15/2020	Active	No
SW 3		and all One of the state of the state			
SW 3 Current Condition:	Good Condition - Comme to the 4/15/20 inspection.	rcial Seeding installed s	traw wattles above the curb	inlets adjacent to the c	oncrete washout p

Current Condition:	Fair Condition -							
	Minor street cleaning is needed around active lots.							
	All builders were informed	All builders were informed to complete by 8/6/20. Not done as of the last inspection.						
		Camelback Ave and S						
SWPPP Sign	Misc/Other	180th Street	1/29/2020	Active	No			
Current Condition:	Good Condition - E&A inspector installed 3 SWPPP signs at the intersection of S 180th Street and Laquinta Street, at the intersection of S 180th Street and Camelback Road, and at the intersection of Cornhusker Road and S 181st Street during the 1/29/20 inspection. E&A inspector relocated the SWPPP sign at the Laquinta Street entrance to the south side of the street during the 3/25/20 inspection.							
Inspector Signature:	Jule Month			Reviewed By:	Coto Sul			