E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services De	ept. Manager			Engineering Answ	
		E&A - P201	19.328.000		
Inspector: Jason Brackett					Stage
		Bridgeport	t Development		
		SAR-20161	1228-3910-GP1		1
Droject Name:			201701381		
Project Name:					20100
For Week Ending:			14/2020		68136
Project Location:	SW of Co	ornhusker Road and	I S 180th Street, Sarpy Cou	unty, NE	
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	95%				
Seeding:	75%				
Utilities:	100%				
Overall Development:	60%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	1.07"	11/10/2020	Cloudy 35/28	11:55 AM	
Wednesday:	0.06"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
	Ts.				
Complaints:	None				
I					
Construction Sequencing:					
Which portion(s) (i.e. drainage base	sins) of the site have had a temp	orary or permanent cessa	ation of grading, earthwork, or gro	ound disturbance in the last	14 days?
Grading in Phase I was comp	oleted prior to E&A being hir	ed to conduct SWPPI	P inspections (1/3/20).		
Miletele word out of the start	aluan at the alter de mat h		d distant as a sale dade di 100		
Which portion(s) (i.e. drainage base	· ·			ext 14 days?	
Grading in Phase I was comp	pleted prior to E&A being hir	ed to conduct SWPPI	P inspections (1/3/20).		

What temporary or permanent stabilization measures listed in this section are being implemented?

Site was seeded prior to E&A being hired to conduct SWPPP inspections (1/3/20). Trails/sidewalks around the site were backfilled and partially matted (4/9/2020).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

No. Void areas around the site were seeded and partially matted prior to the 4/27/20 inspection, the inspector will monitor growth.

Create Corrective Action?

No, See Findings section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, See BMPs and Findings section.

Are construction entrances and adjacent streets being maintained adequately?

Nο

Create Corrective Action?
No, See BMP section.
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A

## Comments:

Comments: Site was active for homebuilding during the most recent inspection.

Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) All inactive areas of the site that have no planned ground disturbance within 14 days need to be stabilized.
- A. Overgraded lots during homebuilding need to be stabilized. All builders were informed to complete by 1/17/20 when weather allows and as-needed. Not done as of the last inspection. All builders were reminded on 5/19/20, 6/20/20, 8/5/20.
- B. Void areas south of Camelback Ave need to be stabilized and erosion at the southwest section of the wetland needs to be repaired and stabilized. Gene Graves was informed to complete by 6/1/20. Not done as of the last inspection. Gene Graves was reminded on 6/12/20. Void areas along the south of Camelback have been removed as of the 9/9/20 inspection due to active grading of the property to the south.
- 3) Trash dumpsters on site need to be emptied if they are above the fill line and trash needs to be picked up to prevent trash and debris from blowing around the site. All builders were informed to complete by 2/12/20. Not done as of the last inspection. All builders were reminded on 5/19/20, 6/20/20, 8/5/20.
- A. Trash needs to be picked up around the site. Gene Graves was informed to complete by 5/25/20. Not done as of the last inspection. Gene Graves was reminded on 6/12/20.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenand		
AI 1	Area Inlet Protection	See SWPPP		Removed			
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 2, to						
	prevent flooding the inlet p	protection will not be rein	nstalled.				
Al 2	Area Inlet Protection	See SWPPP		Removed			
Current Condition:	Removed - Commercial S	Seeding removed the inle	et protection prior to the 4/23	/20 inspection. Inlet	drains to SB 2, to		
	prevent flooding the inlet p	protection will not be rein	nstalled.				
Al 3	Area Inlet Protection	See SWPPP		Removed			
Current Condition:	Removed - The area inlet	protection is now include	led with the new grading proj	ect to the south of Br	idgeport as of the		
	inspection.						
Al 4	Area Inlet Protection	See SWPPP	3/12/2020	Active	No		
Current Condition:	Active - Area inlet was ins	stalled prior to the 3/12/2	0 inspection. To prevent floo	oding of the area, no	inlet protection will		
			W is recommended in the fir				
AI 5	Area Inlet Protection	See SWPPP	8/12/2020	Active	No		
Current Condition:		a around the inlet was s	eeded/matted prior to the 4/2				
	installed around the inlet p	orior to the 8/12/20 inspe	ection.	'	,		
Al 6	Area Inlet Protection	See SWPPP		Removed			
Current Condition:	Removed - The area arou	ind the inlet was seeded	/matted prior to the 4/23/20 i	nspection.	<b>J</b>		
	Stabilized Construction	Cornhusker and S		•			
CE 1	Entrance	181st Street	1/10/2020	Pending	No		
Current Condition:	Pending - Due to the likely	y probability that the Cou	unty Road project will start so	on, rock is no longer	necessary at the		
	entrance. The inspector will monitor trackout and continue to recommend street cleaning as-needed as of the 3/12/20						
	inspection.						
	Stabilized Construction	Cornhusker and S					
CE 2	Entrance	184th Street	1/10/2020	Pending	Yes		
Current Condition:	Pending - Commercial Se	eding closed off the ent	rance prior to the 4/15/20 ins	pection. CE 2 will re	main on this repor		
	event that the entrance is	improperly used in the f	uture.				
	The entrance needs to be	further closed off. *A s	ign directing traffic to Camell	back Ave should be in	nstalled.		
	Cono Graves was informe	ad to complete by E/2E/2	20. Not done as of the last in	enaction Cons Grav	voc was reminded		
	6/12/20. All builders were		O. Not dolle as of the last in	spection. Gene Grav	res was reminueu		
0)/// 4			4/0/0000	A - 15			
CW 1 Current Condition:	Concrete Washout	Lot 56	1/3/2020 installed on Lot 56 prior to th	Active	Yes		
Current Condition.			· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
	began cleaning out the concrete washout prior to the 6/16/20 inspection, the inspector will continue to monitor. Commer Seeding finished cleaning out the washout prior to the 6/19/20 inspection. Gene Graves cleaned out the concrete washout prior to the 1/19/20 inspection.						
	prior to the 9/22/20 inspection.						
	Rock needs to be added to the approach for the concrete washout to prevent trackout when in use.						
	Gene Graves was informed to complete by 1/10/20. Not done as of the last inspection. Commercial Seeding was hired						
	complete maintenance on	4/9/20. Commercial Se	<mark>eeding was reminded on 4/2</mark> 4	1/20, 6/10/20.			
	complete maintenance on						
IP 1	Inlet Protection	See SWPPP	et protection prior to the 4/23,	Removed			

ID 0	
IP 2	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 3	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
Current Condition.	prevent flooding the inlet protection will not be reinstalled.
IP 4	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 5	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 6	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 7	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled.
IP 8	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
ID 0	prevent flooding the inlet protection will not be reinstalled.
IP 9	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
15.40	
IP 10	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to prevent flooding the inlet protection will not be reinstalled.
IP 11	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surrounding area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 12	
Current Condition:	Inlet Protection See SWPPP Removed  Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surrounding
Current Condition.	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 13	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surrounding
Ourient Condition.	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 14	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surrounding
Guitoiti Gorialion.	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 15	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/5/20 inspection. Inlet drains to a basin and the surrounding
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 16	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/12/20 inspection. Inlet drains to a basin and the surrounding
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 17	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Sudbeck removed the inlet protection prior to the 8/12/20 inspection. Inlet drains to a basin and the surrounding
	area is relatively stabilized. Street cleaning and flushing of the storm sewer will occur as needed.
IP 18	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled. See SW 3.
IP 19	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 1, to
	prevent flooding the inlet protection will not be reinstalled. See SW 3.
IP 20	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to
ID Of	prevent flooding the inlet protection will not be reinstalled.
IP 21	Inlet Protection   See SWPPP   Removed    Removed   Commercial Seeding removed the inlet protection prior to the 4/22/20 inspection, latet drains to SP 4 to
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to prevent flooding the inlet protection will not be reinstalled.
ID 00	
IP 22	Inlet Protection See SWPPP Removed  Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to
Current Condition:	prevent flooding the inlet protection will not be reinstalled.
IP 23	Inlet Protection See SWPPP Removed
Current Condition:	Removed - Commercial Seeding removed the inlet protection prior to the 4/23/20 inspection. Inlet drains to SB 4, to
Ourient Condition.	prevent flooding the inlet protection will not be reinstalled.
IP 24	Inlet Protection See SWPPP Removed
1	

Current Condition:	Removed - Commercial S		et protection prior to the 4/23	3/20 inspection. Inlet d	Irains to SB 4, to
IP 25	Inlet Protection	See SWPPP		Removed	
Current Condition:			et protection prior to the 4/23		Irains to SB 4, to
	prevent flooding the inlet p		nstalled.		
IP 26	Inlet Protection	See SWPPP		Removed	
Current Condition:	prevent flooding the inlet p		et protection prior to the 4/23 astalled.	720 inspection. Inlet o	Irains to SB 4, to
IP 27	Inlet Protection	See SWPPP		Removed	
Current Condition:			et protection prior to the 4/23	/20 inspection. Inlet d	Irains to SB 4, to
ID 00	prevent flooding the inlet p	ı	nstalled.	T 5 .	Τ
IP 28 Current Condition:	Inlet Protection  Removed - Commercial S	See SWPPP	t protection prior to the 4/23	Removed	Irains to SB 4 to
Ourient Condition.	prevent flooding the inlet	•	•	"20 mapeodon: miere	11 di 13 to 0D 4, to
IP 29	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspect	ion. Commercial See	ding maintained the
IP 30	inlet protection prior to the Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspect		
	inlet protection prior to the	4/23/20 inspection.			·
IP 31	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspect dbeck cleaned out the inlet p		
IP 32	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspect		
	<u> </u>		dbeck cleaned out the inlet p		8/5/20 inspection.
IP 33	Inlet Protection	See SWPPP	1/3/2020	Active	No
Current Condition:			ed prior to the 1/3/20 inspect dbeck cleaned out the inlet p		
IP 34	Inlet Protection	See SWPPP		Removed	
Current Condition:			et protection prior to the 4/23	/20 inspection. Inlet d	Irains to SB 5, to
15.05	prevent flooding the inlet p	1	nstalled.	T .	Т
IP 35 Current Condition:	Inlet Protection	See SWPPP	t protection prior to the 4/23	Removed	Irains to SR 5, to
Ourient Condition.	prevent flooding the inlet			"20 mapeodon: miere	inding to OD 0, to
IP 36	Inlet Protection	See SWPPP		Removed	
Current Condition:			et protection prior to the 4/23	3/20 inspection. Inlet d	Irains to SB 5, to
IP 37	prevent flooding the inlet protection	See SWPPP	istalled.	Removed	
Current Condition:			t et protection prior to the 4/23		Irains to SB 5, to
	prevent flooding the inlet p	protection will not be rein	nstalled.		
IP 38	Inlet Protection	See SWPPP		Removed	
Current Condition:	prevent flooding the inlet p		et protection prior to the 4/23	3/20 inspection. Inlet of	Irains to SB 5, to
IP 39	Inlet Protection	See SWPPP	iotaliou.	Removed	
Current Condition:			et protection prior to the 4/23		Irains to SB 5, to
	prevent flooding the inlet p	ı	nstalled.	_	
IP 40	Inlet Protection	See SWPPP	at musta stick muisu to the 4/00	Removed	reine to CD F. to
Current Condition:	prevent flooding the inlet		et protection prior to the 4/23 nstalled.	720 inspection. Inlet o	irains to SB 5, to
IP 41	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - Sudbeck removed	oved the inlet protection	prior to the 8/5/20 inspection	n. Inlet drains to a bas	in and the surrounding
	area is relatively stabilized	d. Street cleaning and fl	ushing of the storm sewer w	ill occur as needed.	
IP 42	Inlet Protection	See SWPPP		Removed	
Current Condition:			prior to the 8/5/20 inspection ushing of the storm sewer w		sin and the surrounding
IP 43	Inlet Protection	See SWPPP	l	Removed	
Current Condition:	Removed - IP 43 drains to		n is needed at this time.	1.cmoved	<u> </u>
IP 44	Inlet Protection	See SWPPP		Removed	
Current Condition:	Removed - IP 44 drains to	SB 5, no inlet protection See SWPPP		Activo	No
IP 45 Current Condition:	Inlet Protection Good Condition - Sudbeck		8/5/2020 ections prior to the 8/5/20 ins	Active pection.	No
Lot 1 Replat 1	Individual Lot	Lot 1 Replat 1	1 11 11 11 0/0/20 110	Removed	
Current Condition:	Removed - PHI sodded th		inspection.		
Lot 1 Current Condition:	Individual Lot	Lot 1	ble toilet and sodded the lot	Removed	spection
Lot 1 Replat 2	Individual Lot	Lot 1 Replat 2	8/20/2020	Active	No No
·	•	•		•	

		•	vation of the pool area prior plat 2 as of the 8/20/20 insp	•	ion. SF 4 is in place in
Lot 8	Individual Lot	Lot 8		Removed	
Current Condition:			ior to the 9/22/20 inspection.		
Lot 8 Replat 1	Individual Lot	Lot 8 Replat 1	- 44/40/20 increation	Removed	
Current Condition: Lot 18	Removed - Fools Inc soo Individual Lot	Lot 18	e 11/10/20 inspection.	Removed	
Current Condition:	Removed - Hildy Homes s		e 5/13/20 inspection	Removed	
Lot 24	Individual Lot	Lot 24	11/10/2020	Active	No
Current Condition:			ction on the lot prior to the	e 11/10/20 inspection	n. Dirt piles were
	observed in the ROW du	iring the 11/10/20 inspo	ection, the inspector will m	nonitor for removal a	nd the installation of
	BMPs.				
Lot 27	Individual Lot	Lot 27		Removed	
Current Condition: Lot 34		Lot 34	t prior to the 11/10/20 insp	Removed	
Current Condition:	Individual Lot Removed - McCaul sodde		20 inspection	Removed	
Lot 51	Individual Lot	Lot 51	4/27/2020	Active	No
Current Condition:			or to the 4/27/20 inspection.		-
	corner of the lot adjacent t	to the curb inlet prior to t	he 7/29/20 inspection. Land spection, the inspector will re	lmark Performance G	roup removed the silt
Lot 59	Individual Lot	Lot 59		Removed	
Current Condition:	Removed - Hildy Homes s		e 8/20/20 inspection.		
Lot 60	Individual Lot	Lot 60		Removed	
Current Condition:	Removed - Kavan Homes		he 7/1/20 inspection.		
Lot 64	Individual Lot	Lot 64		Removed	
Current Condition:	Removed - Kavan Homes				
Lot 65	Individual Lot	Lot 65	11/10/2020	Active	No No
Current Condition:	prior to the 6/1/20 inspection.	ction. Pacesetter Hom	entified as Lot 66. Paceset es installed silt fence in th	e rear of the lot prio	r to the 6/10/20
Lot 66 Current Condition:	Individual Lot	Lot 66	6/1/2020 htified as Lot 67. An uniden	Active	No
	to the 7/1/20 inspection.	The unidentified builder i	nstalled silt fence in the rear	of the lot prior to the	7/1/20 inspection.
Lot 67	Individual Lot	Lot 67	7/1/2020	Active	No
Current Condition:  Lot 70	Removed - Lot 67 was m Individual Lot	Lot 70	0.	Removed	
Current Condition:	Removed - Kavan Homes		he 7/15/20 inspection	Removed	
Lot 73	Individual Lot	Lot 73	ne 17 10/20 inspection.	Removed	
Current Condition:			prior to the 4/27/20 inspection		
Lot 80	Individual Lot	Lot 80	4/23/2020	Pending	Yes
Current Condition:	installed silt fence in the refor installation of the retain  1.) The portable toilet nee  2.) Silt fence needs to be	ear of the lot prior to the ning wall prior to the 9/16 ds to be moved away fro reinstalled on either side		removed the silt fenc	
	on 9/17/20. 2.) Nielsen Custom Home	s was informed to comp	lete by 6/8/20. Not done as dete by 9/23/20. Not done as	s of the last inspection	ı.
Lot 82	on 9/17/20. 2.) Nielsen Custom Home Individual Lot	es was informed to comp	lete by 9/23/20. Not done as 7/23/2020	s of the last inspection	No
Current Condition:	on 9/17/20.  2.) Nielsen Custom Home Individual Lot Active - Landmark began the lot prior to the 8/12/20 installation of the retaining installation of the retaining construction is complete.	Lot 82 construction on the lot p inspection, the silt fence g wall, the inspector will r g wall prior to the 9/30/20	lete by 9/23/20. Not done as 7/23/2020 rior to the 7/23/20 inspection is not behind all of the groumonitor. Landmark Performation inspection, the inspector wi	s of the last inspection Active Landmark installed and disturbance to ma ance Group removed Il recommend reinstal	No silt fence in the rear of ke room for the the silt fence for lation when
Current Condition:  Lot 84	on 9/17/20.  2.) Nielsen Custom Home Individual Lot Active - Landmark began the lot prior to the 8/12/20 installation of the retaining installation of the retaining construction is complete. Individual Lot	Lot 82 construction on the lot p inspection, the silt fence g wall, the inspector will r g wall prior to the 9/30/20	lete by 9/23/20. Not done as 7/23/2020 rior to the 7/23/20 inspection is not behind all of the groumonitor. Landmark Performation inspection, the inspector with 10/28/2020	s of the last inspection Active Landmark installed and disturbance to ma ance Group removed II recommend reinstal	No silt fence in the rear of ke room for the the silt fence for lation when
Current Condition:	on 9/17/20.  2.) Nielsen Custom Home Individual Lot Active - Landmark began the lot prior to the 8/12/20 installation of the retaining installation of the retaining construction is complete.  Individual Lot Fair Condition - Echelon F the lot and will be attribute ROW during the 10/28/20 The silt fence in the rear of	Lot 84  Lot 85  Lot 86  Lot 86  Lot 86  Lot 86  Lot 87  Lot 86  Lot 87  Lot 88  Lot 88  Lot 88  Lot 88  Lot 88  Lot 88	lete by 9/23/20. Not done as 7/23/2020 rior to the 7/23/20 inspection is not behind all of the groumonitor. Landmark Performation inspection, the inspector with 10/28/2020 in of the lot prior to the 10/28/20 in will monitor for removal.	s of the last inspection Active Landmark installed and disturbance to ma ance Group removed II recommend reinstal  Active 20 inspection. SF 4 is aspection. Dirt piles v	No silt fence in the rear of ke room for the the silt fence for lation when  Yes sin place in the rear of
Current Condition:  Lot 84	on 9/17/20.  2.) Nielsen Custom Home Individual Lot Active - Landmark began the lot prior to the 8/12/20 installation of the retaining installation of the retaining construction is complete.  Individual Lot Fair Condition - Echelon F the lot and will be attribute ROW during the 10/28/20 The silt fence in the rear of	Lot 84  Lot 85  Lot 86  Lot 86  Lot 86  Lot 86  Lot 87  Lot 86  Lot 87  Lot 88  Lot 88  Lot 88  Lot 88  Lot 88  Lot 88	lete by 9/23/20. Not done as 7/23/2020 rior to the 7/23/20 inspection is not behind all of the groumonitor. Landmark Perform 0 inspection, the inspector will not the lot prior to the 10/28/2020 not the lot prior to the 10/28/20 in will monitor for removal.	s of the last inspection Active Landmark installed and disturbance to ma ance Group removed II recommend reinstal  Active 20 inspection. SF 4 is aspection. Dirt piles v	No silt fence in the rear of ke room for the the silt fence for lation when  Yes sin place in the rear of

	T					
Lot 87	Individual Lot	Lot 87		Removed		
Current Condition:	Removed - Hildy Homes s	sodded the lot prior to th	e 3/12/20 inspection.	T		
Lot 89	Individual Lot	Lot 89	7/23/2020	Active	No	
Current Condition:			on the lot prior to the 7/23/2			
			ill be recommended to Hildy			
Lot 90	Individual Lot	Lot 90	11/10/2020	Active	Yes	
Current Condition:	Fair Condition - An unid	lentified builder began	construction on the lot pr	ior to the 11/10/20 in	spection.	
	The silt fence in the real	r of the lot needs to be	repaired.			
	The best described to the feet		(47/00			
L at 01	The builder will be infor Individual Lot	Lot 91	4/1/2020	Activo	No	
Lot 91 Current Condition:			construction on the lot prior	Active	No The let backs up to	
Current Condition.	SF 4 in the rear any new	maintenance to SF 4 in	the area will be sent to Adva	ntage Development a	on. The lot backs up to	
Lot 93	Individual Lot	Lot 93	line area wiii be sent to nava	Removed	3 01 4/ 1/20.	
Current Condition:			r to the 9/22/20 inspection.	Removed		
Lot 94	Individual Lot	Lot 94	1/3/2020	Active	No	
Current Condition:			on the lot prior to the 1/3/20 in			
			the 4/23/20 inspection. Lan			
			k repaired the silt fence pr			
Lot 95	Individual Lot	Lot 95		Removed	1	
Current Condition:	Removed - Vencil sodded		20 inspection	rtemoved		
Lot 100	Individual Lot	Lot 100	9/30/2020	Active	No	
Current Condition:			e lot prior to the 9/30/20 insp			
			latively flat, the inspector wil			
Lot 119	Individual Lot	Lot 119	2/18/2020	Active	Yes	
Current Condition:			on the lot prior to the 2/18/2			
			lot, street cleaning will be re			
			d cleaned the sidewalk prior			
	1.) Silt fence or straw wattles need to be extended along the sidewalk.					
	*	•	undermined and needs to be	e backfilled/repaired.		
	3.) The sidewalk needs to	be cleaned.				
	4.) Island was information	annominata hii 4/0/00 Niai		an Islanduuna naminule	-d 5/40/00 0/44/00	
	9/17/20.	complete by 4/8/20. No	done as of the last inspection	on. Ideal was reminde	ed on 5/19/20, 6/11/20,	
		complete by 6/17/20 No	ot done as of the last inspect	ion Ideal was remind	ded on 9/17/20	
			ot done as of the last inspect		200 011 0/11/201	
Lot 126	Individual Lot	Lot 126		Removed		
Current Condition:	Removed - Belt Construct		to the 5/6/20 inspection	rtemoved		
Lot 128	Individual Lot	Lot 128	to the ororze mopeotion.	Removed		
Current Condition:	Removed - Belt Construct		to the 7/23/20 inspection.			
Lot 131	Individual Lot	Lot 131	4/23/2020	Active	Yes	
Current Condition:	Fair Condition - Carder Co	onstruction builder bega	n excavation of the lot prior t	to the 4/23/20 inspecti	on. The lot backs up to	
			the area will be sent to the b			
			s maintained prior to the 9/16			
	, ,	· ·	ion. Carder Construction mo	oved the portable toile	et back from the ROW	
	prior to the 9/22/20 inspec	ction, the portable toilet s	still needs to be secured.			
	1) The cilt force is ripped	lin the reer of the let on	d noode to be notebed			
	<ol> <li>The silt fence is ripped</li> <li>The portable toilet nee</li> </ol>		d needs to be patched.			
	2.) The portable tollet flee	ds to be secured.				
	1.) Carder Construction w	ras informed to complete	by 9/23/20. Not done as of	the last inspection.		
	*		by 7/22/20. Not done as of	the state of the s	Carder Construction was	
	reminded on 9/17/20. No		-			
Lot 133	Individual Lot	Lot 133	10/13/2020	Active	No	
Current Condition:			e lot prior to the 10/13/20 insp			
			ea as of the 11/4/20 inspect			
			nonitor for removal and the i			
Lot 134	Individual Lot	Lot 134		Removed		
Current Condition:	Removed - Silverthorn so		8/5/20 inspection.		<u>'</u>	
Lot 135	Individual Lot	Lot 135	·	Removed		
Current Condition:	Removed - Landmark soc	ded the lot prior to the 8	3/20/20 inspection.			
Lot 137	Individual Lot	Lot 137		Removed		
Current Condition:	Removed - HBC Homes		the 11/10/20 inspection.			
SB 1 (Pond 5)	Sediment Basin	See SWPPP	1/3/2020	Active	Yes	
OB 1 (1 olid 5)	Gediment Dasin	000 011111				

Current Condition:			ed prior to the 1/3/20 inspect	ion with a permanent	riser.
	Basin is full and needs to				
	Gene Graves was inform		. Not done as of the last ins		
SB 2 (Pond 4)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 2% fille	d - The basin was installe	ed prior to the 1/3/20 inspect	tion with a permanent	riser.
SB 3 (Pond 3)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:	Good Condition - 2% fille	d - The basin was installed	ed prior to the 1/3/20 inspect	tion with a permanent	riser. A plug was
	installed in the upstream	manhole prior to the 9/2/	20 inspection, the plug is wo	orking effectively.	
SB 4 (Pond 2)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			lled prior to the 1/3/20 inspec		
SB 5 (Pond 1)	Sediment Basin	See SWPPP	1/3/2020	Active	No
Current Condition:			lled prior to the 1/3/20 insper		
SF 1	Silt fence	See SWPPP		Removed	11361.
Current Condition:			fence prior to the 4/23/20 in		1
SF 2	Silt fence	See SWPPP		Removed	1
Current Condition:			fence prior to the 4/15/20 in		ļ.
SF 3	Silt fence	See SWPPP		Removed	1
Current Condition:		Seeding removed the silt	fence prior to the 4/15/20 in		ing silt fence will h
Ourient Condition.	associated with Lot 64.	securing removed the sint	Terior prior to the 4/10/20 in	spection. The remain	ing sin rence will b
SF 4	Silt fence	See SWPPP	1/3/2020	Active	No
Current Condition:			he wetlands and drainagewa		
Curront Containon.			hind SB 4 during the 11/10		
	Tende was in the process	is of being removed be	initia OD 4 daring the 11/10	"20 mapeonom, me n	nopeotor will mo
SF 5	Silt fence	See SWPPP		Removed	1
Current Condition:			fence prior to the 4/15/20 in		1
SF 6	Silt fence	See SWPPP	Tende prior to the 4, 10,20 in	Removed	
Current Condition:			fence prior to the 4/15/20 in		ı
SF 7	Silt fence	See SWPPP		Removed	1
Current Condition:			new grading project to the s		of the 9/9/20 inspe
			now grading project to the c		T 110 0/0/20 110pt
SF 8	Silt fence	See SWPPP		Removed	
Current Condition:	Removed - Silt fence was		/20 inspection.	1	1
SF 9	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		T
SF 10	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		1
SF 11	Silt fence	See SWPPP		Removed	
Current Condition:			fence prior to the 4/15/20 in		1
SF 12	Silt fence	See SWPPP	f	Removed	
Current Condition:			fence prior to the 4/15/20 in		1
SF 13	Silt fence	See SWPPP	lfence prior to the 4/15/20 in	Removed	
Current Condition: SF 14		See SWPPP			1
Current Condition:	Silt fence		I new grading project to the s	Removed	of the 9/9/20 inene
Ourient Condition.	Temoved - The silt rence	13 HOW ITICIAGEA WITH THE	new grading project to the s	boutil of Bridgepoit as	or the 3/3/20 mape
SW 1	Straw Wattles	See SWPPP	1/3/2020	Active	No
Current Condition:			the SW corner of Lot 39 prio		
SW 2	Straw Wattles	See SWPPP	4/9/2020	Active	No
Current Condition:			he base of the slope west of		
Current Contallion.	inspection.	ratios were motalieu al li	io base of the slope west Of	ט שופופ matted pi	101 10 1110 4/3/20
SW 3	Straw Wattles	Coc CIVIDDD	A/4E/2020	Active	NI.
Current Condition:		See SWPPP	4/15/2020 traw wattles above the curb		No
Current Condition:	to the 4/15/20 inspection.		traw watties above the curb	iniets adjacent to the t	concrete washout p
	to the 4/15/20 Hispection.			1	
CTD	Cana at -	Internal/S 132nd and	4/0/0000	A ather	1/11
STR	Streets	Main Street	1/3/2020	Active	Yes
	Fair Condition -				
Current Condition:			i.		
Current Condition:	Minor street cleaning is no	eeded around active lots			
Current Condition:				ection	
	All builders were informed	d to complete by 8/6/20.  Camelback Ave and S	Not done as of the last insp		
SWPPP Sign	All builders were informed  Misc/Other	d to complete by 8/6/20.  Camelback Ave and S 180th Street	Not done as of the last insp	Active	No
	All builders were informed  Misc/Other  Good Condition - E&A insintersection of S 180th St	d to complete by 8/6/20.  Camelback Ave and S 180th Street spector installed 3 SWPF reet and Camelback Roa &A inspector relocated the	Not done as of the last insp	Active of S 180th Street and L Cornhusker Road and	aquinta Street, at d S 181st Street d
SWPPP Sign	All builders were informed  Misc/Other  Good Condition - E&A insintersection of S 180th St the 1/29/20 inspection. E	d to complete by 8/6/20.  Camelback Ave and S 180th Street spector installed 3 SWPF reet and Camelback Roa &A inspector relocated the	Not done as of the last inspirate 1/29/2020 PP signs at the intersection of ad, and at the intersection of	Active of S 180th Street and L Cornhusker Road and	aquinta Street, at d S 181st Street d