E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A- P2005.198.000 Inspector: Patrick Pierce Stage **Clearwater Falls** NER110573 Project Name: 3/6/2010 For Week Ending: Project Location: 48th and Fairview Road- Bellevue, NE (Sarpy County) 68123 Grading: Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 100% Utilities: 95% Overall Development: 40% RAIN FALL AMOUNTS Amount in tenths Date inspected Week Sunday: 0.00" Monday 0.00" 0.00' Tuesday Wednesday 0.00" 03/03/10 Thursday 0.00' Friday 0.00" Saturday 0.33" None Complaints: Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading completed and entire site seeded prior to 2005. Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Grading completed and entire site seeded prior to 2005. Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009) Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08). New phase to be seeded in the Spring of 2010. Comments: Comments:

Home construction is active in various areas of the development.

Some areas of the site are still frozen and snow covered. All BMP's appear to be in good condition unless otherwise noted.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) See BMP section for required maintenance.
- 2) Silt fence around Concrete Washout requires maintenance. Boyer Young was sent another reminder on 6/13/09 of maintenance. Maintenance not completed as of last inspection. A new plan was sent to Boyer Young on 8/8/09 requesting that all maintenance be take care of ASAP. This was not complete prior to last inspection.
- 3) The check above the East part of Silt Fence 9 is undermined. Boyer Young was sent another reminder on 6/13/09 of maintenance. Maintenance not completed as of last inspection. A new plan was sent to Boyer Young on 8/8/09 requesting that all maintenance be take care of ASAP. This was not complete prior to last inspection
- 4) Some lot level silt fence has been requested in the Northwest part of the development to prevent runoff. Boyer Young was sent another reminder on 6/13/09 of maintenance. Maintenance not completed as of last inspection.
- 5) There is one piece of lot level silt fence that needs to be removed as of inspection on 12/3/09. Boyer Young was requested to get this taken care of by 12/10/09. This was not complete as of inspection on 12/7/09, but contractor still has 3 days to complete. This was not complete as of last inspection.
- 6) The new phase that Celebrity Homes graded was finished late in November 2009. Due to the fact that it was late in the season to seed, Celebrity Hon 7) Hill Custom Homes is bulding on lot 197 and has some dirt piled in the R.O.W. Inspector called Tim with Hill Custom Homes requesting that this be re
- Projected **Unique Name** Type Location **Install Date** Status Maintenance N41d00m00s CE 1 Construction Entrance W96d00m00s 11/10/2009 **Pending** Yes **Current Condition:** Not Installed There is no construction entrance installed as of inspection on 11/5/09 and grading is active. Bruce Camden with JC Excavating was called and requested to get this installed by 11/12/09. This was not complete prior to inspection on 11/18/09. Bruce was called on 11/18/09 and reminded to get this installed ASAP. Maintenance not completed as of last inspection. Site is idle at this time. The construction entrance will not be installed until there is active construction in this area. N41d00m00s Sediment Basin W96d00m00s In Place Active SB₁ No **Current Condition:** Good Condition - 15% Filled N41d00m00s SB 2 Sediment Basin W96d00m00s In Place Active No **Current Condition:** Good Condition - 18% Filled- Debris cleaned out of basin by Commercial Seeding prior to inspection on 5-7-09. N41d00m00s In Place SB3 Sediment Basin W96d00m00s Active No **Current Condition:** Good Condition-17% Filled N41d00m00s Sediment Basin W96d00m00s Removed **Current Condition:** Removed per Hill-Farrell construction N41d00m00s SB 5 Sediment Basin W96d00m00s 11/17/2009 Active No **Current Condition:** Good Condition- 5% Filled JC Excavating installed prior to inspection on 11/18/09. N41d00m00s SF 1 W96d00m00s In Place Silt Fence Active Yes **Current Condition:** Fair Condition- partially removed due to seeding, need to be reinstalled 1) A couple areas are down and need to be retied. 2) As of on 8/4/08, conditions have worsened and due to nearby grading, areas are full and blown out, and undermined around the outlet pipe. 1) Boyer Young was sent another reminder on 6/13/09 of maintenance. Maintenance not completed as of last inspection. A new plan was sent to Boyer Young on 8/8/09 requesting that all maintenance be take care of ASAP. This area is well vegetated now and this silt fence can be removed. Boyer Young was requested to get this removed by 12/14/09 or as soon as the weather allows. This was not complete as of last inspection. 2) Boyer Young was sent another reminder on 6/13/09 of maintenance. Maintenance not completed as of last inspection. A new plan was sent to Boyer Young on 8/8/09 requesting that all maintenance be take care of ASAP. This area is well vegetated now and this silt fence can be removed. Boyer Young was requested to get this removed by 12/14/09 or as soon as the weather allows. This was not complete as of last inspection. N41d00m00s Silt Fence W96d00m00s Removed No **Current Condition:** Removed for grading on 8/4/08

		N41d00m00s					
SF 3	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to home cons	struction.	*	•			
		N41d00m00s					
SF 4	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to home cons		1				
07.5	a =	N41d00m00s					
SF 5	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to home cons			i			
SF 6	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed due to road const			Removed			
Current Condition.	Removed due to road const	N41d00m00s					
SF 7	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition -		II.	l .			
	- Installed/Repaired by JC E	excavating prior to inspe	ection on 11/18/0	9.			
		N41d00m00s					
SF 8	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition -	Woodcomoo	11111400	7101170	110		
	- Installed/Repaired by JC E	excavating prior to inspe	ection on 11/18/0	9.			
SF 9	Silt Fence	N41d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition			7.00.70	100		
	1) Boyer Young was sent at as of last inspection. A new be take care of ASAP. This and this silt fence can be retresponsible for all maintenat to get this removed by 12/14 inspection. 2) Boyer Young was sent at as of last inspection. A new be take care of ASAP. This and this silt fence can be retresponsible for all maintenations.	plan was sent to Boye was not complete prio moved. Celebrity Home nce in the South half of 4/09 or as soon as the va- nother reminder on 6/1 plan was sent to Boye was not complete prior moved. Celebrity Home	r Young on 8/8/09 r to last inspection es now owns this the developmen weather allows. T 3/09 of maintenan r Young on 8/8/09 to last inspection es now owns this	Prequesting that and an	Il maintenance I vegetated now they will be s was requested ete as of last not completed ill maintenance vegetated now they will be		
SF 10	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition	vv 30d00iii003	III I Idoc	7101170	103		
	One area of the fence is full Boyer Young was sent anot of last inspection. A new platake care of ASAP. This was	ther reminder on 6/13/0 In was sent to Boyer Yo	oung on 8/8/09 re	questing that all m			
		N41d00m00s					
SF 11	Silt Fence	W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition						
	One section of the silt fence is undermined. Boyer Young was sent another reminder on 6/13/09 of maintenance. Maintenance not completed as of last inspection. A new plan was sent to Boyer Young on 8/8/09 requesting that all maintenance be take care of ASAP. This was not complete prior to last inspection.						
		N41d00m00s					
	0.00 =		1				
SF 12	Silt Fence	W96d00m00s		Removed			
SF 12 Current Condition:	Removed due to landscapin	g.	1	Removed			
Current Condition:	Removed due to landscapin	g. N41d00m00s	40/20/2000		N-		
Current Condition: SF A	Removed due to landscapin Silt Fence	g.	10/30/2009	Active	No		
Current Condition:	Removed due to landscapin	g. N41d00m00s W96d00m00s	10/30/2009		No		

Current Condition:	Good Condition -Installed prior to inspection on 10/30/09					
STR Current Condition:	Street Cleaning Good Condition- No major	N41d00m00s W96d00m00s sigsn of track off	5/1/2007	Active	No	
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 48th and Birchwood Drive					
pector Signature:			Reviewed By:	Zodnavy k. J	ilelC	