E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E&A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC

ENGINEERING • PLANNING • FIELD SERVICES

	LGA- FZ	005.198.000		Stage	
nspector: Patrick Pierce					
Clearwater Falls				2	
Project Name:		NER110573			
or Week Ending:		nty) 68123			
Project Location:	48th and Fairview Road- Bellevue, NE (Sarpy County)				
N P	1.	.00/		Γ Τ	
Grading:		0%			
Sanitary Sewer: Storm Sewer:		0%		<b>-</b>	
Paving:		0%		<u> </u>	
Seeding:		0%			
Jtilities:		0%			
Overall Development:		2%			
			<del></del>	<del>!</del>	
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
				We	
Sunday:	1.72"				
Monday	0.08"	07/12/10			
uesday	0.00"				
Vednesday	1.30"				
hursday	0.00"	07/15/10			
Friday	0.01"				
Saturday	0.01"				
Seem doors	0.04"			We	
Sunday:	0.01"				
Monday	0.01"	07/20/10			
Tuesday Vednesday	0.57" 0.26"	07/20/10			
rhursday Thursday	0.26"	+			
Friday	0.01"				
Saturday	0.00"			+	
Juliu au y	0.00			We	
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday	N/A	N/A			
Saturday	N/A	N/A			
	None				
Complaints:					
				1	
Construction Sequencing:					
Construction Sequencing: Vhich portion(s) (i.e. drainage basins) of the site	have had a temporary or permaner	t cossation of grading par	rthwork or ground dietu	urhance in the last 14 days?	
which portion(s) (i.e. uralliage basilis) of the site	nave had a temporary or permanen	ic cessation of grading, ear	ranwork, or ground distu	Thanke III the last 14 days?	
Grading completed and entire site seeded	prior to 2005.				
Entire Site: IC Everysting completed	ling Late 246 through 400 C	on II drainage eres 4 -	and 2 (11/2000)		
Entire Site; JC Excavating completed grad	ing Lois 346 through 480 Section	on ii, drainage area 1 a	iiiu ∠ (11/2009).		
	do not have grading, earthwork, or	ground disturbance sche	duled in the next 14 days	s? :	
Vhich portion(s) (i.e. drainage basins) of the site					
			and 2 (11/2009)		
Grading completed and entire site seeded	ing Lots 346 through 480 Section	on II, drainage area 1 a			
Grading completed and entire site seeded	ling Lots 346 through 480 Section	on II, drainage area 1 a			
Grading completed and entire site seeded	ling Lots 346 through 480 Section	on II, drainage area 1 a			
Mhich portion(s) (i.e. drainage basins) of the site Grading completed and entire site seeded Entire Site; JC Excavating completed grad What temporary or permanent stabilization meas					
Grading completed and entire site seeded Entire Site; JC Excavating completed grad What temporary or permanent stabilization meas	sures listed in this section are being	implemented?	(0)5 (40(0); 7		
Grading completed and entire site seeded entire Site; JC Excavating completed grad what temporary or permanent stabilization meason and landscaping	sures listed in this section are being	implemented?	er of SID (10/08), Soc	d on various lots (Fall '08), Ne	
Grading completed and entire site seeded Entire Site; JC Excavating completed grad	sures listed in this section are being	implemented?	er of SID (10/08), Soc	d on various lots (Fall '08), Ne	

## Comments:

Celebrity Homes is actively building in the SW part of the development. Four other builders are active in the NW part of the development. Anchor Construction is actively working on storm sewer in the new phase of the development, but not during inspection on 07/15/10 or 07/20/10 due to wet and muddy conditions.

## Findings / Corrective Actions (Date)

## Findings / Corrective Actions (Date):

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	N41d00m00s W96d00m00s	5/5/2010	Active	No
Current Condition:	Good Condition- 80% Effect		0/0/2010	7.00	
	- Installed by Anchor Constru	uction prior to inspection	on on 5/5/10		
CW 1	Concrete Washout	Lot 303	6/12/2000	Active	Yes
Current Condition:	Poor Condition	LUI 303	6/13/2009	Active	162
	Silt fence around concrete w Boyer Young was sent a ren on 08/08/09, 03/17/10, 04/06 This was not complete as of	ninder on 6/13/09 of m 6/10, 5/13/10, and 6/16	aintenance. A nev		, ,
Lot 10	Silt Fence	Lot 10	6/21/2010	Active	No
Current Condition:	Good Condition-Silt Fence	LOI 10	6/21/2010	Active	INO
Current Condition.	-Horizon Homes installed sil	t fence prior to inspect	ion on 6/21/10.		_
Lot 13	Silt Fence	Lot 13	4/14/2010	Pending	Yes
Current Condition:	No BMP's installed but some	e are needed on lot- ad	ctive construction	<u> </u>	
	Horizon Homes was called on by 04-14-10. Inspector called to get some type of BMP ins	d Horizon Homes durir	ng inspection on 5	<mark>/21/10 and 6/5/1</mark>	0 to remind the
Lot 262 Current Condition:	Silt Fence No BMP's installed and som	Lot 262 e are needed- active o	5/24/2010	Pending	Yes
		e are needed- active of t on by Sherwood Hom d during inspection on od was called and rem	construction on lot nes and there is no 5/17/10 and reque inded to complete	o BMP installed. ested to get some	e type of BMP
Current Condition:	No BMP's installed and som Lot 262 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This was	e are needed- active of t on by Sherwood Hon d during inspection on od was called and rem was not complete prior	nes and there is no 5/17/10 and reque inded to complete to last inspection	o BMP installed. ested to get som e maintenance A	e type of BMP SAP during
	No BMP's installed and som Lot 262 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo	e are needed- active of t on by Sherwood Hon d during inspection on od was called and rem vas not complete prior Lot 266	nes and there is no 5/17/10 and reque inded to complete to last inspection 5/24/2010	o BMP installed. ested to get some maintenance A	e type of BMP
Current Condition:  Lot 266	No BMP's installed and som Lot 262 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This v Silt Fence	e are needed- active of t on by Sherwood Hon d during inspection on od was called and rem vas not complete prior  Lot 266 e are needed- active of t on by Sherwood Hon d during inspection on od was called and rem	nes and there is not 5/17/10 and reque to last inspection 5/24/2010 construction on lot nes and there is not 5/17/10 and reque to last inspection on lot nes and there is not 5/17/10 and requesting to complete	pested to get some maintenance A Pending  BMP installed.  Pending  BMP installed.  Bested to get some maintenance A	e type of BMP SAP during Yes
Current Condition:  Lot 266	No BMP's installed and som  Lot 262 is actively being buil  Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This value installed by 5/24/10. Sherwood BMP's installed and som  Lot 266 is actively being buil  Sherwood Homes was caller installed by 5/24/10. Sherwood	e are needed- active of t on by Sherwood Hon d during inspection on od was called and rem vas not complete prior  Lot 266 e are needed- active of t on by Sherwood Hon d during inspection on od was called and rem	nes and there is not 5/17/10 and reque to last inspection 5/24/2010 construction on lot nes and there is not 5/17/10 and reque to last inspection on lot nes and there is not 5/17/10 and requesting to complete	pested to get some maintenance A Pending  BMP installed.  Pending  BMP installed.  Bested to get some maintenance A	e type of BMP SAP during Yes
Current Condition:  Lot 266  Current Condition:	No BMP's installed and som Lot 262 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This v Silt Fence No BMP's installed and som Lot 266 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This v	e are needed- active of ton by Sherwood Hon of during inspection on od was called and remwas not complete prior  Lot 266 e are needed- active of ton by Sherwood Hon of during inspection on od was called and remwas not complete prior  Lot 268 ed on lot- active constr	5/17/10 and requestion on lot of the same and there is not solve to last inspection on lot of the same and there is not same and the same	po BMP installed.  Dested to get some maintenance A  Pending  Dested to get some maintenance A  Dested to get some maintenance A  Dested to get some maintenance A	Yes  Te type of BMP  Yes  The type of BMP  SAP during
Current Condition:  Lot 266 Current Condition:  Lot 268	No BMP's installed and som  Lot 262 is actively being built  Sherwood Homes was caller installed by 5/24/10. Sherwoo inspection on 6/28/10. This was sittle and som  Lot 266 is actively being built  Sherwood Homes was caller installed by 5/24/10. Sherwoo inspection on 6/28/10. This was sittle was a sittle with the sittle was a sit was a sittle was a sittle was a sittle was a sittle was a sittl	e are needed- active of ton by Sherwood Hon of during inspection on od was called and remwas not complete prior  Lot 266 e are needed- active of ton by Sherwood Hon of during inspection on od was called and remwas not complete prior  Lot 268 ed on lot- active constr	5/17/10 and requestion on lot of the same and there is not solve to last inspection on lot of the same and there is not same and the same	po BMP installed.  Dested to get some maintenance A  Pending  Dested to get some maintenance A  Dested to get some maintenance A  Dested to get some maintenance A	Yes  Te type of BMP  Yes  The type of BMP  SAP during
Current Condition:  Lot 266 Current Condition:  Lot 268 Current Condition:	No BMP's installed and som  Lot 262 is actively being buil  Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This was sittle and som  Lot 266 is actively being buil  Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10. This was simple to be installed by 5/24/10. Sherwo inspection on 6/28/10.	e are needed- active of ton by Sherwood Hon of during inspection on od was called and remyas not complete prior Lot 266 e are needed- active of ton by Sherwood Hon of during inspection on od was called and remyas not complete prior Lot 268 ed on lot- active constrict or to inspection on 5/3	5/17/10 and requestion on lot of the same and there is not solve to last inspection on lot of the same and there is not solve to last inspection on lot of the same and there is not solve to last inspection on lot of last inspection on last inspection o	pending	Yes  Te type of BMP SAP during  Yes  The type of BMP SAP during  No
Lot 266 Current Condition:  Lot 268 Current Condition:  Lot 270 Current Condition:	No BMP's installed and som Lot 262 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This w Silt Fence No BMP's installed and som Lot 266 is actively being buil Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This w Misc No BMP's need to be installe -stockpiles were removed pr Silt Fence Removed -Silt fence debris was cleane	e are needed- active of ton by Sherwood Hon of during inspection on od was called and remwas not complete prior Lot 266 e are needed- active of ton by Sherwood Hon of during inspection on od was called and remwas not complete prior Lot 268 ed on lot- active constrict to inspection on 5/2 Lot 270 ed up by Tim Hill prior to the control of the control	5/17/10 and requestion on lot of the same and there is not solve to last inspection on lot of the same and there is not solve to last inspection on lot of the same and there is not solve to last inspection on lot of last inspection on last inspection o	Pending  Pending  BMP installed.  Pending  BMP installed.  BMP installed.  Pending  Pending  Pending  Removed	Yes  Te type of BMP SAP during  Yes  The type of BMP SAP during  No
Lot 266 Current Condition:  Lot 268 Current Condition:  Lot 268 Current Condition:	No BMP's installed and som  Lot 262 is actively being buil  Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This was  Silt Fence  No BMP's installed and som  Lot 266 is actively being buil  Sherwood Homes was caller installed by 5/24/10. Sherwo inspection on 6/28/10. This was  Misc  No BMP's need to be installer -stockpiles were removed proceeded.	e are needed- active of ton by Sherwood Hon of during inspection on od was called and remy vas not complete prior Lot 266 e are needed- active of ton by Sherwood Hon of during inspection on od was called and remy vas not complete prior Lot 268 ed on lot- active constrict or to inspection on 5/2 Lot 270 ed up by Tim Hill prior to Lot 295	ponstruction on lot ones and there is not shall be a sh	pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending  Pending  Removed	Yes  Te type of BMP SAP during  Yes  The type of BMP SAP during  No  No

Current Condition:	No BMP's installed on lot but some are needed- active home construction - Stockpiles were removed prior to inspection on 5/17/10.					
	There is no lot level silt fence installed behind lots 225-230  Dave Hausman was requested to get this silt fence installed by 05/07/10. Dave Hausman was sent a reminder plan on 7/14/10. This was not complete prior to last inspection.					
Pod B	Silt Fence	Lots 212-224	4/21/2010	Active	Yes	
Current Condition:	Fair Condition					
	Dave Hausman did not clean out silt fence properly behind lots 212-216.					
	Dave Hausman was given a This was not complete prior 04/25/10 and 7/14/10 reques inspection.	to inspection on 04/23/ sting to get this taken c	10, Dave Hausm	<mark>an was given anot</mark>	her plan on	
SB 2	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 18% Filled- Debris cleaned out of basin by Commercial Seeding prior to inspectio on 5-7-09.					
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition-17% Filled					
SB 4	Sediment Basin	N41d00m00s W96d00m00s		Removed	$\exists$	
Current Condition:	Removed per Hill-Farrell cor			nemoveu		
00.5	O. Frank Barris	N41d00m00s	44/47/0000		NI.	
SB 5 Current Condition:	Sediment Basin Good Condition- 5% Filled	W96d00m00s	11/17/2009	Active	No	
Carrent Condition.	- JC Excavating installed price	or to inspection on 11/1	8/09.			
054	Oile Fanna	N41d00m00s	In Diago	A -45	V	
SF 1 Current Condition:	Silt Fence Fair Condition- partially remo	W96d00m00s	In Place	Active ed	Yes	
	blown out, and undermined a  1) Boyer Young was sent a that this be completed ASAF 2) Boyer Young was sent a that this be completed ASAF	reminder plan on 06/13 P. This was not compler reminder plan on 06/13	te as of last inspe 3/09, 08/08/09, 04	ection. 1/06/10, and 6/16/		
	That this be completed 7.671	N41d00m00s	I	Journal I		
SF 2	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed for grading on 8/4/		1		No	
SF 3	Silt Fence	N41d00m00s W96d00m00s			No	
Current Condition:	Removed due to home cons			Removed	No	
SF 4		truction.		Removed	No	
	Silt Fence			Removed Removed	No	
Current Condition:	Silt Fence Removed due to home cons	truction. N41d00m00s W96d00m00s truction.			No	
	Removed due to home cons	truction.  N41d00m00s  W96d00m00s  truction.  N41d00m00s		Removed	No	
Current Condition:  SF 5  Current Condition:	•	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.			No	
SF 5 Current Condition:	Removed due to home cons Silt Fence Removed due to home cons	truction.  N41d00m00s  W96d00m00s  truction.  N41d00m00s  W96d00m00s  truction.  N41d00m00s		Removed Removed	No	
SF 5	Removed due to home cons Silt Fence	truction.  N41d00m00s  W96d00m00s  truction.  N41d00m00s  W96d00m00s  truction.  N41d00m00s  W96d00m00s		Removed	No	
SF 5 Current Condition: SF 6 Current Condition:	Removed due to home cons Silt Fence Removed due to home cons Silt Fence Removed due to road constr	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s N41d00m00s		Removed  Removed		
SF 5 Current Condition: SF 6	Removed due to home cons Silt Fence Removed due to home cons Silt Fence	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s	In Place	Removed Removed	No	
SF 5 Current Condition:  SF 6 Current Condition:  SF 7	Removed due to home cons Silt Fence Removed due to home cons Silt Fence Removed due to road constr Silt Fence Fair Condition There are various areas that Boyer Young was requested on 04/06/10 and 6/16/10 req	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s ruction  N41d00m00s w96d00m00s ruction  N41d00m00s truction  N41d00m00s truction  N41d00m00s truction  N41d00m00s truction  N41d00m00s truction  Output  The state of	ed as of inspectio	Removed Removed Active n on 3/10/10. Boyer was sent a	Yes reminder plan	
SF 5 Current Condition:  SF 6 Current Condition:  SF 7	Removed due to home cons Silt Fence Removed due to home cons Silt Fence Removed due to road constr Silt Fence Fair Condition There are various areas that Boyer Young was requested	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s ruction  N41d00m00s w96d00m00s ruction  N41d00m00s truction  N41d00m00s truction  N41d00m00s truction  N41d00m00s truction  N41d00m00s truction  Output  The state of	ed as of inspectio	Removed Removed Active n on 3/10/10. Boyer was sent a	Yes reminder plan	
SF 5 Current Condition:  SF 6 Current Condition:  SF 7 Current Condition:	Removed due to home cons Silt Fence Removed due to home cons Silt Fence Removed due to road constr Silt Fence Fair Condition There are various areas that Boyer Young was requested on 04/06/10 and 6/16/10 req complete as of last inspectio	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s ruction  N41d00m00s W96d00m00s ruction  N41d00m00s W96d00m00s  The control of the contr	ed as of inspectio by 3/17/10. Nick enance taken car	Removed  Removed  Active  n on 3/10/10.  Boyer was sent are of ASAP. This was	Yes  reminder plan vas not	
SF 5 Current Condition:  SF 6 Current Condition:  SF 7	Removed due to home cons Silt Fence Removed due to home cons Silt Fence Removed due to road constr Silt Fence Fair Condition There are various areas that Boyer Young was requested on 04/06/10 and 6/16/10 req	truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s truction.  N41d00m00s W96d00m00s ruction  N41d00m00s v96d00m00s ruction  N41d00m00s V96d00m00s  The company of the compa	ed as of inspection by 3/17/10. Nick enance taken car In Place	Removed  Removed  Active  n on 3/10/10.  Boyer was sent are of ASAP. This was Active	Yes reminder plan	

Current Condition:	Fair Condition					
	1) One area is down and needs to be retied.					
	2) One area found undermined on 8-4-08 inspection.					
	3) The check above the East part of Silt Fence 9 is undermined.					
	1) Boyer Young was sent a	reminder plan on 06/13	/09, 08/08/09, 04	/06/10, and 6/16/1	0 requesting	
	1) Boyer Young was sent a reminder plan on 06/13/09, 08/08/09, 04/06/10, and 6/16/10 requesting that this be completed ASAP. This was not complete as of last inspection.					
	<ol><li>Boyer Young was sent a that this be completed ASAI</li></ol>				0 requesting	
	3) Boyer Young was sent a	reminder plan on 06/13.	/09, 08/08/09, 04	/06/10, and 6/16/1	0 requesting	
	that this be completed ASAI	P. This was not comple	te as of last inspe	ection.		
		N41d00m00s				
SF 10	Silt Fence	W96d00m00s	In Place	Active	Yes	
Current Condition:	Fair Condition					
	One area of the fence is full	and undermined.				
	Boyer Young was sent a rer	ninder plan on 06/13/00	0.08/08/09.04/06	8/10, and 6/16/10	requesting that	
	this be completed ASAP. Th				requesting that	
	· ·	N41d00m00s	1			
SF 11	Silt Fence	W96d00m00s	In Place	Active	Yes	
Current Condition:	Fair Condition					
	One section of the silt fence	is undermined.				
	Boyer Young was sent a rer	ninder plan an 00/40/00	0.00/00/00 04/00	2/10 and 6/40/40	roquesting that	
	this be completed ASAP. The				requesting that	
	· ·	N41d00m00s	1			
SF 12	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed due to landscapin					
SF A	Silt Fence	N41d00m00s W96d00m00s	10/30/2009	Active	Yes	
Current Condition:	Fair Condition		10,00,000			
	There is an area that is also			40		
	There is an area that is down and damaged as of inspection on 3/10/10.					
	Celebrity Homes was reque					
	Boyer Young still owns this property, therefore they are still responsible for this maintenance. Boyer Young was forwarded the new maintenance plan and requested to complete the maintenance by					
	3/17/10. This was not complete as of last inspection, Nick Boyer was sent a reminder plan on					
	04/06/10 and 5/13/10 requesting to get all maintenance taken care of ASAP. This was not complete					
	as of last inspection.	N41d00m00s	1			
SF B	Silt Fence	W96d00m00s	10/30/2009	Active	No	
Current Condition:	Good Condition	and and a land Time Online		5/47/40		
	-Silt fence was repaired and	extended by 11m Gels	prior to inspectio	n on 5/17/10.		
OTD	01	N41d00m00s	5/4/0007	A		
STR Current Condition:	Street Cleaning Fair Condition- No major sign	W96d00m00s	5/1/2007	Active	Yes	
	,					
	1) There is some runoff coming from the new phase where sanitary sewer constuction is active as of inspection on 7/6/10.					
	2) Sherwood Homes has some runoff from lot 262 as of inspection on 7/15/10.					
	3) Celebrity Homes has some trackoff along Clearwater Drive as of inspection on 7/15/10.					
	1) Nick Boyer was called an	d requested to have the	ase cleaned up by	, 07/06/10 Nick P	over was called	
	1) Nick Boyer was called an during inspection on 7/15/10					
	during inspection on 7/15/10 as of last inspection.	and 7/20/10 to remind	him to clean this	up ASAP. This w	as not complete	
	during inspection on 7/15/10 as of last inspection.  2) Sherwood Homes was ca	and 7/20/10 to remind	him to clean this	up ASAP. This w	as not complete	
	during inspection on 7/15/10 as of last inspection.  2) Sherwood Homes was cainspection on 7/20/10.  3) Tim Moore was called an	and 7/20/10 to remind	him to clean this	up ASAP. This was o	as not complete	
	during inspection on 7/15/10 as of last inspection.  2) Sherwood Homes was cainspection on 7/20/10.	and 7/20/10 to remind	him to clean this	up ASAP. This was o	as not complete	
	during inspection on 7/15/10 as of last inspection.  2) Sherwood Homes was cainspection on 7/20/10.  3) Tim Moore was called an	and 7/20/10 to remind	him to clean this	up ASAP. This was o	as not complete	
SWPPP Sign	during inspection on 7/15/10 as of last inspection.  2) Sherwood Homes was cainspection on 7/20/10.  3) Tim Moore was called an to inspection on 7/20/10.  Signs	and 7/20/10 to remind	him to clean this	up ASAP. This was o	as not complete	
SWPPP Sign Current Condition:	during inspection on 7/15/10 as of last inspection.  2) Sherwood Homes was cainspection on 7/20/10.  3) Tim Moore was called an to inspection on 7/20/10.	and 7/20/10 to remind alled and requested to o d requested to have thi	him to clean this clean this up by 7/ s cleaned up by 7	up ASAP. This was o	as not complete complete prior to complete prior	
	during inspection on 7/15/10 as of last inspection. 2) Sherwood Homes was cainspection on 7/20/10. 3) Tim Moore was called an to inspection on 7/20/10.  Signs Good Condition:	and 7/20/10 to remind alled and requested to o d requested to have thi	him to clean this clean this up by 7/3 s cleaned up by 7/8 s clean	up ASAP. This was of 116/10. This was of 1/16/10. This was Active	as not complete complete prior to complete prior No	
	during inspection on 7/15/10 as of last inspection. 2) Sherwood Homes was cainspection on 7/20/10. 3) Tim Moore was called an to inspection on 7/20/10.  Signs Good Condition:	and 7/20/10 to remind alled and requested to o d requested to have thi	him to clean this clean this up by 7/3 s cleaned up by 7/8 s clean	up ASAP. This was o	as not complete complete prior to complete prior  No	