E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com E&A CONSULTING GROUP, INC. Zachary A. Jilek, CPESC, CISEC ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A- P2005.198.000 Stage Inspector: Patrick Pierce 2 **Clearwater Falls** NER110573 Project Name: 9/11/2010 For Week Ending: 48th and Fairview Road- Bellevue, NE (Sarpy County) Project Location: 68123 Grading: 100% Sanitary Sewer: 100% 85% Storm Sewer: Paving: 80% Seeding: 70% Utilities 75% Overall Development: 45% Amount in tenths RAIN FALL AMOUNTS Date inspected Week Sunday: 0.00" Monday 0.00" 08/30/10 Tuesday 0.60" Wednesday 0.34' 09/01/10 Thursday 0.01" Friday 0.00' Saturday 0.00" Week 2 Sunday: 0.00" Monday 0.04 Tuesday 0.00" Wednesday 0.00" Thursday Trace Friday Trace Saturday 0.00" Wo Sunday: NA NA Monday NA NA Tuesday NA NA Wednesday NA NA Thursday NA NA Friday NA NA Saturday NA NA None Complaints: Construction Sequencing: Which portion(s) (i.e. drainage ba sins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading completed and entire site seeded prior to 2005. Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009). tion(s) (i.e. drainage basins) of the site ar a. earthwork, or a d distur d in the next 14 days? Grading completed and entire site seeded prior to 2005. Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009) ng impl Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10). Comments:

/ Corrective Actions (Date): MP section for required maintena	ince.							
Unique Name	Туре	Location N41d00m00s	Projected Install Date	Status	Maintenance			
CE 1	Construction Entrance	W96d00m00s	5/5/2010	Active	No			
Current Condition:	Good Condition- 80% Effectiveness - Installed by Anchor Construction prior to inspection on 5/5/10							
CW 1	Concrete Washout	Lot 303	6/13/2009	Active	Yes			
Current Condition:	Poor Condition		•					
	 Silt fence around concrete washout is down and damaged. This concrete washout is full and spoils are being deposited on the outside of the washout as of inspection on 7/26/10. Boyer Young was sent a reminder on 6/13/09 of maintenance. A new plan was sent to Boyer Youn on 08/08/09, 03/17/10, 04/06/10, 5/13/10, 6/16/10 and 8/25/10 requesting that this be taken care of ASAP. This was not complete as of last inspection. Boyer Young was requested to clean out this concrete washout by 8/2/10. Nick Boyer was sent a reminder plan on 8/25/10. This was not complete prior to last inspection. 							
CW 2 Current Condition:	Concrete Washout	Lot 198	8/25/2010	Active	No			
Current Condition:	Good Condition -Concrete washout was cleaned out by Tim Moore for Celebrity Homes prior to inspection on 09/01/10.							
Lot 10	Silt Fence	Lot 10		Removed				
Current Condition:	Lot was sodded prior to inspe		Horizon Homes.	Removed				
Lot 13	Silt Fence	Lot 13		Removed				
Current Condition:	Lot was sodded prior to inspended on this lot.		Horizon Homes, the		e is no longer			
Lot 32	Silt Fence	Lot 32	8/4/2010	Active	Yes			
Current Condition:	Fair Condition	LOI 32	8/4/2010	Active	Tes			
	There is a stockpile in the ROW as of inspection on 8/19/10.							
	Horizon Homes was called and requested to remove this stockpile prior to inspection on 8/26/10. Thi was not complete prior to inspection on 8/25/10, but due to recent rains an extension will be given to complete this maintenance. The new completion date is 08/31/10. This was not complete prior to inspection on 8/31/10.							
Lot 262	Silt Fence	Lot 262	7/26/2010	Active	No			
Current Condition:	Good Condition -Sherwood Homes installed sockfilter prior to inspection on 7/26/10 to prevent runoff.							
Lot 266	Silt Fence	Lot 266	5/24/2010	Pending	Yes			
Current Condition:	No BMP's installed and some are needed- active construction on lot							
	Lot 266 is actively being built on by Sherwood Homes and there is no BMP installed.							
	Sherwood Homes was called during inspection on 5/17/10 and requested to get some type of BMP installed by 5/24/10. Sherwood was called and reminded to complete maintenance ASAP during inspection on 6/28/10 and 8/25/10. This was not complete prior to last inspection.							
	Misc	Lot 268		Removed				
Lot 268	Lot was sodded by Sherwood	d Homes prior to insp	ection on 8/25/10.					
Lot 268 Current Condition:								
Current Condition:		Lots 225-254	5/7/2010	Pendina	No			
	Silt Fence Good Condition -Dave Hausman installed silt	Lots 225-254 fence to protect sode	5/7/2010 ded lots prior to ins	Pending pection on 7/26	•			
Current Condition: Pod A	Silt Fence Good Condition							

	Good Condition -Silt fence was cleaned out b	y Dave Hausman pric	or to inspection on	7/26/10.		
Pod 1	Silt Fence	Lots 426-454	8/31/2010	Pending	Yes	
Current Condition:	Fair Condition					
	There is some silt fence needed in various areas of this pod to prevent runoff as of inspection on 8/25/10.					
	Boyer Young was given a pla prior to inspection on 8/30/10					
		,				
Pod 2	Silt Fence	Lots 455-473	8/31/2010	Pending	Yes	
Current Condition:	Fair Condition					
	There is some silt fence need 8/25/10. Boyer Young was given a pla prior to inspection on 8/30/10	in requesting to have	this installed by 08	3/31/10. This was	not comple	
		N41d00m00s				
SB 2	Sediment Basin	W96d00m00s	In Place	Active	No No	
Current Condition:	Good Condition - 18% Filled- on 5-7-09.	Debris cleaned out o	Dasin by Comme	arcial Seeding price	u to inspect	
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition-17% Filled	11 3000011100S	IIIIIIdue	AUIVE	INU	
		N41d00m00s		Removed		
SB 4 Current Condition:	Sediment Basin Removed per Hill-Farrell con	W96d00m00s struction.		Removed	1	
		N41d00m00s				
SB 5 Current Condition:	Sediment Basin Good Condition- 5% Filled	W96d00m00s	11/17/2009	Active	No	
Sarrent Sonution:	- JC Excavating installed price	or to inspection on 11/	18/09.			
		N41d00m00s				
SF 1 Current Condition:	Silt Fence Fair Condition- partially remo	W96d00m00s	In Place	Active	Yes	
	2) As of inspection on 8/4/08	and the second second second second				
	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. 1/06/10, 6/16/10 a	and 8/25/10	
	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. 1/06/10, 6/16/10 a	and 8/25/10	
SF 2	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. 1/06/10, 6/16/10 a	and 8/25/10	
SF 2 Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41400m00s W96d00m00s 08	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. I/06/10, 6/16/10 a of last inspection.	and 8/25/10	
Current Condition: SF 3	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. I/06/10, 6/16/10 a of last inspection.	and 8/25/10	
Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s 08 N41d00m00s W96d00m00s ruction.	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. 1/06/10, 6/16/10 a of last inspection. Removed	and 8/25/10	
Current Condition: SF 3	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/ Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41000m00s 08 N41000m00s W96000m00s	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. 1/06/10, 6/16/10 a of last inspection. Removed	and 8/25/10	
Current Condition: SF 3 Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/ Silt Fence Removed due to home cons	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction.	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. I/06/10, 6/16/10 a of last inspection. Removed Removed	and 8/25/10	
Current Condition: SF 3 Current Condition: SF 4	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/ Silt Fence Removed due to home const Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s 08 N41d00m00s ruction. N41d00m00s W96d00m00s	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. I/06/10, 6/16/10 a of last inspection. Removed Removed	and 8/25/10	
Current Condition: SF 3 Current Condition: SF 4 Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 3 Silt Fence 3 Removed for grading on 8/4/ 3 Silt Fence 3 Removed due to home consi 3 Silt Fence 3 Remov	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41400m00s W96d00m00s ruction. N41400m00s W96d00m00s ruction. N41400m00s W96d00m00s ruction. N41400m00s W96d00m00s ruction.	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. /06/10, 6/16/10 a of last inspection. Removed Removed Removed	and 8/25/10	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 3) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Young was sent a requesting that this be comp 4) Boyer Was sent a requesting that this be comp 4) Boyer Was sent a requesting that this be comp 4) Boyer Was sent a requesting that this be comp 4) Boyer Was sent a requesting that the text a requesting that this be comp 4) Boyer Was sent a requesting that this be comp 4) Boyer Was sent a requesting that the t	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. (/06/10, 6/16/10 a of last inspection. Removed Removed Removed Removed	and 8/25/10	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/ Silt Fence Removed due to home consi Silt Fence Removed due to home consi Silt Fence Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s N41d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction.	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. /06/10, 6/16/10 a of last inspection. Removed Removed Removed	and 8/25/10	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6 Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 3 Silt Fence Removed for grading on 8/4/ Silt Fence Removed due to home consi Silt Fence Remove	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s 08 N41d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s uction N41d00m00s	3/09, 08/08/09, 04 not complete as 3/09, 08/08/09, 04 not complete as 4	of last inspection. //06/10, 6/16/10 a of last inspection. Removed Removed Removed Removed Removed	and 8/25/10 No	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/ Silt Fence Removed due to home const Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s N41d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction.	3/09, 08/08/09, 04 not complete as (3/09, 08/08/09, 04	of last inspection. (/06/10, 6/16/10 a of last inspection. Removed Removed Removed Removed	and 8/25/10	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6 Current Condition: SF 7	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp Silt Fence Removed for grading on 8/4/ Silt Fence Removed due to home const Silt Fence Removed due to nome const Silt Fence Removed due to nome const Silt Fence Removed due to nome const Silt Fence	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s uv96d00m00s	3/09, 08/08/09, 04 not complete as a 3/09, 08/08/09, 04 not complete as a 	of last inspection. (/06/10, 6/16/10 a of last inspection. Removed Removed Removed Removed Removed Active n on 3/10/10. Boyer was sent a	No No	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6 Current Condition: SF 7 Current Condition:	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 3) Silt Fence 3 Removed for grading on 8/4/ 3) Silt Fence 3 Removed due to home consi 3) Silt Fence 3 Removed due to home consi 3) Silt Fence 3 Removed due to home consi 3) Silt Fence 4 Removed due to nome consi 3) Silt Fence 4 Removed due to nome consi 3) Silt Fence 4 Removed due to nome consi 3) Silt Fence 4 Removed due to nome consi 3) Silt Fence 4 Removed due to nome consi 4 Silt Fence 4 Removed due to road constr 5 Silt Fence 4 Removed due to nome consi 4 Silt Fence 4 Removed due to nome co	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41400m00s W96d00m00s 08 N41400m00s W96d00m00s ruction. N41400m00s W96d00m00s ruction. N41400m00s W96d00m00s uction N41400m00s w96d00m00s uction N41400m00s Uter plan this silt fence 5/10 requesting to ge N41400m00s	3/09, 08/08/09, 04 not complete as of not complete as of not complete as of lin Place	of last inspection. (/06/10, 6/18/10 a of last inspection. Removed Removed Removed Removed Removed Active n on 3/10/10. Boyer was sent a taken care of AS/	And 8/25/10 No No No No Arreninder p AP. This was	
Current Condition: SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6 Current Condition: SF 7	blown out, and undermined a 1) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 2) Boyer Young was sent a requesting that this be comp 3) Silt Fence 3 Removed for grading on 8/4/ 3 Silt Fence 3 Removed due to home cons 3 Silt Fence 4 Removed due to home cons 5 Silt Fence 4 Removed due to home cons 5 Silt Fence 5 Removed due to nome cons 5 Silt Fence 6 Removed due to nome cons 5 Silt Fence 6 Removed due to nome cons 6 Silt Fence 7 Si	eminder plan on 06/1 eted ASAP. This was eminder plan on 06/1 eted ASAP. This was N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s ruction. N41d00m00s W96d00m00s uction N41d00m00s w96d00m00s uction N41d00m00s w96d00m00s uction N41d00m00s uction N41d00m00s w96d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s uction N41d00m00s	3/09, 08/08/09, 04 not complete as a 3/09, 08/08/09, 04 not complete as a 	of last inspection. (/06/10, 6/16/10 a of last inspection. Removed Removed Removed Removed Removed Active n on 3/10/10. Boyer was sent a	No No	

		N41d00m00s							
SF 9	Silt Fence	W96d00m00s	In Place	Active	Yes				
Current Condition:	Fair Condition								
	1) One area is down and needs to be retied. 2) One area found undermined on 8-4-08 inspection.								
	2) One area found undermined on 8-4-08 inspection.3) The check above the East part of Silt Fence 9 is undermined.								
	 Boyer Young was sent a reminder plan on 06/13/09, 08/08/09, 04/06/10, 6/16/10 and 8/25/10 requesting that this be completed ASAP. This was not complete as of last inspection. 								
	2) Boyer Young was sent a reminder plan on 06/13/09, 08/08/09, 04/06/10, 6/16/10 and 8/25/10								
	requesting that this be completed ASAP. This was not complete as of last inspection.								
	 Boyer Young was sent a reminder plan on 06/13/09, 08/08/09, 04/06/10, 6/16/10 and 8/25/10 requesting that this be completed ASAP. This was not complete as of last inspection. 								
SF 10	Silt Fence	N41d00m00s W96d00m00s	In Place	Active	Yes				
Current Condition:	Fair Condition	1100000111000	intidoo	7.00170					
	One area of the fence is full and undermined.								
	Boyer Young was sent a rer	minder plan on 06/13/09		\$/10_6/16/10_and	8/25/10				
	requesting that this be comp				0/23/10				
		N41d00m00s							
SF 11 Current Condition:	Silt Fence Fair Condition	W96d00m00s	In Place	Active	Yes				
Current Condition.									
	One section of the silt fence is undermined.								
	Boyer Young was sent a reminder plan on 06/13/09, 08/08/09, 04/06/10, and 6/16/10 requesting that this be completed ASAP. This was not complete as of last inspection.								
SF 12	Silt Fence	N41d00m00s W96d00m00s		Removed					
Current Condition:	Removed due to landscapin								
SF A	Silt Fence	N41d00m00s W96d00m00s	10/30/2009	Active	Yes				
Current Condition:	Fair Condition	Woodoomood	10/00/2000	7101170	100				
	There is an area that is dow	n and damaged as of in	spection on 3/10)/10					
	There is an area that is down and damaged as of inspection on 3/10/10.								
	Celebrity Homes was requested to get this repaired by 3/17/10. Celebrity responded and stated that Rever Young still every this property, therefore they are still responsible for this maintenance. Bower								
	Boyer Young still owns this property, therefore they are still responsible for this maintenance. Boyer Young was forwarded the new maintenance plan and requested to complete the maintenance by								
	3/17/10. This was not complete as of last inspection, Nick Boyer was sent a reminder plan on								
	04/06/10, 5/13/10 and 8/25/10 requesting to get all maintenance taken care of ASAP. This was not complete as of last inspection.								
		N41d00m00s							
SF B Current Condition:	Silt Fence Fair Condition	W96d00m00s	10/30/2009	Active	Yes				
Current Condition.									
	There is a few areas of this silt fence that are full as of inspection on 8/25/10.								
	Nick Boyer was sent a plan requesting to clean this out by 8/31/10. This was not complete prior to								
	inspection on 8/30/10, but contractor still has one day to complete this maintenance.								
STR	Street Cleaning	N41d00m00s W96d00m00s	5/1/2007	Active	Yes				
Current Condition:	Fair Condition- No major sig	ons of track off.							
	-Horizon Homes cleaned up	runoff prior to inspection	on on 8/30/10.						
	There is some runoff coming from the new phase where storm sewer constuction and paving is active as of inspection on 7/6/10. Nick Boyer was called and requested to have these cleaned up by 07/06/10. Nick Boyer was called								
	during inspection on 7/15/10, 7/20/10, 8/4/10, 8/25/10 and 09/01/10 to remind him to clean this up ASAP. This was not complete as of last inspection.								
	ASAP. This was not comple	ae as or last inspection.							
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No				
Current Condition:	Good Condition: 48th and Birchwood Drive								
					110				
	Inspector Signature: Zadrany k								
Inspector Signature:	·		Reviewed By:						