E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A-P2005.198.000 (Clearwater Falls) E&A-P2005.198.009 (Clearwater Falls Trail)

	E&A-P2005.198	8.009 (Clearwater Falls	i irali)			
Inspector: Aaron Tulley					Stage	
	CI	learwater Falls/Clea	rwater Falls Trail		3	
Project Name:		CSW-2017	01144		3	
For Week Ending:						
Project Location:	484	3/14/2020 48th and Fairview Road- Bellevue, NE (Sarpy County)				
r roject Location.	400	in and I all view Road- Delic	svue, NE (Jaipy County)		68123	
Grading:	l 1	00% 100	%			
Sanitary Sewer:	1	00% N				
Storm Sewer:		00% 100				
Paving:		00% 100				
Seeding:		00% 99				
Utilities:			/A			
Overall Development:		99% 99	%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
TAIL ALL AMOUNTO	7 anount in tentro	Date inspected	Weather Conditions	Time	Week '	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.00"				Week 2	
Sunday:	0.00"					
Monday	0.01"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				We also	
Sunday	0.00"				Week 3	
Sunday:	0.00"					
Monday						
Tuesday	0.00"					
Wednesday	0.00"	00/07/00	Dantha Olassaha 40/00	0.50		
Thursday	0.00"	02/27/20	Partly Cloudy 42/23	3 2:50 p.m.		
Friday	0.00"					
Saturday	0.00"					
	0.00				Week 4	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Model	
Sunday:	0.00"				Week 8	
	0.00° 0.44"					
Monday Tuesday	0.44"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.03"					
Saturday	0.36"					
	None					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Grading for the Clearwater Falls Trail has ceased as of inspection on 12/18/17.

Grading has begun at Clearwater Falls Trail for installation of Storm Sewer on N side of trail. Grading has ceased for storm sewer on N side of trail.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014); John Navarro installed the erosion control matting 1 & 2 for the trail project (1/17/18). Park Area has been seeded and matted (5/9/18). Storm Sewer Installed and disturbed area has been seeded and matted (5/9/18). Area surrounding new sidewalk in NE portion of site has been seeded and matted (7/5/18). NW corner of site has been seeded and matted (7/5/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

IN/A

Is dust associated with the construction activity adequately controlled on the site

Yes

Create Corrective Action

N/A

Comments:

Comments:

Home Construction is inactive as of the last inspection. There is currently 0 active lots and 2 vacant lots (147 & 163) throughout the development.

Outlot J was disturbed when construction equipment used it to access lot 279.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP Section.
- 2.) Some re-seeding is necessary throughout the Clearwater Falls Trail project.
 - a. The area around the area inlet needs to be reseeded and matted.
 - b. The erosion in the middle of the trail area needs to be backfilled and reseeded/matted
 - c. The northwest corner of the trail needs to be reseeded/matted
 - d. The western portion of the trail needs to be overseeded.

- Commercial Seeding was informed to complete as conditions allow on 3/19/19. Not done as of the last inspection. Commercial Seeding was reminded on 5/13/19, 6/5/19. Commercial Seeding completed the pending maintenance prior to inspection on 6/24/19. E&A will continue to monitor for seed growth.

Overseeding is required in all areas. Commercial Seeding was informed to complete ASAP on 9/26/19. E&A will monitor. Not done as of the last inspection.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CW 5	Concrete Washout	Lot 387		Removed	
Current Condition:	Removed - Celebrity Homes removed the concrete washout prior to inspection on 11/12/2015.				
CW 6	Concrete Washout	Lot 359		Removed	

Current Condition:	Removed - Washout pit was	removed by Celebrity Ho	omes prior to 3/30/2016		
		,			
CW 7	Concrete Washout Removed - due to the progr	Lot 361	ral lata will be reenensible f	Removed	wasta
Current Condition:	Builders will washout on the install a washout.				
Lot 81	Individual Lot	Lot 81		Removed	
Current Condition:	Removed - Pacesetter Hom	es sodded the lot prior to	inspection on 9/30/19.		
Lot 297	Individual Lot	Lot 297		Removed	
Current Condition:	Removed - Pacesetter Hom		inspection on 8/12/19.		
Pod F	Silt Fence	Lots 426-454	14/20451 2 1 1 1	Removed	
Current Condition: Pod G	Removed - Lots 427 and 42 Silt Fence	8 were sodded prior to 12 Lots 404-425	2/1/2015 by Celebrity Home		
Current Condition:	Removed - Lot 404 was soo		od has been built out	Removed	
Pod H	Silt Fence	Lots 455-473	da rias been bailt out.	Removed	
Current Condition:	Removed - Lot 460 was soo		prior to the inspection on 4/		
Pod I	Silt Fence	Lots 346-355	'	Removed	
Current Condition:	Removed - Lot 355 was soc	ded prior to 8/18/2015 by	Celebrity Homes.		
Pod J	Silt Fence	Lots 381-394		Removed	
Current Condition:	Removed - Pod J is built ou		T		
Pod K	Silt Fence	Lots 372-403	1/00/10	Removed	
Current Condition: Pod L	Removed - Celebrity Homes		17/22/16 completing the poor		
Current Condition:	Silt Fence Removed - Celebrity Homes	Lots 371-356	1 250 completing the ned	Removed	
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition - 25% Filled				
	by the SID prior to inspection inspection on 9/19/17.	n on 10/23/14. Vegetation	n was removed from the ba	sin by the SID pr	ior to
SB 2	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition - 15% Filled - JC Excavating installed pri		/09.		
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition - 20% Filled - Cleaned out 02/06	ater Falls Trail			
CD 1	Check Dam	Northern side of site	10/2/2017	Active	No
Current Condition:	Good Condition - John Nava				INU
EM 1		East side of site	I	Removed	
Current Condition:	Erosion Control Matting Removed - Due to establish		n control matting will no lo		d as a BMP
EM 2	Erosion Control Matting	West side of site		Removed	d as a Divii .
Current Condition:	Removed - Due to establish		on control matting will no lo		ed as a BMP.
SF 1	Silt Fence	Southern side of site	l	Removed	
Current Condition:	Removed - BMP no longer l	peing recommended beca	ause of stabilization of area		
SF 2	Silt Fence	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer l Silt Fence	peing recommended beca Southern side of site	ause of stabilization of area	Removed	
SF 3 Current Condition:	Removed - John Navarro st required.		nspection on 3/6/18 and the		longer
SF 4	Silt Fence	Northern side of site		Removed	
Current Condition:	Removed - BMP no longer l		ause of stabilization of area		
IP 1	Inlet Protection	Southern side of site		Removed	
Current Condition:	Removed - BMP no longer l				
STR	Street Cleaning	streets	5/1/2007	Active	No
Current Condition:	Good Condition - Pacesette Pacesetter Homes cleaned out in front of lot 329. Track trail entrance and park was to inspection on 6/4/19. Par	the track out from along loot was cleaned in front cleaned prior to inspection	ot 292 prior to 7/13/17. Reg of lot 302 prior to inspectior n on 5/9/18. Dostal Constru	gency Homes cle n on 10/9/17. Str uction cleaned th	aned the track eet in between e streets prior
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No
Current Condition:	Good Condition - 48th and I	birchwood Drive			