E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



L					E & A CONSOLITING GROOT, INC.		
Zachary A. Jilek, CPESC, CIS Environmental Services Dep				Engineering Answers			
		E&A- P2006.056.01	9				
Inspector: Zach Roza					Stage		
Ducient Name:			1				
Project Name:		CSW-202207403 11/4/2023					
For Week Ending: Project Location:	South Lakeview Way	inty)	68003				
rojest Lesation.	Count Editorion Tray	una countyara count	Activation (Continuous Continuous				
Grading:	80%	-					
Sanitary Sewer: Storm Sewer:	0%						
Paving:	0%	!			+		
Seeding:	0%	_					
Utilities:	0%						
Overall Development:	10%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration		
0 - 1	0.00				Week		
Sunday: Monday:	0.00"				+		
Tuesday:	0.00"				1		
Wednesday:	0.00"	11/1/2023	Mostly Sunny 51 / 21	11:15 AM	1		
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
	None						
Complaints:							
Grubbing began (7/5/23). Grad				st 14 days?			
Grubbing began (7/5/23). Grad	ins) of the site do not have grading, earthwork, or grou ling began (9/13/23).	una disturbance scheduled	in the next 14 days?				
What temporary or permanent stab Existing Vegetation (7/5/23).	ilization measures listed in this section are being imp	lemented?					
Checklist Questions:							
	nt to the project free of any significant signs	of erosion or sedime	nt that would be associated	with the constructio	n activity?		
Yes Create Corrective Action?							
N/A							
Have disturbed areas been s prevent erosion.	eeded or otherwise stabilized as required?	List inactive portions	of the project and if stabiliza	tion measure are ad	equate or needed to		
Create Corrective Action?							
Are waste materials (concret Yes	te, construction material, hazardous, etc.) b	eing managed properly	y?				
Create Corrective Action?							
N/A							
	and adjacent streets being maintained adeq	uately?					
No Create Corrective Action?							
No- See BMP Section							
	construction activity adequately controlled o	on the site?					
Yes Create Corrective Action?							
N/A							
Comments							
Comments:							
Site was active for grading dur	ing the last inspection.						
Findings / Corrective Actions	s (Date):						

- Findings / Corrective Actions (Date):
 1.) There are some findings in the BMP Section.
 2.) Silt fence should be installed along western boundary. Pruss Excavation was informed to complete by 11/1/23. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
ČE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes		
Current Condition:	Pending - Pruss Excavation installed a construction entrance prior to the inspection on 9/20/23. Pruss Excavation removed the						
	construction entrance prior to the inspection on 10/25/23.						
	Construction entrance should be re-installed with horm or silt force should be installed to prevent addition to the street						
	Construction entrance should be re-installed with berm or silt fence should be installed to prevent sediment running onto street.						
	Pruss Excavation was informed to complete by 11/1/23.						
		<u> </u>					
DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	lled a diversion berm prior to	the inspection on 10/11/23	i.			
DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	lled a diversion berm prior to	the inspection on 10/18/23	i.			
DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed a diversion berm prior to the inspection on 10/18/23.						
FT 01	Fuel Tank	On Site		Removed			
Current Condition:	Removed- Pruss Excavation removed		nspection on 11/1/23.				
IP 1 - 2	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	Yes		
Current Condition:	Pending-						
	Inlet protection should be installed.						
	Inlet protection should be installed.						
	Pruss Excavation was informed to comp	elete by 11/1/23. Not done as	of the last inspection.				
IP 3 - 4	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	l No		
Current Condition:	Pending- Inlet protection will be installed		01012020	ı r chung	1 140		
IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pendina	No		
Current Condition:	Pending- Inlet protection will be installed		0/3/2023	renaing	I INO		
IP 7	<u> </u>		8/5/2023	Dan din n	N-		
Current Condition:	Inlet Protection Pending- Inlet protection will be installed	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition.	r ending- mier protection will be installed			ı	1		
MT 01	Erosion Matting	South East portion of the	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in	stalled the erosion matting	prior to the inspection of	n 11/1/23			
Carroni Condition.	Good Golidition 11400 Excavation in	<u>. </u>	prior to the mopeotion o				
MT 02	Erosion Matting	South East portion of the site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in		prior to the inspection of	on 11/1/23.			
		South West portion of the	prior to the mopeonion o				
MT 03	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in		prior to the inspection of	n 11/1/23.			
MT 04	Erosion Matting	ADJ to Private Drive	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in				110		
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed		0/3/2023	rending	INO		
MT 06	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in				INO		
MT 07	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in				INU		
PT 01			prior to the inspection c				
Current Condition:	Portable Toilet Removed- Pruss Excavation removed	On Site	the inspection on 11/1/2	Removed			
SF 01 - 09	Silt Fence	Eastern Perimeter	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation in						
SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Pending	No		
Current Condition:	Pending- Pruss Excavation installed SF						
	inspection on 9/20/23. Due to erosion in longer be recommended as of 11/2/23	0,	•	installed, silt fence	11,13, and 14 will no		
	•	<u> </u>					
SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	No		
Current Condition: SF 19	Good Condition- Pruss Excavation in Silt Fence	stalled Silt fence 1-9 prior to Northern Perimeter	to the inspection on 11/1. 7/12/2023	Active	Yes		
Current Condition:	Fair Condition- Pruss Excavation installe						
	on 9/27/23.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			3 p		
	Silt fence should be repaired where down	Silt fence should be repaired where down.					
	Pruss excavation was informed to complete by 10/4/23. Not done as of the last inspection. Pruss Excavation was reminded on 10/26/23.						
		0					
SF 20 - 30	Silt Fence	Southern Half of Courtyard	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed once	grading starts	I.	l	I		
Janon Vollation.	. S.Iding Oil Iones will be installed title		I		I		
SF 31 - 34	Silt Fence	Northern Half of Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed once		<u> </u>	<u> </u>	l .		
	Janes IIII 30 Instance Office	Jg					
SF 35 - 42	Silt Fence	Eastern Perimeter Checks	11/1/2023	Active	No		
01 00 72	!	I			l		

Current Condition:	Good Condition- Pruss Excavation in	stalled Silt fence 35-42 prio	r to the inspection on 11	1/1/23.			
SF 43 - 48	Silt Fence	Southern Half of Western Perimeter	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
SF 49 - 51	Silt Fence	West of Courtyard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
SF 52 - 55	Silt Fence	Northern Half of Western Perimeter	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
STR	Streets	ADJ and Internal Streets	8/5/2023	Active	Yes		
Current Condition:	Fair Condition-						
	Adjacent streets should be cleaned. Pruss Excavation was informed to complete by 10/26/23. Not done as of the last inspection.						
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No		
Current Condition:	Good Condition- E&A inspector installed a SWPPP sign during the inspection on 10/11/23.						
WO 01	Concrete Washout	On Site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed a concrete washout prior to the inspection on 11/1/23.						
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No		
Current Condition:	Pending- Waste storage will be installed as necessary.						
Certification Statement	system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	Joh Roge			Reviewed By:	to be		