E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



| | | | | | L & A CONSOLITING GROOT, INC. | | |
|--|---|--------------------------------|-------------------------------------|-----------------------|-------------------------------|--|--|
| Zachary A. Jilek, CPESC, CIS Environmental Services Dep | | | | Engineering Answers | | | |
| • | | E&A- P2006.056.019 |) | | | | |
| Inspector: Zach Roza | | | | | | | |
| | | | 1 | | | | |
| Project Name: | | CSW-202207 12/2/2023 | | | | | |
| For Week Ending: | | | 68003 | | | | |
| Project Location: | South Lakeview Way | and Courtyard Court - | Ashland, NE (Saunders Cou | inty) | | | |
| Grading: | 80% | 5 | | | | | |
| Sanitary Sewer: | 0% | 5 | | | | | |
| Storm Sewer: | 0% | | | | | | |
| Paving: | 0% | | | | | | |
| Seeding: | 10% | | | | _ | | |
| Utilities: Overall Development: | 0% | | | | + | | |
| Overall Development. | 107 | 21 | | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | Time | Storm Event Duration | | |
| Sunday: | 0.02" | | | | Week | | |
| Monday: | 0.00" | | | | | | |
| Tuesday: | 0.00" | | | | | | |
| Wednesday: | 0.00" | 11/29/2023 | Mostly Sunny 54 / 28 | 10:50 AM | | | |
| Thursday: | 0.00" | | , | | | | |
| Friday: | 0.00" | | | | | | |
| Saturday: | 0.00" | | | | | | |
| | Mana | | | | | | |
| Complaints: | None | | | | | | |
| | | | | | | | |
| Construction Sequencing: | | | | | | | |
| | ns) of the site have had a temporary or permanent ce | essation of grading, earthwork | k, or ground disturbance in the las | t 14 days? | | | |
| Grubbing began (7/5/23). Grad | ling began (9/13/23). Grading ceased (11/22/2 | 3). | | | | | |
| Which portion(s) (i.e. drainage basi | no) of the cite do not have grading conthwerk or are | und disturbance schoduled i | n the next 14 days? | | | | |
| | ns) of the site do not have grading, earthwork, or gro | | n the next 14 days? | | | | |
| Grubbling began (7/5/25). Grad | ling began (9/13/23). Grading ceased (11/22/2 | ა). | | | | | |
| What temporary or permanent stab | ilization measures listed in this section are being imp | plemented? | | | | | |
| Existing Vegetation (7/5/23). E | rosion Matting 1,2,3,4,6,7 installed (11/1/23). § | Seeding under erosion ma | tting (11/1/23). | | | | |
| 0 | | | | | | | |
| Checklist Questions: | at to the preject free of any circuitioent circu | a of avanian av andiman | t that would be accepted to | with the construction | n oativity? | | |
| Yes | nt to the project free of any significant sign | s of erosion or sealmen | t that would be associated t | with the construction | on activity? | | |
| Create Corrective Action? | | | | | | | |
| N/A | | | | | | | |
| Have disturbed areas been s prevent erosion. | eeded or otherwise stabilized as required? | List inactive portions o | f the project and if stabiliza | tion measure are ac | lequate or needed to | | |
| Create Corrective Action? | | | | | | | |
| N/A | | | | | | | |
| | te, construction material, hazardous, etc.) t | peing managed properly | ? | | | | |
| Yes Create Corrective Action? | | | | | | | |
| N/A | | | | | | | |
| | | | | | | | |
| No No | and adjacent streets being maintained adec | juately? | | | | | |
| Create Corrective Action? | | | | | | | |
| No- See BMP Section | | | | | | | |
| Is dust associated with the c | construction activity adequately controlled | on the site? | | | | | |
| Yes | | | | | | | |
| Create Corrective Action? N/A | | | | | | | |
| | | | | | | | |
| Comments: | | | | | | | |
| Comments: | et inspection | | | | | | |
| Site was inactive during the las | · | | | | | | |
| Findings / Corrective Actions (Date): | | | | | | | |

| | <u> </u> | | | | | | |
|----------------------------------|---|---|------------------------------------|----------------------|--------------------------|--|--|
| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | | |
| CE 01 | Construction Entrance | Off 113th Street | 9/20/2023 | Pending | Yes | | |
| Current Condition: | Pending - Pruss Excavation installed a c | | the inspection on 9/20/23. | Pruss Excavation ren | noved the construction | | |
| | entrance prior to the inspection on 10/25/23. | | | | | | |
| | Construction entrance should be re-installed with berm or silt fence should be installed to prevent sediment running onto street. | | | | | | |
| | Pruss Excavation was informed to complete by 11/1/23. Not done as of the last inspection. | | | | | | |
| DB 01 | Diversion Berm | North Side of Site | 10/11/2023 | Active | l No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | | | 110 | | |
| DB 02 | Diversion Berm | Eastern Side of Site | 10/18/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | led a diversion berm prior to | the inspection on 10/18/23 | • | | | |
| DB 03 | Diversion Berm | Eastern Side of Site | 10/18/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | · · · · · · · · · · · · · · · · · · · | the inspection on 10/18/23 | = | | | |
| FT 01 | Fuel Tank | On Site | +i 44/4/00 | Removed | | | |
| Current Condition: | Removed- Pruss Excavation removed the Inlet Protection | Along Courtyard Court | 11/8/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | led IP 1 and 2 prior to the ins | pection on 11/8/23. | | | | |
| IP 3 - 4 Current Condition: | Inlet Protection Pending- Inlet protection will be installed | Along Courtyard Court | 8/5/2023 | Pending | No | | |
| IP 5 - 6 | <u> </u> | | 0/5/0000 | Dandina | N ₁ - | | |
| Current Condition: | Inlet Protection Pending- Inlet protection will be installed | Along Courtyard Court once paving is complete. | 8/5/2023 | Pending | No | | |
| IP 7 | Inlet Protection | Along Courtyard Court | 8/5/2023 | Pending | No | | |
| Current Condition: | Pending- Inlet protection will be installed | | 0,0,2020 | . onang | | | |
| | Erosion Matting | South East portion of the | 11/1/2023 | Active | No | | |
| MT 01 | · · | site | | | INU | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | to the inspection on 11/1/2 | 3. | | | |
| MT 02 | Erosion Matting | South East portion of the site | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | Lto the inspection on 11/1/2 | 3. | | | |
| | | South West portion of the | | | I | | |
| MT 03 | Erosion Matting | site | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | led the erosion matting prior | to the inspection on 11/1/2 | 3. | | | |
| MT 04 | Erosion Matting | ADJ to Private Drive | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | | | | | |
| MT 05 Current Condition: | Erosion Matting Pending- Erosion Matting will be installed | ADJ to Private Drive | 8/5/2023 | Pending | No | | |
| MT 06 | Erosion Matting | North of Courtyard Court | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | | | 110 | | |
| MT 07 | Erosion Matting | North of Courtyard Court | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | to the inspection on 11/1/2 | 3. | | | |
| PT 01 | Portable Toilet | On Site | | Removed | | | |
| Current Condition: SF 01 - 09 | Removed- Pruss Excavation removed the Silt Fence | ne portable toilet prior to the in Eastern Perimeter | nspection on 11/1/23. 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | | Active | INO | | |
| SF 10 - 14 | Silt Fence | Northern Checks | 7/12/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal the inspection on 9/20/23. Due to erosion | | | | | | |
| | be recommended as of 11/2/23. Pruss E | | | | 3, and 14 will no longer | | |
| SF 15 - 18 | Silt Fence | Western Perimeter | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | led Silt fence 1-9 prior to the | inspection on 11/1/23. | | | | |
| SF 19 | Silt Fence | Northern Perimeter | 7/12/2023 | Active | No No | | |
| Current Condition: | Good Condition- Pruss Excavation instal inspection on 9/27/23. Pruss Excavation | | | | aown auring the | | |
| | | Southern Half of Courtvard | | | | | |
| SF 20 - 30 | Silt Fence | Court | 8/5/2023 | Pending | No | | |
| Current Condition: | Pending- Silt fence will be installed once | | | | | | |
| OF 24 24 | Silt Fence | Northern Half of Courtyard | 8/5/2023 | Pending | No | | |
| SF 31 - 34 Current Condition: | Pending- Silt fence will be installed once | Court grading starts. | | | | | |
| | | l | | _ | | | |
| SF 35 - 42 | Silt Fence | Eastern Perimeter Checks | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | • | ne inspection on 11/1/23. | | | | |
| OF 42 40 | Silt Fence | Southern Half of Western | 11/1/2023 | Active | No | | |
| SF 43 - 48 Current Condition: | Good Condition- Pruss Excavation instal | Perimeter led Silt fence 35-42 prior to the | ne inspection on 11/1/23 | | | | |
| SF 49 - 51 | Silt Fence | West of Courtyard Court | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | | | , 101110 | 110 | | |
| | Silt Fence | Northern Half of Western | 11/1/2022 | Active | No | | |
| SF 52 - 55 | | Perimeter | 11/1/2023 | Active | No | | |
| Current Condition: | Good Condition- Pruss Excavation instal | • | | | | | |
| STR Current Condition: | Streets Good Condition, Streets were clean duri | ADJ and Internal Streets | 8/5/2023 | Active | No | | |
| Current Condition: | Good Condition- Streets were clean duri | ng the inspection on 11/22/23 |). | | | | |

| SWPPP Sign | SWPPP Sign | On Site | 10/11/2023 | Active | No | | |
|-------------------------|---|---------|------------|--------------|--------|--|--|
| Current Condition: | Good Condition- E&A inspector installed a SWPPP sign during the inspection on 10/11/23. | | | | | | |
| WO 01 | Concrete Washout | On Site | | Removed | | | |
| Current Condition: | Removed- Pruss Excavation removed the concrete washout prior to the inspection on 11/22/23. | | | | | | |
| WS 01 | Waste Storage Area | On Site | 8/5/2023 | Pending | No | | |
| Current Condition: | Pending- Waste storage will be installed as necessary. | | | | | | |
| Certification Statement | "I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations." | | | | | | |
| Inspector Signature: | 2 h Ry | | | Reviewed By: | to Sel | | |