E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dept. Manager Engineering Answers						
La contra Trata De la		E&A- P2006.056.019			Ctore	
Inspector: Zach Roza		Stage				
Project Name:						
For Week Ending:			68003			
Project Location:	South Lakeview Way and Courtyard Court - Ashland, NE (Saunders County)					
Grading:	80%	6				
Sanitary Sewer:	0%					
Storm Sewer:	0%	6				
Paving:	0%					
Seeding: Utilities:	10%					
Overall Development:	10%					
		• <u> </u>				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
Sunday:	0.00"				Week 1	
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"	2/21/2024	Mostly Sunny 67 / 32	12:05 PM		
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
Complaints:	None					
Construction Sequencing:						
Which portion(s) (i.e. drainage basins) o	f the site have had a temporary or permanent ce	essation of grading, earthwork, o	r ground disturbance in the las	t 14 days?		
0 11: 1 (7/5/00) 0 1: 1		20)				
Grubbing began (7/5/23). Grading i	began (9/13/23). Grading ceased (11/22/2	.3).				
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?						
Grubbing began (7/5/23). Grading I	began (9/13/23). Grading ceased (11/22/2	23).				
	ion measures listed in this section are being imp					
Existing Vegetation (7/5/23). Erosic	on Matting 1,2,3,4,6,7 installed (11/1/23). S	Seeding under erosion mattin	ig (11/1/23).			
Checklist Questions:						
	the project free of any significant sign	s of erosion or sediment th	nat would be associated w	with the construction	activity?	
Yes	the project nee of any eighteent eight				l douvity :	
Create Corrective Action?						
N/A						
prevent erosion.	ed or otherwise stabilized as required?	List inactive portions of the	ne project and if stabilizat	ion measure are ade	equate or needed to	
Yes Create Corrective Action?						
N/A						
Are waste materials (concrete. c	onstruction material, hazardous, etc.) b	peing managed properly?				
Yes	······································	S a superior of the				
Create Corrective Action?						
Are construction entrances and adjacent streets being maintained adequately?						
No Create Corrective Action?						
No- See BMP Section						
Is dust associated with the cons Yes	truction activity adequately controlled	on the site?				
Create Corrective Action?						
N/A						
Comments:						
Comments:						
1.) Site was inactive during the last inspection. Findings / Corrective Actions (Date):						

Findings / Corrective Actions (Date): There are some findings in the BMP Section.						
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
ČE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes	
Current Condition:	Pending - Pruss Excavation installed a construction entrance prior to the inspection on 9/20/23. Pruss Excavation removed the construction					

	Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
	CE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes	
	Current Condition:	Pending - Pruss Excavation installed a c		the inspection on 9/20/23.	Pruss Excavation ren	noved the construction	
		entrance prior to the inspection on 10/25/23.					
		Or an effective sector and a should be as insta					
		Construction entrance should be re-insta	lied with berm of slit tence sr	iouid be installed to preven	t sediment running or	ito street.	
		Pruss Excavation was informed to comp	lete by 11/1/23. Not done as	of the last inspection. Prus	s Excavation was ren	ninded on 12/7/23	
		Thus Excavation was informed to comp		or the last hispection. I rus			
	DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal				INO	
	DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/18/23.			
	DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/18/23.			
	FT 01	Fuel Tank	On Site		Removed		
	Current Condition:	Removed- Pruss Excavation removed th		tion on 11/1/23	Removed		
	IP 1 - 2	Inlet Protection	Along Courtyard Court	11/8/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal		pection on 11/8/23.			
	IP 3 - 4	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No	
	Current Condition:	Pending- Inlet protection will be installed	once paving is complete.				
	IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No	
	Current Condition:	Pending- Inlet protection will be installed		0/0/2020	i onding		
	IP 7	Inlet Protection	Along Courtyard Court	8/5/2023	Danding	No	
		Pending- Inlet protection will be installed		6/5/2023	Pending	INU	
	Current Condition:						
		Erosion Matting	South East portion of the	11/1/2023	Active	No	
<u> </u>	MT 01		site				
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.		
		Erosion Matting	South East portion of the	11/1/2023	Active	No	
	MT 02	, , , , , , , , , , , , , , , , , , ,	site			NO	
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.		
			South West portion of the				
	MT 03	Erosion Matting	site	11/1/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal		to the inspection on 11/1/23	3.		
-	MT 04	Erosion Matting	ADJ to Private Drive	11/1/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal				NU	
				· · · · · · · · · · · · · · · · · · ·			
	MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No	
	Current Condition:	Pending- Erosion Matting will be installed					
	MT 06	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.		
	MT 07	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal	led the erosion matting prior	to the inspection on 11/1/23	3.		
_	PT 01	Portable Toilet	On Site		Removed		
_	Current Condition:	Removed- Pruss Excavation removed th		I spection on 11/1/23	Removed		
	SF 01 - 09	Silt Fence	Eastern Perimeter	11/1/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal			7101170		
	SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal	led SF 11 prior to the inspect	ion on 7/12/23. Pruss exca	vation removed SF 1	1 due to grading prior to	
		the inspection on 9/20/23. Due to erosion					
		be recommended as of 11/2/23. Pruss E	xcavation installed silt fence	11 and 14 prior to the inspe	ection on 11/8/23.		
\vdash	SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal			7,01170	110	
	SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	No	
	Current Condition:	Good Condition- Pruss Excavation instal					
						-	
<u> </u>	current contaition.	inspection on 9/27/23. Pruss Excavation					
			repaired the silt fence prior to	o the inspection on 11/8/23			
	SF 20 - 30	inspection on 9/27/23. Pruss Excavation Silt Fence			Pending	No	
⊢			repaired the silt fence prior to Southern Half of Courtyard Court	o the inspection on 11/8/23		No	
1	SF 20 - 30	Silt Fence Pending- Silt fence will be installed once	repaired the silt fence prior to Southern Half of Courtyard Court grading starts.	o the inspection on 11/8/23		No	
	SF 20 - 30 Current Condition:	Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard	o the inspection on 11/8/23		No	
	SF 20 - 30 Current Condition: SF 31 - 34	Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court	o the inspection on 11/8/23 8/5/2023	Pending		
	SF 20 - 30 Current Condition:	Silt Fence Pending- Silt fence will be installed once	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court	o the inspection on 11/8/23 8/5/2023	Pending		
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court	o the inspection on 11/8/23 8/5/2023	Pending		
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023	Pending Pending	No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023	Pending Pending	No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 ne inspection on 11/1/23.	Pending Pending Active	No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023	Pending Pending	No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active	No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active	No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter led Silt fence 35-42 prior to th West of Courtyard Court	b the inspection on 11/8/23 8/5/2023 11/1/2023 he inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active	No No No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th Southern Half of Western Perimeter led Silt fence 35-42 prior to th West of Courtyard Court led Silt fence 35-42 prior to th	b the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 be inspection on 11/1/23. 11/1/2023 11/1/2023 be inspection on 11/1/23. 11/1/2023 be inspection on 11/1/23. 11/1/2023 be inspection on 11/1/23. 11/1/2023	Pending Pending Active Active	No No No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to th West of Courtyard Court led Silt fence 35-42 prior to th West of Courtyard Court led Silt fence 35-42 prior to th Northern Half of Western	b the inspection on 11/8/23 8/5/2023 11/1/2023 he inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active	No No No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51 Current Condition: SF 52 - 55	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Silt Fence	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to tf Southern Half of Western Perimeter led Silt fence 35-42 prior to tf West of Courtyard Court led Silt fence 35-42 prior to tf Northern Half of Western Perimeter	a the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 ne inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active Active	No No No	
	SF 20 - 30 Current Condition: SF 31 - 34 Current Condition: SF 35 - 42 Current Condition: SF 43 - 48 Current Condition: SF 49 - 51 Current Condition:	Silt Fence Pending- Silt fence will be installed once Silt Fence Pending- Silt fence will be installed once Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal Silt Fence Good Condition- Pruss Excavation instal	repaired the silt fence prior to Southern Half of Courtyard Court grading starts. Northern Half of Courtyard Court grading starts. Eastern Perimeter Checks led Silt fence 35-42 prior to tf Southern Half of Western Perimeter led Silt fence 35-42 prior to tf West of Courtyard Court led Silt fence 35-42 prior to tf Northern Half of Western Perimeter	a the inspection on 11/8/23 8/5/2023 8/5/2023 11/1/2023 ne inspection on 11/1/23. 11/1/2023 11/1/2023 11/1/2023	Pending Pending Active Active Active	No No No	

Current Condition:	Good Condition- Streets were clean durin	ng the inspection on 11/22/23				
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No	
Current Condition:	Good Condition- E&A inspector installed a SWPPP sign during the inspection on 10/11/23.					
WO 01	Concrete Washout	On Site		Removed		
Current Condition:	Removed- Pruss Excavation removed the concrete washout prior to the inspection on 11/22/23.					
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No	
Current Condition:	Pending- Waste storage will be installed as necessary.					
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	Joh Ray			Georgeneer Reviewed By:	to See	