E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



www.eacg.com	chary A. Jilek, CPESC, CISEC vironmental Services Dept. Manager			E & A CONSULTING GROUP, INC.  Engineering Answers		
		&A- P2006.056.01	9		_	
nspector: Zach Roza					Stage	
	C	Courtyards @ Iron Horse CSW-202207403				
Project Name:						
For Week Ending:		4/6/2024			68003	
Project Location:	South Lakeview Way	and Courtyard Court -	Ashland, NE (Saunders Cou	inty)		
Grading:	80%					
Sanitary Sewer:	5%					
Storm Sewer:	0%					
Paving:	0%					
Seeding: Utilities:	80%					
Overall Development:	10%					
Overall Bevelopment.	1070					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Durati	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"	4/3/2024	Partly Cloudy 53 / 37	12:15 PM		
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.10"					
	None					
Complaints:						
Grubbing began (7/5/23). Grad  What temporary or permanent stabi	ns) of the site do not have grading, earthwork, or grouing began (9/13/23). Grading ceased (11/22/23) ilization measures listed in this section are being implication Matting 1,2,3,4,6,7 installed (11/1/23). Section Matting 1,2,3,4,6,7 installed (11/1/23).	). Sanitary Installation be emented?	egan (3/20/24).	eded (3/13/24).		
	nt to the project free of any significant signs	of erosion or sedimen	t that would be associated	with the construction	on activity?	
Yes					•	
Create Corrective Action?  N/A						
Have disturbed areas been so prevent erosion.	eeded or otherwise stabilized as required? I	List inactive portions of	f the project and if stabiliza	tion measure are ac	lequate or needed to	
Create Corrective Action?						
N/A						
	te, construction material, hazardous, etc.) be	eing managed properly	?			
Yes Create Corrective Action?						
N/A						
Are construction entrances a	and adjacent streets being maintained adequ	uately?				
Create Corrective Action?						
No- See BMP Section						
Is dust associated with the c	construction activity adequately controlled o	n the site?				
Yes						
Create Corrective Action?  N/A						
1977 \$						
Comments:						
Comments: 1.) Site was inactive during the	last inspection.					
Findings / Corrective Actions	s (Date):					

## Findings / Corrective Actions (Date): There are some findings in the BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes			
Current Condition:	Pending - Pruss Excavation installed a d							
	entrance prior to the inspection on 10/25	5/23.						
	Construction entrance should be re-installed with berm or silt fence should be installed to prevent sediment running onto street.							
	Pruss Excavation was informed to complete by 11/1/23. Not done as of the last inspection. Pruss Excavation was reminded or							
				Excavation was re	minded on 12/7/23,			
22.01	3/21/24. Great Plains Contractor Serv	· · · · · · · · · · · · · · · · · · ·						
DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta	lled a diversion berm prior to	the inspection on 10/11/23.					
DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta	lled a diversion berm prior to	the inspection on 10/18/23.					
DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta							
FT 01	Fuel Tank	On Site	·	Removed				
Current Condition:	Removed- Pruss Excavation removed to		tion on 11/1/23	Removed				
IP 1 - 2	Inlet Protection	Along Courtyard Court	11/8/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta			7101170	110			
IP 3 - 4	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No			
Current Condition:	Pending- Inlet protection will be installed	once paving is complete.			•			
IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No			
Current Condition:	Pending- Inlet protection will be installed		JOILOLO	. origing	1 110			
IP 7	Inlet Protection	Along Courtvard Court	8/5/2023	Donding	Nia			
Current Condition:	Pending- Inlet protection will be installed		0/3/2023	Pending	No			
Carrent Contaition:	- Chaing- miet protection will be illistalled		,		T			
MT C4	Erosion Matting	South East portion of the	11/1/2023	Active	No			
MT 01	, and the second	Is d the areaign matting prior t	11111222		1			
Current Condition:	Good Condition- Pruss Excavation insta		to the inspection on 11/1/23	i.				
	Erosion Matting	South East portion of the	11/1/2023	Active	No			
MT 02		site			140			
Current Condition:	Good Condition- Pruss Excavation insta	lled the erosion matting prior	to the inspection on 11/1/23	3.				
	Erosion Matting	South West portion of the	11/1/2023	Active	No			
MT 03	· ·	site			INO			
Current Condition:	Good Condition- Pruss Excavation insta	lled the erosion matting prior	to the inspection on 11/1/23	3.				
MT 04	Erosion Matting	ADJ to Private Drive	11/1/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta				•			
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No			
Current Condition:	Pending- Erosion Matting will be installe		0/0/2020	rending	140			
MT 06			14/4/0000	A 11				
Current Condition:	Erosion Matting Good Condition- Pruss Excavation insta	North of Courtyard Court	11/1/2023	Active	No			
			·					
MT 07	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta	lled the erosion matting prior t	to the inspection on 11/1/23	5.				
PT 01	Portable Toilet	On Site		Removed				
Current Condition:	Removed- Pruss Excavation removed to							
SF 01 - 09	Silt Fence	Eastern Perimeter	11/1/2023	Active	No			
Current Condition: SF 10 - 14	Good Condition- Pruss Excavation insta			A 11	V.			
Current Condition:	Silt Fence	Northern Checks	7/12/2023	Active	Yes			
Current Condition:	Fair Condition- Pruss Excavation installed SF 11 prior to the inspection on 7/12/23. Pruss excavation removed SF 11 due to grading prior the inspection on 9/20/23. Due to erosion matting, diversion berms, and other silt fence being installed, silt fence 11,13, and 14 will no long							
	the inspection on 9/20/23. Due to erosion matting, diversion berms, and other silt fence being installed, silt fence 11,13, and 14 will no lone be recommended as of 11/2/23. Pruss Excavation installed silt fence 11 and 14 prior to the inspection on 11/8/23. SF 11 was removed an							
	be recommended as of 11/2/23. Pruss Excavation installed silt fence 11 and 14 prior to the inspection on 11/8/23. SF 11 was removed and 14 was damaged prior to the inspection on 3/20/24 due to sanitary installation. SF 14 was removed prior to the 4/3/24 inspection.							
	The state of the s	and to durindiry inc		p				
	Silt fence 11 and 14 should be re-inst	alled when work allows.						
	<b>Great Plains Contractor Services was</b>	Great Plains Contractor Services was informed to complete by 4/10/24.						
SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	Yes			
Current Condition:	Fair Condition- Pruss Excavation insta	lled Silt fence 15-18 prior to th	ne inspection on 11/1/23.					
	Silt fence 15 should be repaired when	re damaged.						
	Great Plains Contractor Services was	s informed to complete by 4	/10/24.					
SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	No			
Current Condition:	Good Condition- Pruss Excavation insta	lled the silt fence prior to the i			down during the			
	inspection on 9/27/23. Pruss Excavation	repaired the silt fence prior to	the inspection on 11/8/23					
	C!4 F	Southern Half of Courtyard	0/5/0000	D				
SF 20 - 30	Silt Fence	Court	8/5/2023	Pending	No			
Current Condition:	Pending- Silt fence will be installed once							
		Northern Half of Courtyard	Г		T			
SF 31 - 34	Silt Fence	Court	8/5/2023	Pending	No			
Current Condition:	Pending- Silt fence will be installed once		<u> </u>		1			
Carrent Containion.	- Shaling- Oilt forfice will be installed Office	grading starts.	<u> </u>		T			
	Silt Fence	Eastern Perimeter Checks	11/1/2023	Active	No			
05.05.45	) Sill Ferice	Lastelli Lellilletei Ciletiva	11/1/2025					
SF 35 - 42 Current Condition:	Good Condition- Pruss Excavation insta			Active	140			

SF 43 - 48	Silt Fence	Southern Half of Western Perimeter	11/1/2023	Active	No	
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.					
SF 49 - 51	Silt Fence	West of Courtyard Court	11/1/2023	Active	No	
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.					
SF 52 - 55	Silt Fence	Northern Half of Western Perimeter	11/1/2023	Active	No	
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.					
STR	Streets	ADJ and Internal Streets	8/5/2023	Active	No	
Current Condition:	Good Condition- Streets were clean during the inspection on 11/22/23.					
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No	
Current Condition:	Good Condition- E&A inspector installed a SWPPP sign during the inspection on 10/11/23.					
WO 01	Concrete Washout	On Site		Removed		
Current Condition:	Removed- Pruss Excavation removed the concrete washout prior to the inspection on 11/22/23.					
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No	
Current Condition:	Pending- Waste storage will be installed	as necessary.				
Certification Statement	"I certify, under penalty of law, that this of system designed to assure that qualified person or persons who manage the syst the best of my knowledge and belief, tru information including the possibility of fin	d personnel properly gathered tem or those persons directly e, accurate, and complete. I a	and evaluated the informates responsible for gathering am aware that there are sign	ation submitted. Based the information, the inf	d on my inquiry of the formation submitted is, to	
Inspector Signature:	Zoh Rigo			Reviewed By:	et su	