E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dep	. Manager			Engineering	Answers	
Increator: Zach Boza		E&A- P2006.056.019			Stage	
Inspector: Zach Roza Project Name:		Courtyards @ Iron Horse CSW-202207403				
For Week Ending:		4/27/2024			68003	
Project Location:	South Lakeview V	Vay and Courtyard Court - A	shland, NE (Saunders Cou	nty)		
Grading: Sanitary Sewer:		0% 0%				
Storm Sewer:		0%				
Paving:		0%				
Seeding:		0%				
Utilities:		0%				
Overall Development:	1	0%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
					Week 1	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"	A/0.4/000.4	Moothy Provent 70 / 50	0.50 414		
Wednesday:	0.00"	4/24/2024	Mostly Sunny 70 / 52	9:50 AM		
Thursday:	0.01"				00.45 40.55	
Friday: Saturday:	0.97"				00:15 - 16:55	
Saturday:	0.10					
Complaints:	None					
Grubbing began (7/5/23). Grad	ns) of the site have had a temporary or permanen ing began (9/13/23). Grading ceased (11/2 ns) of the site do not have grading, earthwork, or	2/23). Sanitary Installation be	gan (3/20/24).	t 14 days?		
	ing began (9/13/23). Grading ceased (11/2		gan (3/20/24).			
	lization measures listed in this section are being rosion Matting 1,2,3,4,6,7 installed (11/1/23		ting (11/1/23). Entire site see	ded (3/13/24).		
Checklist Questions:						
	t to the project free of any significant si	gns of erosion or sediment	that would be associated v	vith the constructio	on activity?	
Yes Create Corrective Action?						
N/A						
prevent erosion. _{Yes}	eeded or otherwise stabilized as require	d? List inactive portions of	the project and if stabilizat	ion measure are ad	lequate or needed to	
Create Corrective Action?						
Are waste materials (concret Yes Create Corrective Action?	e, construction material, hazardous, etc	.) being managed properly?	·			
N/A Are construction entrances a	nd adjacent streets being maintained ad	lequately?				
No Create Corrective Action? No- See BMP Section						
Is dust associated with the c Yes	onstruction activity adequately controlle	ed on the site?				
Create Corrective Action?						
N/A						
Comments:						
Comments: 1.) Site was inactive during the	last inspection.					
Findings / Corrective Actions	(Date):					

Unique Name CE 01	Type Construction Entrance	Location Off 113th Street	Projected Install Date 9/20/2023	Status Pending	Maintenan Yes		
Current Condition:	Pending - Pruss Excavation installed a c	onstruction entrance prior to	the inspection on 9/20/23.	Pruss Excavation rer	noved the constru		
	entrance prior to the inspection on 10/25		or Services installed silt f	ence to prevent sed	iment from leavi		
	site prior to the inspection on 4/24/24.						
	Construction entrance should be re-installed.						
	Pruss Excavation was informed to complete by 11/1/23. Not done as of the last inspection. Pruss Excavation was reminded on 12/7/23 3/21/24. Great Plains Contractor Services was informed to complete by 4/10/24. Not done as of the last inspection. Great Plains Contractor Services was informed to complete by 4/10/24. Not done as of the last inspection.						
	Services was reminded on 4/17/24.		<i>sy ii</i> 10,2 tot doile do e.	and have mopeonionin a			
DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta	lled a diversion berm prior to	the inspection on 10/11/23				
DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta	lled a diversion berm prior to	the inspection on 10/18/23				
DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta		the inspection on 10/18/23				
FT 01	Fuel Tank	On Site	11/1/00	Removed			
Current Condition: IP 1 - 2	Removed- Pruss Excavation removed th Inlet Protection	Along Courtyard Court	tion on 11/1/23. 11/8/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta	led IP 1 and 2 prior to the ins	pection on 11/8/23.				
IP 3 - 4	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Inlet protection will be installed						
IP 5 - 6 Current Condition:	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
	Pending- Inlet protection will be installed		0/5/0000				
IP 7 Current Condition:	Inlet Protection Pending- Inlet protection will be installed	Along Courtyard Court	8/5/2023	Pending	No		
	. siding mot prototion will be installed	South East portion of the			1		
MT 01	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta		to the inspection on 11/1/2	3.	•		
		South East portion of the	44/4/0000	A =411	Ne		
MT 02	Erosion Matting	site	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta	lled the erosion matting prior	to the inspection on 11/1/2	3.			
17.00	Erosion Matting	South West portion of the	11/1/2023	Active	No		
MT 03 Current Condition:	Good Condition- Pruss Excavation insta	site	to the increation on 11/1/2	2			
		÷.	•				
MT 04 Current Condition:	Erosion Matting Good Condition- Pruss Excavation instal	ADJ to Private Drive	11/1/2023	Active	No		
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed		0/3/2023	rending	IN0		
MT 06	Erosion Matting	North of Courtvard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal						
MT 07	Erosion Matting	North of Courtyard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta						
PT 01	Portable Toilet	On Site		Removed			
Current Condition:	Removed- Pruss Excavation removed th						
SF 01 - 09	Silt Fence	Eastern Perimeter	11/1/2023	Active	No		
Current Condition: SF 10 - 14	Good Condition- Pruss Excavation insta Silt Fence	Northern Checks	7/12/2023	Active	Yes		
Current Condition:	Fair Condition- Pruss Excavation installe	d SF 11 prior to the inspection	n on 7/12/23. Pruss excav	ation removed SF 11	due to grading p		
	the inspection on 9/20/23. Due to erosio						
	be recommended as of 11/2/23. Pruss Excavation installed silt fence 11 and 14 prior to the inspection on 11/8/23. SF 11 was removed a						
	14 was damaged prior to the inspection on 3/20/24 due to sanitary installation. SF 14 was removed prior to the 4/3/24 inspection.						
	Silt fence 11 and 14 should be re-installed when work allows.						
	Great Plains Contractor Services was in was reminded on 4/17/24.	tormed to complete by 4/10/2	4. Not done as of the last	nspection. Great Pla	ns Contractor Se		
SF 15 - 18	Silt Fence	Western Perimeter	11/1/2023	Active	Yes		
Current Condition:	Fair Condition- Pruss Excavation installe				103		
	Silt fence 15 should be repaired where damaged.						
	Great Plains Contractor Services was informed to complete by 4/10/24. Not done as of the last inspection. Great Plains Contractor Serv						
	was reminded on 4/17/24.			, in croat in			
SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation insta	led the silt fence prior to the	nspection on 7/12/23. Part	of the silt fence was			
	inspection on 9/27/23. Pruss Excavation		o the inspection on 11/8/23				
	Silt Fence	Southern Half of Courtyard	8/5/2023	Pending	No		
SF 20 - 30	1	Court			1		
Current Condition:	Pending- Silt fence will be installed once				•		

Current Condition:	Pending- Silt fence will be installed onc	e grading starts.					
SF 35 - 42	Silt Fence	Eastern Perimeter Checks	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
SF 43 - 48	Silt Fence	Southern Half of Western Perimeter	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
SF 49 - 51	Silt Fence	West of Courtyard Court	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
SF 52 - 55	Silt Fence	Northern Half of Western Perimeter	11/1/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation installed Silt fence 35-42 prior to the inspection on 11/1/23.						
STR	Streets	ADJ and Internal Streets	8/5/2023	Active	Yes		
	Adjacent streets should be cleaned. Great Plains Contractor Services was i	informed to complete by 4/18/2	4. Not done as of the las	t inspection.			
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No		
Current Condition:	Good Condition- E&A inspector installe	<u> </u>	pection on 10/11/23.				
WO 01	Concrete Washout	On Site		Removed			
Current Condition:	Removed- Pruss Excavation removed the concrete washout prior to the inspection on 11/22/23.						
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No		
Current Condition:	Pending- Waste storage will be installed as necessary.						
Certification Statement	"I certify, under penalty of law, that this system designed to assure that qualifie person or persons who manage the sys the best of my knowledge and belief, tr information including the possibility of fi	ed personnel properly gathered stem or those persons directly r ue, accurate, and complete. I a	and evaluated the informative responsible for gathering to am aware that there are significant to the sis significant to the si	tion submitted. Based of he information, the info	on my inquiry of the rmation submitted is,		