E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Yes

N/A

Create Corrective Action?

Engineering Answers

		E&A- P2022.10	1.004		Stage		
Inspector: Josh Ellington	pector: Josh Ellington						
		Diers 8th Addition					
Project Name:		CSW-202307620					
<u> </u>							
For Week Ending:		12/9/2023					
Project Location:	E 22nd Str	eet and Deer Cross	ing, Fremont, NE (Dodge	County)			
Grading:	80%			1			
Sanitary Sewer:	15%						
Storm Sewer:	2%						
Paving:	0%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	20%			+			
Overall Bevelopment.	2070		ļ	ļ			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
		Date mepeeted	Treatile Containent		Wee		
Sunday:	0.00"				1100		
Monday:	0.00"	12/4/2023	Mostly cloudy 31	10:00 AM			
Tuesday:	0.00"			101001111			
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
	14.44						
Complaints:	None						
· 							
Construction Sequencing:							
Which portion(s) (i.e. drainage basins	<u> </u>						
Stripping and grading began (6/	5/2023). Grading along Elkhor	n Drive east of Deer	Crossing (6/12/2023). Grad	ling along Elkhorn D	rive west of Deer		
Crossing (6/26/2023).							
Allelah madian (a) (i a daalaana haala	-) -5 db d		trade and a selection of the Alexander	44 4			
Which portion(s) (i.e. drainage basin							
Stripping and grading began (6/ Crossing (6/26/2023).	5/2023). Grading along Eikhor	n Drive east of Deer	Crossing (6/12/2023). Grad	ing along Elknorn D	rive west of Deer		
What temporary or permanent stabili	zation measures listed in this secti	on are being implemente	ed?				
Existing vegetation.		 					
Checklist Questions:							

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction

Yes					
Create Corrective Action?					
N/A					
Are waste materials (concrete, con	struction material, haza	ordous, etc.) being mai	naged properly?		
Yes	iotraotron material, naze	naoas, etc., being mai	lugeu property :		
Create Corrective Action?					
N/A					
Are construction entrances and ad	liacent etreete heina ma	intained adequately?			
No	ijacent streets being ma	initalileu auequately:			
Create Corrective Action?					
No - See BMP section					
la divet acceptated with the country	ration patholter adamenta	le controlled on the cit			
Is dust associated with the constru	action activity adequate	ly controlled on the Si	.e <i>r</i>		
Create Corrective Action?					
N/A					
0					
Comments: Comments:					
Comments: 1.) Site was active for storm sewer in	stallation during the most	recent inspection			
,		Teochi inspection.			
Findings / Corrective Actions (Date					
Findings / Corrective Actions (Date 1.) Some maintenance is required in					
1.) Some maintenance is required in	the Bivip section.				
	T				
Unique Name	Tuno	Location	Brain atad Inatall Data	Status	Maintananaa
Unique Name Berm	Type Dirt Berm	Location On Site	Projected Install Date	Status Removed	Maintenance
Current Condition:			e site was installed in lieu		meter control prior to
Garront Gorialion.	Removed - A berm in the northwest portion of the site was installed in lieu of silt fence as perimeter control prior to the 6/12/23 inspection. The berm in the northwest portion of the site was removed prior to the 6/26/23 inspection				
			A berm was installed to t		
	BMP was changed as of	7/6/23.			
B 1	Berm	See SWPPP		Removed	
Current Condition:	Removed - Berm was re	moved due to grading a	ctivity prior to the 9/11/23	inspection.	
B 2	Berm	See SWPPP		Removed	
Current Condition:			ctivity prior to the 9/11/23		
			,	·	
B 3 Current Condition:	Berm Was ro	See SWPPP	ativity prior to the 0/11/22	Removed	
	Removed - Berm was removed due to grading activity prior to the 9/11/23 inspection.				
B 4 Current Condition:	Berm	See SWPPP	ativity prior to the 0/11/22	Removed	
		moved due to grading a	ctivity prior to the 9/11/23	inspection.	
CE 1	Construction Entrance	N Luther Road	7/3/2023	Active	Yes
Current Condition:			moved prior to the 7/17/2		
	installed the construction	entrance and slit tence	on either side of the entr	ance prior to the 10/2	2/23 inspection.
	Additional rock should be	e added			
	Thompson Construction	was informed to comple	ete by 11/27/23. Not done	as of last inspection	
05.0	2		0.40=40000		
CE 2 Current Condition:	Construction Entrance	Elkhorn Drive	9/25/2023 porary barricade for the el	Pending Pending	No 0/0/22 inspection
Current Condition.			ce once soil compaction i	•	-
			ction. Thompson reinstalle		
			parricade prior to the 11/1		
CE 3	Construction Entrance	Elk Lane	10/16/2023	Pending	No
Current Condition:			as of 10/16/23 inspection.		
	temporary entrance barr	ier prior to the 10/23/23	inspection. Sawyer Const	ruction from First Co	mmunity Bank (CSW
	- 202272520) moved the	entrance barriers and o	caused track out prior to th	ne 10/30/23 inspectio	on. See Street
			vyer Construction reinstal		or to the 11/6/23
	linspection. The barricac	de was removed prior	to the 12/4/23 inspection	1.	

D 1	Diversion	See SWPPP	7/3/2023	Pending	No		
Current Condition:			rading in the area begins.	· · · · · · · · · · · · · · · · · · ·	ı		
D 2	Diversion	See SWPPP	7/3/2023	Pending	No		
Current Condition:			rading in the area begins.		ı		
D 3	Diversion	See SWPPP	7/3/2023	Pending	No		
Current Condition:			rading in the area begins.				
FT	Fuel Tank	On Site	9/11/2023	Active	No		
Current Condition:			led a fuel tank with secon				
		Construction installed th	e drainage plug to the fue	l tank's secondary co	ontainment prior to t		
	10/9/23 inspection.						
IF 1	Inlet Filter	See SWPPP	7/6/2023	Active	No		
Current Condition:			the inlet filter prior to the				
					ı		
IF 2	Inlet Filter	See SWPPP	7/6/2023	Active	No No		
Current Condition:			the inlet filter prior to the et filter prior to the 9/11/23		3. Sawyer		
IF 3	Inlet Filter	See SWPPP	7/3/2023	Pending	No		
Current Condition:	I .		when necessary. E&A ins				
					I		
IF 4	Inlet Filter	See SWPPP	7/3/2023	Pending	No :		
Current Condition:	Pending - The inlet filter	will be installed on site	when necessary. E&A ins	spector will continue	to monitor.		
PT	Portable Toilet	On Site	9/11/2023	Active	No		
Current Condition:			led a portable toilet prior				
	Construction removed the portable toilet prior to the		the 9/18/23 inspection. T	hompson Constructi	on reinstalled the		
MS 01	Material Storage	On Site	7/3/2023	Pending	No		
Current Condition:	Pending - The material			rending	INO		
SF 01	Silt Fence	P22 to L7	7/3/2023	Pending	No		
	I .						
Current Condition:			s of the 9/11/23 due to the		buller and the liat		
	grade of the project; E&	A inspector will monitor	for installation as necessa	ary.			
SF 02	Silt Fence	X21 to T24	7/3/2023	Pending	No		
Current Condition:	Pending - Silt fence will	not be recommended a	s of the 9/11/23 due to the	e existing vegetative	buffer and the flat		
	grade of the project; E&	A inspector will monitor	for installation as necessa	ary.			
SF 03	Silt Fence	M7 to T7	7/3/2023	Pending	No		
Current Condition:			s of the 9/11/23 due to the	,			
Current Condition.			for installation as necessar		buller and the hat		
SF 04	Silt Fence	J15 to M18	7/3/2023	Pending	No		
Current Condition:			s of the 9/11/23 due to the for installation as necessa		buffer and the flat		
SF 05	Silt Fance	115 to M17	7/2/2022	Donding	No		
	Silt Fence	J15 to M17	7/3/2023	Pending	No		
Current Condition:			s of the 9/11/23 due to the		buller and the liat		
	grade of the project, E&	A inspector will monitor	for installation as necessa	ary.			
SF 06	Silt Fence	L16	7/3/2023	Pending	No		
Current Condition:			s of the 9/11/23 due to the		buffer and the flat		
	grade of the project; E&	A inspector will monitor	for installation as necessa	ary.			
SF 07	Silt Fence	M18 to P 22	7/3/2023	Pending	No		
Current Condition:		-	s of the 9/11/23 due to the				
Carrent Condition.			for installation as necessa		bullet and the hat		
		-		-			
SF CE 1	Silt Fence	CE 1	10/2/2023	Active	No		
Current Condition:		yer Construction insta	lled silt fence on either	side of CE 1 prior to	o the 10/2/23		
	inspection.						
	Streets	ADJ and Internal Streets	7/3/2023	Active	Yes		
STR	1		ho trook out from Elk Lan	nrior to the 11/6/22	Linspection		
STR Current Condition:	Fair Condition Courses	(onetrijetion removed t	Fair Condition - Sawyer Construction removed the track out from Elk Lane prior to the 11/6/23 inspection. Thompson Construction removed the track out from Elkhorn Drive prior to the 11/13/23 inspection.				
STR Current Condition:							
	Thompson Construction	removed the track out t					
		removed the track out t					
	Thompson Construction Clean streets along N Li	removed the track out t		o the 11/13/23 inspec	ction.		

SWPPP Sign 01	SWPPP Signs	East entrance	6/30/2023	Active	No	
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign during the 6/30/23 inspection.					
WO 01	Concrete Washout	On site	7/3/2023	Pending	No	
Current Condition:	Pending - A concrete washout will be installed on site as necessary.					
WS 01	Waste Storage Area	On site	7/3/2023	Pending	No	
Current Condition:	Pending - The waste storage area will be installed as necessary.					
	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.					
nspector Signature:	HE			Reviewed By:	Ports Sol	