E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Saturday

N/A



E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept Manager

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.		ENGINEERING	· PLANNING · ENVIRONMEN	TAL & FIELD SERVICES
Environmental del vices Dept.		&A - P2004.245.000)	
Inspector: Alex Emerson		27(1 200-12-0.000	•	Stage
mopeotor: Alex Emerson		Elkhorn	Viow	3
Project Name:		0687 2014		
For Week Ending:				
Project Location:	192nd	& Bedford Ave- Oma	ha, NE (Douglas County)	68022
-	•			•
Grading:		00%		
Sanitary Sewer:		00%		
Storm Sewer:		00%		
Paving:		00%		
Seeding:		00%		
Utilities:		00%		
Overall Development:		55%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	
				Week
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.12"			
	<u></u>			Week
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.05"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week
Sunday:	0.00"			
Monday	0.00"			
Tuesday	1.58"			
Wednesday	1.94"			
Thursday	0.06"	10/02/14	65/50 Cloudy	
Friday	0.00"			
Saturday	0.00"			
Sunday	0.00"			Week
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday				
Saturday	0.00"			Week
Sunday	N/A	NI/A	NI/A	Week
Sunday:	N/A N/A	N/A N/A	N/A N/A	
Monday Tuesday	N/A N/A	N/A N/A	N/A N/A	
Wednesday	N/A N/A	N/A N/A	N/A N/A	
	N/A N/A	N/A N/A	N/A N/A	
Thursday Friday	N/A N/A			
Friday	N/A	N/A	N/A	+ + +

N/A

N/A

	None				
Complaints:					
	_		1		
Construction Sequencing:					
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or perm	nanent cessation of grading	, earthwork, or ground distur	bance in the las	st 14 days?
Entire site; grading completed and site	seeded Spring 2005.				
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwo	rk. or ground disturbance s	cheduled in the next 14 days	?:	
3,111	3,	, , ,			
Entire site; grading completed and site	seeded Spring 2005				
Entire site, grading completed and site	Seeded Opting 2000.				
What temporary or permanent stabilization me	nacurae lietad in this caction are b	ooing implemented?			
		being implemented:			
Paving, dense vegetation and landscap	ping were completed on site.		1		
Comments:					
Comments:					
Home construction is active on a few lo	ots				
Findings / Corrective Actions (Date)					
Findings / Corrective Actions (Date):	•				
Fig. disc. 1 (0 - m 4) A - 4 - m - (D - 4 - 1)	_				
Findings / Corrective Actions (Date):					
 Some maintenance is required in the 	e BMP Section.				
	1		1		
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
		N41d17m09s			
CE 1	Construction Entrance	W96d12m58s		Removed	
Current Condition:	Removed				
Carrent Contanton.	rtomovod	N41d17m09s			
CE 2	Construction Entrance	W96d13m05s		Removed	
		W 900 1311038		Kemoved	
Current Condition:	Removed - Entrance Paved		0/4/00/4		
Lot 8	Individual Lot	Lot 8	8/1/2014	Pending	No
Current Condition:	Pending-There is no constru			A silt fence	e was installed
	on the back of the lot by unk	known party prior to insp	pection on 8/1/14.		
Lot 9	Individual Lot	Lot 9	6/28/2014	A otivo	No
				Active	No Daile
Current Condition:	Good Condition-Silt fence ar		re installed on the back o	if the lot by D	ave Paik
	Builders prior to inspection of	on 8/1/14.			
Lot 17	Silt Fence	Lot 17		Removed	
Current Condition:	Removed-SF was removed,		was renaired in turf area		ulk was alaanad
Current Condition:				s, and sidewa	iik was cleaned
	by Ramm Construction prior	to inspection on 6/23/1	14.		
Lot 25	Silt Fence	Lot 25		Removed	
Current Condition:	Lot was sodded prior to insp	ection on 11/26/12 by N	Marque Homes.		
Lot 29	Individual Lot	Lot 29	8/1/2014	Active	Yes
Current Condition:	Fair Condition-Silt fence was	s extended to the SW c	orner and straw wattles v	vere installed	along the curb
Carroni Conanioni	by R&A Builders prior to insp		onior and onan mamoo .	roro miotamoa	along alo oalo
	by Ran Ballacis prior to map	Section on 6/29/14.			
		of increation on 10/2/	4.4		
	SF is down in a few areas as	s of inspection on 10/2/	14.		
	R&A was requested to repai	r down SF by 10/9/14.			
Lot 33	Misc/Other	Lot 33		Removed	
	Lot was sodded prior to insp		I AMM Construction	Nemoveu	
Current Condition:	·		RAIVINI CONSTRUCTION.		
Lot 34	Misc/Other	Lot 34		Removed	
Current Condition:	Removed-The lot was sodde	, ,	n prior to inspection on 6		
Lot 35	Misc/Other	Lot 35		Removed	
Current Condition:	Removed-Concept Homes a	and Designs sodded the	e lot prior to inspection or	n 8/25/14.	
Lot 36	Silt Fence	Lot 36		Removed	
Current Condition:	Removed-Concept Homes a	and Designs sodded the	e lot prior to inspection or		
	La disciplination of	Lat 00	The state of the s	A - 41	V

Current Condition:	Active						
	1) There is active construction on the lot and no BMP in place as of inspection on 10/2/14. 2) There is some trackout as of inspection on 10/2/14.						
		1) Inspire was requested to install SF on the front of the lot by 10/9/14. 2) Inspire was requested to clean trackout by 10/3/14.					
Lot 41	Silt Fence	Lot 41		Removed			
Current Condition:	Removed-John Caniglia Ho		r to inspection on 10/2/1				
Lot 43	Misc/Other	Lot 43		Removed			
Current Condition:	Removed-Lot was sodded removed as of 2/4/14.	by Malibu Homes prior to	o inspection on 12/6/13 a	and the porate	able toilet was		
Lot 47	Misc/Other	Lot 47		Removed			
Current Condition:	Removed-Lot was sodded						
Lot 49	Individual Lot	Lot 49	8/1/2014	Active	No		
Current Condition:	Active-Matrix Homes has active construction on the lot as of inspection on 8/1/14. A BMP is not being requested on the lot due to the lot being flat as of inspection on 8/1/14. Inspector will monitor.						
Lot 56	Misc/Other	Lot 56		Removed			
Current Condition:	Removed-All BMPs have b	een removed from the lo	ot and there is no constru	uction activity	as of inspection		
Lot 57	on 3/6/14. Silt Fence	Lot 57		Removed			
Current Condition:	Removed-Filter socks are b		andmark Homes	Removed			
Lot 58	Silt Fence	Lot 58	10/16/2013	Active	Yes		
Current Condition:	Fair Condition-	201.00	10/10/2010	7101170	100		
	 Silt fence is undermined in the front as of inspection on 6/23/14. Landmark Homes was requested to complete the maintenance items by 6/11/14. Not done as of last inspection. Steve with Landmark Homes was reminded on 6/23/14, 10/3/14. Steve with Landmark Homes was requested to repair the undermined silt fence by 6/30/14. Not done as of last inspection. Steve with Landmark Homes was reminded on 10/3/14 						
Lot 69	Silt Fence	Lot 69		Removed			
Current Condition:	Removed-Ramm Construct		dded the lot prior to insp		14.		
Lot 73	Silt Fence	Lot 73	<u>'</u>	Removed			
Current Condition:	Removed-SF was removed 6/23/14.	l, rill was repaired and lo	t was sodded by Malibu	Homes prior	o inspection on		
Lot 76	Misc/Other	Lot 76		Removed			
Current Condition:	Removed-The disturbed are		shed natural vegetation a				
OLB Current Condition:	Silt fence Silt fence in the outlot was	OLB	ion on 11/E/12 by Mark I	Removed	n on 8/1/14.		
Current Condition.	Silt ferice in the outlot was			Honkine w/ M			
Ì			1011 011 11/5/12 by Wark I	Hopkins w/ M			
SB A	Sediment Basin	N41d17m09s					
SB A Current Condition:	Sediment Basin Good Condition - 36% Fille the basin as of inspection of 8/1/14.	N41d17m09s W96d13m14s d. An unknown contracto	In place	Active removing volu	No unteer trees from		
Current Condition:	Good Condition - 36% Fille the basin as of inspection of 8/1/14.	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector	In place	Active removing volu mark during in	No unteer trees from		
	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed prior	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0	In place or was in the process of repainted the cleanout in the process of the repainted the cleanout in the process of the pr	Active removing volumark during in Removed ense vegetation	No Inteer trees from aspection on		
Current Condition:	Good Condition - 36% Fille the basin as of inspection of 8/1/14.	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0	In place or was in the process of repainted the cleanout in the process of the repainted the cleanout in the process of the pr	Active removing volumark during in Removed ense vegetation	No Inteer trees from aspection on		
Current Condition:	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed prior	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0	In place or was in the process of repainted the cleanout in the process of the repainted the cleanout in the process of the pr	Active removing volumark during in Removed ense vegetation	No Inteer trees from aspection on		
Current Condition: SF 1 Current Condition:	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed price was notified that this silt fer	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0 nce is to be re-installed of N41d17m10s W96d13m03s	In place or was in the process of repainted the cleanout in the process of repainted the cleanout in the process of repainted the cleanout in the process of	Active removing volumark during in Removed ense vegetations active in this Removed	No Inteer trees from aspection on		
SF 1 Current Condition: SF 2	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed pric was notified that this silt fer Silt Fence	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0 nce is to be re-installed of N41d17m10s W96d13m03s	In place or was in the process of repainted the cleanout in the process of repainted the cleanout in the process of repainted the cleanout in the process of	Active removing volumark during in Removed ense vegetations active in this Removed	No Inteer trees from aspection on		
SF 1 Current Condition: SF 2 Current Condition: ST B	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed pric was notified that this silt fer Silt Fence Silt fence has been removed Sediment Trap	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0 nce is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s	In place or was in the process of repainted the cleanout in the process of repainted the cleanout in the process of repainted the cleanout in the process of	Active removing volumark during in Removed ense vegetations active in this Removed	No Inteer trees from aspection on		
SF 1 Current Condition: SF 2 Current Condition:	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed pric was notified that this silt fer Silt Fence Silt fence has been remove	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0 nce is to be re-installed of N41d17m10s W96d13m03s ad. All drainage area is s N41d17m18s W96d13m14s	In place or was in the process of repainted the cleanout in the process of repainted the cleanout in the process of repainted the cleanout in the process of	Active removing volumark during in Removed ense vegetations active in this Removed owing.	No Inteer trees from aspection on		
SF 1 Current Condition: SF 2 Current Condition: ST B	Good Condition - 36% Fille the basin as of inspection of 8/1/14. Silt Fence Silt fence was removed pric was notified that this silt fer Silt Fence Silt fence has been removed Sediment Trap	N41d17m09s W96d13m14s d. An unknown contractor on 8/1/14. E&A inspector N41d17m12s W96d13m15s or to inspection on 8/18/0 nce is to be re-installed of N41d17m10s W96d13m03s d. All drainage area is s N41d17m18s	In place or was in the process of repainted the cleanout in the process of repainted the cleanout in the process of repainted the cleanout in the process of	Active removing volumark during in Removed ense vegetations active in this Removed owing.	No Inteer trees from aspection on		

Current Condition:	Good Condition-No major si inspection on 8/1/14.	gns of trackout. John	Caniglia Homes cleane	d trackout from lo	t 41 prior to
SWPPP Sign	Signs	2 signs	8/19/2008	Active	No
Current Condition:	Good Condition:				
	192nd and Miami / 192nd a	nd Corby			
Inspector Signature:	2		Reviewed By:	Zadnany	L. Jilde