E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Aaron Tulley		E&A - P2018.109.002				
		Gallery 23 East				
	CSW-201702253 (Mass Grading) CSW-210802622 (Intersection Improv-Pending)					
		CSW-201802623 (Water Main Improvements) CSW-201802624 (East Lift Station)				
Project Name:	CS					
For Week Ending:		2/23/2019				
Project Location:	County Road	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				
	Gallery 23 East	Water Main Project	Lift Station & Force Main	Intersection Impr.		
Grading:	85%			0%		
Sanitary Sewer:	70%			0%		
Storm Sewer:	0%			0%		
Paving: Seeding:	0%			0% 0%		
Utilities:	60%			0%		
Overall Development:	20%		99%	0%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
Cundow	0.06"				Week	
Sunday:	0.00"					
Monday	0.02					
Tuesday Wednesday	0.00"					
Thursday	0.00"					
Friday	0.01"					
	0.06"					
Saturday	0.00				Week	
Sunday:	0.07"				Week	
Monday	0.00"					
Tuesday	0.03"					
Wednesday	0.17"	2/20/2019	Snow 29/7			
Thursday	0.00"		0.10.11.20,7			
Friday	0.04"					
Saturday	0.12"					
					Week	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
Complaints:						
Construction Sequencing:						
) of the site have had a temporary or perm	anent cessation of grading.	earthwork, or ground disturband	ce in the last 14 days?		

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occured in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection.

Highway 30 intersection improvements have not begun as of last inspection.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :
Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occured in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection.

Highway 30 intersection improvements have not begun as of last inspection.

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18).

Summary Questions:

d entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Checklist Questions:

No - See Findings Section

Is dust associated with the construction activity adequately controlled on the site?

Comments:

The site was inactive during the last inspection for the Gallery 23 East project. Interior sanitary work is occurring by Thompson and major grading activities have ceased with the Gallery 23 East project by Pruss Excavation. Grading for water tie in along Rd 25 as of last inspection. Grading has ceased.

Lift Station and Sanitary Force Main projects are nearing completion. Work is occurring on the southeast intersection of County Road U and the project. County Road U Blvd and East 16th Street ditches will be stabilized in the coming weeks as of 8/30/2018. E&A will continue to monitor. Street ditches were seeded and matted prior to inspection on 9/19/18. During inspection on 2/20/19, the road side ditches on the E side of Hwy 275 for the sanitary project were covered in snow, therefore the status of the wattles could not be visually verified.

Water Improvements project has begun as of last inspection. Dirt piles from water main improvement project are being moved over to Gallery 23 East project in low areas. Dirt will be spread at a later date (2/7/19).

Highway 30 intersection improvements project has not been transferred to E&A Consulting Group, Inc. for inspections or construction observation. E&A will continue to monitor and update when more permitting information is known.

According to Jim Hammit, the E&A Construction monitor on site, the project is currently in a winter shutdown stage and no new work should be occurring until Spring.

Work for overhead electric occurring during inspection on 1/10/19 by Fremont Public Works around perimeter of Gallery 23 East. Overhead electric work no longer occurring as of last inspection.

During inspection on 2/20/19, the site was covered in 4-6 inches of snow. Due to snow cover, the inspector could not visually verify the status of all BMPs.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. See BMP section for required maintenance.
- 2. Diesel fuel tanks need to be bermed on site as of 8/30/2018. Pruss Excavation will be informed to complete by 9/6/2018. Not done as of last inspection. Thompson Construction was informed to complete by 10/16/18. Not done as of last inspection.
- 3. One portable toilet on the site needs to be staked down. Thompson Construction will be informed to complete when conditions allow as of 12/19/18. Not done as of the last inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
Gallery 23 East						
CE 1	Construction Entrance	County Road Blvd U	8/30/2018	Active	No	

Current Condition:	Good Condition - 70% effective. Pruss is off site as of 10/8/18. Thompson Construction added rock to the entrance prior to inspection on 11/6/18.						
		County Road					
CE 2	Construction Entrance	25/Highway 30	8/30/2018	Active	No		
Current Condition:	Good Condition - 70% effect						
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No		
Current Condition:	Pending - Culvert protection			1 chaing	110		
				 			
CP #2	Culvert protection Pending - Culvert protection	Southeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Culvert protection	i wiii be iristalled at a lat	er date.				
CW	Concrete Washout	Gallery 23 East	8/30/2018	Pending	No		
Current Condition:	Pending - Washouts will be	installed once paving be	egins.	<u> </u>			
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle check	ks will be installed when	grading has ended.				
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle check	ks will be installed when	grading has ended.				
		1					
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No		
Current Condition:	Good Condition - Wattles ch	necks were installed on	the southeast side prior to	8/30/2018.			
	D: : D:: 1	I 100 (1 1	1.10/0010	1 60 1			
DD #1 Current Condition:	Diversion Ditch Good Condition - After further	NW Corner of Lake	11/6/2018	Active Active	No recommended		
Current Condition:	Good Condition - After further	ei evaluation, as of 1/10	// 19 mspection, watties/che	cks will no longer be	recommended.		
DD #2	Diversion Ditch	W side of Lake	I	Active			
Current Condition:	Removed - Thompson Cons		L version ditch prior to insper				
DD #3	Diversion Ditch	SW corner of lake		Active			
Current Condition:	Removed - Thompson Cons		l version ditch prior to insper				
DD #4	Diversion Ditch	S Side of lake		Active			
Current Condition:	Removed - Thompson Cons		L version ditch prior to insper				
DD #5	Diversion Ditch	E side of lake	I	Active			
Current Condition:	Removed - Thompson Cons		Varsion ditch prior to inspec				
DD #6	Diversion Ditch	NE corner of lake	8/30/2018	Active	No		
Current Condition:	Good Condition - After further						
Guirent Gondition.	Cood Condition 7 liter furth	ci cvaidation, as or 1710	, 15 mapeonom, wantes/one	oks will no longer be	recommended.		
DD #7	Diversion Ditch	N side of lake	9/25/2018	Active	No		
Current Condition:	Good Condition - Due to gra	de of the lot and an acc	ess road being installed, s	ilt fence or straw bale	checks will not		
	be recommended at this tim	e. E&A will monitor.					
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Erosion control m	atting and seeding will be	pe installed when grading h	as ended.			
		Around Lake (Outlot					
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No		
Current Condition:	Pending - Erosion control m	atting and seeding will b	be installed when grading h	as ended.			
_							
SB #1	Sediment Basin	Central portion of site	8/30/2018	Pending	No		
Current Condition:	Pending - Basin will be insta	alled once grading has d	ommenced at a later date.				
SB #2	Sediment Basin	Southeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Basin will be insta	alled once grading has c	ommenced at a later date.				
05 "1	0% E	Countries	0/00/0043		N1 -		
SF #1	Silt Fence Pending - Silt Fence will be	Southeast corner	8/30/2018	Pending	No		
Current Condition:		motaneu at a later date.					
SF #2	Silt Fence	Northeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Silt Fence will be	installed at a later date.					
STR	Stroot clooping	Off-Site	In Place	Active 1	No		
Current Condition:	Street cleaning Good Condition - No signs of		III FIACE	Active	No		
			10/0/2212	D			
SWPPP Sign-SI Current Condition:	Signs Pending - Inspector installed	2 Entrances	10/9/2018	Pending Other SWPPP sign	Yes will be installed		
Current Condition:	at the County Rd U Blvd ent		uning mapecuon on 10/9/18	J. Other Sweep Sign	wiii be iristalied		
	at the County Na C Biva ent						
	The SWPPP sign blew off the t-post prior to inspection on 2/7/19 and needs reinstalled						
	Inspector will reinstall during	next inspection when o	conditions allow. Not done	as of the last inspe	ction.		
•							

	Sanitary Lift	Station and I	Force Main		
CE 1	Construction Entrance	County Road Blvd U	1	Removed	
Current Condition:	Removed - See CE1 for G		0/2018.	1100100	
CW	Concrete Washout	County Road Blvd U	1	Removed	
Current Condition:			0/2018. No concrete is being		itarv lift proiect.
		, ,		51	,
DC #1	Ditch Wattle Checks	Sheet C-603	9/13/2018	Active	No
Current Condition:			prior to inspection on 9/19/		
DC #2	Ditch Wattle Checks	Sheet C-604	9/13/2018	Active	No
Current Condition:			prior to inspection on 9/19/		110
DC #3	Ditch Wattle Checks	Sheet C-605	9/13/2018	Active	No
Current Condition:			prior to inspection on 9/19/		110
DC #4	Ditch Wattle Checks	Sheet C-606	9/13/2018	Active	No
Current Condition:			prior to inspection on 9/19/		
		Along ditch between	1	1	
EB #1	Erosion Blanket	Rd 25 and lift station	9/13/2018	Active	No
Current Condition:			led prior to inspection on 9/		
		Along ditch W of 25 E		1	
EB #2	Erosion Blanket	of Hwy 275	9/13/2018	Active	No
Current Condition:			led prior to inspection on 9/		1
EB #3	Erosion Blanket	E of Roundabout	9/25/2018	Active	No
Current Condition:			led prior to inspection on 9/2		
					N1.
STR Current Condition:	Street cleaning Good Condition - No signs	Off-Site	In Place	Active	No
Current Condition:	Good Condition - No signs	oi tiackout.			
SWPPP Sign-SI	Signs	2 Entrances		Removed	
Current Condition:	Removed - See SWPPP si		st project	Ttomovou	
	Water	r Main Extens	sion		
CW	Concrete Washout	County Road Blvd U	10/4/2018	Pending	No
Current Condition:	Pending - Washouts will be			i onding	110
0= ""	O.U. =	1			1
SF #1	Silt Fence	Area #1	A I D O (DMD- '- A	Removed	
SF #1 Current Condition:		fence in this area, see IF	2 1 and IP 2 for BMPs in Are		
Current Condition:	Removed - There is no silt	fence in this area, see IF N side of 24th St		ea #1	
Current Condition:	Removed - There is no silt Inlet Protection	fence in this area, see IF N side of 24th St (Enlarged Area #1)	10/23/2018	ea #1 Active	No No
Current Condition:	Removed - There is no silt Inlet Protection	fence in this area, see IF N side of 24th St (Enlarged Area #1)		ea #1 Active	
Current Condition: IP 1 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St	10/23/2018 alled inlet protection prior to	Active inspection on 10/23	3/18.
Current Condition: IP 1 Current Condition: IP 2	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1)	10/23/2018 alled inlet protection prior to 10/23/2018	Active Active Active Active	3/18. No
Current Condition: IP 1 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1)	10/23/2018 alled inlet protection prior to	Active Active Active Active	3/18. No
Current Condition: IP 1 Current Condition: IP 2	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018	Active Active Active Active	3/18. No
Current Condition: IP 1 Current Condition: IP 2 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018	Active inspection on 10/23 Active inspection on 10/23	3/18. No 3/18.
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2 installed when grading re	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area.	Active inspection on 10/23 Active inspection on 10/23 Pending	3/18. No 3/18.
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2 installed when grading re	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018	Active inspection on 10/23 Active inspection on 10/23 Pending	3/18. No 3/18.
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence Pending - Silt fence will be 2 straw wattles should be i	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2 installed when grading re	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. side ditch on the E side of A	Active inspection on 10/23 Active inspection on 10/23 Pending rea #2	3/18. No 3/18. Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2 installed when grading re	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area.	Active inspection on 10/23 Active inspection on 10/23 Pending rea #2	3/18. No 3/18. Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was informeminded on 12/19/18.	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. side ditch on the E side of A	Active inspection on 10/23 Active inspection on 10/23 Pending rea #2 pection. H.R. Books	No 3/18. No 3/18. Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Boo Inlet Protection Good Condition - H.R. Boo Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst S side of 24th St (Enlarged Area #1) kstrom Construction inst Area #2 installed when grading re installed across the roads med to complete by 11/20 Area #3	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. side ditch on the E side of A 1/18. Not done as of last insp 10/4/2018	Active inspection on 10/23 Active inspection on 10/23 Pending rea #2	3/18. No 3/18. Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads area to complete by 11/20 Area #3 installed when grading restalled when grading restalled across the roads area #3 installed when grading restalled when	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. 5ide ditch on the E side of A 6/18. Not done as of last insp 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Pending rea #2 Dection. H.R. Books Pending	No 3/18. No 3/18. Yes trom was
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads med to complete by 11/20 Area #3 installed when grading restalled when grading restalled when grading restalled across the roads Area #3 installed when grading restalled restalle	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ide ditch on the E side of A 10/4/2018 eaches area. 10/4/2018 eaches area.	Active inspection on 10/23 Active inspection on 10/23 Pending rea #2 pection. H.R. Books	No 3/18. No 3/18. Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads med to complete by 11/20 Area #3 installed when grading restalled when grading restalled when grading restalled across the roads Area #3 installed when grading restalled restalle	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ide ditch on the E side of A 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Pending rea #2 Dection. H.R. Books Pending	No 3/18. No 3/18. Yes trom was
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading results are to complete by 11/20 Area #3 installed when grading results are to complete by 11/20 Area #4 installed when grading results are to complete by 11/20 Area #4 installed when grading results are to complete by 11/20 Area #4 installed when grading results are to complete by 11/20	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Pending rea #2 Dection. H.R. Books Pending	No 3/18. No 3/18. Yes trom was
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading results are to complete by 11/20 Area #3 installed when grading results are to complete by 11/20 Area #4 installed when grading results are to complete by 11/20 Area #4 installed when grading results are to complete by 11/20 Area #4 installed when grading results are to complete by 11/20	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Pending rea #2 Dection. H.R. Books Pending	No 3/18. No 3/18. Yes trom was
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled on the S perimeter of across the second	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/23 Active Inspection on 10/23 Active Inspection on 10/23 Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled on the S perimeter of across the second	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Active Inspection on 10/23 Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt fence will be Silt fence will be silt fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled on the S perimeter of across the second	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4	Active Inspection on 10/23 Active Inspection on 10/23 Active Inspection on 10/23 Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #4 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be silt fence should be installed. H.R. Bookstrom was inform reminded on 12/19/18.	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads area #3 installed when grading restalled restalled restalled when grading restall	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ided ditch on the E side of A ided ditch o	Active Inspection on 10/23 Active Inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #4 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was informate reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt fence should be installed. H.R. Bookstrom was informate in the silt fence will be will fence will	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled to complete by 11/20 Area #4 installed when grading restalled grading restalled when grading restalled g	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ide ditch on the E side of A 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4 10/18. Not done as of last insp 10/4/2018 eaches area. Area #4 10/18. Not done as of last insp 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt fence will be Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled to complete by 11/20 Area #4 installed when grading restalled grading restalled when grading restalled g	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ide ditch on the E side of A 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4 10/18. Not done as of last insp 10/4/2018 eaches area. Area #4 10/18. Not done as of last insp 10/4/2018 eaches area.	Active Inspection on 10/23 Active Inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt fence should be installed. H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence should be installed. Silt Fence Pending - Silt fence will be Silt Fence should be installed.	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads ned to complete by 11/20 Area #3 installed when grading restalled on the S perimeter of the document of the stalled when grading restalled on the S perimeter of a grading restalled when grading restalled on the S perimeter of a grading restalled when grading restalled when grading restalled when grading restalled on the S perimeter of a grading restalled when grading restalled on the S perimeter of a grading restalled when grading restalled on the S perimeter of a grading restalled r	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ide ditch on the E side of A 1/18. Not done as of last insp 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4 1/18. Not done as of last insp 10/4/2018 eaches area. Area #4 10/4/2018 eaches area. Area #4	Active inspection on 10/23 Active inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes trom was Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt fence should be installed H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt fence should be installed Silt fence should be installed Silt fence will be sold fence will be	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads ned to complete by 11/20 Area #3 installed when grading restalled on the S perimeter of the document of the stalled when grading restalled on the S perimeter of a grading restalled when grading restalled on the S perimeter of a grading restalled when grading restalled when grading restalled when grading restalled on the S perimeter of a grading restalled when grading restalled on the S perimeter of a grading restalled when grading restalled on the S perimeter of a grading restalled r	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ide ditch on the E side of A 10/4/2018 eaches area. 10/4/2018 eaches area. 10/4/2018 eaches area. Area #4 10/18. Not done as of last insp 10/4/2018 eaches area. Area #4 10/18. Not done as of last insp 10/4/2018 eaches area.	Active inspection on 10/23 Active inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes trom was Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence will be Silt fence should be installed. H.R. Bookstrom was inform reminded on 12/19/18. Silt fence should be installed. H.R. Bookstrom was inform reminded on 12/19/18.	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled to complete by 11/20	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. Area #4 10/18. Not done as of last inspection prior to	Active inspection on 10/23 Active inspection on 10/23 Active inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending Pending Pending	3/18. No 3/18. Yes trom was No Yes trom was Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #4 Current Condition: SF #4 Current Condition: SF #5 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be interest of the silt fence will be 3 silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt Fence Pending - Silt fence will be Silt fence should be installed H.R. Bookstrom was inform reminded on 12/19/18. Silt fence Pending - Silt fence will be Silt fence should be installed H.R. Bookstrom was inform reminded on 12/19/18. Silt fence should be installed H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled to complete by 11/20 Area #6	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ided ditch on the E side of A ided ditch o	Active inspection on 10/23 Active inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending Pending Pending	No 3/18. No 3/18. Yes trom was No Yes trom was Yes
Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2 Current Condition: SF #3 Current Condition: SF #4 Current Condition: SF #4 Current Condition:	Removed - There is no silt Inlet Protection Good Condition - H.R. Bood Inlet Protection Good Condition - H.R. Bood Silt Fence Pending - Silt fence will be 2 straw wattles should be i H.R. Bookstrom was inform reminded on 12/19/18. Silt Fence Pending - Silt fence will be Silt Fence will be Silt fence should be installed. H.R. Bookstrom was inform reminded on 12/19/18. Silt fence should be installed. H.R. Bookstrom was inform reminded on 12/19/18.	fence in this area, see IF N side of 24th St (Enlarged Area #1) kstrom Construction inst. S side of 24th St (Enlarged Area #1) kstrom Construction inst. Area #2 installed when grading restalled across the roads and to complete by 11/20 Area #3 installed when grading restalled to complete by 11/20 Area #6	10/23/2018 alled inlet protection prior to 10/23/2018 alled inlet protection prior to 10/4/2018 eaches area. ided ditch on the E side of A ided ditch o	Active inspection on 10/23 Active inspection on 10/23 Active inspection on 10/23 Pending Pending Pending Pending Pending Pending Pending Pending Pending	3/18. No 3/18. Yes trom was No Yes trom was Yes

Current Condition:	Good Condition - Streets showed signs of improvement, however, some street cleaning is still necessary. H.R. Bookstrom Construction cleaned the streets at 24th St prior to inspection on 1/10/19.				
SWPPP Sign-SI	Signs	2 Entrances		Removed	
Current Condition:	Removed - See SWPPP signs under Gallery 23 East project				
Inspector Signature:	-Z7		Reviewed By:	Post Sul	