E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Aaron Tulley		E&A - P2018.109.002 Gallery 23 East					
	C	SW-201702253 (Mass Grading)		2		
	CSW-210	802622 (Intersec	tion Improv-Pendi	na)	2		
		•	-				
Due to at Name		CSW-201802623 (Water Main Improvements) CSW-201802624 (East Lift Station)					
Project Name:							
For Week Ending:	8/24/2019						
Project Location:	oject Location: County Road U and Lincoln Highway- Fremont, NE (Dodge County)						
	Gallery 23 East	Gallery 23 East Water Main Project Lift Station & Force Main Intersection Impr.					
Grading:	92%		99%	0%			
Sanitary Sewer:	96%		100%	0%			
Storm Sewer:	62% 65%	N/A N/A	N/A N/A	0% 0%			
Paving: Seeding:	1%		N/A 99%	0%			
Utilities:	81%		N/A	0%			
Overall Development:	25%	99%	99%	0%			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions				
Sunday:	1.23"				Wee		
Monday	0.51"	08/12/19	Tstorm 86/71				
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.33"						
Friday	0.00"						
Saturday	0.00"						
					Weel		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
					Weel		
Sunday:	N/A						
Monday	N/A						
Tuesday	N/A						
Wednesday	N/A						
Thursday	N/A						
Friday	N/A						
Saturday	N/A						
Complaints:							
Construction Sequencing:	•						
	of the site have had a temporary or perma	anent cessation of grading,	earthwork, or ground disturband	ce in the last 14 days?			

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19)

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements have not begun as of last inspection.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19)

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements have not begun as of last inspection.

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18).

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

No - See BMP Section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No - See Findings Section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments

The site was **inactive** during the last inspection for the Gallery 23 East project for paving, storm, and utility installation. The majority of the site has vegetated with weeds, so site will not be seeded at this time.

Lift Station and Sanitary Force Main projects are nearing completion. Work is occurring on the southeast intersection of County Road U and the project. County Road U Blvd and East 16th Street ditches will be stabilized in the coming weeks as of 8/30/2018. E&A will continue to monitor. Street ditches were seeded and matted prior to inspection on 9/19/18.

Water Improvements project has begun as of last inspection. Dirt piles from water main improvement project are being moved over to Gallery 23 East project in low areas. Dirt will be spread at a later date (2/7/19). Water project was inactive during last inspection. All HR Bookstrom equipment was removed from the site prior to inspection on 5/20/19.

Highway 30 intersection improvements project not active as of the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. See BMP section for required maintenance.
- 2. Diesel fuel tanks need to be bermed on site as of 8/30/2018. Pruss Excavation will be informed to complete by 9/6/2018. Not done as of last inspection. Thompson Construction was informed to complete by 10/16/18. Not done as of last inspection. Thompson Construction was reminded on 3/27/19, 5/3/19, 6/18/19.
- 3. The portable toilet on site needs to be secured. E&A inspector informed Jim Hammit to inform Thompson Construction to complete by 5/10/19. Not done as of the last inspection. The portable toilet was knocked over prior to inspection on 5/28/19. Portable toilet needs to be picked up and secured. Thompson Construction was informed to complete by 6/4/19. The portable toilet was picked up prior to inspection on 6/3/19. Thompson was reminded to secure the portable toilet on 6/18/19, 7/8/19.
- 4. The water main project areas need to be stabilized due to lack of activity in the area. Per a conversation with Jim Hammit of E&A Consulting Group, HR Bookstrom is aware of the stabilization needed and will be performing the maintenance soon. E&A will monitor. No signs of seeding as of the last inspection. HR Bookstrom was reminded on 6/18/19. The project areas are filling with volunteer vegetation as of the last inspection. E&A will continue to monitor for final stabilization.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Gallery 23 East							
Janot y 20 Last							
CE 1	Construction Entrance	County Road Blvd U	8/30/2018	Active	Yes		

Current Condition:	Poor Condition - 5% effective Portions of the entrance was entrance and added rock programmer.	shed out prior to inspect ior to inspection on 6/17	ion on 3/24/19. Thompson (/19.			
	Rock should be added to the entrance to prevent trackout Thompson Construction was informed to complete by 6/25/10. Not done as of the last inspection.					
	Thompson Construction was informed to complete by 6/25/19. Not done as of the last inspection.					
05.0	Occasionalism Fatanasa	County Road		Damanad		
CE 2 Current Condition:	Construction Entrance Removed - Pruss was remo	25/Highway 30 ving the construction en	L trance during inspection on	Removed 6/18/19 in preparat	ion for paving.	
		-				
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No	
Current Condition:	Pending - Culvert protection			,		
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Culvert protection	will be installed at a late	er date.			
CIM	Consests Mashaut	Northeast corner of	7/0/2040	Danding	Na	
CW Current Condition:	Concrete Washout Pending - A concrete washo	site	7/8/2019	Pending or to inspection on	No 6/17/19 The old	
Guirent Gonation.	concrete washout pit was re					
	inspection on 7/8/19. The co					
	pit was temporarily removed		/2/19. E&A will recommend	reinstallation prior t	o paving	
DW #4	commencing in the southern		0/00/0040	Dandina.	Na	
DW #1 Current Condition:	Ditch Wattle Checks Pending - Ditch wattle check	Middle Central	8/30/2018	Pending	No	
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Donding	No	
Current Condition:	Pending - Ditch wattle check			Pending	No	
DW #3	<u> </u>			A ativo	No	
Current Condition:	Ditch Wattle Checks Good Condition - Wattles ch	Southeast corner	8/30/2018	Active /30/2018	No	
Guirent Gonation.	Cood Corrainer Wallios of	Tooko woro inotanoa orr				
DD #1	Diversion Ditch	NW Corner of Lake	11/6/2018	Active	No	
Current Condition:	Good Condition - After furth	er evaluation, as of 1/10	/19 inspection, wattles/ched	ks will no longer be	recommended.	
		T				
DD #2	Diversion Ditch	W side of Lake	and a Probable of the Commen	Active		
Current Condition:	Removed - Thompson Cons	struction removed the di	version ditch prior to inspec	tion on 9/19/18.		
DD #10	5 5					
DD #3	Diversion Ditch	SW corner of lake		Active		
Current Condition:	Removed - Thompson Cons	SW corner of lake struction removed the div		Active tion on 9/19/18.		
Current Condition: DD #4	Removed - Thompson Cons Diversion Ditch	SW corner of lake struction removed the di	version ditch prior to inspec	Active tion on 9/19/18.		
Current Condition: DD #4 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons	SW corner of lake struction removed the di S Side of lake struction removed the di	version ditch prior to inspec	Active tion on 9/19/18. Active tion on 9/19/18.		
Current Condition: DD #4 Current Condition: DD #5	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch	SW corner of lake struction removed the distruction removed the distriction re	version ditch prior to inspec version ditch prior to inspec	Active tion on 9/19/18. Active tion on 9/19/18. Active Active		
Current Condition: DD #4 Current Condition: DD #5 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons	SW corner of lake struction removed the diverse S Side of lake struction removed the diverse Str	version ditch prior to inspect version ditch prior to inspect version ditch prior to inspect	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18.	No	
Current Condition: DD #4 Current Condition: DD #5	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch	SW corner of lake struction removed the distruction re	version ditch prior to inspect 8/30/2018	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active Active	No recommended.	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth	SW corner of lake struction removed the distruction removed the distruction, as of 1/10	version ditch prior to inspec 8/30/2018 /19 inspection, wattles/chec	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be	recommended.	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch	SW corner of lake struction removed the direct S Side of lake struction removed the direct S side of lake struction removed the direct S side of lake struction removed the direct NE corner of lake ser evaluation, as of 1/10 N side of lake	version ditch prior to inspec 8/30/2018 /19 inspection, wattles/chec	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active Active ks will no longer be Active	recommended.	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth	SW corner of lake struction removed the direct struction, as of 1/10 N side of lake side of the lot and an according to the struction removed the direct struction.	version ditch prior to inspec 8/30/2018 /19 inspection, wattles/chec	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active Active ks will no longer be Active	recommended.	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra	SW corner of lake struction removed the direct struction, as of 1/10 N side of lake side of the lot and an according to the struction removed the direct struction.	version ditch prior to inspec 8/30/2018 /19 inspection, wattles/chec	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active Active ks will no longer be Active	recommended.	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim	SW corner of lake struction removed the direct struction, as of 1/10 N side of lake and of the lot and an acce. E&A will monitor.	version ditch prior to inspectiversion ditch prior to inspective 8/30/2018 9/25/2018 9/25/2018 ess road being installed, siles/2018	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active ks will no longer be Active t fence or straw bale	No e checks will not	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim	SW corner of lake struction removed the direct struction, as of 1/10 N side of lake and of the lot and an acce. E&A will monitor.	version ditch prior to inspectiversion ditch prior to inspective 8/30/2018 9/25/2018 9/25/2018 ess road being installed, siles/2018	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active ks will no longer be Active t fence or straw bale	No e checks will not	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 NE corner of lake er evaluation, as of 1/10 N side of lake ade of the lot and an acce. E&A will monitor. Northeast corner atting and seeding will to Around Lake (Outlot B)	version ditch prior to inspectiversion ditch prior to inspective 8/30/2018 9/25/2018 9/25/2018 9/25/2018 9/30/2018 8/30/2018 8/30/2018	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bale Pending as ended. Pending	No e checks will not	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 NE corner of lake er evaluation, as of 1/10 N side of lake ade of the lot and an acce. E&A will monitor. Northeast corner atting and seeding will to Around Lake (Outlot B)	version ditch prior to inspectiversion ditch prior to inspective 8/30/2018 9/25/2018 9/25/2018 9/25/2018 9/30/2018 8/30/2018 8/30/2018	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bale Pending as ended. Pending	No e checks will not	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 NE corner of lake er evaluation, as of 1/10 N side of lake ade of the lot and an acce. E&A will monitor. Northeast corner atting and seeding will be atting and seeding will be atting and seeding will be attended.	version ditch prior to inspective version, wattles/chective version, wattles/chective version, wattles/chective version, wattles/chective version	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tks will no longer be Active t fence or straw bale Pending as ended. Pending as ended.	No e checks will not No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 NE corner of lake er evaluation, as of 1/10 N side of lake ade of the lot and an acce. E&A will monitor. Northeast corner atting and seeding will be atting at the distriction of the distriction	version ditch prior to inspectiversion ditch prior to inspective 8/30/2018 9/25/2018 9/25/2018 9/25/2018 9/30/2018 8/30/2018 8/30/2018	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bale Pending as ended. Pending	No e checks will not	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 NE corner of lake er evaluation, as of 1/10 N side of lake ade of the lot and an acce. E&A will monitor. Northeast corner atting and seeding will be atting and seeding will be atting and seeding will be attended.	version ditch prior to inspective version, wattles/chective version, wattles/chective version, wattles/chective version, wattles/chective version	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tks will no longer be Active t fence or straw bale Pending as ended. Pending as ended.	No e checks will not No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be a triangle and seeding will be atting and seeding will be a triangle and see	version ditch prior to inspective version, wattles/chective version, wattles/chective version, wattles/chective version, wattles/chective version	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tks will no longer be Active t fence or straw bale Pending as ended. Pending as ended.	No e checks will not No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be	SW corner of lake struction removed the distruction re	version ditch prior to inspectiversion ditch prior to inspective solution wattles/check places road being installed, siles as road being installed, siles as road being installed, siles installed when grading have a siles as a sile of the prior to inspect to installed when grading have installed when grading have a siles as a sile of the prior to inspect to	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bale Pending as ended. Pending as ended. Pending	No e checks will not No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition: IP 1 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an access and seed and an access and seed in the lot and an access and seed in the lot and an access and seed in the lot and seed in the lot and seed in s	version ditch prior to inspect 8/30/2018 /19 inspection, wattles/chect 9/25/2018 ress road being installed, sile 8/30/2018 re installed when grading has a sile installed when grading ha	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bala Pending as ended. Pending as ended. Pending by 8/19/19.	No e checks will not No No Yes	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition: IP 1 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be a latting and seeding will be a latt	version ditch prior to inspect 8/30/2018 /19 inspection, wattles/chect 9/25/2018 ress road being installed, sile installed when grading have installed when gradi	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bale Pending as ended. Pending as ended. Pending	No e checks will not No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition: IP 1 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be a latting and seeding will be a latt	version ditch prior to inspect 8/30/2018 /19 inspection, wattles/chect 9/25/2018 ress road being installed, sile installed when grading have installed when gradi	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bala Pending as ended. Pending as ended. Pending by 8/19/19.	No e checks will not No No Yes	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition: IP 1 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed Sediment Basin Pending - Basin will be insta	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be attinguished to inform Thompson atting and seeding portion of site attended to concept and seeding will be attinguished at the information of site attended to concept and seeding will be attinguished at the information of site attended to concept and seeding will be attended	version ditch prior to inspect version wattles/chect version v	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bala Pending as ended. Pending as ended. Pending by 8/19/19.	No e checks will not No No Yes	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition: IP 1 Current Condition: SB #1 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to grabe recommended at this time Erosion Blanket Pending - Erosion control me Erosion Blanket Pending - Erosion control me Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed Sediment Basin Pending - Basin will be instated	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be attinguished to inform Thompson atting and seeding portion of site attended to concept and seeding will be attinguished at the information of site attended to concept and seeding will be attinguished at the information of site attended to concept and seeding will be attended	version ditch prior to inspect version wattles/chect version v	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active ks will no longer be Active t fence or straw bale Pending as ended. Pending by 8/19/19. Pending	No e checks will not No No No No No No No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: EB #3 Current Condition: IP 1 Current Condition: SB #1 Current Condition: SB #2	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed Sediment Basin Pending - Basin will be insta	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be attinguished to inform Thompson atting and seeding portion of site attended to concept and seeding will be attinguished at the information of site attended to concept and seeding will be attinguished at the information of site attended to concept and seeding will be attended	version ditch prior to inspect version, wattles/chect version ditch prior to inspect version, wattles/chect version	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active cks will no longer be Active t fence or straw bala Pending as ended. Pending by 8/19/19. Pending Pending	No checks will not No No No No No No No No	
Current Condition: DD #4 Current Condition: DD #5 Current Condition: DD #6 Current Condition: DD #7 Current Condition: EB #2 Current Condition: IP 1 Current Condition: SB #1 Current Condition: SB #2 Current Condition:	Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Removed - Thompson Cons Diversion Ditch Good Condition - After furth Diversion Ditch Good Condition - Due to gra be recommended at this tim Erosion Blanket Pending - Erosion control m Erosion Blanket Pending - Erosion control m Inlet Protection Pending - Inlet protection should be Jim Hammitt was informed Sediment Basin Pending - Basin will be instate Sediment Basin Pending - Basin will be instate	SW corner of lake struction removed the distruction removed the distruction, as of 1/10 N side of lake and an acce. E&A will monitor. Northeast corner atting and seeding will be atting and seeding atting and seeding atting and seeding atting and seeding atting atting and seeding atting a	version ditch prior to inspect version ditch prior to inspect version ditch prior to inspect 8/30/2018 /19 inspection, wattles/chect 9/25/2018 ress road being installed, siles installed when grading have installed have	Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active tion on 9/19/18. Active ks will no longer be Active t fence or straw bale Pending as ended. Pending by 8/19/19. Pending	No e checks will not No No No No No No No No	

SF #2 Current Condition:	Silt Fence Pending - Silt Fence will be	Northeast corner e installed at a later date.	8/30/2018	Pending	No		
CTD	Ctuant alagains	O# C:+=	In Diago	A =4:	l Na		
STR Current Condition:	Street cleaning Good Condition - The street	Off-Site	In Place	Active	No		
Current Condition.	Good Condition - The street	Sto flear OL 2 Were clear	at time of mapection on 7	70/13.			
SWPPP Sign-SI	Signs	2 Entrances	10/9/2018	Active	Yes		
Current Condition:	Fair Condition - Inspector i						
	installed at the County Rd						
	inspection on 4/19/19. The						
	E&A inspector reinstalled tinspection on 8/12/19.	E&A inspector reinstalled the SWPPP sign during inspection on 7/16/19. The SWPPP sign fell over prior to					
	The SWPPP sign needs t	o be reinstalled					
	E&A inspector will attem	pt to reinstall during ne	ext inspection by 8/26/19				
		Station and	Force Main				
CE 1	Construction Entrance	County Road Blvd U	20/0040	Removed			
Current Condition:	Removed - See CE1 for G						
CW	Concrete Washout	County Road Blvd U		Removed			
Current Condition:	Removed - See CW for Ga	allery 23 project as of 8/3		ing poured for the sar	nitary lift proje		
DC #1	Ditch Wattle Checks	Sheet C-603	9/13/2018	Active	Yes		
Current Condition:	Fair Condition - Ditch wattl	e checks were installed b	oy Carstensen Contracting	g prior to inspection or	า 9/19/18		
	Ditch wattle checks on the east side of CE 1 need to be repositioned/repaired E&A inspector informed Jim Hammit to inform Thompson Construction to complete by 3/31/19. Not done as of the last inspection. Thompson was reminded on 5/3/19, 6/18/19, 7/23/19.						
			•				
DC #2	Ditch Wattle Checks	Sheet C-604	9/13/2018	Active	Yes		
Current Condition:	Fair Condition - Ditch wattle checks were installed by Carstensen Contracting prior to inspection on 9/19/18						
	Ditch wattle checks need to be repositioned/repaired						
	E&A inspector informed Jir last inspection. Thompson			mplete by 3/31/19. No	t done as of t		
DC #3	Ditch Wattle Checks	Sheet C-605	9/13/2018	Active	No		
Current Condition:	Good Condition - Ditch was Some of the ditch checks wand biodegradable nature	were minorly damaged do	uring mowing prior to inspe	ection on 7/8/19. Due	to stabilization		
DC #4	Ditch Wattle Checks	Sheet C-606	9/13/2018	Active	No		
Current Condition:	Good Condition - Ditch war ditch wattle checks located reinstallation will not be red	I in front of the house we					
		Along ditch between					
EB #1	Erosion Blanket	Rd 25 and lift station	9/13/2018	Active	No No		
Current Condition:	Good Condition - Erosion of The blanket is underwater during natural gas installat	as of inspection on 3/24/ ion prior to inspection on	19. E&A will monitor once 7/8/19.	01			
ED "**		Along ditch W of 25 E		1			
EB #2	Erosion Blanket	of Hwy 275	9/13/2018	Active	Yes		
Current Condition:	Fair Condition - Erosion co	introi bianket was installe	ed by Carstensen Contract	ling prior to inspection	on 9/19/18		
	The blanket has been washed away in multiple locations along the run and should be repaired/reinstalled						
	E&A inspector informed Jim Hammit to inform Thompson Construction to complete by 3/31/19. Not done as of the last inspection. Thompson was reminded on 5/3/19, 6/18/19, 7/23/19.						
EB #3	Erosion Blanket	E of Roundabout	9/25/2018	Active	No		
Current Condition:	Good Condition - Erosion of						
STR	Street cleaning	Off-Site	In Place	Active	No		
Current Condition:	Good Condition - No signs			7.00170	1 110		
SWPPP Sign-SI	Signs	2 Entrances		Removed			
Current Condition:	Removed - See SWPPP si		st project	, iveilloved	I		
January Condition		· .					
	Wate	r Main Extens	sion				
CW	Concrete Washout	County Road Blvd U		Removed			
		·					

Current Condition:	Removed - Concrete wash	Removed - Concrete washouts will not be necessary for the water main project as of the 8/2/19 inspection.					
SF #1	Silt Fence	Area #1		Removed			
Current Condition:	Removed - There is no silt	Removed - There is no silt fence in this area, see IP 1 and IP 2 for BMPs in Area #1					
		N side of 24th St					
IP 1	Inlet Protection	(Enlarged Area #1)		Removed			
Current Condition:	Removed - HR Bookstrom	Removed - HR Bookstrom removed the inlet protection prior to inspection on 6/24/19.					
		S side of 24th St					
IP 2	Inlet Protection	(Enlarged Area #1)		Removed			
Current Condition:	Removed - HR Bookstrom	removed the inlet protection	on prior to inspection on	6/24/19.			
SF #2	Silt Fence	Area #2		Removed			
Current Condition:	Removed - Due to establis E&A will monitor.	Removed - Due to established vegetation in the area, straw wattles will no longer be recommended in the area.					
SF #3	Silt Fence	Area #3		Removed			
Current Condition:	Removed - Silt fence will n	Removed - Silt fence will not be needed in the area due to stabilization as of 7/21/19 inspection.					
SF #4	Silt Fence	Area #4	10/4/2018	Pending	No		
Current Condition:		Pending - Silt fence will be installed when grading reaches area. Due to improvement in stabilization, silt fence will no longer be recommended. E&A will monitor.					
SF #5	Silt Fence	Area #5	10/4/2018	Pending	No		
Current Condition:		Pending - Silt fence will be installed when grading reaches area. Due to improvement in stabilization, silt fence will no longer be recommended. E&A will monitor.					
SF #6	Silt Fence	Area #6		Removed			
Current Condition:	Removed - Silt fence will not be needed in the area due to stabilization as of 7/21/19 inspection.						
STR	Street cleaning	Off-Site	In Place	Active	No		
Current Condition:	Good Condition - Streets showed signs of improvement, however, some street cleaning is still necessary. H.R. Bookstrom Construction cleaned the streets at 24th St prior to inspection on 1/10/19. HR Bookstrom cleaned the streets prior to inspection on 6/24/19.						
SWPPP Sign-SI	Signs	2 Entrances		Removed			
Current Condition:	Removed - See SWPPP s	igns under Gallery 23 East	t project				
pector Signature:	L7		Reviewed By:	Set Su	-		