E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599

www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Aaron Tulley		E&A - P2018.109.002 <u>Gallery 23 East</u>				
	CSW-201702253 (Mass Grading)					
		CSW-210802622 (Intersection Improvements)				
		•	-	,		
			Main Improvements)		
Project Name:	C	SW-201802624 (E				
For Week Ending:		10/26/2019				
Project Location:	County Road	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				
	Gallery 23 East	Water Main Project	Lift Station & Force Main	Intersection Impr.		
Grading:	95%			3%		
Sanitary Sewer:	97%		100%	N/A		
Storm Sewer: Paving:	90%		N/A N/A	N/A 0%		
Seeding:	1%		99%	0%		
Utilities:	84%		N/A	N/A		
Overall Development:	27%	100%	99%	5%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
Sunday:	0.00"				Week	
Monday.	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.03"					
					Week	
Sunday:	0.00"					
Monday	0.10"	10/21/19	Tstorm 54/42			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
Complaints:						
Construction Sequencing:						

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching in the southeast portion of the site for utility installation (10/22/19).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18).

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No - See Findings Section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments

Comments

The site was **in**active during the last inspection for the Gallery 23 East project. The majority of the site has vegetated with weeds, so site will not be seeded at this time. Building Construction has begun in northeast corner of the site as of the 8/26/19 inspection.

Lift Station and Sanitary Force Main projects are nearing completion. Work is occurring on the southeast intersection of County Road U and the project. County Road U Blvd and East 16th Street ditches will be stabilized in the coming weeks as of 8/30/2018. E&A will continue to monitor. Street ditches were seeded and matted prior to inspection on 9/19/18.

Water Improvements project has begun as of last inspection. Dirt piles from water main improvement project are being moved over to Gallery 23 East project in low areas. Dirt will be spread at a later date (2/7/19). Water project was inactive during last inspection. All HR Bookstrom equipment was removed from the site prior to inspection on 5/20/19. Vegetative cover has improved as of the 8/26/19 inspection.

Highway 30 intersection improvements project active as of the last inspection for culvert installation (09/30/19). E&A will monitor the need for downstream BMPs.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. See BMP section for required maintenance.
- 2. Diesel fuel tanks need to be bermed on site as of 8/30/2018. Pruss Excavation will be informed to complete by 9/6/2018. Not done as of last inspection. Thompson Construction was informed to complete by 10/16/18. Not done as of last inspection. Thompson Construction was reminded on 3/27/19, 5/3/19, 6/18/19, 8/26/19.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
Gallery 23 East						
CE 1	Construction Entrance	County Road Blvd U		Removed		
Current Condition:	Removed - Thompson Construction removed the construction entrance in preparation for paving prior to inspection on 9/9/19.					

CE 2	Construction Entrance	County Road 25/Highway 30		Removed		
Current Condition:	Removed - Pruss was remo	oving the construction er	ntrance during inspection or	6/18/19 in prepara	tion for paving.	
CP #1	Culvert protection	Central portion of site		Pending	No	
Current Condition:	Pending - Culvert protection	n will be installed at a la	ter date.			
CP #2 Current Condition:	Culvert protection Pending - Culvert protection	Southeast corner n will be installed at a lat	8/30/2018 ter date.	Pending	No	
CW	Concrete Washout	Northeast corner of site		Removed		
Current Condition:	Removed - The concrete v			n 10/21/19. No pav	ing is	
DW #1	underway at this time. E&	A will monitor the need Middle Central		Donding	No	
Current Condition:	Ditch Wattle Checks Pending - Ditch wattle chec		8/30/2018	Pending	No	
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No	
Current Condition:	Pending - Ditch wattle chec			Fending	INO	
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No	
Current Condition:	Good Condition - Wattles cl				110	
DD #1	Diversion Ditch	NW Corner of Lake	11/6/2018	Active	No	
Current Condition:	Good Condition - After furth	er evaluation, as of 1/10	0/19 inspection, wattles/che	cks will no longer be	e recommended.	
DD #2	Diversion Ditch	W side of Lake		Active		
Current Condition:	Removed - Thompson Cons		iversion ditch prior to inspec	ction on 9/19/18.		
DD #3	Diversion Ditch	SW corner of lake		Active		
Current Condition:	Removed - Thompson Cons	struction removed the d	iversion ditch prior to inspec	ction on 9/19/18.		
DD #4	Diversion Ditch	S Side of lake		Active		
Current Condition:	Removed - Thompson Cons	struction removed the d	iversion ditch prior to inspec	ction on 9/19/18.		
DD #5	Diversion Ditch	E side of lake		Active		
Current Condition:	Removed - Thompson Cons	struction removed the d	iversion ditch prior to inspec	ction on 9/19/18.		
DD #6	Diversion Ditch	NE corner of lake	8/30/2018	Active	No	
Current Condition:	Good Condition - After furth			cks will no longer be	e recommended.	
DD #7	Diversion Ditch	N side of lake	9/25/2018	Active	No	
Current Condition:	Good Condition - Due to grabe recommended at this time		cess road being installed, si	it tence or straw ba	e checks will not	
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m	natting and seeding will	be installed when grading h	as ended.		
		Around Lake (Outlot				
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m			as ended.		
ID 4		Area Inlet in SE	I .	Danding	Vaa	
IP 1 Current Condition:	Inlet Protection Pending -	portion of the site	8/19/2019	Pending	Yes	
Current Condition.	Inlet protection should be installed					
	Jim Hammitt was informed to inform Thompson Construction to complete by 8/19/19. Not done as of the last					
	inspection. Jim Hammitt wa	s informed to remind Tr	nompson Construction on 10	0/7/19.		
SB #1	Sediment Basin	Central portion of site	8/30/2018	Pending	No	
Current Condition:	Pending - Basin will be insta	alled once grading has	commenced at a later date.			
SB #2	Sediment Basin	Southeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Basin will be insta	alled once grading has o	commenced at a later date.			
SF #1	Silt Fence	Southeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Silt Fence will be			, chang	1 140	
SF #2	Silt Fence	Northeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Silt Fence will be	installed at a later date				
STR	Street cleaning	Off-Site	In Place	Active	No	
Current Condition:	Good Condition - The street	ts near CE 2 were clean	at time of inspection on 7/8	3/19.		
SWPPP Sign-SI	Signs	2 Entrances	10/9/2018	Active	No	

Current Condition:	Good Condition - Inspector installed at the County Rd I inspection on 9/19/19.		· · · ·		•
	Sanitary Lift	Station and I	Force Main		
CE 1	Construction Entrance	County Road Blvd U		Removed	
Current Condition:	Removed - See CE1 for Ga		30/2018.	removed	
CW	Concrete Washout	County Road Blvd U	1	Removed	
Current Condition:	Removed - See CW for Ga		I 0/2018. No concrete is bei		itary lift projec
DC #1	Ditch Wattle Checks	Sheet C-603	9/13/2018	Active	Yes
Current Condition:	Fair Condition - Ditch wattle Ditch wattle checks on the		,		n 9/19/18
	E&A inspector informed Jin last inspection. Thompson			mplete by 3/31/19. No	ot done as of th
DC #2	Ditch Wattle Checks	Sheet C-604	9/13/2018	Active	Yes
Current Condition:	Fair Condition - Ditch wattle	e checks were installed t	oy Carstensen Contracting	prior to inspection or	n 9/19/18
DC #3	Ditch wattle checks need to E&A inspector informed Jin last inspection. Thompson Ditch Wattle Checks	n Hammitt to inform Tho	mpson Construction to cor	mplete by 3/31/19. No	ot done as of th
Current Condition:	Removed - The ditch wattle		nrior to inspection on 8/26/		
			r		
DC #4	Ditch Wattle Checks	Sheet C-606	L	Removed	
Current Condition:	Removed - The ditch wattle	e checks were removed p	prior to inspection on 8/26/	19.	
EB #1	Erosion Blanket	Along ditch between Rd 25 and lift station	9/13/2018	Active	No
Current Condition:	Good Condition - Erosion c				
	The blanket is underwater a during natural gas installati continue to monitor vegetat	on prior to inspection on tive establishment.	7/8/19. Weedy vegetation		
EB #2	Erosion Blanket	Along ditch W of 25 E of Hwy 275	9/13/2018	Active	Yes
Current Condition:	Fair Condition - Erosion co				
EB #3	The blanket has been wash E&A inspector informed Jin last inspection. Thompson	n Hammitt to inform Tho	mpson Construction to cor	·	stalled
	Erosion Blanket Removed - Vegetation is w	E of Roundabout	ea, therefore, the erosion c	Removed	
Current Condition:	Removed - Vegetation is w		ea, therefore, the erosion c		
Current Condition:	Removed - Vegetation is w inspected as its own BMP.	ell established in the are		ontrol matting will no	longer be
	Removed - Vegetation is w	ell established in the are	ea, therefore, the erosion c		
Current Condition: STR Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs	ell established in the are Off-Site of trackout.		ontrol matting will no Active	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs	ell established in the are Off-Site of trackout. 2 Entrances	In Place	ontrol matting will no	longer be
Current Condition: STR Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si	Off-Site Offrackout. 2 Entrances gns under Gallery 23 Ea	In Place	ontrol matting will no Active	longer be
STR Current Condition: SWPPP Sign-SI Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea	In Place	ontrol matting will no Active Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si	Off-Site Offrackout. 2 Entrances gns under Gallery 23 Ea	In Place	ontrol matting will no Active	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Water Concrete Washout Removed - Concrete washe	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessar	In Place In Place In Sion	Active Removed Removed Removed t as of the 8/2/19 ins	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Concrete Washout Removed - Concrete washout Silt Fence	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal	In Place In Place In Place In Place	Active Removed Removed Removed Removed Removed Removed Removed Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Water Concrete Washout Removed - Concrete washe	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If	In Place In Place In Place In Place	Active Removed Removed Removed Removed Removed Removed Removed Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Water Concrete Washout Removed - Concrete washout Silt Fence Removed - There is no silt	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If N side of 24th St	In Place In Place In Place In Place	Active Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Concrete Washout Removed - Concrete washout Silt Fence Removed - There is no silt Inlet Protection	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1)	In Place Ist project SION Irry for the water main project P 1 and IP 2 for BMPs in A	Removed Removed t as of the 8/2/19 ins Removed Removed Removed Removed Removed Removed Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition: IP 1 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Water Concrete Washout Removed - Concrete washout Removed - There is no silt Inlet Protection Removed - HR Bookstrom	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1) removed the inlet protect S side of 24th St	In Place Ist project SION Irry for the water main project P 1 and IP 2 for BMPs in A	Removed Removed t as of the 8/2/19 ins Removed Removed Removed Removed Removed Removed Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition: IP 1 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Concrete Washout Removed - Concrete washout Removed - There is no silt Inlet Protection Removed - HR Bookstrom Inlet Protection	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1) removed the inlet protect S side of 24th St (Enlarged Area #1)	In Place Ist project SiON Irry for the water main project P 1 and IP 2 for BMPs in A In Place	Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition: IP 1 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Water Concrete Washout Removed - Concrete washout Removed - There is no silt Inlet Protection Removed - HR Bookstrom	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1) removed the inlet protect S side of 24th St (Enlarged Area #1)	In Place Ist project SiON Irry for the water main project P 1 and IP 2 for BMPs in A In Place	Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition: IP 1 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Concrete Washout Removed - Concrete washout Removed - There is no silt Inlet Protection Removed - HR Bookstrom Inlet Protection	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessal Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1) removed the inlet protect S side of 24th St (Enlarged Area #1)	In Place Ist project SiON Irry for the water main project P 1 and IP 2 for BMPs in A In Place	Removed	longer be
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition: IP 1 Current Condition: IP 2 Current Condition:	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Concrete Washout Removed - Concrete washout Removed - There is no silt Inlet Protection Removed - HR Bookstrom Removed - HR Bookstrom	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessar Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1) removed the inlet protect S side of 24th St (Enlarged Area #1) removed the inlet protect Area #2	In Place Ist project SION Try for the water main project P 1 and IP 2 for BMPs in A strion prior to inspection on the strip prior to inspect prior	Active Removed Removed	No No spection.
Current Condition: STR Current Condition: SWPPP Sign-SI Current Condition: CW Current Condition: SF #1 Current Condition: IP 1 Current Condition: IP 2 Current Condition: SF #2	Removed - Vegetation is w inspected as its own BMP. Street cleaning Good Condition - No signs Signs Removed - See SWPPP si Concrete Washout Removed - Concrete washout Removed - There is no silt Inlet Protection Removed - HR Bookstrom Inlet Protection Removed - HR Bookstrom Silt Fence Removed - HR Bookstrom Silt Fence Removed - Due to establisl	Off-Site Off-Site of trackout. 2 Entrances gns under Gallery 23 Ea Main Extens County Road Blvd U outs will not be necessar Area #1 fence in this area, see If N side of 24th St (Enlarged Area #1) removed the inlet protect S side of 24th St (Enlarged Area #1) removed the inlet protect Area #2 hed vegetation in the area	In Place Ist project SION Try for the water main project P 1 and IP 2 for BMPs in A strion prior to inspection on the strion prior to inspection on the sa, straw wattles will no lore.	Removed	No No spection.

SF #4	Silt Fence	Area #4	10/4/2018	Pending	No		
Current Condition:	Pending - Silt fence will be	e installed when grading r	eaches area. Due to impro	vement in stabilizatio	n, silt fence will		
	no longer be recommende	ed. E&A will monitor.					
SF #5	Silt Fence	Area #5	10/4/2018	Pending	No		
Current Condition:							
	no longer be recommende	ed. E&A will monitor.					
SF #6	Silt Fence	Area #6		Removed			
Current Condition:	Removed - Silt fence will	not be needed in the area	due to stabilization as of 7	/21/19 inspection.			
STR	Street cleaning	Off-Site	In Place	Active	No		
Current Condition:		0 1	ment, however, some street	O .	,		
		Bookstrom Construction cleaned the streets at 24th St prior to inspection on 1/10/19. HR Bookstrom cleaned the					
	streets prior to inspection	on 6/24/19.					
SWPPP Sign-SI	Signs	2 Entrances		Removed			
Current Condition:	Removed - See SWPPP	signs under Gallery 23 Ea	st project				
	Intersec	ction Improve	ments				
		West of Gallery East					
SF 1	Silt Fence	Drive culvert	11/1/2019	Pending	No		
Current Condition:	Pending - Silt Fence will b	pe installed at a later date.	•				
		West of Farm Field					
SF 2	Silt Fence	Road culvert	11/1/2019	Pending	No		
Current Condition:	Pending - Silt Fence will be installed at a later date.						
		East of Farm Field					
SF 3	Silt Fence	Road culvert	11/1/2019	Pending	Yes		
Current Condition:	Pending -						
	The silt fence should be installed						
	The sile terior should be in	notalica					
	Jim Hammitt was told to in	nform Thompson Constru	ction or Luxa to complete b	y 10/17/19. Not done	as of the last		
	inspection.	· ·	•	ŕ			
	1 ~						
	han Los			Get Sul	-		
Inspector Signature:			Reviewed By:	-3 -30 -8			