E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Luke Antholz		E&A - P2018	3.109.002		Stage	
	Gallery 23 East					
		CSW-201702253 (Mass Grading)				
	CSW-2	CSW-210802622 (Intersection Improvements)				
		CSW-201802623 (Water Main Improvements)				
Project Name:		SW-201802624 (F	-			
•		4/25/2	,			
For Week Ending:		4/23/2	020		68025	
Project Location:	County Roa	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				
	Gallery 23 East	Water Main Project	Lift Station & Force Main	Intersection Impr.		
Grading:	95			3%		
Sanitary Sewer:	97'			N/A		
Storm Sewer: Paving:	95° 99°		N/A N/A	N/A 0%		
Seeding:		% 100%		0%		
Utilities:	98'			N/A		
Overall Development:	45'	% 100%	99%	5%		
RAIN FALL AMOUNTS	Amount in inches	Data insuranted	N/a ath an Canditions	Time		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time	Week	
Sunday:	0.02"					
Monday	0.00"					
Tuesday	0.00"	04/14/20	Clear 48/21	11:05 AM		
Wednesday	0.00"					
Thursday	0.48"					
Friday	0.00"					
Saturday	0.00"					
<u> </u>					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00 0.02"					
Friday	0.02					
Saturday	0.03				Week	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
O a manufacture						
Complaints:						
Complaints: Construction Sequencing:						

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19). Grading has temporarily ceased due to winter conditions (1/13/20).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19). Grading has temporarily ceased due to winter conditions (1/13/20).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See BMP section

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for the Gallery 23 East project. Building Construction has begun in northeast corner of the site as of the 8/26/19 inspection.

Lift Station and Sanitary Force Main projects are complete. Street ditches were seeded and matted prior to inspection on 9/19/18. Due to the biodegradable nature of the BMPs, repair will not be recommended at this time. E&A will monitor for final stabilization.

Water Improvements project has begun as of last inspection. Dirt piles from water main improvement project are being moved over to Gallery 23 East project in low areas. Dirt will be spread at a later date (2/7/19). Water project was inactive during last inspection. All HR Bookstrom equipment was removed from the site prior to inspection on 5/20/19. Vegetative cover has improved as of the 8/26/19 inspection. Water Improvements project is complete.

Highway 30 intersection improvements project inactive as of the last inspection for culvert installation (9/30/19).

Findings / Corrective Actions (Date):

dings / Corrective Actions (Da ee BMP section for required ma					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenan
oquo mao		llery 23 East			
CE 1	Construction Entrance	County Road Blvd U	•	Removed	1
Current Condition:			onstruction entrance in prep		prior to
CE 2	Construction Entrance	County Road 25/Highway 30		Removed	
Current Condition:	Removed - Pruss was remo	oving the construction er	ntrance during inspection on	i 6/18/19 in prepara	ation for pavin
		NE Corner - Hwy 30 &			
CE 3	Construction Entrance	Christine Drive	12/30/2019	Active	No
Current Condition:			any installed a construction Company added rock to the		
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection		er date.	<u> </u>	
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No
Current Condition:	Pending - Culvert protection	n will be installed at a lat	er date.		•
		Northeast corner of			
CW	Concrete Washout	site		Removed	
Current Condition:			ed prior to inspection on 10/2	21/19. No paving is	s underway at
	this time. E&A will monitor t				
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec	ks will be installed when	n grading has ended.		
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No
Current Condition:	Pending - Ditch wattle chec	ks will be installed when	grading has ended.		-
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No
Current Condition:			the southeast side of the sit		
DD #1	Diversion Ditch	NW Corner of Lake		Removed	
Current Condition:	Removed - The diversion d	itch was removed during	regrading/paving in the are	ea prior to inspection	on on 12/30/1
DD #2	Diversion Ditch	W side of Lake		Removed	
Current Condition:			version ditch prior to inspec		1
DD #3	Diversion Ditch	SW corner of lake		Removed	
Current Condition:			version ditch prior to inspec		1
DD #4	Diversion Ditch	S Side of lake	I	Removed	1
Current Condition:			I version ditch prior to inspec		1
DD #5					1
	Person Utten	E side of lake	lversion ditch prior to inspec	Removed	1
Current Condition:			rversion unch prior to inspec		
DD #6	Diversion Ditch	NE corner of lake		Removed	10/00/
Current Condition:	Removed - The diversion d	itch was removed during	g regrading/paving in the are	ea prior to inspection	on on 12/30/19
DD #7	Diversion Ditch	N side of lake		Removed	
Current Condition:			regrading/paving in the are		on on 12/30/19
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No
Current Condition:			be installed when grading ha		•

		Around Lake (Outlot		1			
EB #3	Erosion Blanket	В) `	8/30/2018	Pending	No		
Current Condition:	Pending - Erosion control n		be installed when grading h	as ended.	1		
IP 1	Inlet Protection	Area Inlet in SE portion of the site	8/19/2019	Pending	Yes		
Current Condition:	Pending -	portion of the site	0/13/2013	1 chaing	103		
	ŭ	antalla d					
	Inlet protection should be installed						
		Jim Hammitt was informed to inform Thompson Construction to complete by 8/19/19. Not done as of the last					
	reminded on 11/18/19, 4/1/		nompson Construction on 10	0/7/19. Thompson (Construction was		
IP 2	Curb Inlet protection	W Curb inlet on Christine Dr	11/25/2019	Pending	Yes		
Current Condition:	Pending - Due to construct	on on the villas being th	e main source of dirt in the	streets/need for inl			
			ty for installation of inlet pro	tection.			
	Curb inlet protection should	be installed					
			by 11/25/19. Not done as o				
	Company was informed to reminded on 2/11/20, 4/1/2		lot done as of the last inspe	ction. The Home C	ompany was		
		E Curb inlet on					
IP 3	Curb Inlet protection	Christine Dr	11/25/2019	Pending	Yes		
Current Condition:			ne main source of dirt in the try for installation of inlet pro		et protection, the		
	Curb inlet protection should	be installed					
	Thompson Construction we	as informed to complete	by 11/25/19. Not done as o	f the leat inequation	The Home		
			lot done as of the last inspe				
	reminded on 2/11/20, 4/1/2		iot dono do or ano idot mopo		ompany mas		
		Block 1, Replat 2					
		(Northeast corner of					
Lots 1-10, Block 1, Replat 2 Current Condition:	Individual Lots	site)	11/18/2019 uction on the Villas in the no	Active	Yes		
Current Condition.							
	inspection on 8/26/19. No BMPs are required at this time. E&A will monitor. Two portable toilets were added on the lots prior to inspection on 2/10/20.						
	lots phor to inspection on 2	lots prior to inspection on 2/10/20.					
	The portable toilets should be secured						
	The Home Company was in was reminded on 4/1/20	nformed to complete by	2/17/20. Not done as of last	inspection. The Ho	ome Company		
		Block 2, Replat 2			<u> </u>		
		(Northeast corner of					
Lots 1-10, Block 2, Replat 2	Individual Lots	site)	11/18/2019	Active	No		
Current Condition:			n the Villas in the northeast				
	on 8/26/19. No BMPs are required at this time. E&A will monitor. The Home Company secured the portable toilet prior to inspection on 12/16/19. The portable toilet was moved further away from the inlet prior to inspection on						
		•	Replat 2 prior to inspection	•	rispection on		
Lots 2 & 3, Block 7	Individual Lots	Block 7	11/18/2019	Active	No		
Current Condition:	Active - Construction began	on the lots prior to insp	pection on 11/18/19. No BM	Ps are required at t	his time. E&A		
				T			
SB #1 Current Condition:	Sediment Basin	Central portion of site	8/30/2018 commenced at a later date a	Pending	No necessary		
SB #2	Sediment Basin	Southeast corner	8/30/2018	Pending	No		
Current Condition:			commenced at a later date				
SF #1	Silt Fence	Southeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Silt Fence will be			Dandina	l Na		
SF #2 Current Condition:	Silt Fence Pending - Silt Fence will be	Northeast corner	when deemed necessary	Pending	No		
STR	Street cleaning	Off-Site	In Place	Active	Yes		
Current Condition:			at time of inspection on 7/8/				
	Interior streets should be cl	eaned throughout the de	evelopment to prevent track	out on adjacent str	eets		
	Jim Hammitt with E&A was	told to inform Thompso	n Construction on 11/22/19	Not done as of the	last inspection		
			eets in the northeast portion				
	Company was reminded to			25			
SWPPP Sign-SI	Signs	2 Entrances	10/9/2018	Active	No		
3							

Current Condition:	Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPP sign will I installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPP sign during inspection on 9/19/19. The E&A inspector installed the SWPPP sign during the 2/24/20 inspection. The E&A
	inspector reinstalled the SWPPP sign prior to the inspection on 3/31/20. Sanitary Lift Station and Force Main
CE 1	Construction Entrance
Current Condition:	Removed - See CE1 for Gallery 23 project as of 8/30/2018.
CW	Concrete Washout County Road Blvd U Removed
Current Condition:	Removed - See CW for Gallery 23 project as of 8/30/2018. No concrete is being poured for the sanitary lift proje
DC #1	Ditch Wattle Checks Sheet C-603 Removed
Current Condition:	Removed - Due to the biodegradable nature of the straw wattles and the ditch being consistently under water, the straw wattles will not be repaired/replaced at this time. E&A will monitor for final stabilization/reseeding potential
DC #2	Ditch Wattle Checks Sheet C-604 Active
Current Condition:	Removed - Due to the biodegradable nature of the straw wattles and the ditch being consistently under water, the straw wattles will not be repaired/replaced at this time. E&A will monitor for final stabilization/reseeding potential
DC #3	Ditch Wattle Checks Sheet C-605 Removed
Current Condition:	Removed - The ditch wattle checks were removed prior to inspection on 8/26/19.
DC #4	Ditch Wattle Checks Sheet C-606 Removed
Current Condition:	Removed - The ditch wattle checks were removed prior to inspection on 8/26/19.
Carrent Condition:	
	Along ditch between
EB #1	Erosion Blanket Rd 25 and lift station 9/13/2018 Active No
Current Condition:	Fair Condition - Erosion control blanket was installed by Carstensen Contracting prior to inspection on 9/19/18. The blanket is underwater as of inspection on 3/24/19. E&A will monitor once water subsides. Ditch was disturbed during natural gas installation prior to inspection on 7/8/19. Weedy vegetation has filled in the ditch. E&A will continue to monitor vegetative establishment.
EB #2	Along ditch W of 25 E Erosion Blanket of Hwy 275 9/13/2018 Active No
Current Condition:	Erosion Blanket of Hwy 275 9/13/2018 Active No Fair Condition - Erosion control blanket was installed by Carstensen Contracting prior to inspection on 9/19/18.
	The area associated with EB #2 is fully vegetated as of the 11/4/19 inspection. E&A will monitor the need for repairs if/when vegetation subsides.
EB #3 Current Condition:	Erosion Blanket E of Roundabout Removed Removed - Vegetation is well established in the area, therefore, the erosion control matting will no longer be
STR	inspected as its own BMP.
Current Condition:	Street cleaning Off-Site Removed Removed Removed Removed - See Street Cleaning for Gallery 23 East as of 12/02/19 inspection.
SWPPP Sign-SI	Signs 2 Entrances Removed Removed
Current Condition:	Removed - See SWPPP signs under Gallery 23 East project
	Water Main Extension
CW	Concrete Washout County Road Blvd U Removed
Current Condition:	Removed - Concrete washouts will not be necessary for the water main project as of the 8/2/19 inspection.
SF #1	Silt Fence Area #1 Removed
Current Condition:	Removed - There is no silt fence in this area, see IP 1 and IP 2 for BMPs in Area #1 N side of 24th St
IP 1	Inlet Protection (Enlarged Area #1) Removed
Current Condition:	Removed - HR Bookstrom removed the inlet protection prior to inspection on 6/24/19.
ourient condition.	S side of 24th St
IP 2	Inlet Protection (Enlarged Area #1) Removed
Current Condition:	Removed - HR Bookstrom removed the inlet protection prior to inspection on 6/24/19.
SF #2	Silt Fence Area #2 Removed
Current Condition:	Removed - Due to established vegetation in the area, straw wattles will no longer be recommended in the area. E&A will monitor.
SF #3	Silt Fence Area #3 Removed
Current Condition:	Removed - Silt fence will not be needed in the area due to stabilization as of 7/21/19 inspection.
SF #4	Silt Fence Area #4 Removed
Current Condition: SF #5	Removed - Silt fence will not be needed in the area due to stabilization as of 11/4/19 inspection. Silt Fence Area #5 Removed
Current Condition:	Removed - Silt fence will not be needed in the area due to stabilization as of 11/4/19 inspection.
SF #6	Silt Fence Area #6 Removed
Current Condition:	Removed - Silt fence will not be needed in the area due to stabilization as of 7/21/19 inspection.
STR Current Condition:	Street cleaning Off-Site Removed Removed Removed - See Street Cleaning for Gallery 23. Water improvements are complete as of the 11/4/19 inspection.
SWPPP Sign-SI	Signs 2 Entrances Removed
Current Condition:	Removed - See SWPPP signs under Gallery 23 East project
	Intersection Improvements

		West of Gallery East			
SF 1	Silt Fence	Drive culvert	12/9/2019	Pending	No
Current Condition:	Pending - Silt Fence will be	installed at a later date	Per conversation with Jim I	Hammitt on 4/1/20 t	he silt fence no
	longer needs to be installed due to immanent regrading.				
		West of Farm Field			
SF 2	Silt Fence	Road culvert	12/9/2019	Pending	No
Current Condition:	Pending - Silt Fence will be installed at a later date. Per conversation with Jim Hammitt on 4/1/20 the silt fen				
	longer needs to be installed due to immanent regrading.				
		East of Farm Field			
SF 3	Silt Fence	Road culvert	10/17/2019	Pending	Yes
Current Condition:	Pending -				
	The silt fence should be installed				
	Jim Hammitt was told to inform Thompson Construction or Luxa to complete by 10/17/19. Not done as of the last inspection. Thompson Construction was reminded on 11/6/19, 11/18/19. Luxa was reminded on 12/3/19, 4/1/20				
- Luk O Inspector Signature:	thal		Reviewed By:	Gut Sur.	-