E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Joe Manning		E&A - P2018.109.002					
		Gallery 23 East					
		CC	M 204702252 /	Mass Cradina			
		CSW-201702253 (Mass Grading) CSW-210802622 (Intersection Improvements) CSW-201802623 (Water Main Improvements)					
	CSV						
Project Name:	CSW-201802624 (East Lift Station)						
For Week Ending:	10/24/2020						
Project Location:	County R	County Road U and Lincoln Highway- Fremont, NE (Dodge County)					
	Gallery 23 East	In	tersection Impr.			1	
Grading:		95%	95%				
Sanitary Sewer:		97%	N/A				
Storm Sewer:		95% 99%	N/A 85%				
Paving: Seeding:		1%	75%				
Jtilities:		98%	N/A				
Overall Development:		45%	75%				
RAIN FALL AMOUNTS	Amount in inches	Da	ate inspected	Weather Conditions	Time		
			· ·			Wee	
Sunday:	0.00"						
Monday	0.31"						
Tuesday	0.00"						
Vednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
						Wed	
Sunday:	0.25"		10/18/20	Cloudy 44/35	3:40 PM		
Monday	0.00"						
Гuesday	0.00"						
Wednesday	0.03"						
Thursday	0.00"						
riday	0.00"						
Saturday	0.00"					Mod	
Sunday:	N/A					Wee	
Monday	N/A						
Гuesday	N/A						
Wednesday	N/A						
Thursday	N/A						
riday	N/A						
Saturday	N/A						
Complaints:							
Construction Sequencing:							

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Grading for Highway 30 intersection improvements has begun (7/27/20). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/20)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Grading for Highway 30 intersection improvements has begun (7/27/20). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/20)

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18). Seeding for Highway 30 Intersection Improvements (10/18/20).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A - Luxa seeded along the Highway 30 intersection improvements. E&A inspector will monitor for adequacy of stabilization

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See Findings Section

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for the Gallery 23 East project. Building Construction has begun in northeast corner of the site as of the 8/26/19 inspection.

Lift Station and Sanitary Force Main projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project was inactive during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. See BMP section for required maintenance.
- 2. Luxa placed a portable toilet on site for the Highway 30 Improvements prior to the inspection on 8/17/20. The portable toilet should be secured. Jim Hammitt was informed to contact Luxa on 8/19/20. Not done as of the last inspection.
- 3. The areas of the intersection improvements where work has ceased should be stabilized. Jim Hammitt was informed to contact Luxa on 10/06/20. Luxa seeded along the intersection improvements and along the Highway 30 ditch prior to the inspection on 10/18/20. The E&A inspector will monitor for vegetation establishment and stabilization.

<mark>etation establishment and</mark>	d stabilization.	I	l	I	I		
Unique Name	Туре	Location	Projected Install Date	Status	Maintenan		
	Ga	allery 23 East		•			
CE 1	Construction Entrance	<u> </u>	•	Removed	I		
Current Condition:			ı onstruction entrance in prep		rior to		
ourient condition.	inspection on 9/9/19.	Struction Temoved the of	onstruction entrance in prop	didion for paving p	mor to		
		County Road					
CE 2	Construction Entrance	25/Highway 30		Removed			
Current Condition:		Removed - Pruss was removing the construction entrance during inspection on 6/18/19 in preparation for					
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed			
Current Condition:			l as a part of the Highway 3		l Vemente nri		
	to the inspection on 8/05/20	D. E&A inspector will mo	nitor and recommend reinst	allation at a later da	ite if necess		
CP #1	Culvert protection	Central portion of site	8/30/2018	Pending	No		
Current Condition:	Pending - Culvert protection						
CP #2	Culvert protection	Southeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Culvert protection		er date.				
0141		Northeast corner of					
CW	Concrete Washout	site		Removed			
Current Condition:			ed prior to inspection on 10/	21/19. No paving is	underway a		
	this time. E&A will monitor t						
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle chec	cks will be installed wher	n grading has ended.				
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No		
Current Condition:	Pending - Ditch wattle chec	ks will be installed wher	grading has ended.	,	•		
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No		
Current Condition:	_		the southeast side of the si				
DD #1	Diversion Ditch	NW Corner of Lake	The southeast side of the si	Removed). 		
Current Condition:			regrading/paving in the are		n on 12/30/1		
DD #2	Diversion Ditch	W side of Lake		Removed			
Current Condition:	Removed - Thompson Con	struction removed the di	version ditch prior to inspec	tion on 9/19/18.			
DD #3	Diversion Ditch	SW corner of lake		Removed			
Current Condition:	Removed - Thompson Con	struction removed the di	version ditch prior to inspec	tion on 9/19/18.			
DD #4	Diversion Ditch	S Side of lake	<u> </u>	Removed			
Current Condition:			version ditch prior to inspec		I		
DD #5	Diversion Ditch	E side of lake	F	Removed	l		
Current Condition:			lversion ditch prior to inspec		l		
	·		recision unon prior to inspec				
DD #6	Diversion Ditch	NE corner of lake	<u> </u>	Removed	40/00:		
Current Condition:	Removed - The diversion d	itch was removed during	g regrading/paving in the are	ea prior to inspection	n on 12/30/1		
DD #7	Diversion Ditch	N side of lake		Removed			
Current Condition:	Removed - The diversion d	litch was removed during	regrading/paving in the are	ea prior to inspection	n on 12/30/1		
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No		

Current Condition:	Pending - Erosion control m	atting and seeding will	be installed when grading h	as ended.			
ED #0	For sion Display	Around Lake (Outlot	1	D din	N1-		
EB #3 Current Condition:	Erosion Blanket Pending - Erosion control m	B)	be installed when grading h	Pending	No		
Current Condition.	Pending - Liosion control in	Area Inlet in SE	be installed when grading in	las ended.			
IP 1	Inlet Protection	portion of the site		Removed			
Current Condition:	Removed - The area east of the area inlet naturally stabilized prior to the 8/05/20 inspection. Inlet Protection no longer needed at this time.						
IP 2	Curb Inlet protection	W Curb inlet on Christine Dr		Removed			
Current Condition:	Removed - The Home Company sodded lots 1-8 prior to the inspection on 6/10/20. Inlet protection is no long required.						
IP 3	Curb Inlet protection	E Curb inlet on Christine Dr		Removed			
Current Condition:	Removed - The Home Company sodded lots 1-8 prior to the inspection on 6/10/20. Inlet protection is required.						
Lots 1-10, Block 1, Replat 2 Current Condition:	Individual Lots Removed - The Home Com on 7/01/20.	Block 1, Replat 2 (Northeast corner of site) pany sodded the remain	ning lots and removed the p	Removed portable toilets prior t	to the inspect		
		Block 2, Replat 2 (Northeast corner of					
Lots 1-10, Block 2, Replat 2	Individual Lots	` site)	11/18/2019	Active	No		
Lots 2 & 3, Block 7	on 8/26/19. No BMPs are required at this time. E&A will monitor. The Home Company secured the portable toilet prior to inspection on 12/16/19. The portable toilet was moved further away from the inlet prior to inspection on 1/13/20. The portable toilet was moved to Block 1, Replat 2 prior to inspection on 2/10/20. Individual Lots Block 7 Removed - The Home Company sodded lots 2 & 3 prior to the inspection on 6/10/20.						
Current Condition:	Removed - The Home Con	ipany sodded iots 2 & 3	s prior to the inspection on b	7/10/20. 			
SB #1	Sediment Basin	Central portion of site	8/30/2018	Pending	No		
Current Condition:	Pending - Basin will be insta				ecessary		
SB #2	Sediment Basin	Southeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Basin will be insta						
SF #1 Current Condition:	Silt Fence Pending - Silt Fence will be	Southeast corner	8/30/2018	Pending	No		
SF #2	Silt Fence	Northeast corner	8/30/2018	Pending	No		
Current Condition:	Pending - Silt Fence will be		when deemed necessary	·			
STR	Street cleaning	Off-Site	In Place	Active	No		
Current Condition:	Good Condition - The street time of the inspection on 10	/05/20.	at time of inspection on 7/8	8/19. The streets we	re clean at th		
SWPPP Sign-SI	Signs	2 Entrances	10/9/2018	Active	No		
Current Condition:	Good Condition - Inspector installed at the County Rd L inspection on 9/19/19. The inspector reinstalled the SW the Highway 30 Intersection construction allows. E&A in	J Blvd entrance at a late E&A inspector reinstalle /PPP sign prior to the ir Improvements prior to	er date. The E&A inspector is the SWPPP sign during the spection on 3/31/20. The Street inspection on 8/17/20. It is the inspection on 8/17/20. It is the inspection on 8/17/20.	reinstalled the SWPl the 2/24/20 inspectic SWPPP sign was rer E&A inspector will re	PP sign durin on. The E&A noved during		
	Intersect	ion Improve		_			
SF 1	Silt Fence	West of Gallery East Drive culvert	12/9/2019	Pendina	NI.		
Current Condition:	Pending - Silt Fence will be longer needs to be installed	installed at a later date	. Per conversation with Jim		No he silt fence i		
		West of Farm Field					
SF 2	Silt Fence	Road culvert	12/9/2019	Pending	No		
Current Condition:	Pending - Silt Fence will be longer needs to be installed	due to imminent regrad		Hammitt on 4/1/20 t	he silt fence i		
SF 3	Silt Fence	East of Farm Field Road culvert	8/31/2020	Active	No		
Current Condition:	Good Condition - Luxa insta development and one at the	illed two silt fence ditch	checks, one between the to	wo north entrances o	of the		
pector Signature:	Je lai		Reviewed By:	But Su	-		