E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

| Inspector: Joe Manning   |  | E&A - P2018   | 3.109.002          |          | Stage |  |
|--------------------------|--|---|--------------------|----------|-------|--|
| Project Name:            | Gallery 23 East  CSW-201702253 (Mass Grading)  CSW-210802622 (Intersection Improvements) |   |                    |          | 2     |  |
| •                        | 2/22/2224  |   |                    |          |       |  |
| For Week Ending:         |  | 0/20/2021   |                    |          |       |  |
| Project Location:        | County Road  | County Road U and Lincoln Highway- Fremont, NE (Dodge County) |                    |          |       |  |
|                          | Gallery 23 East  | Intersection Impr.  |                    |          |       |  |
| Grading:                 | 96%  | 6 100%  |                    |          |       |  |
| Sanitary Sewer:          | 97%  | 6 N/A   |                    |          |       |  |
| Storm Sewer:             | 95%  |   |                    |          |       |  |
| Paving:                  | 99%  |   |                    |          |       |  |
| Seeding:                 | 1%   |   |                    |          |       |  |
| Utilities:               | 99%  |   |                    |          |       |  |
| Overall Development:     | 45%  | 6 100%  |                    |          | 1     |  |
| RAIN FALL AMOUNTS        | Amount in inches   | Date inspected  | Weather Conditions | Time     |       |  |
|                          |  |   |                    |          | Week  |  |
| Sunday:                  | 0.12"  |   |                    |          |       |  |
| Monday                   | 0.00"  |   |                    |          |       |  |
| Tuesday                  | 0.00"  |   |                    |          |       |  |
| Wednesday                | 0.00"  |   |                    |          |       |  |
| Thursday                 | 0.00"  |   |                    |          |       |  |
| Friday                   | 0.00"  |   |                    |          |       |  |
| Saturday                 | 0.00"  |   |                    |          |       |  |
| outuruuy                 | 0.00   |   |                    |          | Week  |  |
| Sunday:                  | 0.00"  |   |                    |          | WOOK  |  |
| Monday                   | 0.00"  |   |                    |          |       |  |
|                          | 0.00"  |   |                    |          |       |  |
| Tuesday                  |  |   |                    |          |       |  |
| Wednesday                | 0.00"  | 0/00/0004   |                    | 0.00.014 |       |  |
| Thursday                 | 0.02"  | 8/26/2021   | Mostly Sunny 94/72 | 2:00 PM  |       |  |
| Friday                   | 0.00"  |   |                    |          |       |  |
| Saturday                 | 0.47"  |   |                    |          |       |  |
|                          |  |   |                    |          | Week  |  |
| Sunday:                  | N/A  |   |                    |          |       |  |
| Monday                   | N/A  |   |                    |          |       |  |
| Tuesday                  | N/A  |   |                    |          | 1     |  |
| Wednesday                | N/A  |   |                    |          |       |  |
| Thursday                 | N/A  |   |                    |          |       |  |
| Friday                   | N/A  |   |                    |          |       |  |
| Saturday                 | N/A  |   |                    |          |       |  |
| Complaints:              |  |   |                    |          |       |  |
| Construction Sequencing: | ) of the site have had a temporary or peri   |   |                    |          |       |  |

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/19). Fine grading throughout the site in preparation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Grading for Highway 30 intersection improvements has begun (7/27/20). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/20). Stockpiling on Block 1 Lot 9 (4/20/21). **Disturbance along Eastgate Road entrance (8/26/21).** 

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/18). Grading has temporarily ceased (1/10/19). Grading in the NE corner of site for sanitary installation (4/5/19). Grading for roads (6/4/19). Grading for utilities, storm, and roads throughout project (6/17/19). Excavation along southwest portion ROW for gas installation (6/18/19). Excavation in the southeast portion of the site for utilities (6/18/19). Excavation throughout the site for gas installation (6/24/19). Excavation for storm sewer (7/16/19) Trenching for utility installation for paving (09/09/19). Excavation in the northeast corner of the site for culvert installation (09/19/19). Trenching/excavation in the southeast portion of the site for utility installation (10/22/19). Trenching throughout site for utility installation (11/18/19). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/20).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/18). Grading has temporarily ceased (1/10/19). Grading occurred in between Hwy 30 and Menards to still water main between last inspection (2/7/19) and current inspection (2/20/19), but grading had ceased at time of inspection. Grading along Hwy 275 (4/5/19). Grading for water main project has ceased (4/19/19)

Highway 30 intersection improvements has begun for culvert installation (10/02/19).

Grading for Highway 30 intersection improvements has begun (7/27/20). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/20). Stockpiling on Block 1 Lot 9 (4/20/21). **Disturbance along Eastgate Road entrance (8/26/21).** 

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/18). Seeding around banks of E side of lake (11/6/18). Seeding for Highway 30 Intersection Improvements (10/18/20). Reseeding along the Highway 30 Improvements (3/15/21).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

**Create Corrective Action?** 

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

**Create Corrective Action?** 

No - See Findings Section and BMP Section (CW on Lots 1-10, Block 1, Replat 2).

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP Section and Findings Section (#4).

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

## Comments:

The site was active during the last inspection for home construction.

Lift Station and Sanitary Force Main projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project was inactive during the last inspection.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1.) See BMP section for required maintenance.
- 2.) Trackout was observed on Eastgate Road and Highway 30 from the RTG Lot. Trackout should be cleaned from the street. White Lotus Group was informed to complete by 1/12/21. No trackout was observed from the lot during the inspection on 3/08/21. Trackout was observed during the inspection on 3/15/21. Ronco Construction was informed to clean the street by 3/16/21. Not done as of the last inspection. Ronco Construction was reminded on 4/21/21, 5/18/21. Ronco Construction cleaned the street prior to the inspection on 6/09/21. Trackout should be cleaned from the street as of the inspection on 6/25/21. Ronco Construction was informed to complete by 6/26/21. Not done as of the last inspection.
- 3.) Ronco Construction was stockpiling dirt on Block 1 Lot 9 from grading activities on Lot 2 Replat 1. A construction entrance should be installed or access to this lot should be blocked. Ronco Construction was informed to complete by 4/27/21. Not done as of the last inspection. Ronco Construction was reminded on 5/18/21. Block 1 Lot 9 was not being accessed as of the inspection on 6/09/21. The street was cleaned prior to the inspection on 8/13/21.
- 4.) Concrete waste from the RTG Lot was observed outside of the lot. Concrete waste should be kept on the lot. Ronco Construction was informed to remove the concrete waste by 7/02/21. Not done as of the last inspection.
- 5.) Due to stabilization and removal of all BMPs, the NOT for the Intersection Improvements permit (CSW-210802622) was submitted on 8/26/21. Permit closure was approved by the NDEE on 8/26/21.

|  | T  | T  |                                    | I                      |                   |  |  |
|--|--|--|------------------------------------|------------------------|-------------------|--|--|
| Unique Name  | Type   | Location   | Projected Install Date             | Status                 | Maintenance       |  |  |
| - 4  |  | llory 23 Fast  |                                    |                        |                   |  |  |
| Gallery 23 East  |  |  |                                    |                        |                   |  |  |
| CE 1   | Construction Entrance  | County Road Blvd U   |                                    | Removed                |                   |  |  |
| Current Condition:   | Removed - Thompson Construction removed the construction entrance in preparation for paving prior to |  |                                    |                        |                   |  |  |
|  | inspection on 9/9/19.  |  |                                    |                        |                   |  |  |
| 05.0   | 0  | County Road  |                                    | l <u>.</u> .           |                   |  |  |
| CE 2   | Construction Entrance  | 25/Highway 30  |                                    | Removed                | <u> </u>          |  |  |
| Current Condition:   | Removed - Pruss was removed  | Removed - Pruss was removing the construction entrance during inspection on 6/18/19 in preparation for paving. |                                    |                        |                   |  |  |
|  |  | 1  |                                    |                        | _                 |  |  |
|  |  | NE 0 11 00 0   |                                    |                        |                   |  |  |
| 05.0   | 0  | NE Corner - Hwy 30 &   |                                    | l <u>.</u> .           |                   |  |  |
| CE 3   | Construction Entrance  | Christine Drive  |                                    | Removed                | <u> </u>          |  |  |
| Current Condition:   |  |  | d as a part of the Highway 3       |                        |                   |  |  |
|  | to the inspection on 8/05/20   | 0. E&A inspector will mo   | nitor and recommend reinst         | allation at a later d  | ate if necessary. |  |  |
|  |  | T  |                                    | ı                      | Т                 |  |  |
| 05 ""  |  |  | 0/00/00/0                          |                        |                   |  |  |
| CP #1  | Culvert protection   | Central portion of site  | 8/30/2018                          | Pending                | No                |  |  |
| Current Condition:   | Pending - Culvert protection   |  |                                    |                        |                   |  |  |
| CP #2  | Culvert protection   | Southeast corner   | 8/30/2018                          | Pending                | No                |  |  |
| Current Condition:   | Pending - Culvert protection   |  | er date.                           | ı                      | Т                 |  |  |
|  |  | Northeast corner of  |                                    |                        |                   |  |  |
| CW   | Concrete Washout   | site   |                                    | Removed                |                   |  |  |
| Current Condition:   |  |  | ed prior to inspection on 10/2     | 21/19. No paving i     | s underway at     |  |  |
| 500.00   | this time. E&A will monitor  |  |                                    |                        |                   |  |  |
| DW #1  | Ditch Wattle Checks  | Middle Central   | 8/30/2018                          | Pending                | No                |  |  |
| Current Condition:   | Pending - Ditch wattle ched  |  |                                    | I 5 "                  |                   |  |  |
| DW #2  | Ditch Wattle Checks  | Southwest corner   | 8/30/2018                          | Pending                | No                |  |  |
| Current Condition:   | Pending - Ditch wattle ched  |  |                                    |                        |                   |  |  |
| DW #3  | Ditch Wattle Checks  | Southeast corner   | 8/30/2018                          | Active                 | No                |  |  |
| Current Condition:<br>DD #1  |  |  | the southeast side of the sit      |                        | 8.<br>T           |  |  |
|  | Diversion Ditch  | NW Corner of Lake  |                                    | Removed                | 40/20/40          |  |  |
| Current Condition:   | Removed - The diversion d  | nich was removed during  | g regrading/paving in the are      | ea prior to inspection | on on 12/30/19.   |  |  |
| DD #2  | Diversion Ditch  | W side of Lake   | ſ                                  | Removed                | T                 |  |  |
|  |  |  | line ditab majanta inana           |                        |                   |  |  |
| Current Condition:<br>DD #3  | Diversion Ditch  | SW corner of lake  | version ditch prior to inspec      | Removed                | 1                 |  |  |
|  |  |  | I<br>version ditch prior to inspec |                        |                   |  |  |
| Current Condition:<br>DD #4  | Diversion Ditch  | S Side of lake   | l<br>I                             | Removed                |                   |  |  |
| Current Condition:   |  |  | I<br>version ditch prior to inspec |                        |                   |  |  |
| DD #5  | Diversion Ditch  | E side of lake   | l<br>I                             | Removed                |                   |  |  |
| Current Condition:   |  |  | I<br>version ditch prior to inspec |                        | 1                 |  |  |
| DD #6  | Diversion Ditch  | NE corner of lake  | <br>                               | Removed                |                   |  |  |
| Current Condition:   |  |  | regrading/paying in the are        |                        | n on 12/30/10     |  |  |
| Current Condition: Removed - The diversion ditch was removed during regrading/paving in the area prior to inspection on 12/30/19 |  |  |                                    |                        |                   |  |  |
| DD #7  | Diversion Ditch  | N side of lake   |                                    | Removed                |                   |  |  |
|  | DIVOIDION DIXON  | 11 Slas Si lake  |                                    | 1 1101110104           | 1                 |  |  |

| Current Condition:                               | Pomovod The diversion d  | litah waa ramayad during     | rograding/paying in the or      | on prior to increation | n on 12/20/10     |  |
|--|--|------------------------------|---------------------------------|------------------------|-------------------|--|
| Current Condition:                               | Removed - The diversion d  | nich was removed duning      | g regrading/paving in the ar    | ea prior to inspection | 11 011 12/30/19.  |  |
| EB #2  | Erosion Blanket  | Northeast corner             | 8/30/2018                       | Pending                | No                |  |
| Current Condition:                               | Pending - Erosion control n  | natting and seeding will     | be installed when grading h     | nas ended.             | •                 |  |
|  | _  | Around Lake (Outlot          |                                 |                        |                   |  |
| EB #3  | Erosion Blanket  | B)                           | 8/30/2018                       | Pending                | No                |  |
| Current Condition:                               | Pending - Erosion control n  |                              | be installed when grading h     | nas ended.             |                   |  |
|  |  | Area Inlet in SE             |                                 |                        |                   |  |
| IP 1   | Inlet Protection   | portion of the site          |                                 | Removed                |                   |  |
| Current Condition:                               | Removed - The area east of   | of the area inlet naturally  | stabilized prior to the 8/05/   | 20 inspection. Inlet   | Protection no     |  |
|  | longer needed at this time.  |                              |                                 | ,                      | ,                 |  |
|  |  | W Curb inlet on              |                                 | l                      |                   |  |
| IP 2   | Curb Inlet protection  | Christine Dr                 |                                 | Removed                |                   |  |
| Current Condition:                               | Removed - The Home Company sodded lots 1-8 prior to the inspection on 6/10/20. Inlet protection is no longer               |                              |                                 |                        |                   |  |
|  | required.  |                              | ı                               | 1                      | ı                 |  |
| ID 3   | Curb Inlet protection  | E Curb inlet on              |                                 | Domoved                |                   |  |
| IP 3 Current Condition:                          | Curb Inlet protection  | Christine Dr                 | i an ta tha i nan aatian an C/4 | Removed                | i I               |  |
| Current Condition:                               | Removed - The Home Con   | ipany sodded iots 1-8 pr     | for to the inspection on 6/1    | 0/20. iniet protection | i is no longer    |  |
|  | required.  | Block 1, Replat 2            | T                               | 1                      | I                 |  |
|  |  | · ·                          |                                 |                        |                   |  |
| Lote 1 10 Plack 2 Poplet 2                       | Individual Lots  | (Northeast corner of site)   |                                 | Removed                |                   |  |
| Lots 1-10, Block 2, Replat 2  Current Condition: | Removed - Block 2 was mi   |                              | l ack 1                         | Removed                |                   |  |
| Current Condition.                               | Acinovad - Dioon 2 was IIII  | Block 2, Replat 2            |                                 |                        |                   |  |
|  |  | (Northeast corner of         |                                 |                        |                   |  |
| Block 1 Replat 2, Lots 1-10                      | Individual Lots  | site)                        | 1/11/2021                       | Active                 | Yes               |  |
| Current Condition:                               | Fair Condition - The Home  |                              |                                 |                        |                   |  |
|  | 7/27/20. The Home Compa  |                              |                                 |                        |                   |  |
|  |  |                              |                                 |                        |                   |  |
|  | Company secured the porta  | able toilet prior to the ins | spection on 3/15/21. The Ho     | ome Company begai      | n excavating lots |  |
|  | 1 and 2 prior to the inspect   | ion on 4/7/21. The Home      | e Company removed the co        | ncrete waste from L    | ots 1 and 2 prior |  |
|  | to the inspection on 5/17/2  | 1.                           |                                 |                        | · ·               |  |
|  |  |                              |                                 |                        |                   |  |
|  | 1.) Silt fence or straw wattle   | e should be installed al     | ong the south side of Late (    | and 10 or the lote of  | should be         |  |
|  | stabilized.  | 23 SHOULD DE INSTAILEU AN    | ong the south side of Lots s    | and to or the lots s   | silould be        |  |
|  |  | Alexandra alexandri bereda e |                                 |                        |                   |  |
|  | 2.) The streets surrounding  |                              |                                 | 0 140 1 111            |                   |  |
|  | 3.) Silt fence should be installed along the backs of Lots 1-2 and 9-10 (or Lots 9 and 10 should be stabilized).           |                              |                                 |                        |                   |  |
|  |  |                              |                                 |                        |                   |  |
|  | 1.) The Home Company was informed to complete by 3/15/21. Not done as of the last inspection. The Home                     |                              |                                 |                        |                   |  |
|  | Company was reminded on 4/21/21, 6/10/21, 7/21/21  |                              |                                 |                        |                   |  |
|  | 2.) The Home Company was informed to complete by 3/09/21. Not done as of the last inspection. The Home                     |                              |                                 |                        |                   |  |
|  | Company was reminded or  |                              |                                 |                        |                   |  |
|  | 3.) The Home Company wa  | as informed to complete      | by 4/27/21. Not done as of      | the last inspection.   | The Home          |  |
|  | Company was reminded or  | 6/10/21, 7/21/21             |                                 |                        |                   |  |
| Block 3 Replat 2, Lots 9-12                      | Individual Lots  | Block 3                      | 6/9/2021                        | Active                 | No                |  |
| Current Condition:                               | Active - Hubbell Homes be  |                              |                                 |                        |                   |  |
|  | surrounding the lots and the   |                              |                                 |                        |                   |  |
|  | monitor.   | ,                            |                                 |                        |                   |  |
| Block 3 Replat 2, Lots 13-16                     | Individual Lots  | Block 3                      | 6/9/2021                        | Pending                | Yes               |  |
| Current Condition:                               | Pending - Hubbell Homes  |                              |                                 |                        | 165               |  |
| Current Condition.                               | Feliding - Hubbell Homes   | began construction on t      | tots 13-10 phot to the hispe    | CHOIT OIT 0/09/21.     |                   |  |
|  | 1.) Silt fence or straw wattles should be installed along the front of the lots.   |                              |                                 |                        |                   |  |
|  | ,  |                              |                                 |                        |                   |  |
|  | 2.) The street in front of the lots should be cleaned.   |                              |                                 |                        |                   |  |
|  | 1.) The E&A inspector will make an attempt to identify the huilder and inform them to complete by 7/46/31. Not             |                              |                                 |                        |                   |  |
|  | 1.) The E&A inspector will make an attempt to identify the builder and inform them to complete by 7/16/21. Not             |                              |                                 |                        |                   |  |
|  | done as of the last inspection. Hubbell Homes was informed to complete by 8/20/21. <b>Not done as of the last</b>          |                              |                                 |                        |                   |  |
|  | inspection. 2.) The E&A inspector will make an attempt to identify the builder and inform them to complete by 7/16/21. Not |                              |                                 |                        |                   |  |
|  |  |                              |                                 |                        |                   |  |
|  | done as of the last inspecti   | on. Hubbell Homes was        | informed to complete by 8/      | 14/21. Not done as     | of the last       |  |
| Block A Daniet O. Late O. 40                     | inspection.  | Diagle 4                     | 0/40/0004                       | A =4:                  | NI-               |  |
| Block 4 Replat 2, Lots 8-12                      | Individual Lots  | Block 4                      | 8/13/2021                       | Active                 | No<br>No          |  |
| Current Condition:                               | Good Condition - Hubbell F   | · ·                          | •                               |                        |                   |  |
|  | vegetation surrounding the   | · ·                          | *                               |                        |                   |  |
|  | inspector will monitor. Hubl   | pell Homes secured a po      | ortable toilet on Lot 9 prior t | o the inspection on 8  | 8/13/21.          |  |
|  |  | <del></del>                  |                                 |                        |                   |  |
| Block 6, Lot 9                                   | Individual Lots  | Block 6                      | 8/13/2021                       | Active                 | No                |  |
| Current Condition:                               | Active - Hubbell Homes be  | •                            |                                 |                        | •                 |  |
|  | and the surrounding vegeta   | ation no BMPs will be red    | commended at this time. E       | &A inspector will mo   |                   |  |
| 1  | 3 3  |                              |                                 | art mopeotor will mo   | nitor.            |  |
|  |  |                              |                                 | art mopeotor will mo   | nitor.            |  |
| Block 6, Lot 24                                  | Individual Lots  | Block 6                      | 4/20/2021                       | Active                 | nitor. Yes        |  |

| Current Condition:   | Fair Condition - Jeff Wearden Homes began construction on the lot prior to the inspection on 4/20/21. Jeff Wearden Homes installed silt fence at the back of the lot prior to the inspection on 5/17/21. The street in front of the lot was cleaned prior to the inspection on 6/09/21. Jeff Wearden Homes removed the concrete waste, secured the portable toilet, and trenched in the silt fence at the back of the lot prior to the inspection on 7/09/21.  The silt fence should be cleaned out and repaired at the back of the lot.  |                                    |                               |                      |                 |
|----------------------|---|------------------------------------|-------------------------------|----------------------|-----------------|
|                      |   |                                    |                               |                      |                 |
|                      | Jeff Wearden Homes was informed to complete by 7/17/21. Not done as of the last inspection.   |                                    |                               |                      |                 |
| Block 7, Lots 2 & 3  | Individual Lots   | Block 7                            |                               | Removed              |                 |
| Current Condition:   | Removed - The Home Com  | pany sodded lots 2 & 3             | prior to the inspection on 6  | 10/20.               |                 |
| Block 7, Lot 6       | Individual Lots   | Block 7                            | 3/24/2021                     | Active               | No              |
| Current Condition:   | Good Condition - Rick Walk  | up Construction began              | construction on the lot prior | to the inspection of | n 3/24/21. Rick |
|                      | Walkup Construction secure  | ed a portable toilet on th         | e lot prior to the inspection | on 3/24/21. Rick W   | alkup           |
|                      | Construction removed the d  |                                    |                               |                      |                 |
|                      | was cleaned prior to the ins  |                                    |                               |                      |                 |
|                      | ·   |                                    |                               |                      |                 |
| SB #1                | Sediment Basin  | Central portion of site            | 8/30/2018                     | Pending              | No              |
| Current Condition:   | Pending - Basin will be insta   |                                    | commenced at a later date a   | and when deemed r    | necessary       |
| SB #2                | Sediment Basin  | Southeast corner                   | 8/30/2018                     | Pending              | No              |
| Current Condition:   | Pending - Basin will be insta   |                                    | commenced at a later date a   | nd when deemed r     | necessary       |
| SF #1                | Silt Fence  | Southeast corner                   | 8/30/2018                     | Pending              | No              |
| Current Condition:   | Pending - Silt Fence will be installed at a later date when deemed necessary  |                                    |                               |                      |                 |
| SF #2                | Silt Fence  | Northeast corner                   | 8/30/2018                     | Pending              | No              |
| Current Condition:   | Pending - Silt Fence will be  |                                    |                               |                      |                 |
| STR                  | Street cleaning   | Off-Site                           | In Place                      | Active               | No              |
| Current Condition:   | Good Condition - The streets near CE 2 were clean at time of inspection on 7/8/19. The streets were clean at the time of the inspection on 10/05/20.  |                                    |                               |                      |                 |
| SWPPP Sign           | Signs   | 2 Entrances                        | 10/9/2018                     | Active               | No              |
| Current Condition:   | Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPP sign will be installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPP sign during inspection on 9/19/19. The E&A inspector reinstalled the SWPPP sign during the 2/24/20 inspection. The E&A inspector reinstalled the SWPPP sign prior to the inspection on 3/31/20. The SWPPP sign was removed during the Highway 30 Intersection Improvements prior to the inspection on 8/17/20. E&A inspector will reinstall as construction allows. E&A inspector reinstalled the SWPPP sign during the inspection on 8/31/20. |                                    |                               |                      |                 |
|                      | Intersect   | ion Improve                        | ments                         |                      |                 |
| 05.4                 | 011.5   | West of Gallery East               |                               |                      |                 |
| SF 1                 | Silt Fence  | Drive culvert                      |                               | Removed              |                 |
| Current Condition:   | Removed - Due to comple   |                                    | ill not be recommended as     | s of 8/26/21.        | ı               |
| SF 2                 | Silt Fence  | West of Farm Field<br>Road culvert |                               | Removed              |                 |
| Current Condition:   | Removed - Due to complet  |                                    | ill not be recommended as     | s of 8/26/21.        |                 |
| SF 3                 | Silt Fence  | East of Farm Field<br>Road culvert |                               | Removed              |                 |
| Current Condition:   | Removed - Luxa removed  | the two silt fence ditc            | h checks prior to the inspe   | ection on 8/26/21.   |                 |
| Inspector Signature: | Ge line   |                                    | Reviewed By:                  | to Su                |                 |