E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Josh Ellington			Stage			
inspector. Josh Ellington			Glage			
		<u>Gallery</u>	<u> 23 East</u>		1	
Project Name:		SW-20170225	3 (Mass Grading)		•	
•			2023			
5				2 ()	68025	
Project Location:	County Road	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				
	Gallery 23 East					
Grading:	96%					
Sanitary Sewer:	97%					
Storm Sewer:	95%					
Paving:	99%					
Seeding:	1%					
Utilities:	99%					
Overall Development:	45%					
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
					Week 1	
Sunday:	0.00"					
Monday	0.00"	6/26/2023	Sunny 73	9:50 AM		
Tuesday	0.01"					
Wednesday	0.02"					
Thursday	0.05"					
Friday	0.45"	6/30/2023	Cloudy 75	10:35 AM		
Saturday	1.33"					
Complaints	None					
Complaints:						
Construction Sequencing:						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No - See Findings and BMP Section.

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMPs Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the last inspection for home construction.

Lift Station, Sanitary Force Main, and the Intersection Improvements projects are closed.

Water Improvements project is closed.

Highway 30 intersection improvements project is closed.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Minor disturbance was observed in the northernmost part of Aaron Way near Block 1 Replat 2; E&A inspector will monitor to see if any action is necessary.

The second inspection during this period was to accommodate scheduling requirements.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) See BMP section for required maintenance.
- 2.) Waste storage containers should be emptied when the full line is reached and any litter should be picked up. All developers were informed to complete by 9/13/22. Not done as of the last inspection. Builders were reminded on 5/11/23, 6/14/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Gallery 23 East							
CE 1	Construction Entrance	County Road Blvd U		Removed			
Current Condition:	Removed - Thompson Con	struction removed the co	onstruction entrance in prep	aration for paving p	prior to inspection o		
	Removed - Thompson Construction removed the construction entrance in preparation for paving prior t 9/9/19.						
		County Road					
CE 2	Construction Entrance	25/Highway 30		Removed			
Current Condition:	Removed - Pruss was remo	oving the construction er	ntrance during inspection on	6/18/19 in prepara	ation for paving.		
		INF O	T	T			
05.0	Construction Futures	NE Corner - Hwy 30 &		Damasuad			
CE 3	Construction Entrance	Christine Drive	1	Removed			
Current Condition:			d as a part of the Highway 3				
	<u> </u>	, '	nd recommend reinstallatior	1	ecessary.		
CIP 1	Curb Inlet protection	Sammy Road		Removed			
Current Condition:			prior to the inspection on 1/		1		
CIP 2	Curb Inlet protection	Sammy Road	11/30/2022	Active	No		
Current Condition:	Good Condition - DR Horto	n installed inlet protection	on north of Lot 4 Block 12 pri	ior to the inspection	n on 11/30/22.		
0.00			I=.	I	T		
CIP 3	Curb Inlet protection	East 18th Avenue	1/17/2023 on south of Lot 15 Block 6 pr	Active	No		
Current Condition:	Horton reinstalled the inlet			ioi to the mspectio	11 011 1/11/23. D IX		
		<u> </u>					
CIP 4	Curb Inlet protection	Kara Way	1/17/2023	Pending	No 17/23 DR Horton		
CIP 4 Current Condition:	Pending - DR Horton install	Kara Way led inlet protection south		e inspection on 1/2	17/23. DR Horton		
	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of	1/17/2023 n of Lot 21 Block 6 prior to th on 5/10/23. E&A inspector w	ie inspection on 1/ vill recommend rein Active	17/23. DR Horton estallation as		
Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of	1/17/2023 n of Lot 21 Block 6 prior to th on 5/10/23. E&A inspector w	ie inspection on 1/ vill recommend rein Active	17/23. DR Horton estallation as		
Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of	1/17/2023 n of Lot 21 Block 6 prior to th on 5/10/23. E&A inspector w	ie inspection on 1/ vill recommend rein Active	17/23. DR Horton estallation as		
CIP 5 Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane	1/17/2023 n of Lot 21 Block 6 prior to tho 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 pr	e inspection on 1/ vill recommend rein Active ior to the inspectio Active	No n on 5/31/23.		
CIP 5 Current Condition: CIP 6	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior to the control of L	e inspection on 1/ vill recommend rein Active ior to the inspectio Active	No n on 5/31/23.		
CIP 5 Current Condition: CIP 6	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior to the control of L	e inspection on 1/ vill recommend rein Active ior to the inspectio Active	No n on 5/31/23.		
CIP 5 Current Condition: CIP 6 Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane Taylor Lane	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior to the concrete on northeast of the concrete	e inspection on 1/ ill recommend rein Active ior to the inspectio Active washout pit prior to Active	No n on 5/31/23. No the inspection on No		
CIP 5 Current Condition: CIP 6 Current Condition: CIP 7	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane Taylor Lane	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023	e inspection on 1/ ill recommend rein Active ior to the inspectio Active washout pit prior to Active	No n on 5/31/23. No the inspection on No		
CIP 5 Current Condition: CIP 6 Current Condition: CIP 7	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane Taylor Lane	1/17/2023 n of Lot 21 Block 6 prior to the constraint of Lot 3. E&A inspector with a south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete on northeast of the concrete on northeast of the concrete	e inspection on 1/ ill recommend rein Active ior to the inspectio Active washout pit prior to Active	No n on 5/31/23. No the inspection on No		
Current Condition: CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane n installed inlet protection Central portion of site	1/17/2023 n of Lot 21 Block 6 prior to the point 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018	e inspection on 1//ill recommend rein Active ior to the inspectio Active washout pit prior to Active washout pit prior to	No n on 5/31/23. No the inspection on the inspection on		
CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CIP 7 Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23.	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane n installed inlet protection Central portion of site	1/17/2023 n of Lot 21 Block 6 prior to the point 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018	e inspection on 1//ill recommend rein Active ior to the inspectio Active washout pit prior to Active washout pit prior to	No n on 5/31/23. No the inspection on the inspection on		
CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection Pending - Culvert protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane contral portion of site n will be installed at a late Southeast corner	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018 der date. 8/30/2018	e inspection on 1//ill recommend rein Active ior to the inspectio Active washout pit prior to Active washout pit prior to Pending	No n on 5/31/23. No the inspection on No the inspection on No		
Current Condition: CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition: CP #2	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection Pending - Culvert protection Culvert protection	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane contral portion of site n will be installed at a late Southeast corner	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018 der date. 8/30/2018	e inspection on 1//ill recommend rein Active ior to the inspectio Active washout pit prior to Active washout pit prior to Pending	No n on 5/31/23. No the inspection on No the inspection on No No No		
Current Condition: CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition: CP #2 Current Condition:	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection Pending - Culvert protection Culvert protection Pending - Culvert protection Concrete Washout	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane n installed inlet protection Central portion of site n will be installed at a lat Southeast corner n will be installed at a lat Block 9, Lot 1	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018 der date. 8/30/2018 der date.	e inspection on 1/ ill recommend rein Active ior to the inspectio Active washout pit prior to Active washout pit prior to Pending Pending Active	No n on 5/31/23. No the inspection on No No No No No		
Current Condition: CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition: CP #2 Current Condition: CW	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection Pending - Culvert protection Culvert protection Pending - Culvert protection Pending - Culvert protection Concrete Washout Good Condition - DR Horto	Kara Way led inlet protection south n prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane n installed inlet protection Central portion of site n will be installed at a lat Southeast corner n will be installed at a lat Block 9, Lot 1 n installed a concrete was	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018 ter date. 8/30/2018 ter date. 9/6/2022	e inspection on 1//ill recommend rein Active ior to the inspectio Active washout pit prior to Active washout pit prior to Pending Pending Active n on 9/06/22. DR F	No n on 5/31/23. No the inspection on No		
Current Condition: CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition: CP #2 Current Condition: CW	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Gurb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection Pending - Culvert protection Culvert protection Pending - Culvert protection Pending - Culvert protection Concrete Washout Good Condition - DR Horto concrete washout and instal	Kara Way led inlet protection south prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane n installed inlet protection Central portion of site n will be installed at a lat Southeast corner n will be installed at a lat Block 9, Lot 1 n installed a concrete walled a new washout with	1/17/2023 n of Lot 21 Block 6 prior to the con 5/10/23. E&A inspector w 5/31/2023 on south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior south of Lot 13 Block 6 prior northeast of the concrete 6/19/2023 on northeast of the concrete 8/30/2018 ter date. 8/30/2018 ter date. 9/6/2022 ashout prior to the inspection	Active washout pit prior to Pending Pending Active active washout pit prior to Active washout pit prior to Active ror to the inspection Active washout pit prior to Active to pending Active n on 9/06/22. DR For to the inspection	No n on 5/31/23. No the inspection on No		
Current Condition: CIP 5 Current Condition: CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition: CP #2 Current Condition: CW	Pending - DR Horton install removed the inlet protection necessary. Curb Inlet protection Good Condition - DR Horto Gurb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto 6/19/23. Culvert protection Pending - Culvert protection Culvert protection Pending - Culvert protection Pending - Culvert protection Concrete Washout Good Condition - DR Horto concrete washout and instal	Kara Way led inlet protection south prior to the inspection of East 18th Avenue n installed inlet protection Taylor Lane n installed inlet protection Taylor Lane n installed inlet protection Central portion of site n will be installed at a lat Southeast corner n will be installed at a lat Block 9, Lot 1 n installed a concrete was liled a new washout with crete washout prior to the	1/17/2023 n of Lot 21 Block 6 prior to the constraint of Lot 3. E&A inspector with the solution of 1/10/23. E&A inspector with solution of 1/10/23. E&A inspector with solution of 1/10/2023 on south of Lot 13 Block 6 prior northeast of the concrete of 1/10/2023 on northeast of the concrete of 1/10/2023 on northeast of the concrete of 1/10/2028 a solution of 1/10/2029 a bern and plastic liner prior in spection on 4/10/23. DR	Active washout pit prior to Pending Pending Active active washout pit prior to Active washout pit prior to Active ror to the inspection Active washout pit prior to Active to pending Active n on 9/06/22. DR For to the inspection	No n on 5/31/23. No the inspection on No		

Current Condition:	Pending - Ditch wattle check	s will be installed when	grading has ended			
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No	
Current Condition:	Pending - Ditch wattle check			1		
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No	
Current Condition:	Good Condition - Wattles ch					
DD #1	Diversion Ditch	NW Corner of Lake		Removed	,.	
Current Condition:	Removed - The diversion di	_	regrading/paying in the are		n on 12/30/19	
DD #2	Diversion Ditch	W side of Lake		Removed	1	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec			
DD #3	Diversion Ditch	SW corner of lake		Removed		
Current Condition:	Removed - Thompson Cons		L version ditch prior to inspec			
DD #4	Diversion Ditch	S Side of lake		Removed	1	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec			
DD #5	Diversion Ditch	E side of lake		Removed	1	
Current Condition:	Removed - Thompson Cons		version ditch prior to inspec			
DD #6	Diversion Ditch	NE corner of lake		Removed	1	
Current Condition:	Removed - The diversion di		regrading/paving in the are		n on 12/30/19	
Current Condition.	Tremoved - The diversion di	ion was removed during	g regrading/paving in the art	ca prior to mapeono	11 011 12/30/13.	
DD #7	Diversion Ditch	N side of lake		Removed		
Current Condition:	Removed - The diversion di		regrading/paving in the are		n on 12/30/10	
Current Condition.	Tremoved - The diversion div	ich was removed dunnig	g regrading/paving in the are	ea prior to mapecilo	11 011 12/30/19.	
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m				INO	
Current Condition.	T ending - Erosion control in	Around Lake (Outlot	l	T Tribed.		
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m				INO	
Current Condition.	Fending - Erosion control in	Area Inlet in SE	be installed when grading it	as ended.		
IP 1	Inlet Protection	portion of the site		Removed		
Current Condition:	Removed - The area east of		stabilized prior to the 8/05/		Protection no longer	
Current Condition.	needed at this time.	the area mict naturally	stabilized prior to the 6/03/	zo mapeodon. miet	i rotection no longer	
	necded at this time.	W Curb inlet on	I			
IP 2	Curb Inlet protection	Christine Dr		Removed		
	Removed - The Home Com		iartatha inanastian an 6/1/		is no longer required	
Current Condition:	Removed - The Home Com	pany souded lots 1-6 pr	ior to the inspection on 6/10	7/20. miet protection	i is no longer required.	
				1	1	
ID 0		E Curb inlet on				
IP 3	Curb Inlet protection	Christine Dr		Removed	<u> </u>	
Current Condition:	Removed - The Home Com	pany sodded lots 1-8 pr	or to the inspection on 6/10)/20. Inlet protection	is no longer required.	
		Block 2, Replat 2				
		(Northeast corner of				
Block 1 Replat 2, Lots 1-10	Individual Lots	site)		Removed		
Current Condition:	Removed - The Home Com	pany sodded the lots pr	ior to the inspection on 7/11	/22.		
Block 2 Replat 3, Lot 16	Individual Lots	Block 2, Lot 16		Removed		
Current Condition:	Removed - Lot was added in	n error as of 5/10/23.				
Block 3 Replat 3, Lot 10	Individual Lots	Block 3, Lot 10		Removed		
Current Condition:	Removed - Lot was added in					
Block 3 Replat 2, Lots 1-7	Individual Lots	Block 3	10/5/2022	Active	Yes	
Current Condition:	Active - Hubbell Homes beg	an construction on the	lots prior to the inspection o	n 10/05/22. Due to	the grade of the lots,	
	no BMPs will be recommend	ded at this time. Hubbel	I Homes secured the portab	ole toilets on the lots	prior to the inspection	
	on 11/30/22. Hubbell Homes	s removed the portable	toilets from the lots prior to	the inspection on 2	/15/23. Hubbell Homes	
	placed two portable toilets on site prior to the inspection on 3/13/23. Hubbell Homes secured the portable toilets and					
	cleaned the street in front of			· ·		
	1.) The street in front of the	lots should be cleaned.				
	2.) Portable toilets should be					
	· 1					
	1.) Hubbell Homes was info	rmed to complete by 5/	<mark>18/23. Not done as of last in</mark>	spection. Hubbell H	lomes was reminded	
	on 6/14/23.					
	2.) Hubbell Homes was info	rmed to complete by 6/2	19/23. Not done as of last in	spection.		
DI 10D 1101 1010	<u> </u>	Block 3		Removed		
Block 3 Replat 2, Lots 9-12	Individual Lots					
Block 3 Replat 2, Lots 9-12 Current Condition:	Individual Lots Removed - Hubbell Homes		the inspection on 7/11/22	1		
Current Condition:	Removed - Hubbell Homes	sodded the lots prior to	the inspection on 7/11/22.	Removed		
Current Condition: Block 3 Replat 2, Lots 13-16	Removed - Hubbell Homes Individual Lots	sodded the lots prior to Block 3	·	Removed		
Current Condition: Block 3 Replat 2, Lots 13-16 Current Condition:	Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes	sodded the lots prior to Block 3 sodded the lots prior to	·			
Current Condition: Block 3 Replat 2, Lots 13-16 Current Condition: Block 4 Replat 2, Lots 8-12	Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes Individual Lots	Block 3 sodded the lots prior to Block 4	the inspection on 7/11/22.	Removed	10/05/22.	
Current Condition: Block 3 Replat 2, Lots 13-16 Current Condition:	Removed - Hubbell Homes Individual Lots Removed - Hubbell Homes	Block 3 sodded the lots prior to Block 4	the inspection on 7/11/22.	Removed	10/05/22. Yes	

Current Condition:	Active - Hubbell Homes be no BMPs will be recommen		lots prior to the inspection	on 11/30/22. Due to	the grade of the lots,		
	The street in front of the lots should be cleaned.						
	Hubbell Homes was inform on 3/15/23, 5/11/23, 5/17/2		8/22. Not done as of the las	t inspection. Hubbell	Homes was reminded		
Block 4 Replat 2, Lots 5-7	Individual Lots	Block 4	10/5/2022	Active	Yes		
Current Condition:	Active - Hubbell Homes be	egan construction on the	lots prior to the inspection		the grade of the lots,		
	Active - Hubbell Homes began construction on the lots prior to the inspection on 10/05/22. Due to the grade of the lots, no BMPs will be recommended at this time. The street in front of the lots should be cleaned. Hubbell Homes was informed to complete by 12/28/22. Not done as of the last inspection. Hubbell Homes was reminded on 3/15/23, 5/11/23, 5/17/23, 6/14/23						
Block 4 Replat 2, Lots 13-16	Individual Lots	Block 4	10/5/2022	Active	Yes		
Current Condition:	Active - Hubbell Homes began construction on the lots prior to the inspection on 10/05/22. Due to the grade of the lots, no BMPs will be recommended at this time. Lot 13 was sodded prior to the 5/24/23 inspection. The street in front of the lots should be cleaned. Hubbell Homes was informed to complete by 5/18/23. Not done as of last inspection. Hubbell Homes was reminded on 6/14/23.						
Block 5 Replat 2, Lots 7-9	Individual Lots	Block 5	4/26/2023	Active	Yes		
	Active - Hubbell Homes began construction on the lots prior to the inspection on 4/26/23. Due to the grade of the lots, no BMPs will be recommended at this time. The street in front of the lots should be cleaned. Hubbell Homes was informed to complete by 5/18/23. Not done as of last inspection. Hubbell Homes was reminded on 6/14/23.						
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5	10/5/2022	Active	Yes		
	The street in front of the local Hubbell Homes was inform 6/14/23.		23. Not done as of last insp	pection. Hubbell Hom	nes was reminded on		
Block 6, Lot 9	Individual Lots	Block 6		Removed			
Current Condition:	Removed - Hubbell Homes		the inspection on 8/8/22	rtemoved			
Block 6, Lot 23	Individual Lots	Block 6	I I I I I I I I I I I I I I I I I I I	Removed			
Current Condition:	Removed - Hubbell Homes		the 6/5/23 inspection.	ļ.			
Block 6, Lot 24	Individual Lots	Block 6	<u>.</u>	Removed			
Current Condition:	Removed - Jeff Whearden		prior to the inspection on 1/				
Block 6, Lot 25	Individual Lots	Block 6		Removed			
Current Condition:	Removed - Rick Walkup (lot prior to the inspection o		1		
Block 6, Lot 26	Individual Lots Removed - Hubbell Homes	Block 6	the 5/24/22 inequation	Removed			
Current Condition:				Λ -4:	N.		
Block 6, Lot 27 Current Condition:	Individual Lots Block 6 11/1/2022 Active No Active - TJL Consulting Inc. began construction on the lot prior to the inspection on 11/01/22. A portable toilet was secured on the lot prior to the inspection on 11/01/22. Due to the lot being flat, no BMPs will be recommended at this time. The portable toilet was removed prior to the inspection on 12/27/22. Minor concrete waste was observed during the 6/12/23 inspection; E&A inspector will monitor for removal.						
Block 7, Lot 6	Individual Lots	Block 7		Removed			
Current Condition:	Removed - Rick Walkup C			<u> </u>			
Block 10, Lot 1	Individual Lots	Block 10, Lot 1	11/1/2022	Active	No		
Current Condition:	Good Condition - DR Horto		around the lot prior to the		22. I		
Block 10, Lot 2 Current Condition:	Individual Lots	Block 10, Lot 2	/24/23 inspection	Removed	1		
Current Condition:	Removed - DR Harton and				<u> </u>		
	Removed - DR Horton sod			1			
Block 10, Lot 3	Individual Lots	Block 10, Lot 3	11/1/2022	Active	No No		
Block 10, Lot 3 Current Condition: Block 10, Lot 4		Block 10, Lot 3 on installed straw wattles	11/1/2022 around the lot prior to the				

Current Condition:	Good Condition - DR Hortor			spection on 11/01/2	22. DR Horton began
Pleate 40 Lat 5	construction on the lot prior	<u>'</u>	9/23. 11/1/2022	A =4:	N
Block 10, Lot 5 Current Condition:	Individual Lots Good Condition - DR Hortor	Block 10, Lot 5		Active	No 22 DR Horton began
Current Condition.	construction on the lot prior			13pcction on 11/01/2	22. DIT HORIOR began
Block 10, Lot 6	Individual Lots	Block 10, Lot 6	6/5/2023	Active	No
Current Condition:	Good Condition - DR Hortor		around the lot prior to the in	spection on 6/5/23.	DR Horton began
	construction on the lot prior	to the 6/5/23 inspection	•		
Block 10, Lot 7	Individual Lots	Block 10, Lot 7	6/5/2023	Active	No
Current Condition:	Good Condition - DR Hortor			spection on 6/5/23.	DR Horton began
	construction on the lot prior				
Block 10, Lot 8	Individual Lots	Block 10, Lot 8	6/5/2023	Active	No
Current Condition:	Good Condition - DR Horton the lot prior to the 6/12/23 in		r to the 6/5/2023 inspection.	DR Horton Installe	a straw watties around
Block 10, Lot 9	Individual Lots	Block 10, Lot 9	6/5/2023	Active	No
Current Condition:	Good Condition - DR Hortor	began excavating prio			
	the lot prior to the 6/12/23 in				
Block 10, Lot 10	Individual Lots	Block 10, Lot 10	6/5/2023	Active	No
Current Condition:	Good Condition - DR Hortor		r to the 6/5/2023 inspection.	DR Horton installe	d straw wattles around
	the lot prior to the 6/12/23 in	spection.			
Block 10, Lot 11	Individual Lots	Block 10, Lot 11	2/15/2023	Active	No
Current Condition:	Good Condition - DR Horton	installed straw wattles	around the lot prior to the in	spection on 2/15/23	B. DR Horton began
	construction on the lot prior	-			
Block 10, Lot 12	Individual Lots	Block 10, Lot 11	6/5/2023	Active	No
Current Condition:	Active - DR Horton began ex		· · · · · · · · · · · · · · · · · · ·		
Block 11, Lot 1	Individual Lots	Block 11, Lot 1	11/1/2022	Active	No
Current Condition:	Good Condition - DR Hortor			spection on 11/01/2	22. DR Horton began
	construction on the lot prior	•	13/22.		
Block 11, Lot 2	Individual Lots	Block 11, Lot 2		Removed	
Current Condition:	Removed - DR Horton sodd		spection on 4/19/23.	Domoved	
Block 12, Lot 1	Individual Lots Removed - DR Horton sodd	Block 12, Lot 1	noction on 1/10/23	Removed	
Current Condition: Block 12, Lot 2	Individual Lots	Block 12, Lot 2	Speciion on 4/19/23.	Removed	
Current Condition:	Removed - DR Horton sodd		24/23 inspection.	Tterneved	
Block 12, Lot 3	Individual Lots	Block 12. Lot 3	_	Removed	
Current Condition:	Removed - DR Horton sodd		24/23 inspection.	Ttomovou	
Block 12 Replat 3, Lot 4		Block 12 Replat 3, Lot			
•	Individual Lots	4		Removed	
Current Condition:	Removed - DR Horton sodd		spection on 12/13/22.		
Block 13 Replat 3, Lot 1	Individual Lots	Block 13 Replat 3, Lot		D	
Current Condition:	Removed - DR Horton sodd	od the let prior to the in	nootion on 12/12/22	Removed	
Current Condition: Block 13 Replat 3, Lot 2		Block 13 Replat 3, Lot	Specifori on 12/13/22.		
block to Replat 3, Lot 2	Individual Lots	2		Removed	
Current Condition:	Removed - DR Horton sodd		spection on 11/30/22.		
Block 13 Replat 3, Lot 3	Individual Lots	Block 13 Replat 3, Lot			
		3		Removed	
Current Condition:	Removed - DR Horton sodd				
STR	Street cleaning	Off-Site	In Place	Active	No
Current Condition:	Good Condition - The street	s near CE 2 were clean	at time of inspection on 7/8	/19. The streets we	re clean at the time of
OWEDD O:	the inspection on 10/05/20.	0.5.4	10/0/0010		
SWPPP Sign	Signs Good Condition - Inspector i	2 Entrances	10/9/2018	Active	No DDD sign will be
Current Condition:	installed at the County Rd U				
	inspection on 9/19/19. The E				
	reinstalled the SWPPP sign				
	Intersection Improvements p				
	inspector reinstalled the SW				
		-			
Certification Statement:	I certify, under penalty of law	v, that this document an	d all attachments were prep	ared under my dire	ction or supervision in
	accordance with a system de				
	submitted. Based on my inq				
	for gathering the information			•	· ·
	complete. I am aware that the		alties for submitting false inf	ormation including t	ne possibility of fines
	and imprisonment for knowi	ng violations.			
	JL E		G	Et Sie	
Inspector Signature:	-J~ v		Reviewed By:		