E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Josh Ellington		E&A - P2018.109.002			Stage	
Project Name:	<u>Gallery 23 East</u> CSW-201702253 (Mass Grading)				1	
		3/23	/2024			
Project Location:	County Road	County Road U and Lincoln Highway- Fremont, NE (Dodge County)				
	Gallery 23 East					
Grading:	98%					
Sanitary Sewer:	99%	.				
Storm Sewer:	99%	.				
Paving:	99%					
Seeding:	35%					
Utilities:	99%					
Overall Development:	60%)				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
Sunday:	0.00"				Wee	
Monday:	0.00"	3/18/2024	Sunny 26	10:55 AM		
Tuesday:	0.00"		1			
Wednesday:	0.01"					
Thursday:	0.00"					
Friday:	0.06"					
Saturday:	0.00"					
Complaints:	None					
Construction Sequencing:						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site and excavation for sanitary lift station installation on the west side of the lake (8/26/2019). Fine grading throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Grading has begun on Gallery 23 East project in Phases I, II, and III (8/2017). Major cessation of grading has occurred on Gallery 23 East project and minor grading will occur on Gallery 23 East (8/30/2018). Grading for water installation on NW perimeter and along Rd 25 (10/23/2018). Grading has temporarily ceased (1/10/2019). Grading in the NE corner of site for sanitary installation (4/5/2019). Grading for roads (6/4/2019). Grading for utilities, storm, and roads throughout project (6/17/2019). Excavation along southwest portion ROW for gas installation (6/18/2019). Excavation in the southeast portion of the site for utilities (6/18/2019). Excavation throughout the site for gas installation (6/24/2019). Excavation for storm sewer (7/16/2019) Trenching for utility installation throughout the site in preparation for paving (9/09/2019). Excavation in the northeast corner of the site for culvert installation (9/19/2019). Trenching/excavation in the southeast portion of the site for utility installation (10/22/2019). Trenching throughout site for utility installation (11/18/2019). Minor trenching/excavation west of HWY 275 for communications/data installation (1/27/2020).

Lift Station and Sanitary Force Main grading/excavation began (7/23/2018). Minor grading to be completed at a later date.

Water improvements grading/excavation has begun (10/9/2018). Grading has temporarily ceased (1/10/2019). Grading occurred in between HWY 30 and Menards to still water main between last inspection (2/7/2019) and current inspection (2/20/2019), but grading had ceased at time of inspection. Grading along HWY 275 (4/5/2019). Grading for water main project has ceased (4/19/2019)

Highway 30 intersection improvements have begun for culvert installation (10/02/2019).

Grading for Highway 30 intersection improvements has begun (7/27/2020). Fine grading occurred along the Highway 30 intersection improvements west of County Road Blvd U (8/31/2020). Stockpiling on Block 1 Lot 9 (4/20/2021). Disturbance along Eastgate Road entrance (8/26/2021). Landscaping along Eastgate Road entrance (10/11/2021).

Grading for lot construction active (6/2020).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (8/30/2018). Seeding and matting in ditch for sanitary lift main (9/19/2018). Seeding around banks of E side of lake (11/6/2018). Seeding for Highway 30 Intersection Improvements (10/18/2020). Reseeding along the Highway 30 Improvements (3/15/2021).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? No Create Corrective Action? No - See BMPs section Create Corrective Action? No - See BMPs section S.) Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A Comments: Comments: Comments: The site was active during the last inspection for home construction.

Based on the amount of lot construction active in the development as of the 4/26/23 inspection, Gallery 23 East will be inspected at the Stage 1 frequency. E&A inspector will monitor and adjust inspection frequency as necessary.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1.) See BMP section for required maintenance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	(Gallery 23 Eas	st		
CE 1	Construction Entrance	County Road Blvd U		Removed	
Current Condition:	Removed - Thompson Cor 9/9/19.				
CE 2	Construction Entrance	County Road 25/Highway 30		Removed	
Current Condition:	Removed - Pruss was rem	oving the construction en	trance during inspection on	6/18/19 in preparat	tion for paving.
CE 3	Construction Entrance	NE Corner - Hwy 30 & Christine Drive		Removed	
Current Condition:			l as a part of the Highway 3 nd recommend reinstallatior		
CIP 1	Curb Inlet protection	Sammy Road		Removed	
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the inspection on 1/	17/23.	
CIP 2	Curb Inlet protection	Sammy Road		Removed	
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the 11/6/23 inspecti	on.	
CIP 3	Curb Inlet protection	East 18th Avenue	2/12/2024	Active	No
Current Condition:	Good Condition - DR Horto error. DR Horton repaired t		ection prior to the 11/6/23 in the 3/4/24 inspection.	spection. This BMP	was removed in
CIP 4	Curb Inlet protection	Kara Way		Removed	
Current Condition:	Removed - DR Horton rem	oved the inlet protection	prior to the 10/16/23 inspec	tion.	
CIP 5	Curb Inlet protection	East 18th Avenue	F/01/0000	A 11	
	Good Condition - DR Horton installed inlet protection south of Lot 13 Block 6 prior to the inspection on 5/31/23. DR Horton cleaned out the curb inlet prior to the 11/27/23 inspection. DR Horton cleaned around the curb inlet prior to the 12/29/23 inspection.			Active	No
Current Condition:	Horton cleaned out the cur	n installed inlet protectio		ior to the inspection	on 5/31/23. DR
Current Condition:	Horton cleaned out the cur	n installed inlet protectio	n south of Lot 13 Block 6 pr	ior to the inspection	on 5/31/23. DR
	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection	n installed inlet protectio b inlet prior to the 11/27/2 Taylor Lane	n south of Lot 13 Block 6 pr 23 inspection. DR Horton cl	ior to the inspection eaned around the co Active	on 5/31/23. DR urb inlet prior to the No
CIP 6	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection Good Condition - DR Horto	n installed inlet protectio b inlet prior to the 11/27/2 Taylor Lane	n south of Lot 13 Block 6 pr 23 inspection. DR Horton clo 6/19/2023	ior to the inspection eaned around the co Active	on 5/31/23. DR urb inlet prior to the No
CIP 6 Current Condition:	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection	n installed inlet protectio b inlet prior to the 11/27/2 Taylor Lane n installed inlet protectio Taylor Lane n removed the inlet prote	n south of Lot 13 Block 6 pr 23 inspection. DR Horton cl 6/19/2023 n northeast of the concrete	ior to the inspection eaned around the contract Active washout pit prior to Active	o on 5/31/23. DR urb inlet prior to the No the inspection on No
CIP 6 Current Condition: CIP 7	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto	n installed inlet protectio b inlet prior to the 11/27/2 Taylor Lane n installed inlet protectio Taylor Lane n removed the inlet prote	n south of Lot 13 Block 6 pr 23 inspection. DR Horton cl 6/19/2023 n northeast of the concrete 6/19/2023	ior to the inspection eaned around the contract Active washout pit prior to Active	o on 5/31/23. DR urb inlet prior to the No the inspection on No
CIP 6 Current Condition: CIP 7 Current Condition:	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto protection prior to the 10/30	n installed inlet protection b inlet prior to the 11/27/2 Taylor Lane n installed inlet protectio Taylor Lane n removed the inlet protectio. J/23 inspection. Central portion of site	n south of Lot 13 Block 6 pr 23 inspection. DR Horton cl 6/19/2023 n northeast of the concrete 6/19/2023 ection prior to the 10/16/23 i 8/30/2018	ior to the inspection eaned around the contractive washout pit prior to Active nspection. DR Horte	n on 5/31/23. DR urb inlet prior to the No the inspection on No on reinstalled the in
CIP 6 Current Condition: CIP 7 Current Condition: CP #1	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto protection prior to the 10/30 Culvert protection	n installed inlet protection b inlet prior to the 11/27/2 Taylor Lane n installed inlet protectio Taylor Lane n removed the inlet protectio. J/23 inspection. Central portion of site	n south of Lot 13 Block 6 pr 23 inspection. DR Horton cl 6/19/2023 n northeast of the concrete 6/19/2023 ection prior to the 10/16/23 i 8/30/2018	ior to the inspection eaned around the contractive washout pit prior to Active nspection. DR Horte	n on 5/31/23. DR urb inlet prior to the No the inspection on No on reinstalled the in
CIP 6 Current Condition: CIP 7 Current Condition: CP #1 Current Condition:	Horton cleaned out the cur 12/29/23 inspection. Curb Inlet protection Good Condition - DR Horto 6/19/23. Curb Inlet protection Good Condition - DR Horto protection prior to the 10/30 Culvert protection Pending - Culvert protectio	n installed inlet protectio b inlet prior to the 11/27/2 Taylor Lane n installed inlet protectio Taylor Lane n removed the inlet prote 0/23 inspection. Central portion of site n will be installed at a late Southeast corner	n south of Lot 13 Block 6 pr 23 inspection. DR Horton cl 6/19/2023 n northeast of the concrete 6/19/2023 ection prior to the 10/16/23 i 8/30/2018 er date. 8/30/2018	ior to the inspection eaned around the contractive washout pit prior to Active nspection. DR Horto Pending	n on 5/31/23. DR urb inlet prior to the No the inspection on No on reinstalled the ir No

	Fair Condition - DR Horton installed a concrete washout prior to the inspection on 9/06/22. DR Horton removed the concrete washout and installed a new washout with a berm and plastic liner prior to the inspection on 3/13/23. DR Horton cleaned out the concrete washout prior to the inspection on 4/10/23. DR Horton cleaned out the concrete washout prior to the 6/19/23 inspection. DR Horton removed the concrete washout and the surrounding area prior to the 10/16/23 inspection. DR Horton relocated the concrete washout to Block 7 Lot 1 prior to the 11/20/23 inspection. DR Horton removed the concrete waste outs in Blocks 7, 8, and 9 prior to the 11/27/23 inspection.					
	Any concrete waste outside of the pit should be removed.					
	DR Horton was informed to 3/12/24	complete by 2/19/24. No	ot done as of last inspectio	n. DR Horton was rem	inded on 2/20/24,	
DW #1	Ditch Wattle Checks	Middle Central	8/30/2018	Pending	No	
Current Condition:	Pending - Ditch wattle chec	ks will be installed when	grading has ended.	· · · ·		
DW #2	Ditch Wattle Checks	Southwest corner	8/30/2018	Pending	No	
Current Condition:	Pending - Ditch wattle chec	ks will be installed when	grading has ended.			
DW #3	Ditch Wattle Checks	Southeast corner	8/30/2018	Active	No	
Current Condition:	Good Condition - Wattles c		the southeast side of the s			
DD #1	Diversion Ditch	NW Corner of Lake		Removed		
Current Condition:	Removed - The diversion d		regrading/paving in the ar	<u> </u>	on 12/30/19.	
DD #2	Diversion Ditch	W side of Lake		Removed		
Current Condition:	Removed - Thompson Con		version ditch prior to inspe			
DD #3	Diversion Ditch	SW corner of lake		Removed		
Current Condition:	Removed - Thompson Con		version ditch prior to inspe	1		
DD #4	Diversion Ditch	S Side of lake		Removed		
Current Condition:	Removed - Thompson Con		version ditch prior to inspe			
DD #5	Diversion Ditch	E side of lake		Removed		
Current Condition:	Removed - Thompson Con		version ditch prior to inspe			
DD #6	Diversion Ditch	NE corner of lake		Removed	40/00/40	
Current Condition:	Removed - The diversion d	ltch was removed during	regrading/paving in the ar	ea prior to inspection	on 12/30/19.	
DD #7	Diversion Ditch	N side of lake		Removed		
Current Condition:	Removed - The diversion d	itch was removed during	regrading/paving in the ar	rea prior to inspection	on 12/30/19.	
EB #2	Erosion Blanket	Northeast corner	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m	natting and seeding will b	be installed when grading h	nas ended.		
		Around Lake (Outlot				
EB #3	Erosion Blanket	B)	8/30/2018	Pending	No	
Current Condition:	Pending - Erosion control m		pe installed when grading h	nas ended.		
IP 1	Inlet Protection	Area Inlet in SE portion of the site		Removed		
Current Condition:	Removed - The area east o needed at this time.	f the area inlet naturally	stabilized prior to the 8/05	/20 inspection. Inlet Pr	otection no longer	
IP 2	Curb Inlet protection	W Curb inlet on Christine Dr		Removed		
IP 2 Current Condition:	Curb Inlet protection Removed - The Home Com	Christine Dr	ior to the inspection on 6/1	Removed 0/20. Inlet protection is	s no lonaer reauired	
IP 2 Current Condition:	Curb Inlet protection Removed - The Home Com	Christine Dr	ior to the inspection on 6/1		s no longer required.	
Current Condition:	Removed - The Home Com	Christine Dr pany sodded lots 1-8 pri E Curb inlet on	ior to the inspection on 6/1	0/20. Inlet protection is	s no longer required.	
Current Condition:	Removed - The Home Com Curb Inlet protection	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr		0/20. Inlet protection is		
Current Condition: IP 3 Current Condition:	Removed - The Home Com Curb Inlet protection Removed - The Home Com	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri		0/20. Inlet protection is Removed 0/20. Inlet protection is		
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots	Christine Dr npany sodded lots 1-8 pri E Curb inlet on Christine Dr npany sodded lots 1-8 pri Block 2, Lot 16		0/20. Inlet protection is		
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition:	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23.		0/20. Inlet protection is Removed 0/20. Inlet protection is Removed		
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10		0/20. Inlet protection is Removed 0/20. Inlet protection is		
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition:	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots Removed - Lot was added i	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23.		0/20. Inlet protection is Removed 0/20. Inlet protection is Removed Removed		
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots Removed - Lot was added i Individual Lots Removed - Hubbell Homes	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23. Block 3 sodded the lots prior to	ior to the inspection on 6/1	0/20. Inlet protection is Removed 0/20. Inlet protection is Removed Removed Removed Removed	s no longer required.	
IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition:	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 inst	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23. Block 3 sodded the lots prior to spection.	ior to the inspection on 6/1	0/20. Inlet protection is Removed 0/20. Inlet protection is 0/20. Inlet protection is Removed Removed Removed Removed aned the streets and removed	s no longer required	
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 ins Individual Lots	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4	ior to the inspection on 6/1	0/20. Inlet protection is Removed 0/20. Inlet protection is Removed Removed Removed Removed	s no longer required.	
IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition:	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 inst	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4	ior to the inspection on 6/1	0/20. Inlet protection is Removed 0/20. Inlet protection is 0/20. Inlet protection is Removed Removed Removed Removed aned the streets and removed	s no longer required.	
Current Condition: IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added i Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 ins Individual Lots	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4	ior to the inspection on 6/1	0/20. Inlet protection is Removed 0/20. Inlet protection is 0/20. Inlet protection is Removed Removed Removed Removed aned the streets and removed	s no longer required.	
IP 3 Current Condition: Block 2 Replat 3, Lot 16 Current Condition: Block 3 Replat 3, Lot 10 Current Condition: Block 3 Replat 2, Lots 1-7 Current Condition: Block 4 Replat 2, Lots 1-4 Current Condition:	Removed - The Home Com Curb Inlet protection Removed - The Home Com Individual Lots Removed - Lot was added in Individual Lots Removed - Hubbell Homes toilet prior to the 8/21/23 ins Individual Lots Removed - Hubbell Homes	Christine Dr pany sodded lots 1-8 pri E Curb inlet on Christine Dr pany sodded lots 1-8 pri Block 2, Lot 16 in error as of 5/10/23. Block 3, Lot 10 in error as of 5/10/23. Block 3 sodded the lots prior to spection. Block 4 sodded the lots prior to Block 4	ior to the inspection on 6/1 the 8/14/23 inspection, cle the 8/14/23 inspection.	0/20. Inlet protection is Removed 0/20. Inlet protection is 0/20. Inlet protection is Removed Removed Removed Removed Removed Removed Removed Removed Removed Removed	s no longer required.	

Current Condition:	Active - Hubbell Homes bega no BMPs will be recommend cleaned the street in front of inspection.	ed at this time. Lots 13	and 14 were sodded prior	r to the 5/24/23 inspec	tion. Hubbell Hom
Block 4 Replat 2, Lots 17-19	Individual Lots	Block 4	7/6/2023	Active	No
Current Condition:	Active - Hubbell Homes bega BMPs will be recommended pile was removed prior to the maintenance for concrete wa	at this time. Dirt pile wa 9/25/23 inspection. St	as observed in the right of treets were scraped prior to	way during the 9/18/23 o the 1/11/24 inspection	3 inspection. The c
Block 4 Replat 2, Lots 20-22	Individual Lots	Block 4	7/31/2023	Active	Yes
Current Condition:	Active - Hubbell Homes bega BMPs will be recommended the portable toilets to these I The portable toilets should b Hubbell Homes was informe 9/11/23, 10/9/23, 11/6/23, 12	at this time. Streets we ots prior to the 2/26/24 e secured. d to complete by 7/24/2	ere scraped prior to the 1/1 inspection. 23. Not done as of last insp	1/24 inspection. Hubb	ell Homes relocat
Block 4 Replat 2, Lots 23-25	Individual Lots	Block 4	11/6/2023	Active	Yes
Current Condition:	Active Hild/Idda Lots Block 4 Hild/Idda Lots Active Active Hest Active - Hubbell Homes graded the lots prior to the 11/6/23. Due to the grade of the lots, no BMPs will be recommended at this time. Streets were scraped prior to the 1/11/24 inspection. Concrete waste should be removed from the lot. Hubbell Homes was informed to complete by 10/16/23. Not done as of last inspection. Hubbell Homes was remind 11/6/23, 12/4/23, 1/5/24, 2/13/24, 3/12/24 Streets were scraped prior to the street waste should be removed from the lot.				
Block 5 Replat 2, Lots 1-6	Individual Lots	Block 5	8/28/2023	Active	No
Block 5 Replat 2, Lots 7-9	lots. Streets were scraped pr under Blk 4 Replat 2 Lots 20 Individual Lots Removed - Hubbell Homes s	-22. Block 5		Removed	bilets will be found
Block 5 Replat 2, Lots 10-13	Individual Lots	Block 5		Removed	20
Current Condition: Block 6, Lot 23	Removed - Hubbell Homes s		aned the streets prior to th		.3.
Current Condition:	Individual Lots Removed - Hubbell Homes s	Block 6	he 6/5/23 inspection	Removed	
Block 6, Lot 26	Individual Lots	Block 6	L	Removed	
Current Condition:	Removed - Hubbell Homes s				
Block 6, Lot 27	Individual Lots Removed - TJL Consulting I	Block 6	to the inerpetion on 0/11/	Removed	
Current Condition:	-	-	-	20.	
Block 7, Lot 13	Individual Lots	Block 7	3/11/2024	Active	Yes
Current Condition:	Fair Condition - DR Horton in The portable toilet should be DR Horton was informed to o	secured.		tion.	No
Block 7, Lot 14 Current Condition:	Active - DR Horton began f			Active	No monitor for BME
Current Condition:	installation.		to the or forza inspection	, LOA Inspector Will	monitor for BMP
Block 7, Lot 15	Individual Lots	Block 7	3/18/2024	Active	No
Current Condition:	Active - DR Horton began f	oundation work prior	to the 3/18/24 inspectior	n; E&A inspector will	monitor for BMP
Block 7, Lot 16	Individual Lots	Block 7	12/18/2023	Active	No
Current Condition:	Good Condition - DR Horton on Block 6 Lot 10 prior to the scraped the streets prior to the maintenance is found under	began foundation worl 2 12/18/23 inspection. E he inspection on 2/5/24	k prior to the 12/18/23 insp DR Horton installed straw v	pection. DR Horton sec wattles along the perim	cured a portable to neter of the site ar
Block 7, Lot 17	Individual Lots	Block 7	12/18/2023	Active	No
, ··					

Current Condition:	Good Condition - DR Hort along the perimeter of the		k prior to the 12/18/23 insp on 2/5/24.	pection. DR Horton in	stalled straw wattles
Block 7, Lot 18	Individual Lots	Block 7	12/18/2023	Active	No
Current Condition:	Good Condition - DR Hort the back of the lot prior to		k prior to the 12/18/23 insp	bection. DR Horton in	stalled straw wattles
Block 7, Lot 19	Individual Lots	Block 7	12/18/2023	Active	No
Current Condition:	Good Condition - DR Hort	on began foundation wor			stalled straw wattles
	the back of the lot prior to				
Block 7, Lot 20	Individual Lots	Block 7	11/13/2023	Active	No
Current Condition:	Good Condition - DR Hort				
	the back of the lot prior to to the east prior to the 3/4/		DR Horton fine-graded the	e lot and relocated the	e straw wattles farthe
Block 7, Lot 21	Individual Lots	Block 7	11/6/2023	Active	No
Current Condition:	Good Condition - DR Hort wattles at the back of the I inspection. DR Horton clea	lot prior to the 11/6/23 ins		foundation work price	or to the 11/13/23
Block 7, Lot 22	Individual Lots	Block 7	10/23/2023	Active	No
Current Condition:	Good Condition - DR Hort at the back of the lot prior the 11/27/23 inspection. D 3/4/24 inspection.	to the 10/30/23 inspection	n. DR Horton reinstalled st	raw wattles at the ba	ck of the lot prior to
Block 7, Lot 23	Individual Lots	Block 7	7/6/2023	Active	No
Current Condition:	Good Condition - DR Hort straw wattles along the ba reinstalled straw wattles al the back of the lot prior to to the east prior to the 3/4/	ick of the lot and began co long the back of the lot pr the 11/27/23 inspection. I	onstruction on the lot prior rior to the 10/30/23 inspect	to the 10/23/23 inspe tion. DR Horton reins	ection. DR Horton talled straw wattles a
Block 7, Lot 24	Individual Lots	Block 7	7/6/2023	Active	No
	construction on the lot pric to the 10/30/23 inspection piles were observed in the inspection. DR Horton fine inspection.	DR Horton reinstalled st ROW during the 12/29/2	traw wattles at the back of 23 inspection. DR Horton re	the lot prior to the 11 emoved the dirt pile p	/27/23 inspection. Di prior to the 1/11/24
Block 7, Lot 25	Individual Lots	Block 7	7/6/2023	Active	No
Current Condition:			nd the lot prior to the inspe		
	excavating the lot prior to t 11/27/23 inspection. As of grade along the south. DR were observed in the ROV DR Horton fine-graded the	f 12/4/23, straw wattles alo R Horton removed the deb N during the 1/5/24 inspe- e lot and relocated the stra	ong the south side of the lo pris from around the lot prio ction. DR Horton removed aw wattles farther to the ea	ot are no longer nece or to the 12/29/23 ins the dirt pile prior to t ast prior to the 3/4/24	essary due to the flat pection. Dirt piles he 1/11/24 inspection inspection.
Block 8, Lot 1	Individual Lots	Block 8	8/7/2023	Active	Yes
Current Condition:	Fair Condition - DR Hortor container prior to the inspe removed the straw wattles during the 1/5/24 inspection Straw wattles should be re DR Horton was informed to 3/12/24	ection on 8/14/23. DR Ho debris from the ROW pri on. DR Horton removed th einstalled along the north	rton installed straw wattles ior to the 11/6/23 inspectio he dirt pile prior to the 1/11 side of the lot or the lot sh	prior to the 9/11/23 n. Dirt piles were ob: /24 inspection. ould be stabilized.	nspection. DR Hortc served in the ROW
Block 9, Lot 1	Individual Lots	Block 9		Removed	
Current Condition:	Removed - DR Horton soc	Ided the lot prior to the 12	2/18/23 inspection.	•	,
Block 10, Lot 1	Individual Lots	Block 10, Lot 1		Removed	
Current Condition:	Removed - DR Horton soc		1/20/23 inspection.		
Block 10, Lot 2	Individual Lots	Block 10, Lot 2		Removed	
Block 10, Lot 2 Current Condition:	Individual Lots Removed - DR Horton soc		24/23 inspection.	Removed	
			/24/23 inspection. 11/1/2022	Active	No

Current Condition:	Good Condition - DR Horton installed straw wattles around the lot prior to the inspection on 11/01/22 construction on the lot prior to the inspection on 4/19/23. DR Horton removed the straw wattles at the to the 12/11/23 inspection.	
Block 10, Lot 5	Individual Lots Block 10, Lot 5 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 7/06/23.	
Block 10, Lot 6	Individual Lots Block 10, Lot 6 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 11/6/23.	
Block 10, Lot 7	Individual Lots Block 10, Lot 7 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 12/18/23 inspection.	
Block 10, Lot 8	Individual Lots Block 10, Lot 8 6/5/2023 Active	No
Current Condition:	Good Condition - DR Horton began excavating prior to the 6/5/2023 inspection. DR Horton installed the lot prior to the 6/12/23 inspection.	
Block 10, Lot 9	Individual Lots Block 10, Lot 9 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection.	
Block 10, Lot 10	Individual Lots Block 10, Lot 10 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 10/16/23 inspection.	
Block 10, Lot 11	Individual Lots Block 10, Lot 11 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 8/14/23 inspection.	
Block 10, Lot 12	Individual Lots Block 10, Lot 12 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 12/18/23 inspection.	
Block 11, Lot 1	Individual Lots Block 11, Lot 1 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 11/20/23 inspection.	
Block 11, Lot 2	Individual Lots Block 11, Lot 2 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 4/19/23.	
Block 12, Lot 1	Individual Lots Block 12, Lot 1 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the inspection on 4/19/23.	
Block 12, Lot 2	Individual Lots Block 12, Lot 2 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/24/23 inspection.	
Block 12, Lot 3	Individual Lots Block 12, Lot 3 Removed	
Current Condition:	Removed - DR Horton sodded the lot prior to the 5/24/23 inspection.	
STR	Street cleaning Off-Site In Place Active	Yes
Current Condition:	Fair Condition - DR Horton cleaned the streets prior to the 2/19/24 inspection. Streets along all active lots should be cleaned. DR Horton and Hubbell Homes were informed to complete by 2/06/24. Not done as of last inspection Hubbell Homes were reminded on 2/13/24, 3/12/24	n. DR Horton and
		Ne
SWPPP Sign	Signs Gallery East Drive 10/9/2018 Active	No
Current Condition:	Good Condition - Inspector installed 1 of 2 SWPPP signs during inspection on 10/9/18. Other SWPPF installed at the County Rd U Blvd entrance at a later date. The E&A inspector reinstalled the SWPPF inspection on 9/19/19. The E&A inspector reinstalled the SWPPP sign during the 2/24/20 inspection reinstalled the SWPPP sign prior to the inspection on 3/31/20. The SWPPP sign was removed durin Intersection Improvements prior to the inspection on 8/17/20. E&A inspector reinstalled the SWPPP inspection on 8/31/20.	P sign during The E&A inspector ng the Highway 30
WSX	Waste Storage On Site 11/6/2023 Active	Yes
Current Condition:	 Fair Condition - Hubbell Homes installed several waste storage containers on their lots prior to the 1 Hubbell Homes emptied the waste storage containers prior to the 11/20/23 inspection. Hubbell Hom waste storage containers prior to the 12/11/23 inspection. DR Horton installed waste storage contain 1/11/24 inspection. Hubbell Homes emptied the waste storage containers prior to the 1/29/24 inspection. Hubbell Homes emptied the waste storage containers prior to the 1/29/24 inspection. Empty waste storage containers and remove any debris from lots. DR Horton was informed to complete by 2/26/24. Not done as of last inspection. DR Horton was removed and the storage containers of last inspection. 	nes emptied the ners prior to the ction. DR Horton
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direct accordance with a system designed to assure that qualified personnel properly gathered and evalua submitted. Based on my inquiry of the person or persons who manage the system or those persons for gathering the information, the information submitted is, to the best of my knowledge and belief, tr complete. I am aware that there are significant penalties for submitting false information including th and imprisonment for knowing violations.	ated the information directly responsible rue, accurate, and

Inspector Signature:	Reviewed By: