E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E&A - P2020.100.002

				Stage
	1			
	51526			
Golden				
100%				
100%				
100%				
100%				
70%				
100%				
50%				
	100% 100% 100% 100% 70% 100%	IA - <u>Golden Hills Drive & Old</u> 100% 100% 100% 100% 100% 100%	100% 100% 100% 100% 70% 100%	IA - 38142 - 37869 7/2/2022 Golden Hills Drive & Old Mormon Bridge Road (Crescent, Iowa) 100% 100% 100% 100% 100% 100% 100%

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday	0.00"				
Monday	0.00"				
Tuesday	0.00"	6/28/2022	Sunny 88/61	2:00 PM	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.29"				
Saturday	0.00"				

Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days'

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast guarter of the site (5/17/22).

What temporary or permanent stabilization measures listed in this section are being implemented

Existing vegetation (3/17/22). Slope along SW corner of the site seeded / matted in fall 2021 (3/17/22). Area west of Lot 33 and Lot 61 seeded / matted (3/29/22). North side of Silver Lane and east side of Copper Mountain Drive seeded / matted (3/29/22). South side of Silver Lane and west side of Copper Mountain Drive seeded / matted (4/5/22). Rear of Lots 58 - 60 partially seeded / matted (4/5/22). Disturbed area behind Lots 38 - 40 seeded / matted (4/5/22). Lots 34-40 and 59-61 sodded (4/12/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes Create Corrective Action? N/A Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion Create Corrective Action? No, see Findings Section Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Yes Create Corrective Action? N/A Are construction entrances and adjacent streets being maintained adequately? Create Corrective Action? lo, see BMP Section

Is dust associated with the construction activity adequately controlled on the site? Yes

Create Corrective Action?

Comments:

Comments:

1.) Site was active during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

2) E&A began inspecting the site on 3/17/22 after being contracted for SWPPP services by Neal Drickey. 3.) All disturbed areas, located north of active lots, that are not scheduled for imminent work should be temporarily stabilized. Neal Drickey was informed to complete by 3/24/22. Not done as of last inspection. Neal Drickey seeded/matted the ROW on the east side of Copper Mountain Drive prior to the 3/29/22 inspection. Neal Drickey seeded/matted the ROW on the west side of Copper Mountain Drive prior to the 4/5/22 inspection. E&A inspector will continue to monitor. Neal Drickey was reminded on 4/21/22, 5/24/22, 6/24/22

4.) The slope in the rear of lots 55 - 58 should be stabilized. Neal Drickey was informed to complete by 4/26/22. Not done as of last inspection. Neal Drickey was reminded on 5/24/22, 6/24/22

					1		
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	X3		Removed			
Current Condition:	Removed - Neal Drickey paved the entrance prior to the 3/17/22 inspection.						
CE 02	Construction Entrance	D6		Removed			
Current Condition:	Removed - Neal Drickey paved the entrance prior to the 3/17/22 inspection.						
CE A	Construction Entrance	BB7	4/1/2021	Active	Yes		
Current Condition:	Poor Condition - 5% effective - Neal Drickey installed the entrance prior to the 3/17/22 inspection. A 6" layer of 2" diameter rock should be added to the entrance, or the entrance should be stabilized and closed off to prevent a from accessing the site from this location. Neal Drickey was informed to complete by 3/24/22. Not done as of last inspection. Neal Drickey was reminded on 4/21/22, 5/2						
DS 1 - 6	6/24/22 Diversion	See SWPPP	4/1/2021	Pending	Yes		
Current Condition:	Pending - Due to progress of lot-level construction, installation DS 1, DS 2, and DS 3 is not recommended as of 3/24/22. Existing perimeter silt fence is adequately containing sediment around CE 1, so installation of DS 5 and DS 6 is not recommended as of 3/24/22. E&A inspector will continue to monitor. Diversion 4 should be installed. Neal Drickey was informed to complete by 3/31/22. Not done as of last inspection. Neal Drickey was reminded on 5/24/22, 6/24/22						
DS A - O	Diversion	See SWPPP	4/1/2021	Active	Yes		
	 so installation will not be recommended. Installation of DS C, DC E - H and DS O is not recommended as of 3/17/22 due to progress o lot-level construction and existing grade of the site. E&A inspector will continue to monitor. 1.) Diversions B, I, J, K, L, and M should be re-defined to funnel runoff into the sediment traps. 2.) Diversions D and N should be installed. 1.) Neal Drickey was informed to complete by 3/31/22. Not done as of last inspection. Neal Drickey was reminded on 5/24/22, 6/24/22 2.) Neal Drickey was informed to complete by 3/31/22. Not done as of last inspection. Neal Drickey was reminded on 5/24/22, 6/24/22 						
ECM 1	Erosion Control Matting	SW Corner	4/1/2021	Active	No		
Current Condition:	Good Condition - Neal Drickey installed the erosion control matting along the slope prior to the 3/17/22 inspection. Neal Drickey extended the matting north and east to cover lots 38-40 and 35-40 prior to the 4/5/22 inspection.						
ECM 2	Erosion Control Matting	East Side of Copper Mountain Drive	3/29/2022	Active	No		
Current Condition:	Good Condition - Neal Drickey installed the erosion control matting along the ROW of Copper Mountain Drive and Silver Lane prior to the 3/29/22 inspection. Some of the matting was removed for utility work prior to the 4/26/22 inspection. E&A inspector will continue to monitor.						
ECM 3	Erosion Control Matting	West Side of Copper Mountain Drive	4/5/2022	Active	No		
Current Condition:	Good Condition - Neal Drick the 4/5/22 inspection.	Good Condition - Neal Drickey installed the erosion control matting along the ROW of Copper Mountain Drive and Silver Lane prior to					
ECM 3	Erosion Control Matting	Western Perimeter	4/5/2022	Active	No		
Current Condition:	Good Condition - Neal Drick	ey installed the erosion of	control matting along several se	ections of SF 3 prior to the	4/5/22 inspection.		
FT 01	Fuel Tank	On Site	3/17/2022	Active	No		
Current Condition:	Good Condition - Neal Drickey installed a fuel tank north of SB A prior to the 3/17/22 inspection. Neal Drickey built a berm around the fuel tank prior to the 4/5/22 inspection.						
IP 1 - 10	Inlet Protection	On Site	3/24/2022	Pending	Yes		

Current Condition:	Pending -				
	, i i i i i i i i i i i i i i i i i i i				
	Inlet protection should be ins	stalled on the ten grate ir	llets on Silver Lane.		
	Neal Drickey was informed to 6/24/22	o complete by 3/24/22. N	lot done as of last inspection. N	Neal Drickey was reminded	l on 4/21/22, 5/24/22,
Lot 33	Individual Lot	Lot 33		Removed	
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/5/22 inspection.		
Lot 34	Individual Lot	Lot 34		Removed	
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/12/22 inspection.		
Lot 35	Individual Lot	Lot 35		Removed	
Current Condition:	Removed - Neal Drickey soc	· · · · · · · · · · · · · · · · · · ·	/12/22 inspection.		r
Lot 36 Current Condition:	Individual Lot Removed - Neal Drickey soo	Lot 36	/12/22 increation	Removed	
Lot 37	Individual Lot	Lot 37	T TZ/ZZ Inspection.	Demoved	
Current Condition:	Removed - Neal Drickey soc		1/12/22 inspection	Removed	
Lot 38	Individual Lot	Lot 38		Removed	
Current Condition:	Removed - Neal Drickey soc		/12/22 inspection.	Romovou	
Lot 39	Individual Lot	Lot 39		Removed	
Current Condition:	Removed - Neal Drickey soc		/12/22 inspection.	Romovou	
Lot 40	Individual Lot	Lot 40		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.		
Lot 54	Individual Lot	Lot 54	3/17/2022	Active	No
Current Condition:			lot prior to the 3/17/22 inspect		
			o the 4/5/22 inspection. Neal D	rickey installed wattles alo	ng the south side of the
Lot 55	driveway prior to the 4/26/22		3/17/2022	A atives	Na
Current Condition:	Individual Lot	Lot 55	lot prior to the 3/17/2022 inspect	Active	No silt fence on the northeast
Current Contaition.			rickey installed wattles along the		
			g sediment as of the 5/24/22 in		
	recommended. E&A inspect	or will continue to monito	or.		
Lot 56	Individual Lot	Lot 56	3/17/2022	Active	No
Current Condition:	Good Condition - Neal Drick	ey began building on the	lot prior to the 3/17/22 inspect	ion. Neal Drickey installed	wattles along the south
	side of the driveway prior to	the 4/26/22 inspection. E	xisting wattles are adequately	containing segiment as of i	ine 5/24/22 inspection so I
Lot 57			inspector will continue to monit		No
Lot 57 Current Condition:	additional wattles are no long Individual Lot	ger recommended. E&A Lot 57	inspector will continue to monit	tor. Active	No
	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E	inspector will continue to moni 3/17/2022 tot prior to the 3/17/22 inspect existing wattles are adequately	tor. <u>Active</u> ion. Neal Drickey installed containing sediment as of	No wattles along the south
Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect	tor. Active ion. Neal Drickey installed containing sediment as of i	No wattles along the south
Current Condition: Lot 58	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni	tor. <u>Active</u> ion. Neal Drickey installed containing sediment as of	No wattles along the south
Current Condition: Lot 58 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni	tor. Active ion. Neal Drickey installed containing sediment as of tor. Removed	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni /17/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of i	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni /17/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of tor. Removed Removed	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni /17/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of tor. Removed	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni /17/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of tor. Removed Removed Removed	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 61	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect inspector will continue to moni /17/22 inspection. /12/22 inspection. /12/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of tor. Removed Removed	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 61 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection.	tor. Active Active containing sediment as of tor. Removed Removed Removed Removed	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 61 Current Condition: MS 01	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect inspector will continue to moni /17/22 inspection. /12/22 inspection. /12/22 inspection. /12/22 inspection. /12/22 inspection.	tor. Active Active on. Neal Drickey installed containing sediment as of tor. Removed Removed Removed Removed Removed Active	No wattles along the south
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 61 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect existing wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection.	tor. Active Active on. Neal Drickey installed containing sediment as of tor. Removed Removed Removed Removed Removed Active	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: Lot 61 Current Condition: MS 01 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 No Site ey added a designated r	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni /17/22 inspection. /12/22 inspection. /12/22 inspection. /12/22 inspection. /12/22 inspection.	tor. Active Active Active Active Active Active Removed Removed Removed Active a/17/22 inspection. Active Active Active Active Active Active	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni /1/17/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection.	tor. Active Active Active Active Active Active Removed Removed Removed Active a/17/22 inspection. Active Active Active Active Active Active	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //12/22 inspection. //12/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of 1 tor. Removed Removed Removed Removed Active a 3/17/22 inspection. Active /17/22 inspection. The E&.	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect	inspector will continue to moni 3/17/2022 lot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni /1/17/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection. /1/2/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of 1 tor. Removed Removed Removed Removed Active a 3/17/22 inspection. Active /17/22 inspection. The E&.	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //12/22 inspection. //12/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of 1 tor. Removed Removed Removed Removed Active a 3/17/22 inspection. Active /17/22 inspection. The E&.	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Dricke Sediment Basin Poor Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installed properly elevated dewatering	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 No Site ey added a designated r No f CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, is pholes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //12/22 inspection. //12/22 inspection.	tor. Active ion. Neal Drickey installed containing sediment as of it tor. Removed Removed Removed Removed Active e 3/17/22 inspection. Active /17/22 inspection. The E&. es, anti-vortex device, eme	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d The basin should be installe properly elevated dewatering Neal Drickey was informed t 6/24/22	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r Nof CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, i g holes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni /1/17/22 inspection. /1/17/22 inspection. /1/1/22 inspection. /1/1/22 inspection. /1/1/22 inspection. /1/1/22 inspection. /1/1/22 inspection. /1/1/2021 naterial storage area prior to the /1/1/2021 ne sediment basin prior to the 3 ion. ////////////////////////////////////	tor. Active ion. Neal Drickey installed containing sediment as of it tor. Removed Removed Removed Active e 3/17/22 inspection. Active /17/22 inspection. Active /17/22 inspection. /17/122 inspection. /17/122 inspection. /17/122 inspection. /17/122 inspection. /17/122 inspection. /17/122 inspection.	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d The basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect of complete by 3/24/22. No See SWPPP	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 insp	tor. Active Active containing sediment as of tor. Removed Removed Removed Removed Removed Active a3/17/22 inspection. Active s, anti-vortex device, eme	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Sediment Basin Poor Condition - Neal Drickey soc Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installer properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect of per the SWPPP plan, if g holes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2 inspection. //1	tor. Active Active Active Active Active Removed Removed Removed Removed Active Active Active Active Active Active Active Active Active Active Active Ac	No wattles along the south the 5/24/22 inspection, so No <u>Yes</u> A inspector painted the rgency spillway, and I on 4/21/22, 5/24/22, <u>Yes</u> lation of SF 2 is no longer
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Sediment Basin Poor Condition - Neal Drickey Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser drive Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey, recommended as of 4/5/22.	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect of per the SWPPP plan, i g holes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2 inspecti	tor. Active Active Active Active Active Removed Removed Removed Removed Active Active Active Active Active Active Active Active Active Active Active Ac	No wattles along the south the 5/24/22 inspection, so No <u>Yes</u> A inspector painted the rgency spillway, and I on 4/21/22, 5/24/22, <u>Yes</u> lation of SF 2 is no longer
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Sediment Basin Poor Condition - Neal Drickey soc Sediment Basin Poor Condition - Neal Drickey soc Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect of per the SWPPP plan, i g holes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2 inspecti	tor. Active Active Active Active Active Removed Removed Removed Removed Active Active Active Active Active Active Active Active Active Active Active Ac	No wattles along the south the 5/24/22 inspection, so wattles along the south the 5/24/22 inspection, so wattles wattles along the south wattles along
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d The basin should be installer properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, i g holes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2	tor. Active ion. Neal Drickey installed containing sediment as of 1 tor. Removed Removed Removed Removed Active 9/17/22 inspection. Active 9/17/22 inspection. Active es, anti-vortex device, eme Neal Drickey was reminded Active tabilization of Lot 33, instal prior to the 4/5/22 inspection	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drick Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser d The basin should be installer properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, i g holes.	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2/2 inspection. //12/2 i	tor. Active ion. Neal Drickey installed containing sediment as of 1 tor. Removed Removed Removed Removed Active 9/17/22 inspection. Active 9/17/22 inspection. Active es, anti-vortex device, eme Neal Drickey was reminded Active tabilization of Lot 33, instal prior to the 4/5/22 inspection	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Material Storage Good Condition - Neal Drickey soc Sediment Basin Poor Condition - Neal Drickey Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installee properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is 1.) SF 3 should be cleaned of	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 Mon Site ey added a designated r N of CE 1 Neal Drickey installed the uring the 4/19/22 inspect of per the SWPPP plan, if g holes. o complete by 3/24/22. N See SWPPP y installed SF 3 prior to the Neal Drickey cleaned ou no longer recommende out where full in the rear- out where full in the rear-	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2 ins	tor. Active ion. Neal Drickey installed containing sediment as of it tor. Removed Removed Removed Removed Removed Active 9/17/22 inspection. Active /17/22 inspection. Active value Active Value Active Active Active Active Active Value Active Active Value Active Active Active Active Active Total Active Active Active Active Active Active Active Active Active	No wattles along the south the 5/24/22 inspection, so
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey Sediment Basin Poor Condition - Neal Drickey Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installer properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is 1.) SF 3 should be cleaned of 1.) Neal Drickey was informed	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, if g holes. o complete by 3/24/22. N See SWPPP (installed SF 3 prior to th Neal Drickey cleaned ou no longer recommende out where full in the rear out where full in the rear	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 insp	tor. Active Active Active Active Active Active Removed Removed Removed Removed Active alignment Active Act	No wattles along the south the 5/24/22 inspection, so No Yes A inspector painted the rgency spillway, and I on 4/21/22, 5/24/22, Yes lation of SF 2 is no longer on. Due to stabilization of ded on 5/24/22, 6/24/22
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey Sediment Basin Poor Condition - Neal Drickey Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installer properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is 1.) SF 3 should be cleaned of 1.) Neal Drickey was informed	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, if g holes. o complete by 3/24/22. N See SWPPP (installed SF 3 prior to th Neal Drickey cleaned ou no longer recommende out where full in the rear out where full in the rear	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 inspection. //12/2/2 inspection. //12/2 ins	tor. Active Active Active Active Active Active Removed Removed Removed Removed Active alignment Active Act	No wattles along the south the 5/24/22 inspection, so No Yes A inspector painted the rgency spillway, and I on 4/21/22, 5/24/22, Yes lation of SF 2 is no longer on. Due to stabilization of ded on 5/24/22, 6/24/22
Current Condition: Lot 58 Current Condition: Lot 59 Current Condition: Lot 60 Current Condition: MS 01 Current Condition: SB 1 Current Condition:	additional wattles are no long Individual Lot Good Condition - Neal Drick side of the driveway prior to additional wattles are no long Individual Lot Removed - Neal Drickey soc Individual Lot Removed - Neal Drickey soc Material Storage Good Condition - Neal Drickey Sediment Basin Poor Condition - Neal Drickey Sediment Basin Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installer properly elevated dewatering Neal Drickey was informed to 6/24/22 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is 1.) SF 3 should be cleaned of 1.) Neal Drickey was informed	ger recommended. E&A Lot 57 ey began building on the the 4/26/22 inspection. E ger recommended. E&A Lot 58 Ided the lot prior to the 5 Lot 59 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 60 Ided the lot prior to the 4 Lot 61 Ided the lot prior to the 4 On Site ey added a designated r N of CE 1 Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, if g holes. o complete by 3/24/22. N See SWPPP (installed SF 3 prior to th Neal Drickey cleaned ou no longer recommende out where full in the rear out where full in the rear	inspector will continue to moni 3/17/2022 Iot prior to the 3/17/22 inspect ixisting wattles are adequately inspector will continue to moni //17/22 inspection. //12/22 insp	tor. Active Active Active Active Active Active Removed Removed Removed Removed Active alignment Active Act	No wattles along the south the 5/24/22 inspection, so

Current Condition:	Good Condition - Neal Drick	ev installed SF A-D and	SF L. M. O. P prior to the 3/1	7/22 inspection. Neal Drick	ev removed SF C and D		
	Good Condition - Neal Drickey installed SF A-D and SF L, M, O, P prior to the 3/17/22 inspection. Neal Drickey removed SF C and D during lot-level fine grading prior to the 3/29/22 inspection. Reinstallation will not be recommended. Due to seeding / matting behind lot						
	61, reinstallation of SF N is no longer recommended as of the 3/29/22 inspection. E&A inspector will continue to monitor. Neal Drickey						
	1 7	0	spection. SF I is adequately		,		
			I continue to monitor. Due to				
			ill continue to monitor. Minor				
	inspection. E&A inspector w			damage was observed to e			
ST A - K			4/1/2021	Activo	No		
Current Condition:	Sediment Trap	See SWPPP	D - J prior to the 3/17/22 ins	Active			
Current Condition:							
			ecommended as of 3/24/22. E				
	installed ST A and ST C prior to the 3/29/22 inspection. Neal Drickey reinstalled ST G, H, I, and J prior to the 5/17/22 inspection.						
	-				1		
STR	Streets	On Site	4/1/2021	Active	No		
Current Condition:			Mountain Drive during the 3/2				
	prior to the 4/5/22 inspection. Neal Drickey cleaned the streets prior to the 5/17/22 inspection. No major signs of trackout were observed						
	during the most recent inspe	ection.					
SWPPP Sign	SWPPP Sign	On Site	3/31/2022	Active	No		
Current Condition:	Good Condition - The E&A i	nspector installed the sig	n north of the Silver Lane ent	trance during the 4/26/22 in	spection.		
		East Side of Copper		1	İ		
W 1	Straw Wattles	Mountain Drive	3/29/2022	Active	No		
Current Condition:	Good Condition - Neal Drick		long the ROW of Copper Mo	untain Drive and Silver Lan	e prior to the 3/29/22		
	Good Condition - Neal Drickey installed the wattles along the ROW of Copper Mountain Drive and Silver Lane prior to the 3/29/22 inspection.						
WA-H	Straw Wattles	See SWPPP	4/5/2022	Active	No		
Current Condition:	Good Condition - Neal Drick	ev installed erosion cont	rol matting in place of W A. in	stalled W B. and installed	silt fence in place of W C		
	Good Condition - Neal Drickey installed erosion control matting in place of W A, installed W B, and installed silt fence in place of W C prior to the 4/5/22 inspection. Due to progress of lot-level construction, installation of W D - H is not recommended. E&A inspector will						
	continue to monitor.						
WO 1	Concrete Washout	On site	3/24/2022	Active	No		
Current Condition:							
Current Condition.	Good Condition - Neal Drickey cleaned up the concrete waste and installed a designated concrete washout east of SB 1 prior to the 4/5/22 inspection.						
					-		
WS 01	Waste Storage Area	On site	4/1/2021	Pending	No		
Current Condition:	Pending - Dumpsters were in place on individual lots during the 3/17/22 inspection. General site waste storage will be recommended as						
	necessary. E&A inspector w	ill continue to monitor.					
WT A - H	Wattles	See SWPPP		Removed			
Current Condition:	Removed - Maintenance for	wattles will be assigned	to individual lots as 3/17/22.	•	•		
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance						
			onnel properly gathered and e				
	inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the						
	information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant						
	penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
		, mormation molading an	e possibility of filles and impr	isonment for knowing viola	10113.		
	Na /				\geq 1 1		
spector Signature	VN'T			Reviewed By:	to be		
spector Signature:	/	1		Revieweu by.			