E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

3:52 PM -12:00 AM

12:00 AM - 6:52 PM

		E&A - F	2020.100.002			
Inspector: Nathan Hack					Stage	
Project Name:	Golden Hills Phase II IA - 38142 - 37869				1	
For Week Ending:	4/15/2023				51526	
Project Location:	Golden Hills Drive & Old Mormon Bridge Road (Crescent, Iowa)					
Grading:	100%	Ι		T		
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	70%					
Utilities:	100%					
Overall Development:	70%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times Week 1	
Sunday	0.00"				Week I	
Monday	0.11"					
Tuesday	0.00"	4/11/2023	Mostly Cloudy 82/50	3:10 PM		
Wednesday	0.00"					

Complaints:

Thursday

Friday Saturday

0.00"

1.07'

0.08"

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23)

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (3/17/22). Slope along SW corner of the site seeded / matted in fall 2021 (3/17/22). Area west of Lot 33 and Lot 61 seeded / matted (3/29/22). North side of Silver Lane and east side of Copper Mountain Drive seeded / matted (3/29/22). South side of Silver Lane and west side of Copper Mountain Drive seeded / matted (4/5/22). Rear of Lots 58 - 60 partially seeded / matted (4/5/22). Disturbed area behind Lots 38 - 40 seeded / matted (4/5/22). Lots 34-40 and 59-61 sodded (4/12/22). Rear of Lots 55 - 57 seeded / matted (7/26/22). Rear of lot 42 seeded / matted (11/8/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

reate Corrective Action?

See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, see BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action? No, see BMP Section Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A

Comments:

1.) Site was active during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- Some maintenance is required in the BMP section.
 E&A began inspecting the site on 3/17/22 after being contracted for SWPPP services by Neal Drickey.

Unique Name	1					
Unique Name	1					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	X3		Removed		
Current Condition:	Removed - Neal Drickey paved the entrance prior to the 3/17/22 inspection.					
CE 02	Construction Entrance	D6		Removed		
Current Condition:	Removed - Neal Drickey pav	red the entrance prior to	the 3/17/22 inspection.			
CE A	Construction Entrance	BB7	4/1/2021	Active	Yes	
Current Condition:	Poor Condition -5% effective - Neal Drickey installed the entrance prior to the 3/17/22 inspection. CE A is no longer effective; a negligible amount of rock remains present (2/14/23). CE A continues to experience use despite its ineffectiveness (2/28/23). CE A was compacted without the addition of rock to the entrance prior to the 3/21/23 inspection. A 6" layer of 2" diameter rock should be added to the entrance, or the entrance should be stabilized and closed off to prevent anyone from accessing the site from this location.					
	6/24/22, 7/20/22, 8/3/22, 8/10		Not done as of last inspection. N	neal Drickey was reminded	1 on 4/21/22, 5/24/22,	
DS 1 - 6	Diversion	See SWPPP	[Removed	l	
Current Condition:			diversions 1-6 will no longer be		1/01/2022 inspection.	
DS A - O	Diversion	See SWPPP	4/1/2021	Active	Yes	
	Fair Condition - Neal Drickey installed DS B and DS I - M prior to the 3/17/22 inspection. DS A is not indicated on the SWPPP map, so installation will not be recommended. Installation of DS C, DC E - H and DS O is not recommended as of 3/17/22 due to progress of lot-level construction and existing grade of the site. E&A inspector will continue to monitor. Neal Drickey removed DS B, I, J, K, L and M prior to the 8/9/22 inspection. Due to grading and lot-level construction in the area, reinstallation will not be recommended. Neal Drickey installed Diversion N prior to the inspection on 11/8/22. Diversion D should be installed. Neal Drickey was informed to complete by 3/31/22. Not done as of last inspection. Neal Drickey was reminded on 5/24/22, 6/24/22,					
ECM 1	7/20/22, 11/30/22, 2/03/23					
		CM/ C	4/4/0004	A -4:	l N-	
Current Condition:		and east to cover lots 38-	4/1/2021 control matting along the slope 40 and 35-40 prior to the 4/5/2		No tion. Neal Drickey	
Current Condition: ECM 2	Good Condition - Neal Drick extended the matting north a Erosion Control Matting	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022	prior to the 3/17/22 inspect 2 inspection. Active	tion. Neal Drickey	
Current Condition:	Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick	ey installed the erosion of ind east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem	control matting along the slope 40 and 35-40 prior to the 4/5/2:	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive	tion. Neal Drickey No and Silver Lane prior to	
Current Condition: ECM 2	Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Some monitor. Erosion Control Matting	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem West Side of Copper Mountain Drive	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A in	No and Silver Lane prior to nspector will continue to	
Current Condition: ECM 2 Current Condition: ECM 3 Current Condition:	Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection.	ey installed the erosion of the east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was rem	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW oved for utility work prior to the 4/5/2022 control matting along the ROW	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A in Active of Copper Mountain Drive	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to	
Current Condition: ECM 2 Current Condition: ECM 3 Current Condition:	Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the work was the work of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of western Perimeter	ontrol matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW oved for utility work prior to the 4/5/2022 control matting along the ROW	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A i Active of Copper Mountain Drive Active	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to	
Current Condition: ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition:	Good Condition - Neal Drick- extended the matting north at Erosion Control Matting Good Condition - Neal Drick- the 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drick- the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick-	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the wastern Perimeter ey installed the erosion of the matting was rem	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 2/5/2022 control matting along several se	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A i Active of Copper Mountain Drive Active active active	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No A/5/22 inspection.	
Current Condition: ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition:	Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Fuel Tank	ey installed the erosion of the east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the ey installed a fuel tank not expected the ey installed a fuel tank not expected to the erosion of the ey installed a fuel tank not expected the erosion of the erosio	ontrol matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW oved for utility work prior to the 4/5/2022 control matting along the ROW	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A i Active of Copper Mountain Drive Active of Copper Mountain Drive Active ections of SF 3 prior to the Active	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection.	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10	Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Fuel Tank Good Condition - Neal Drick fuel tank prior to the 4/5/22 in Inlet Protection	ey installed the erosion of the east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the ey installed a fuel tank not expected the ey installed a fuel tank not expected to the erosion of the ey installed a fuel tank not expected the erosion of the erosio	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW oved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 3/17/2022 control matting along several second of the slope	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A i Active of Copper Mountain Drive Active of Copper Mountain Drive Active ections of SF 3 prior to the Active	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection.	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10 Current Condition:	Good Condition - Neal Dricklextended the matting north at Erosion Control Matting Good Condition - Neal Dricklethe 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Dricklethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Dricklethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Dricklethe A/5/22 inspection - Neal Dricklethe - Neal Dricklethe A/5/22 inspection - Neal Dricklethe - Neal Dric	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was rem Western Perimeter ey installed the erosion of the matting was remediately installed the erosion of the complete ey installed a fuel tank nonspection. On Site ey installed on the ten grate in the complete by 3/24/22. No 6/22, 11/9/22, 11/30/22	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW oved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 4/5/2022 control matting along several se 3/17/2022 orth of SB A prior to the 3/17/22 control silver Lane. Solution of last inspection. Note that the slope is the slope in the slope is the slope in the slope is the slope in the slope in the slope is the slope in the	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A is Active of Copper Mountain Drive Active Active Active Active 2 citions of SF 3 prior to the Active 2 inspection. Neal Drickey Pending	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection. No built a berm around the	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10	Good Condition - Neal Dricklextended the matting north at Erosion Control Matting Good Condition - Neal Drickles (19/22) inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drickles (19/22) inspection. Erosion Control Matting Good Condition - Neal Drickles (19/22) inspection. Fuel Tank Good Condition - Neal Drickles (19/22) in Inlet Protection Pending - Inlet protection should be inspected in the protection should be inspected in Inlet Protection (19/24/22, 7/20/22, 8/3/22, 8/1) Individual Lot	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was remediately installed the erosion of the matting was remediately installed the erosion of the ey installed the erosion of the ey installed a fuel tank non-spection. On Site Stalled on the ten grate in the process of the matting was remediately installed a fuel tank non-spection. On Site Stalled on the ten grate in the process of the	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 3/17/2022 control matting along several se 3/17/2022 orth of SB A prior to the 3/17/22 control matting along several se 3/24/2022 control matting along several se 3/17/2022 control matting along the ROW 4/5/2022 control matting along several se 3/17/2022 control of SB A prior to the 3/17/22 control of SB	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A is Active of Copper Mountain Drive Active Active Active Active 2 citions of SF 3 prior to the Active 2 inspection. Neal Drickey Pending	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection. No built a berm around the	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10 Current Condition:	Good Condition - Neal Dricklextended the matting north at Erosion Control Matting Good Condition - Neal Dricklethe 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Dricklethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Dricklethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Dricklethe A/5/22 inspection - Neal Dricklethe - Neal Dricklethe A/5/22 inspection - Neal Dricklethe - Neal Dric	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was remediately installed the erosion of the matting was remediately installed the erosion of the ey installed the erosion of the ey installed a fuel tank non-spection. On Site Stalled on the ten grate in the process of the matting was remediately installed a fuel tank non-spection. On Site Stalled on the ten grate in the process of the	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 3/17/2022 control matting along several se 3/17/2022 orth of SB A prior to the 3/17/22 control matting along several se 3/24/2022 control matting along several se 3/17/2022 control matting along the ROW 4/5/2022 control matting along several se 3/17/2022 control of SB A prior to the 3/17/22 control of SB	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 2 4/26/22 inspection. E&A i Active of Copper Mountain Drive Active of Copper Mountain Drive Active ections of SF 3 prior to the Active 2 inspection. Neal Drickey Pending	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection. No built a berm around the	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10 Current Condition:	Good Condition - Neal Drickextended the matting north at Erosion Control Matting Good Condition - Neal Drickethe 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drickethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drickethe 4/5/22 inspection. Fuel Tank Good Condition - Neal Drickethe tank prior to the 4/5/22 in Inlet Protection Pending - Inlet protection should be insected by the section of the tank prior to the tank	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was remediately installed the erosion of the ey installed the erosion of the ey installed the erosion of the ey installed a fuel tank nonspection. On Site ey installed on the ten grate in the erosion of the ey installed a fuel tank nonspection. On Site extalled on the ten grate in the erosion of the erosion o	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along several se 3/17/2022 orth of SB A prior to the 3/17/22 control matting along several se 3/24/2022 control matting along several se 3/17/2022 control matting along the ROW 4/5/2022 control matting along the	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 2 4/26/22 inspection. E&A i Active of Copper Mountain Drive Active of Copper Mountain Drive Active ections of SF 3 prior to the Active 2 inspection. Neal Drickey Pending	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection. No built a berm around the	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10 Current Condition: Lot 33 Current Condition:	Good Condition - Neal Drickextended the matting north at Erosion Control Matting Good Condition - Neal Drickethe 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drickethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drickethe 4/5/22 inspection. Fuel Tank Good Condition - Neal Drickethe A/5/22 in Inlet Protection Pending - Inlet protection should be insupported to the 4/5/22 in Inlet Protection Pending - Inlet Protection Should be insupported to the 4/24/22, 7/20/22, 8/3/22, 8/11 Individual Lot Removed - Neal Drickey social Removed - Neal Drickey	ey installed the erosion of and east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was remediately installed the erosion of the ey installed the erosion of the ey installed the erosion of the ey installed a fuel tank nonspection. On Site ey installed on the ten grate in the erosion of the ey installed a fuel tank nonspection. On Site extalled on the ten grate in the erosion of the erosion o	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along several se 3/17/2022 orth of SB A prior to the 3/17/22 control matting along several se 3/24/2022 control matting along several se 3/17/2022 control matting along the ROW 4/5/2022 control matting along the	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A in Active of Copper Mountain Drive Active ections of SF 3 prior to the Active 2 inspection. Neal Drickey Pending Neal Drickey was reminded Removed	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection. No built a berm around the	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: FT 01 Current Condition: IP 1 - 10 Current Condition: Lot 33 Current Condition: Lot 33 Current Condition: Lot 34	Good Condition - Neal Drickextended the matting north at Erosion Control Matting Good Condition - Neal Drickethe 3/29/22 inspection. Some monitor. Erosion Control Matting Good Condition - Neal Drickethe 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drickethe 4/5/22 inspection. Fuel Tank Good Condition - Neal Drickethe tank prior to the 4/5/22 in Inlet Protection Pending - Inlet protection should be insected by the section of the tank prior to the tank	ey installed the erosion of conditional east to cover lots 38- East Side of Copper Mountain Drive ey installed the erosion of e of the matting was rem West Side of Copper Mountain Drive ey installed the erosion of the matting was remediately installed the erosion of the ey installed the erosion of the ey installed a fuel tank nonspection. On Site extended on the ten grate in the erosion of the ey installed on the ten grate in the erosion of the extended on the ten grate in the erosion of the extended erosion. On Site extended on the ten grate in the erosion of the extended erosion of the erosion	control matting along the slope 40 and 35-40 prior to the 4/5/2: 3/29/2022 control matting along the ROW loved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along several se 3/17/2022 orth of SB A prior to the 3/17/22 control matting along several se 3/24/2022 control matting along several se 3/17/2022 control matting along the ROW 4/5/2022 control matting along the	prior to the 3/17/22 inspect 2 inspection. Active of Copper Mountain Drive 4/26/22 inspection. E&A in Active of Copper Mountain Drive Active ections of SF 3 prior to the Active 2 inspection. Neal Drickey Pending Neal Drickey was reminded Removed	No and Silver Lane prior to nspector will continue to No and Silver Lane prior to No and Silver Lane prior to No 4/5/22 inspection. No built a berm around the	

Lot 36	Individual Lot	Lot 36		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.		
Lot 37	Individual Lot	Lot 37		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.		•
Lot 38	Individual Lot	Lot 38	Ī	Removed	I
Current Condition:	Removed - Neal Drickey soc		I /12/22 inspection	removed	L
			r 12/22 inspection.		
Lot 39	Individual Lot	Lot 39		Removed	
Current Condition:	Removed - Neal Drickey soc	lded the lot prior to the 4	/12/22 inspection.		
Lot 40	Individual Lot	Lot 40		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.	-	•
Lot 41	Individual Lot	Lot 41	8/2/2022	Active	No
Current Condition:			** * *		
Carronic Containion.	Good Condition - Neal Drickey began excavating the lot prior to the 8/2/22 inspection. Neal Drickey repaired the erosion rills prior to the inspection on 11/29/22. Sidewalk paving was completed in front of the lot prior to the 3/14/23 inspection. Neal Drickey installed wattles on the front and downhill side of the lot prior to the 3/21/23 inspection. E&A inspector will monitor for lot stabilization.				
Lot 42	Individual Lot	Lot 42	8/2/2022	Active	No
Current Condition:	Good Condition - Neal Drick	ev began excavating the	lot prior to the 8/2/22 inspection	n. Sidewalk paving was co	ompleted in front of the lot
	prior to the 3/14/23 inspection E&A inspector will monitor for	on. Neal Drickey installed or lot stabilization.	wattles on the front and downl	nill side of the lot prior to the	ne 3/21/23 inspection.
Lot 43	Individual Lot	Lot 43	8/2/2022	Active	No
Current Condition:	prior to the 3/14/23 inspection E&A inspector will monitor for	n. Neal Drickey installed or lot stabilization.	lot prior to the 8/2/22 inspection wattles on the front and downline.	nill side of the lot prior to th	
Lot 54	Individual Lot	Lot 54		Removed	
Current Condition:	Removed - Neal Drickey soc		inspection on 10/11/22.		
Lot 55	Individual Lot	Lot 55		Removed	
Current Condition:	Removed - Neal Drickey soc		inspection on 10/11/22.		
Lot 56	Individual Lot	Lot 56		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lots prior to the	inspection on 10/11/22.		
Lot 57	Individual Lot	Lot 57		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lots prior to the	inspection on 10/11/22.		
Lot 58	Individual Lot	Lot 58		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 5	/17/22 inspection.		
Lot 59	Individual Lot	Lot 59		Removed	I
Current Condition:	Removed - Neal Drickey soo		/12/22 inspection		•
	·	· · · · · · · · · · · · · · · · · · ·			1
Lot 60	Individual Lot	Lot 60	140/00:	Removed	
Current Condition:	Removed - Neal Drickey soc	ided the lot prior to the 4	/12/22 inspection.		
Lot 61	Individual Lot	Lot 61		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.	-	•
MS 01	Material Storage	On Site	4/1/2021	Active	No
Current Condition:			naterial storage area prior to th		
	used as construction materia	al staging areas. No BMF	es are being recommended for		
PB X	Portable Bathroom	On Site	7/12/2022	Active	Yes
Current Condition:	The portable toilet should be Neal Drickey was informed to 11/9/22, 11/30/22, 2/03/23	secured. o complete by 7/19/22. N	on Lot 49 prior to the 7/12/22 in lot done as of last inspection.	Neal Drickey was reminded	
SB 1	Sediment Basin	N of CE 1	4/1/2021	Active	Yes
Current Condition:		· ·	e sediment basin prior to the 3	/17/22 inspection. The E&	A inspector painted the
	cleanout mark on the riser during the 4/19/22 inspection. The basin should be installed per the SWPPP plan, including a berm around all sides, anti-vortex device, emergency spillway, and properly elevated dewatering holes. Neal Drickey was informed to complete by 3/24/22. Not done as of last inspection. Neal Drickey was reminded on 4/21/22, 5/24/22, 6/24/22, 7/20/22, 8/3/22, 8/16/22, 11/30/22, 2/03/23				
SF 1 - 3	Silt Fence	See SWPPP	4/1/2021	Active	Yes
Current Condition:	Fair Condition - Neal Drickey installed SF 3 prior to the 4/20/21 inspection. Due to stabilization of Lot 33, installation of SF 2 is no longer recommended as of 4/5/22. Neal Drickey cleaned out, repaired, and extended SF 3 prior to the 4/5/22 inspection. Due to stabilization of Lot 61, installation of SF 1 is no longer recommended as of 4/12/22. Silt fence should be cleaned out and removed. The area should then be stabilized. Neal Drickey was informed to complete by 10/18/22. Not done as of last inspection. Neal Drickey was reminded on 11/9/22, 11/30/22,				
	Silt fence should be cleaned	out and removed. The a	rea should then be stabilized.	Neal Drickey was reminde	ed on 11/9/22, 11/30/22.
	Silt fence should be cleaned	out and removed. The a	rea should then be stabilized.	Neal Drickey was reminde	ed on 11/9/22, 11/30/22,
SF A - Q	Silt fence should be cleaned Neal Drickey was informed to	out and removed. The a	rea should then be stabilized.	Neal Drickey was reminde	ed on 11/9/22, 11/30/22, Yes

Current Condition:	Fair Condition - Neal Drickey installed SF A-D and SF L, M, O, P prior to the 3/17/22 inspection. Neal Drickey removed SF C and D during lot-level fine grading prior to the 3/29/22 inspection. Reinstallation will not be recommended. Due to seeding / matting behind lot 61, reinstallation of SF N is no longer recommended as of the 3/29/22 inspection. E&A inspector will continue to monitor. Neal Drickey removed SF B and installed SF I prior to the 4/5/22 inspection. SF I is adequately containing sediment, so installation of SF H is no longer recommended as of 4/15/22. E&A inspector will continue to monitor. Due to sodding of upgradient lots, installation of SF E is no longer recommended as of 4/15/22. E&A inspector will continue to monitor. Minor damage was observed to SF L during the 5/3/22 inspection. E&A inspector will continue to monitor. Neal Drickey removed SF L, M, and O prior to the 8/2/22 inspection. Vegetation has covered 70% of exposed dirt near SF L, M, O prior to the inspection on 8/23/22. E&A inspector will continue to monitor. Silt fence should be installed around the ground disturbance in the northeast quadrant of the site. Neal Drickey was informed to complete by 7/26/22. Not done as of last inspection. Neal Drickey was reminded on 8/3/22, 8/16/22, 11/9/22, 11/30/22, 2/03/23				
ST A - K	Sediment Trap	See SWPPP	4/1/2021	Active	No
Current Condition:	storage capacity of ST D, ins installed ST A and ST C prio Drickey cleaned out ST C pri	stallation of ST K is not real real to the 3/29/22 inspection to the 8/2/22 inspection grading and lot-level co	OD - J prior to the 3/17/22 inspector of 3/24/22. E& on. Neal Drickey reinstalled ST on. Neal Drickey cleaned out Sonstruction in the area, reinstallate inspection on 11/8/22.	A inspector will continue t G, H, I, and J prior to the S T A and removed ST B, S	o monitor. Neal Drickey 5/17/22 inspection. Neal Γ G, H, I, and J prior to
STR	Streets	On Site	4/1/2021	Active	No
Current Condition:	prior to the 4/5/22 inspection. during the most recent inspe- observed during the most rec	Neal Drickey cleaned to ction. Neal Drickey clean cent inspection. Neal Dri	Mountain Drive during the 3/17, the streets prior to the 5/17/22 in and the streets prior to the 8/23, ckey cleaned the streets prior to the 8/23.	nspection. No major signs /22 inspection. No major s o the 2/21/23 inspection.	of trackout were observed igns of trackout were
SWPPP Sign	SWPPP Sign	On Site	3/31/2022	Active	No
Current Condition:	Good Condition - The E&A inspector installed the sign north of the Silver Lane entrance during the 4/26/22 inspection. E&A inspector updated the SWPPP sign with the correct permit information during the 1/3/2023 inspection.				
W 1	Straw Wattles	East Side of Copper Mountain Drive	3/29/2022	Active	No
Current Condition:	Good Condition - Neal Dricks inspection.	ey installed the wattles a	long the ROW of Copper Moun	itain Drive and Silver Lane	prior to the 3/29/22
W A - H	Straw Wattles	See SWPPP	4/5/2022	Active	No
Current Condition:			rol matting in place of W A, inst evel construction, installation of		
WO 1	Concrete Washout	On site	3/24/2022	Active	Yes
Current Condition:	4/5/22 inspection. Some min- Due to hole in the concrete w Neal Drickey was informed to 2/03/23	or concrete waste was overshout, the washout sho complete by 10/18/22.	Not done as of last inspection.	s 41-43 during the 3/28/23 Neal Drickey was reminde	inspection. ed on 11/9/22, 11/30/22,
WS 01	Waste Storage Area	On site	4/1/2021	Active	No
Current Condition:			ual lots during the 3/17/22 insprinue to monitor. Dumpsters wer		
WT A - H	Wattles	See SWPPP		Removed	
Current Condition: Certification Statement	with a system designed to as inquiry of the person or perso information submitted is, to the	w, that this document and sure that qualified perso ons who manage the sys he best of my knowledge	to individual lots as 3/17/22. d all attachments were prepared onnel properly gathered and evaluate on those persons directly real and belief, true, accurate, and e possibility of fines and imprison.	aluated the information sub esponsible for gathering the complete. I am aware tha	omitted. Based on my ne information, the nt there are significant
Inspector Signature:	note m			Reviewed By:	to be