E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

	<u> </u>	E&A - P	2020.100.002		
Inspector: Nathan Hack		Stage			
Project Name:		1			
For Week Ending:		51526			
Project Location:	Golden				
				<u> </u>	
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	70%				
Utilities:	100%				
Overall Development:	70%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times
					Week 1
Sunday	0.00"				
Monday	0.00"				
Tuesday	0.00"	4/18/2023	Mostly Cloudy 71/42	2:05 PM	
Wednesday	0.00"				
Thursday	1.74"				4 AM - 7 AM
Friday	0.00"				
Saturday	0.00"				

Complaints:

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23)

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23)

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (3/17/22). Slope along SW corner of the site seeded / matted in fall 2021 (3/17/22). Area west of Lot 33 and Lot 61 seeded / matted (3/29/22). North side of Silver Lane and east side of Copper Mountain Drive seeded / matted (3/29/22). South side of Silver Lane and west side of Copper Mountain Drive seeded / matted (4/5/22). Rear of Lots 58 - 60 partially seeded / matted (4/5/22). Disturbed area behind Lots 38 - 40 seeded / matted (4/5/22). Lots 34-40 and 59-61 sodded (4/12/22). Rear of Lots 55 - 57 seeded / matted (7/26/22). Rear of lot 42 seeded / matted (11/8/22).

Checklist Questions:

are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

reate Corrective Action?

See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, see BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action? No, see BMP Section Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A

Comments:

Comments:

1.) Site was active during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- Some maintenance is required in the BMP section.
 B&A began inspecting the site on 3/17/22 after being contracted for SWPPP services by Neal Drickey.

,	the site on 3/17/22 after being		<u> </u>				
II N		1	B	04.4			
Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	X3	the 2/17/22 inequation	Removed			
Current Condition:	Removed - Neal Drickey paved the entrance prior to the 3/17/22 inspection.						
CE 02	Construction Entrance	D6	the 2/17/22 increation	Removed			
Current Condition:	Removed - Neal Drickey pay		<u> </u>				
CE A	Construction Entrance	BB7	4/1/2021	Active	Yes		
Current Condition:			the entrance prior to the 3/17/2				
			CE A continues to experience		less (2/26/23). CE A was		
	compacted without the addition of rock to the entrance prior to the 3/21/23 inspection.						
	A 6" laver of 2" diameter roc	A 6" layer of 2" diameter rock should be added to the entrance, or the entrance should be stabilized and closed off to prevent anyone					
	from accessing the site from	this location.			, ,		
			lot done as of last inspection. N	leal Drickey was reminded	d on 4/21/22, 5/24/22,		
D0.4 0	6/24/22, 7/20/22, 8/3/22, 8/1		<u>2/03/23, 4/19/23</u>	-	1		
DS 1 - 6	Diversion	See SWPPP	diversions 1.6 will be leaser be	Removed	11/01/2022 increation		
Current Condition:	Removed - Due to progress	of lot-level construction	diversions 1-6 will no longer be	recommended as of the	11/01/2022 inspection.		
DS A - O	Diversion	See SWPPP	4/1/2021	Active	Yes		
Current Condition:			I - M prior to the 3/17/22 inspec				
Carrent Condition.			OS C, DC E - H and DS O is no				
			inspector will continue to moni				
			level construction in the area, r				
	installed Diversion N prior to						
	Diversion D should be install	ed.					
			lot done as of last inspection. N	leal Drickey was reminded	d on 5/24/22, 6/24/22,		
	7/20/22, 11/30/22, 2/03/23, 4						
ECM 1	Erosion Control Matting	SW Corner	4/1/2021	Active	No No		
Current Condition:			control matting along the slope 40 and 35-40 prior to the 4/5/2		tion. Neal Drickey		
	extended the matting north a		40 and 35-40 phor to the 4/5/2.	z irispection.	1		
ECM 2	Erosion Control Matting	East Side of Copper	3/29/2022	Active	No		
Current Condition:	Good Condition Neal Drick	Mountain Drive	L control matting along the ROW	of Coppor Mountain Drive	and Silver Lane prior to		
Current Condition.			oved for utility work prior to the				
	monitor.	of the matting was ren	loved for dulity work prior to the	4/20/22 mapconon. Lart	inspector will continue to		
		West Side of Copper			1		
ECM 3	Erosion Control Matting	Mountain Drive	4/5/2022	Active	No		
Current Condition:	Good Condition - Neal Drick		control matting along the ROW	of Copper Mountain Drive	and Silver Lane prior to		
	the 4/5/22 inspection.	,	3 3 -	- 11	•		
ECM 3	Erosion Control Matting	Western Perimeter	4/5/2022	Active	No		
Current Condition:	Good Condition - Neal Drick		control matting along several se	ections of SF 3 prior to the	4/5/22 inspection.		
FT 01	Fuel Tank	On Site	3/17/2022	Active	No		
Current Condition:	Good Condition - Neal Drick		orth of SB A prior to the 3/17/22	2 inspection. Neal Drickey	built a berm around the		
	fuel tank prior to the 4/5/22 in	fuel tank prior to the 4/5/22 inspection.					
IP 1 - 10	Inlet Protection	On Site	3/24/2022	Pending	Yes		
Current Condition:	Pending -						
	Inlet protection should be ins	talled on the ten grate in	llets on Silver Lane.				
			lot done as of last inspection. N	leal Drickey was reminded	d on 4/21/22, 5/24/22,		
1 -1.00	6/24/22, 7/20/22, 8/3/22, 8/1		2/03/23, 4/19/23		1		
Lot 33	Individual Lot Lot 33 Removed						
Current Condition:	Removed - Neal Drickey sodded the lot prior to the 4/5/22 inspection.						
Lot 34	Individual Lot	Lot 34	/40/00 in a n a ati a	Removed	1		
Current Condition:	Removed - Neal Drickey sodded the lot prior to the 4/12/22 inspection.						
Lot 35	Individual Lot	Lot 35		Removed			
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.				
	-						

Lot 36	Individual Lot Removed - Neal Drickey soo	Lot 36	(10/00 increation	Removed	
Current Condition:	<u> </u>		12/22 Inspection.	D	<u> </u>
Current Condition:	Individual Lot Removed - Neal Drickey soo	Lot 37	 	Removed	
Lot 38	<u> </u>	Lot 38	12/22 mapection.	Domovad	<u> </u>
Current Condition:	Individual Lot Removed - Neal Drickey soo		/12/22 inspection	Removed	
	·		r 12/22 mapection.		I
Lot 39 Current Condition:	Individual Lot Removed - Neal Drickey soo	Lot 39	 	Removed	
Lot 40	<u> </u>		12/22 Irispection.	D	Γ
Current Condition:	Individual Lot Removed - Neal Drickey soo	Lot 40	/12/22 inspection	Removed	
	· ·	· · · · · · · · · · · · · · · · · · ·	·	Λ -4'	NI-
Lot 41 Current Condition:	Individual Lot	Lot 41	8/2/2022	Active	No No
Current Condition.	Good Condition - Neal Drickey began excavating the lot prior to the 8/2/22 inspection. Neal Drickey repaired the erosion rills prior to the inspection on 11/29/22. Sidewalk paving was completed in front of the lot prior to the 3/14/23 inspection. Neal Drickey installed wattles on the front and downhill side of the lot prior to the 3/21/23 inspection. E&A inspector will monitor for lot stabilization.				
Lot 42	Individual Lot	Lot 42	8/2/2022	Active	No
Current Condition:	Good Condition - Neal Drick	ey began excavating the	lot prior to the 8/2/22 inspectio	n. Sidewalk paving was co	mpleted in front of the lot
	E&A inspector will monitor for	or lot stabilization.	wattles on the front and downl	·	
Lot 43	Individual Lot	Lot 43	8/2/2022	Active	No
Current Condition:		n. Neal Drickey installed	lot prior to the 8/2/22 inspectio wattles on the front and downl		
Lot 54	Individual Lot	Lot 54		Removed	
Current Condition:	Removed - Neal Drickey soc		nspection on 10/11/22.		
Lot 55	Individual Lot Removed - Neal Drickey soo	Lot 55	noncetion o= 40/44/00	Removed	
Current Condition: Lot 56	Individual Lot	Lot 56	nspection on 10/11/22.	Removed	I
Current Condition:	Removed - Neal Drickey soo		nspection on 10/11/22	Removed	
Lot 57	Individual Lot	Lot 57	nispection on 10/11/22.	Removed	
Current Condition:	Removed - Neal Drickey soo		nspection on 10/11/22.		
Lot 58	Individual Lot	Lot 58		Removed	
Current Condition:	Removed - Neal Drickey soc	dded the lot prior to the 5	/17/22 inspection.		
Lot 59	Individual Lot	Lot 59		Removed	
Current Condition:	Removed - Neal Drickey soc	dded the lot prior to the 4	/12/22 inspection.		
Lot 60	Individual Lot	Lot 60		Removed	
Current Condition:	Removed - Neal Drickey soc	ded the lot prior to the 4	/12/22 inspection.		
Lot 61	Individual Lot	Lot 61		Removed	
Current Condition:	Removed - Neal Drickey soc		/12/22 inspection.	!	
MS 01	Material Storage	On Site	4/1/2021	Active	No
Current Condition:	Good Condition - Neal Drick	ey added a designated n	naterial storage area prior to the s are being recommended for	e 3/17/22 inspection. Lots	
PB X	Portable Bathroom	On Site	7/12/2022	Active	Yes
Current Condition:	Fair Condition - Neal Drickey	y placed a portable toilet	on Lot 49 prior to the 7/12/22 in	nspection.	
	11/9/22, 11/30/22, 2/03/23, 4	o complete by 7/19/22. N 1/19/23	lot done as of last inspection. N		
SB 1	Sediment Basin	N of CE 1	4/1/2021	Active	Yes
Current Condition:			e sediment basin prior to the 3	3/17/22 inspection. The E&	A inspector painted the
	cleanout mark on the riser during the 4/19/22 inspection. The basin should be installed per the SWPPP plan, including a berm around all sides, anti-vortex device, emergency spillway, and properly elevated dewatering holes. Neal Drickey was informed to complete by 3/24/22. Not done as of last inspection. Neal Drickey was reminded on 4/21/22, 5/24/22, 6/24/22, 7/20/22, 8/3/22, 8/16/22, 11/9/22, 11/30/22, 2/03/23, 4/19/23				
SF 1 - 3	Silt Fence	See SWPPP	4/1/2021	Active	Yes
Current Condition:			ne 4/20/21 inspection. Due to s		
	recommended as of 4/5/22. Neal Drickey cleaned out, repaired, and extended SF 3 prior to the 4/5/22 inspection. Due to stabilization of Lot 61, installation of SF 1 is no longer recommended as of 4/12/22.				
	Silt fence should be cleaned out and removed. The area should then be stabilized. Neal Drickey was informed to complete by 10/18/22. Not done as of last inspection. Neal Drickey was reminded on 11/9/22, 11/30/22,				
	2/03/23, 4/19/23				
SF A - Q	Silt Fence	See SWPPP	4/1/2021	Active	No
	I OIL I GIICE	I OCC CAALLI	7/ 1/2021	1 10011	140

Current Condition:	Good Condition - Neal Drickey installed SF A-D and SF L, M, O, P prior to the 3/17/22 inspection. Neal Drickey removed SF C and D during lot-level fine grading prior to the 3/29/22 inspection. Reinstallation will not be recommended. Due to seeding / matting behind lot 61, reinstallation of SF N is no longer recommended as of the 3/29/22 inspection. E&A inspector will continue to monitor. Neal Drickey removed SF B and installed SF I prior to the 4/5/22 inspection. SF I is adequately containing sediment, so installation of SF H is no longer recommended as of 4/5/22. E&A inspector will continue to monitor. Due to sodding of upgradient lots, installation of SF E is no					
	longer recommended as of 4 inspection. E&A inspector wi covered 70% of exposed dirt	1/19/22. E&A inspector will continue to monitor. Name ar SF L, M, O prior to	ill continue to monitor. Minor deal Drickey removed SF L, M, at the inspection on 8/23/22. E& of the site. E&A inspector with	amage was observed to S and O prior to the 8/2/22 ir A inspector will continue to	F L during the 5/3/22 spection. Vegetation has	
ST A - K	Sediment Trap	See SWPPP	4/1/2021	Active	No	
Current Condition:	Good Condition - Neal Drickey installed ST B and SD D - J prior to the 3/17/22 inspection. Due to progress of lot-level construction and storage capacity of ST D, installation of ST K is not recommended as of 3/24/22. E&A inspector will continue to monitor. Neal Drickey installed ST A and ST C prior to the 3/29/22 inspection. Neal Drickey reinstalled ST G, H, I, and J prior to the 5/17/22 inspection. Neal Drickey cleaned out ST C prior to the 8/2/22 inspection. Neal Drickey cleaned out ST A and removed ST B, ST G, H, I, and J prior to the 8/9/22 inspection. Due to grading and lot-level construction in the area, reinstallation will not be recommended. Neal Drickey cleaned out and reshaped ST A and ST K prior to the inspection on 11/8/22.					
STR	Streets	On Site	4/1/2021	Active	No	
Current Condition:	Good Condition - Trackout was observed on Copper Mountain Drive during the 3/17/22 inspection. Neal Drickey cleaned the streets prior to the 4/5/22 inspection. Neal Drickey cleaned the streets prior to the 5/17/22 inspection. No major signs of trackout were observed during the most recent inspection. Neal Drickey cleaned the streets prior to the 8/23/22 inspection. No major signs of trackout were observed during the most recent inspection. Neal Drickey cleaned the streets prior to the 2/21/23 inspection.					
SWPPP Sign	SWPPP Sign	On Site	3/31/2022	Active	No	
Current Condition:	Good Condition - The E&A inspector installed the sign north of the Silver Lane entrance during the 4/26/22 inspection. E&A inspector updated the SWPPP sign with the correct permit information during the 1/3/2023 inspection.					
W 1	Straw Wattles	East Side of Copper Mountain Drive	3/29/2022	Active	No	
Current Condition:	inspection.	ey installed the wattles a	long the ROW of Copper Mou	ntain Drive and Silver Lane	e prior to the 3/29/22	
W A - H	Straw Wattles	See SWPPP	4/5/2022	Active	No	
Current Condition:	Good Condition - Neal Drickey installed erosion control matting in place of W A, installed W B, and installed silt fence in place of W C prior to the 4/5/22 inspection. Due to progress of lot-level construction, installation of W D - H is not recommended. E&A inspector will continue to monitor.					
WO 1 Current Condition:	Concrete Washout	On site	3/24/2022 waste and installed a designation	Active	Yes	
	4/5/22 inspection. Some min Due to hole in the concrete v Neal Drickey was informed to 2/03/23, 4/19/23	or concrete waste was c vashout, the washout sh o complete by 10/18/22.	bserved on site near active lot ould be replaced or repaired. Not done as of last inspection.	s 41-43 during the 3/28/23 Neal Drickey was reminde	inspection. ed on 11/9/22, 11/30/22,	
WS 01	Waste Storage Area	On site	4/1/2021	Active	No	
Current Condition:	recommended as necessary inspection	. E&A inspector will cont	ual lots during the 3/17/22 inspinue to monitor. Dumpsters we	re in place on individual lo	•	
WTA-H	Wattles	See SWPPP		Removed		
Current Condition: Certification Statement	with a system designed to as inquiry of the person or perso information submitted is, to t	v, that this document and ssure that qualified perso ons who manage the sys he best of my knowledge	to individual lots as 3/17/22. d all attachments were prepare onnel properly gathered and eventem or those persons directly read and eventem or those persons directly read and belief, true, accurate, and e possibility of fines and impris	aluated the information sul responsible for gathering the d complete. I am aware tha	omitted. Based on my ne information, the nt there are significant	
nspector Signature:	not m			Reviewed By:	Et Su	