E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

		E&A - F	2020.100.002		
Inspector: Zach Roza		Stage			
Project Name:		1			
For Week Ending:		51526			
Project Location:	Golder				
One discuss	100%	I		T	
Grading:					
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	70%				
Utilities:	100%				
Overall Development:	70%				
		I .			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times
					Week
Sunday	0.20"				8:50 AM - 10:50 AM
Monday	0.44"				8:50 AM - 9:50 AM
Tuesday	0.19"				7:50 AM - 9:50 AM
Wednesday	0.00"				
Thursday	0.00"	7/20/2023	Partly Cloudy 81 / 66	9:55 AM	
Friday	0.00"				
Saturday	0.13"				4:50 AM
Complaints:					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23) Grading on the northeast corner of the site (5/11/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23) Grading on the northeast corner of the site (5/11/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (3/17/22). Slope along SW corner of the site seeded / matted in fall 2021 (3/17/22). Area west of Lot 33 and Lot 61 seeded / matted (3/29/22). North side of Silver Lane and east side of Copper Mountain Drive seeded / matted (3/29/22). South side of Silver Lane and west side of Copper Mountain Drive seeded / matted (4/5/22). Rear of Lots 58 - 60 partially seeded / matted (4/5/22). Disturbed area behind Lots 38 - 40 seeded / matted (4/5/22). Lots 34-40 and 59-61 sodded (4/12/22). Rear of Lots 55 - 57 seeded / matted (7/26/22). Rear of lot 42 seeded / matted (11/8/22). ST K removed and area seeded (5/18/23).

Checklist Questions

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, see Findings Section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

Create Corrective Action?

No, see BMP Section

Are construction entrances and adjacent streets being maintained adequately?

No No
Create Corrective Action?
No, see BMP Section
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
1.) Site was active during the last inspection.
Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):
Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	X3		Removed		
Current Condition:	Removed - Neal Drickey paved the entrance prior to the 3/17/22 inspection.					
CE 02	Construction Entrance	D6		Removed		
Current Condition:	Removed - Neal Drickey pav	red the entrance prior to	the 3/17/22 inspection.			
CE A	Construction Entrance	BB7	4/1/2021	Active	Yes	
Current Condition:	Poor Condition -5% effective	- Neal Drickey installed	the entrance prior to the 3/17/2	22 inspection. CE A is no l	onger effective; a	
	negligible amount of rock remains present (2/14/23). CE A continues to experience use despite its ineffectiveness (2/28/23). CE A was compacted without the addition of rock to the entrance prior to the 3/21/23 inspection. A 6" layer of 2" diameter rock should be added to the entrance, or the entrance should be stabilized and closed off to prevent anyone from accessing the site from this location. Neal Drickey was informed to complete by 3/24/22. Not done as of last inspection. Neal Drickey was reminded on 4/21/22, 5/24/22,					
DS 1 - 6	Diversion	See SWPPP	<mark>2/03/23, 4/19/23, 5/19/23, 6/16</mark> I	Removed	1	
Current Condition:			I diversions 1-6 will no longer be		1 11/01/2022 inspection.	
DS A - O	Diversion	See SWPPP	4/1/2021	Active	Yes	
Current Condition:	Fair Condition - Neal Drickey	installed DS B and DS	I - M prior to the 3/17/22 inspec	tion. DS A is not indicated	on the SWPPP map, so	
	installation will not be recom	mended. Installation of D	OS C, DC E - H and DS O is no	t recommended as of 3/17	7/22 due to progress of lot-	
			inspector will continue to moni			
			level construction in the area, r	einstallation will not be red	commended. Neal Drickey	
	installed Diversion N prior to	the inspection on 11/8/2	2.			
	Diversion D should be installed.					
	Neal Drickey was informed to 7/20/22, 11/30/22, 2/03/23, 4		lot done as of last inspection. N , 7/13/23.	leal Drickey was reminded	d on 5/24/22, 6/24/22,	
ECM 1	Erosion Control Matting	SW Corner	4/1/2021	Active	No	
Current Condition:			control matting along the slope		tion. Neal Drickey	
	extended the matting north a	and east to cover lots 38-	40 and 35-40 prior to the 4/5/2	2 inspection.		
ECM 2	Erosion Control Matting	East Side of Copper Mountain Drive	3/29/2022	Active	No	
Current Condition:	Good Condition - Neal Drickey installed the erosion control matting along the ROW of Copper Mountain Drive and Silver Lane prior to the 3/29/22 inspection. Some of the matting was removed for utility work prior to the 4/26/22 inspection. E&A inspector will continue to monitor.					
ECM 3	Erosion Control Matting	West Side of Copper Mountain Drive	4/5/2022	Active	No	
Current Condition:	Good Condition - Neal Drick the 4/5/22 inspection.	ey installed the erosion o	control matting along the ROW	of Copper Mountain Drive	and Silver Lane prior to	
ECM 3	Erosion Control Matting	Western Perimeter	4/5/2022	Active	No	
Current Condition:	Good Condition - Neal Drick	ey installed the erosion of	control matting along several se	ections of SF 3 prior to the	4/5/22 inspection.	
FT 01	Fuel Tank	On Site	3/17/2022	Active	No	
Current Condition:	Good Condition - Neal Drickey installed a fuel tank north of SB A prior to the 3/17/22 inspection. Neal Drickey built a berm around the fuel tank prior to the 4/5/22 inspection.					
IP 1 - 10	Inlet Protection	On Site	3/24/2022	Pending	Yes	
Current Condition:	Pending -					
	Inlet protection should be installed on the ten grate inlets on Silver Lane. Neal Drickey was informed to complete by 3/24/22. Not done as of last inspection. Neal Drickey was reminded on 4/21/22, 5/24/22, 6/24/22, 7/20/22, 8/3/22, 8/16/22, 11/9/22, 11/30/22, 2/03/23, 4/19/23, 5/19/23, 6/16/23, 7/13/23.					
Lot 33	Individual Lot	Lot 33		Removed		
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/5/22 inspection.			
Lot 34	Individual Lot	Lot 34		Removed		
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/12/22 inspection.			
Lot 35	Individual Lot	Lot 35		Removed		
Current Condition:	Removed - Neal Drickey soc		/12/22 inspection.		•	
	,		· · · · · · · · · · · · · · · · · · ·			

Lot 36	Individual Lot	Lot 36		Removed	
Current Condition:	Removed - Neal Drickey soc		/12/22 inspection.		
Lot 37	Individual Lot	Lot 37		Removed	
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/12/22 inspection.		
Lot 38	Individual Lot	Lot 38		Removed	
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/12/22 inspection.		
Lot 39	Individual Lot	Lot 39		Removed	
Current Condition:	Removed - Neal Drickey soo		/12/22 inspection	rtomorod	
Lot 40	Individual Lot	Lot 40	12,22	Removed	1
Current Condition:	Removed - Neal Drickey soc		/12/22 inspection	Removed	
	· ·	•	12/22 IIIspection.		
Lot 41	Individual Lot	Lot 41		Removed	
Current Condition: Lot 42	Removed- Neal Drickey sod		spection on 5/25/23.	Damas d	Г
	Individual Lot	Lot 42		Removed	
Current Condition: Lot 43	Removed- Neal Drickey sod Individual Lot	Lot 43	spection on 5/25/23.	Removed	I
Current Condition:	Removed- Neal Drickey sod		noction on 5/25/23	Removed	
Lot 51	Individual Lot	Lot 51	6/15/2023	Active	No
Current Condition:			the lot prior to the inspection or		
Current Condition.			9/23. Neal Drickey removed the		
	The state of the s	· · · · · · · · · · · · · · · · · · ·	&A inspector will monitor for		it of the lot due to flome
Lot 52	•				l NI-
	Individual Lot	Lot 52	6/15/2023	Active	No
Current Condition:			the lot prior to the inspection or I Drickey removed the silt fer		
					lot due to nome
			&A inspector will monitor for		
Lot 53	Individual Lot	Lot 53	6/22/2023	Active	No No
Current Condition:			or to the inspection on 6/22/23.		
			y removed the silt fence from the	ne tront of the lot due to ho	me construction prior to
	the inspection on 7/13/23. E	· ·	for reinstallation.		
Lot 54	Individual Lot	Lot 54		Removed	
Current Condition:	Removed - Neal Drickey soc		nspection on 10/11/22.		
Lot 55	Individual Lot	Lot 55		Removed	
Current Condition:	Removed - Neal Drickey soc		nspection on 10/11/22.		
Lot 56	Individual Lot	Lot 56		Removed	
Current Condition:	Removed - Neal Drickey soc		nspection on 10/11/22.		
Lot 57	Individual Lot	Lot 57		Removed	
Current Condition:	Removed - Neal Drickey soc		nspection on 10/11/22.		
Lot 58	Individual Lot	Lot 58		Removed	
Current Condition:	Removed - Neal Drickey soc	lded the lot prior to the 5	/17/22 inspection.		
Lot 59	Individual Lot	Lot 59		Removed	
Current Condition:	Removed - Neal Drickey soc	Ided the lot prior to the 4	/12/22 inspection.		
Lot 60	Individual Lot	Lot 60		Removed	
Current Condition:	Removed - Neal Drickey soo		/12/22 inspection		
	<u> </u>		12,22	Б .	Γ
Lot 61	Individual Lot	Lot 61	(40/00 : "	Removed	
Current Condition:	Removed - Neal Drickey soc	ided the lot prior to the 4	/12/22 Inspection.		
MS 01	Material Storage	On Site	4/1/2021	Active	No
Current Condition:	Good Condition - Neal Drick	ey added a designated n	naterial storage area prior to th	e 3/17/22 inspection. Lots	44 and 45 are being
	used as construction materia	al staging areas. No BMF	s are being recommended for	these lots since there is no	o active grading.
PB X	Portable Bathroom	On Site	7/12/2022	Active	Yes
Current Condition:	Fair Condition - Neal Drickey	placed a portable toilet	on Lot 49 prior to the 7/12/22 in	nspection.	
	The portable toilet should be	secured.			
	Neal Drickey was informed t	o complete by 7/19/22. N	lot done as of last inspection. <mark>N</mark>	<mark>Neal Drickey was reminded</mark>	l on 8/3/22, 8/16/22,
	11/9/22, 11/30/22, 2/03/23, 4	<mark>I/19/23, 5/19/23, 6/16/23</mark>	, 7/13/23.		
SB 1	Sediment Basin	N of CE 1	4/1/2021	Active	Yes
SB 1 Current Condition:			4/1/2021 te sediment basin prior to the 3		
		Neal Drickey installed th	e sediment basin prior to the 3		
	Poor Condition - 10% filled -	Neal Drickey installed th	e sediment basin prior to the 3		
	Poor Condition - 10% filled - cleanout mark on the riser d	Neal Drickey installed thuring the 4/19/22 inspect	e sediment basin prior to the 3	/17/22 inspection. The E&	A inspector painted the
	Poor Condition - 10% filled - cleanout mark on the riser d	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, i	e sediment basin prior to the 3 ion.	/17/22 inspection. The E&	A inspector painted the
	Poor Condition - 10% filled - cleanout mark on the riser d	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, i	e sediment basin prior to the 3 ion.	/17/22 inspection. The E&	A inspector painted the
	Poor Condition - 10% filled - cleanout mark on the riser d The basin should be installed properly elevated dewatering	Neal Drickey installed th uring the 4/19/22 inspect d per the SWPPP plan, i g holes.	e sediment basin prior to the 3 ion.	.//17/22 inspection. The E&	A inspector painted the
	Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installed properly elevated dewatering Neal Drickey was informed to	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, in holes.	e sediment basin prior to the 3 ion.	v/17/22 inspection. The E& es, anti-vortex device, eme	A inspector painted the
	Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installed properly elevated dewatering Neal Drickey was informed to	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, in holes.	e sediment basin prior to the 3 ion. ncluding a berm around all side	v/17/22 inspection. The E& es, anti-vortex device, eme	A inspector painted the
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser during the basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, in the state of the sta	e sediment basin prior to the 3 ion. ncluding a berm around all side lot done as of last inspection. No 2/03/23, 4/19/23, 5/19/23, 6/16	ves, anti-vortex device, eme ves, anti-vortex device, eme veal Drickey was reminded verification and the control of the contro	A inspector painted the organized spillway, and on 4/21/22, 5/24/22,
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence Fair Condition - Neal Drickey	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, in the state of the sta	e sediment basin prior to the 3 ion. ncluding a berm around all side lot done as of last inspection. No 2/03/23, 4/19/23, 5/19/23, 6/16 4/1/2021	Neal Drickey was reminded //23, 7/13/23. Active tabilization of Lot 33, insta	A inspector painted the ergency spillway, and d on 4/21/22, 5/24/22, Yes Elation of SF 2 is no longer
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence Fair Condition - Neal Drickey	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, in the second process of the second per the second process of the second per the second per the second process of the second per the second process of the second per the second process of the second per the second per the second process of the second per the seco	le sediment basin prior to the 3 ion. Including a berm around all side lot done as of last inspection. No 2/03/23, 4/19/23, 5/19/23, 6/16/20/21 inspection. Due to stropaired, and extended SF 3	Neal Drickey was reminded //23, 7/13/23. Active tabilization of Lot 33, insta	A inspector painted the ergency spillway, and don 4/21/22, 5/24/22, Yes Elation of SF 2 is no longer
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser di The basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22.	Neal Drickey installed thuring the 4/19/22 inspected per the SWPPP plan, in the second process of the second per the second process of the second per the second per the second process of the second per the second process of the second per the second process of the second per the second per the second process of the second per the seco	le sediment basin prior to the 3 ion. Including a berm around all side lot done as of last inspection. No 2/03/23, 4/19/23, 5/19/23, 6/16/20/21 inspection. Due to stropaired, and extended SF 3	Neal Drickey was reminded //23, 7/13/23. Active tabilization of Lot 33, insta	A inspector painted the ergency spillway, and don 4/21/22, 5/24/22, Yes Station of SF 2 is no longer
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser du The basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is	Neal Drickey installed the uring the 4/19/22 inspect of per the SWPPP plan, it is holes. In complete by 3/24/22, Neal 22, 11/30/22, See SWPPP or installed SF 3 prior to the Neal Drickey cleaned our no longer recommended.	le sediment basin prior to the 3 ion. Including a berm around all side lot done as of last inspection. No 2/03/23, 4/19/23, 5/19/23, 6/16/20/21 inspection. Due to stropaired, and extended SF 3	Neal Drickey was reminded //23, 7/13/23. Active tabilization of Lot 33, insta	A inspector painted the ergency spillway, and don 4/21/22, 5/24/22, Yes Elation of SF 2 is no longer
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser did a cleanout mark of the cle	Neal Drickey installed the uring the 4/19/22 inspect of per the SWPPP plan, in the property of the second property	e sediment basin prior to the 3 ion. Including a berm around all side of the sediment basin prior to the 3 ion. Including a berm around all side of the sediment based on the	ves, anti-vortex device, eme veal Drickey was reminded veal Drickey was reminded very 23, 7/13/23. Active tabilization of Lot 33, insta prior to the 4/5/22 inspecti	A inspector painted the organic spillway, and on 4/21/22, 5/24/22, Yes Ilation of SF 2 is no longer on. Due to stabilization of
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser during the basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is Silt fence should be cleaned Neal Drickey was informed to	Neal Drickey installed thuring the 4/19/22 inspect of per the SWPPP plan, in the property of the second per the SWPPP plan, in the property of the second per the SWPPP plan, in the property of the second per the seco	le sediment basin prior to the 3 ion. Including a berm around all side lot done as of last inspection. No 2/03/23, 4/19/23, 5/19/23, 6/16 4/1/2021 Including a berm around all side lot done as of last inspection. No late 4/20/21 inspection. Due to st., repaired, and extended SF 3 id as of 4/12/22.	ves, anti-vortex device, eme veal Drickey was reminded veal Drickey was reminded very 23, 7/13/23. Active tabilization of Lot 33, insta prior to the 4/5/22 inspecti	A inspector painted the organic spillway, and on 4/21/22, 5/24/22, Yes Ilation of SF 2 is no longer on. Due to stabilization of
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser did a cleanout mark of the cle	Neal Drickey installed thuring the 4/19/22 inspect of per the SWPPP plan, in the property of the second per the SWPPP plan, in the property of the second per the SWPPP plan, in the property of the second per the seco	e sediment basin prior to the 3 ion. Including a berm around all side of the sediment basin prior to the 3 ion. Including a berm around all side of the sediment based on the	ves, anti-vortex device, eme veal Drickey was reminded veal Drickey was reminded very 23, 7/13/23. Active tabilization of Lot 33, insta prior to the 4/5/22 inspecti	A inspector painted the organic spillway, and on 4/21/22, 5/24/22, Yes Ilation of SF 2 is no longer on. Due to stabilization of
Current Condition:	Poor Condition - 10% filled - cleanout mark on the riser during the basin should be installed properly elevated dewatering Neal Drickey was informed to 6/24/22, 7/20/22, 8/3/22, 8/1 Silt Fence Fair Condition - Neal Drickey recommended as of 4/5/22. Lot 61, installation of SF 1 is Silt fence should be cleaned Neal Drickey was informed to	Neal Drickey installed thuring the 4/19/22 inspect of per the SWPPP plan, in the property of the second per the SWPPP plan, in the property of the second per the SWPPP plan, in the property of the second per the seco	e sediment basin prior to the 3 ion. Including a berm around all side of the sediment basin prior to the 3 ion. Including a berm around all side of the sediment based on the	ves, anti-vortex device, eme veal Drickey was reminded veal Drickey was reminded very 23, 7/13/23. Active tabilization of Lot 33, insta prior to the 4/5/22 inspecti	A inspector painted the regency spillway, and on 4/21/22, 5/24/22, Yes Ilation of SF 2 is no longer on. Due to stabilization of

Current Condition:	Good Condition - Neal Drickey installed SF A-D and SF L, M, O, P prior to the 3/17/22 inspection. Neal Drickey removed SF C and D during lot-level fine grading prior to the 3/29/22 inspection. Reinstallation will not be recommended. Due to seeding / matting behind lot 61, reinstallation of SF N is no longer recommended as of the 3/29/22 inspection. E&A inspector will continue to monitor. Neal Drickey removed SF B and installed SF I prior to the 4/5/22 inspection. SF I is adequately containing sediment, so installation of SF H is no longer recommended as of 4/5/22. E&A inspector will continue to monitor. Due to sodding of upgradient lots, installation of SF E is no longer recommended as of 4/19/22. E&A inspector will continue to monitor. Minor damage was observed to SF L during the 5/3/22 inspection. E&A inspector will continue to monitor. Neal Drickey removed SF L, M, and O prior to the 8/2/22 inspection. Vegetation has covered 70% of exposed dirt near SF L, M, O prior to the inspection on 8/23/22. E&A inspector will continue to monitor. Ground disturbance is minimal in the northeast quadrant of the site. E&A inspector will continue to monitor.					
ST A - K	Sediment Trap	See SWPPP		Removed		
Current Condition:	Removed - Neal Drickey Rer		prior to the inspection on 6/15/2	3. All Sediment traps have	e been removed.	
STR	Streets	On Site	4/1/2021	Active	No	
Current Condition:	Good Condition - Trackout was observed on Copper Mountain Drive during the 3/17/22 inspection. Neal Drickey cleaned the streets prior to the 4/5/22 inspection. Neal Drickey cleaned the streets prior to the 5/17/22 inspection. No major signs of trackout were observed during the most recent inspection. Neal Drickey cleaned the streets prior to the 8/23/22 inspection. No major signs of trackout were observed during the most recent inspection. Neal Drickey cleaned the streets prior to the 2/21/23 inspection. Neal Drickey cleaned the streets prior to the inspection on 6/8/23.					
SWPPP Sign	SWPPP Sign	On Site	3/31/2022	Active	No	
Current Condition:	Good Condition - The E&A ir	th the correct permit info	n north of the Silver Lane entra		pection. E&A inspector	
W 1	Straw Wattles	East Side of Copper Mountain Drive	3/29/2022	Active	No	
Current Condition:	Good Condition - Neal Drick inspection.	ey installed the wattles a	long the ROW of Copper Mour	ntain Drive and Silver Lane	prior to the 3/29/22	
W A - H	Straw Wattles	See SWPPP	4/5/2022	Active	No	
Current Condition:	Good Condition - Neal Drickey installed erosion control matting in place of W A, installed W B, and installed silt fence in place of W C prior to the 4/5/22 inspection. Due to progress of lot-level construction, installation of W D - H is not recommended. E&A inspector will continue to monitor.					
WO 1	Concrete Washout	On site	3/24/2022	Active	Yes	
Current Condition:	Fair Condition - Neal Drickey cleaned up the concrete waste and installed a designated concrete washout east of SB 1 prior to the 4/5/22 inspection. Some minor concrete waste was observed on site near active lots 41-43 during the 3/28/23 inspection. Due to hole in the concrete washout, the washout should be replaced or repaired. Neal Drickey was informed to complete by 10/18/22. Not done as of last inspection. Neal Drickey was reminded on 11/9/22, 11/30/22, 2/03/23, 4/19/23, 5/19/23, 6/16/23, 7/13/23.					
WS 01	Waste Storage Area	On site	4/1/2021	Active	No	
Current Condition:	Good Condition - Dumpsters were in place on individual lots during the 3/17/22 inspection. General site waste storage will be recommended as necessary. E&A inspector will continue to monitor. Dumpsters were in place on individual lots prior to the 9/26/22 inspection					
WT A - H	Wattles	See SWPPP		Removed		
Current Condition:	Removed - Maintenance for	wattles will be assigned	to individual lots as 3/17/22.			
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	Joh Roge			Reviewed By:	Et Sil	