E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P2	2020.100.002				
Inspector: Ethan Anderson		Stage					
Project Name:		1					
For Week Ending:		51526					
Project Location:	Golden Hills Drive & Old Mormon Bridge Road (Crescent, Iowa)						
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	70%						
Utilities:	100%						
Overall Development:	70%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times		
Sunday	0.00"				Week		
Monday	0.00"						
Tuesday	0.00"	3/19/2024	Sunny 66/29	3:05 PM			
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.13"						
	0.00"						

Construction Sequencing:

Complaints:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23) Grading on the northeast corner of the site (5/11/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading began in spring 2021; Entire site graded by fall 2021 (3/17/22). Grading in the northeast quarter of the site (5/17/22). Excavation of hillside on northeast portion of site (11/8/22). Minor ground disturbance for mailbox installation (11/28/22). Sidewalk installation active along lots 41, 42, and 43 (1/10/23). Tree removal and grubbing on northeast corner of site (1/24/23) Grading on the northeast corner of the site (5/11/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (3/17/22). Slope along SW corner of the site seeded / matted in fall 2021 (3/17/22). Area west of Lot 33 and Lot 61 seeded / matted (3/29/22). North side of Silver Lane and east side of Copper Mountain Drive seeded / matted (3/29/22). South side of Silver Lane and west side of Copper Mountain Drive seeded / matted (4/5/22). Rear of Lots 58 - 60 partially seeded / matted (4/5/22). Disturbed area behind Lots 38 - 40 seeded / matted (4/5/22). Lots 34-40 and 59-61 sodded (4/12/22). Rear of Lots 55 - 57 seeded / matted (7/26/22). Rear of lot 42 seeded / matted (11/8/22). ST K removed and area seeded (5/18/23). Rear of Lots 51 - 53 seeded / matted (2/27/24).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

No, see BMP Section

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?
No, see BMP Section
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
1.) Site was active during the last inspection.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	X3	Frojected instan Date	Removed	Wallitellalice	
Current Condition:	Removed - Neal Drickey pay		the 3/17/22 inspection	Removed		
CE 02	Construction Entrance	D6	The 6/17/22 mapediam.	Removed		
Current Condition:	Removed - Neal Drickey paved the entrance prior to the 3/17/22 inspection.					
CE A	Construction Entrance	BB7	4/1/2021	Active	Yes	
Current Condition:			d the entrance prior to the 3/17/			
	was compacted without the A 6" layer of 2" diameter roc from accessing the site from Neal Drickey was informed t 6/24/22, 7/20/22, 8/3/22, 8/1	addition of rock to the e k should be added to th this location. o complete by 3/24/22. 6/22, 11/9/22, 11/30/22	CE A continues to experience intrance prior to the 3/21/23 inspection. The entrance shows	uld be stabilized and clo	osed off to prevent any	
DS 1 - 6	11/29/23, 1/3/24, 2/7/24, 3/1 Diversion	See SWPPP		Removed		
Current Condition:			diversions 1-6 will no longer be			
Current Condition.	itemoved - Due to progress	or lot-level construction	diversions 1-0 will no longer be	recommended as or th	e 11/01/2022 ilispedid	
DS A - O	Diversion	See SWPPP	4/1/2021	Active	Yes	
Current Condition:			I - M prior to the 3/17/22 inspec DS C, DC E - H and DS O is no			
	M prior to the 8/9/22 inspection. Due to grading and lot-level construction in the area, reinstallation will not be recommended. Neal Drickey installed Diversion N prior to the inspection on 11/8/22. Diversion D should be installed. Neal Drickey was informed to complete by 3/31/22. Not done as of last inspection. Neal Drickey was reminded on 5/24/22, 6/24/22, 7/20/22, 11/30/22, 2/03/23, 4/19/23, 5/19/23, 6/16/23, 7/13/23, 7/28/23, 9/28/23, 10/13/23, 11/3/23, 11/29/23, 1/3/24, 2/7/24, 3/13/2					
ECM 1	7/20/22, 11/30/22, 2/03/23, 4 Erosion Control Matting	4/19/23, 5/19/23, 6/16/2 SW Corner	3 <mark>, 7/13/23, 7/28/23, 9/28/23, 10</mark>	<mark>/13/23, 11/3/23, 11/29/2</mark> Active	23, 1/3/24, 2/7/24, 3/13 No	
ECM 1 Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion	3, 7/13/23, 7/28/23, 9/28/23, 10. 4/1/2021 control matting along the slope	/13/23, 11/3/23, 11/29/2 Active prior to the 3/17/22 insp	23, 1/3/24, 2/7/24, 3/13 No	
	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38	3 <mark>, 7/13/23, 7/28/23, 9/28/23, 10</mark>	/13/23, 11/3/23, 11/29/2 Active prior to the 3/17/22 insp	23, 1/3/24, 2/7/24, 3/13 No	
Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper	3, 7/13/23, 7/28/23, 9/28/23, 10. 4/1/2021 control matting along the slope	/13/23, 11/3/23, 11/29/2 Active prior to the 3/17/22 insp	23, 1/3/24, 2/7/24, 3/13 No	
	7/20/22, 11/30/22, 2/03/23, 4 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer	3, 7/13/23, 7/28/23, 9/28/23, 10/28/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/23, 10/28/28/28/28/28/28/28/28/28/28/28/28/28/	Active prior to the 3/17/22 insp. 2 inspection. Active of Copper Mountain Dri	No pection. Neal Drickey No No Neal Drickey	
Current Condition: ECM 2	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 control matting along the slope 3-40 and 35-40 prior to the 4/5/2 3/29/2022 control matting along the ROW	Active prior to the 3/17/22 insp. 2 inspection. Active of Copper Mountain Dri	No pection. Neal Drickey No No Neal Drickey	
ECM 2 Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 4/11/2021 3-40 and 35-40 prior to the 4/5/2 3/29/2022 control matting along the ROW noved for utility work prior to the	Active prior to the 3/17/22 inspection. Active of Copper Mountain Drie 4/26/22 inspection. E8	No	
ECM 2 Current Condition: ECM 3 Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection.	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 36 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 4/11/2021 3-40 and 35-40 prior to the 4/5/2 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW	Active prior to the 3/17/22 inspection. Active of Copper Mountain Drie 4/26/22 inspection. E8	No	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Erosion Control Matting	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 4/11/2021 control matting along the slope 3/40 and 35-40 prior to the 4/5/2 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW	Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri Active of Copper Mountain Dri Active of Copper Mountain Dri Active Active	No Dection. Neal Drickey No Eve and Silver Lane prick inspector will contin No Eve and Silver Lane prick inspector will contin No Eve and Silver Lane prick inspector will contin	
ECM 2 Current Condition: ECM 3 Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Erosion Control Matting	SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter ey installed the erosion	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 4/11/2021 3-40 and 35-40 prior to the 4/5/2 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW	Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri Active of Copper Mountain Dri Active of Copper Mountain Dri Active Active	No Dection. Neal Drickey No Eve and Silver Lane prick inspector will contin No Eve and Silver Lane prick inspector will contin No Eve and Silver Lane prick inspector will contin	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition:	7/20/22, 11/30/22, 2/03/23, 2 Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Erosion Control Matting	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 4/11/2021 control matting along the slope 3/40 and 35-40 prior to the 4/5/2 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW	Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri Active of Copper Mountain Dri Active of Copper Mountain Dri Active Active	No Dection. Neal Drickey No Eve and Silver Lane prick inspector will contin No Eve and Silver Lane prick inspector will contin No Eve and Silver Lane prick inspector will contin	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: ECM 4 Current Condition:	Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Erosion Control Matting Good Condition - Neal Drick	3/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter ey installed the erosion West of Golden Hills Dr ey installed the erosion	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 control matting along the slope 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 2/27/2024 control matting along several set 2/27/2024 control matting behind lots 51, 3/2022	Active of Copper Mountain Dri Active of SF 3 prior to t Active	No Ive and Silver Lane pri A inspector will contin No Ive and Silver Lane pri A inspector will contin No Ive and Silver Lane pri	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: ECM 4 Current Condition: FT 01	Frosion Control Matting Good Condition - Neal Drick extended the matting Horizon Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Erosion Control Matting Good Condition - Neal Drick Frosion Control Matting Good Condition - Neal Drick Frosion Control Matting	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 36 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter ey installed the derosion West of Golden Hills Dr ey installed the erosion On Site	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 control matting along the slope 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW along the	Active prior to the 3/17/23, 11/29/2 Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri 2 4/26/22 inspection. E8 Active of Copper Mountain Dri Active	No Proceedings of the Alberta of the	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: ECM 4 Current Condition:	Fuel Tank Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Erosion Control Matting Good Condition - Neal Drick Fuel Tank Good Condition - Neal Drick	SW Corner ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter ey installed the erosion West of Golden Hills Dr ey installed the erosion On Site ey installed a fuel tank respection. Neal Drickey	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 control matting along the slope 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW 4/5/2022 control matting along the ROW 2/27/2024 control matting along several set 2/27/2024 control matting behind lots 51, 3/2022	Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri 2 4/26/22 inspection. E8 Active of Copper Mountain Dri Active of Copper Mountain Dri Active ections of SF 3 prior to the in Active 2 and 53 prior to the in Active 2 inspection. Neal Drick	No vection. Neal Drickey No vection. Neal Drickey No vection. Neal Drickey No vection and Silver Lane pri value and Silver Lane pri No vection and Silver Lane pri No vection on 2/27/24. No vection on 2/27/24.	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: ECM 4 Current Condition: FT 01 Current Condition:	Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Erosion Control Matting Good Condition - Neal Drick Fuel Tank Good Condition - Neal Drick fuel tank prior to the 4/5/22 i prior to the inspection on 12.	4/19/23, 5/19/23, 6/16/2 SW Corner ey installed the erosion and east to cover lots 36 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion Western Perimeter ey installed the erosion West of Golden Hills Dr ey installed the erosion On Site ey installed a fuel tank r nspection. Neal Drickey (5/23.) On Site	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 control matting along the slope 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW 2/27/2024 control matting along several set 2/27/2024 control matting behind lots 51, 3/317/2022 north of SB A prior to the 3/17/2: moved the fuel tank to along C	Active of Copper Mountain Dri Active octions of SF 3 prior to t Active 52 and 53 prior to the in Active 2 inspection. Neal Drick opper Mountain Dr. and	No Ive and Silver Lane prick inspector will contin No Ive and Silver Lane prick inspector will contin No Ive and Silver Lane prick inspector will contin No Ive and Silver Lane prick inspector. No Ive and Silver Lane prick inspection.	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: ECM 4 Current Condition: FT 01 Current Condition:	Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Erosion Control Matting Good Condition - Neal Drick Fuel Tank Good Condition - Neal Drick fuel tank prior to the 4/5/22 i prior to the inspection on 12 Inlet Protection Pending - Neal Drickey sodo needed on the adjacent inlet Inlet protection should be ins Neal Drickey was informed t	West Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion West Gide of Copper Mountain Drive ey installed the erosion Western Perimeter ey installed the erosion West of Golden Hills Dr ey installed the erosion On Site ey installed a fuel tank respection. Neal Drickey (5/23. On Site led multiple lots along Sts. stalled on the 2 northeas o complete by 3/24/22.	4/1/2021 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW along the slope 4/5/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW along the	Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri 2 4/26/22 inspection. E8 Active of Copper Mountain Dri Active of Copper Mountain Dri Active of Copper Mountain Dri Active 2 inspection of SF 3 prior to to Active 2 and 53 prior to the in Active 2 inspection. Neal Drick opper Mountain Dr. and Pending n on 11/21/23 and inlet	No pection. Neal Drickey No pection. Neal Drickey No pection. Neal Drickey No pection on 2/27/24. No pection on 2/27/24. No pection on 2/27/24. No per built a berm around a berm around a per aro	
ECM 2 Current Condition: ECM 3 Current Condition: ECM 3 Current Condition: ECM 4 Current Condition: FT 01 Current Condition:	Erosion Control Matting Good Condition - Neal Drick extended the matting north a Erosion Control Matting Good Condition - Neal Drick the 3/29/22 inspection. Som monitor. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick the 4/5/22 inspection. Erosion Control Matting Good Condition - Neal Drick Erosion Control Matting Good Condition - Neal Drick Fuel Tank Good Condition - Neal Drick fuel tank prior to the 4/5/22 i prior to the inspection on 12 Inlet Protection Pending - Neal Drickey sodo needed on the adjacent inlet Inlet protection should be ins Neal Drickey was informed t	West Side of Copper Mountain Drive ey installed the erosion and east to cover lots 38 East Side of Copper Mountain Drive ey installed the erosion e of the matting was rer West Side of Copper Mountain Drive ey installed the erosion ey installed the erosion Western Perimeter ey installed the erosion West of Golden Hills Dr ey installed the erosion On Site ey installed a fuel tank inspection. Neal Drickey (5/23. On Site led multiple lots along Sts. stalled on the 2 northead occumplete by 3/24/22.	3, 7/13/23, 7/28/23, 9/28/23, 10/2021 control matting along the slope 3/29/2022 control matting along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW along the ROW noved for utility work prior to the 4/5/2022 control matting along the ROW along the following the ROW along the first along the ROW along the fuel tank to along the fuel tank to along the fuel tank to along the ROW	Active prior to the 3/17/22 inspection. Active of Copper Mountain Dri 2 4/26/22 inspection. E8 Active of Copper Mountain Dri Active of Copper Mountain Dri Active of Copper Mountain Dri Active 2 inspection of SF 3 prior to to Active 2 and 53 prior to the in Active 2 inspection. Neal Drick opper Mountain Dr. and Pending n on 11/21/23 and inlet	No pection. Neal Drickey No pection. Neal Drickey No pection. Neal Drickey No pection on 2/27/24. No pection on 2/27/24. No pection on 2/27/24. No per built a berm around a berm around a per aro	

Lot 42	Individual Lot	Lot 42		Removed	
Current Condition:	Removed- Neal Drickey soc		spection on 5/25/23.		
Lot 43	Individual Lot	Lot 43		Removed	
Current Condition:	Removed- Neal Drickey soc	ded the lot prior to the ir	spection on 5/25/23.		
Lot 44	Individual Lot	Lot 44	9/7/2023	Active	Yes
Current Condition:	Fair Condition - Neal Dricke	v began excavating the	ot prior to the inspection on 9/	7/23. Neal Drickey installe	d silt fence at the front of
		n on 12/26/23. Neal Drick	key repaired and installed silt f		
	Neal Drickey was informed	to complete by 3/12/24.	Not done as of last inspection.		
Lot 45	Individual Lot	Lot 45	9/7/2023	Active	Yes
Current Condition:			ot prior to the inspection on 9/		
	the lot prior to the inspection 2/20/24. Silt fence should be repaired Neal Drickey was informed	on 12/26/23. Neal Drick d. to complete by 3/12/24.	vey repaired and installed silt f	ence at the front of the lot	
Lot 51	Individual Lot	Lot 51		Removed	
Current Condition:	Removed- Neal Drickey soc	lded the lot prior to the in	nspection on 11/21/23.		
Lot 52	Individual Lot	Lot 52		Removed	
Current Condition:	Removed- Neal Drickey soo		spection on 11/21/23.		
Lot 53	Individual Lot	Lot 53		Removed	
Current Condition:	Removed- Neal Drickey soc		spection on 11/21/22		1
MS 01		On Site	4/1/2021	Active	No
	Material Storage				No No
Current Condition:	used as construction materi	al staging areas. No BM	material storage area prior to t Ps are being recommended fo	r these lots since there is	no active grading.
PB X	Portable Bathroom	On Site	7/12/2022	Active	Yes
Current Condition:	Fair Condition - Neal Dricke	y placed a portable toile	t on Lot 49 prior to the 7/12/22	inspection.	
		to complete by 7/19/22.	Not done as of last inspection. 3, 7/13/23, 7/28/23, 9/28/23, 10		
SB 1	Sediment Basin	N of CE 1	4/1/2021	Active	Yes
	properly elevated dewatering Neal Drickey was informed	g holes. to complete by 3/24/22. 16/22, 11/9/22, 11/30/22	including a berm around all sid Not done as of last inspection. 2/03/23, 4/19/23, 5/19/23, 6/1	Neal Drickey was reminde	ed on 4/21/22, 5/24/22,
SF 1 - 3	Silt Fence	See SWPPP	I	Removed	<u> </u>
			- t- t- t- i	Removed	l
Current Condition:			r to the inspection on 2/20/24.		
SC 1	Silt Fence	Rear of lots 51-53	2/20/2024	Active	No
Current Condition:	Good Condition - Neal Drick		cks during the inspection on 2		
SF A - Q	Silt Fence	See SWPPP	4/1/2021	Active	No
Current Condition:	during lot-level fine grading lot 61, reinstallation of SF N Drickey removed SF B and is no longer recommended is no longer recommended 5/3/22 inspection. E&A insp Vegetation has covered 70%	prior to the 3/29/22 inspris no longer recommendinstalled SF I prior to the as of 4/5/22. E&A inspector will continue to motify of exposed dirt near S	SF L, M, O, P prior to the 3/17 ection. Reinstallation will not be ded as of the 3/29/22 inspection. SF I is adetented will continue to monitor. Due to will continue to monitor. Note to will continue to monitor. Note to will continue to monitor. Note of the will be wi	e recommended. Due to s in. E&A inspector will cont quately containing sedime ie to sodding of upgradien dinor damage was observi F L, M, and O prior to the in on 8/23/22. E&A inspect	eeding / matting behind inue to monitor. Neal nt, so installation of SF H t lots, installation of SF E ed to SF L during the 8/2/22 inspection. or will continue to
ST A - K	Sediment Trap	See SWPPP		Removed	
			prior to the inspection on 6/15/		yo hoon romoved
Current Condition:				· · · · · · · · · · · · · · · · · · ·	
STR	Streets	On Site	4/1/2021	Active	No
Current Condition:	prior to the 4/5/22 inspection observed during the most retrackout were observed during the streets	n. Neal Drickey cleaned ecent inspection. Neal Dring the most recent insper prior to the inspection of	Mountain Drive during the 3/1 the streets prior to the 5/17/22 rickey cleaned the streets prior ection. Neal Drickey cleaned the 6/8/23. Neal Drickey scraped	inspection. No major sign to the 8/23/22 inspection. he streets prior to the 2/21.	s of trackout were No major signs of /23 inspection. Neal
SWPPP Sign	SWPPP Sign	On Site	3/31/2022	Active	No
Current Condition:	Good Condition - The E&A i	ith the correct permit info	on north of the Silver Lane ention during the 1/3/2023 in	•	nspection. E&A inspector
W 1	Straw Wattles	East Side of Copper Mountain Drive	3/29/2022	Active	No
Current Condition:	inspection.		along the ROW of Copper Mou		ne prior to the 3/29/22
W A - H	Straw Wattles	See SWPPP	l	Removed	1

Current Condition:	Removed- Neal Drickey removed the remaining wattles prior to the inspection on 8/17/23.					
WO 1	Concrete Washout	On site	3/24/2022	Active	No	
Current Condition:	Good Condition - Neal Drickey cleaned up the concrete waste and installed a designated concrete washout east of SB 1 prior to the					
	4/5/22 inspection. Some minor concrete waste was observed on site near active lots 41-43 during the 3/28/23 inspection. There appeared to be no hole in the concrete washout during the inspection on 10/12/23. Neal Drickey cleaned out the concrete washout					
	prior to the inspection on 12/	12/23.				
WS 01	Waste Storage Area	On site	4/1/2021	Active	Yes	
Current Condition:	Fair Condition - Dumpsters v	vere in place on individu	ial lots during the 3/17/22 inspe	ection. General site waste	storage will be	
	recommended as necessary	. E&A inspector will con	tinue to monitor. Dumpsters w	<mark>ere in place on individual l</mark>	ots prior to the 9/26/22	
	inspection.					
	Debris and construction waste should be cleaned and removed. Neal Drickey was informed to complete by 12/5/23. Not done as of last inspection. Neal Drickey was reminded on 1/3/24, 2/7/24,					
NOT	3/13/24					
WT A - H	Wattles	See SWPPP		Removed		
Current Condition:	Removed - Maintenance for wattles will be assigned to individual lots as 3/17/22.					
Certification Statement						
	with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based of					
inquiry of the person or persons who manage the system or those persons directly responsible for gathering the inform						
	information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are signific					
	penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
	1					
	2 (1-6			6	to Sul	
Inspector Signature:	in con a			Reviewed By:	- 01	