E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

Erosion Control Specialist- Manage	r		10.004		
		E&A- P2006.05	06.001	Т	
Inspector: Mike Jacobson, CISEC					Stage
		Iroi	n Horse		3
Project Name:		NEF	R110574		
For Week Ending:	4/10/2010				68003
Project Location: Hwy 6 & Iron Horse Drive- Ashland, NE (Sanders County)					
	T	T		1	
Grading:	100%				
Sanitary Sewer:	90%				
Storm Sewer:	90%				
Paving: Seeding:	100%				
Utilities:	90%				
Overall Development:	50%				
Overan Bevelopment.	0070	ļ		-	
RAIN FALL AMOUNTS	Amount in tenths	Data increated			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			- Mach
Sundaye	Trace				Week 1
Sunday: Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.17"				
Saturday	0.00"				
,					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.15"				
					Week 3
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday Thursday	0.00"				
Friday	0.00"				
Saturday Saturday	0.00"				
Saturday	0.00				Week 4/5
Sunday:	0.00"				
Monday	0.00"	04/05/10			
Tuesday	0.10"	04/06/10			
Wednesday	0.02"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	None				
Complaints:					
		1	1	, ,	
Construction Sequencing:	alta hava bed e t		an of anodium most.	armal allagrichers (1.12)	leat 4.4 desire0
Which portion(s) (i.e. drainage basins) of the	site nave had a temporar	y or permanent cessation	on of grading, earthwork, or gr	ound disturbance in the	last 14 days?
Entire site; grading completed and sta	hilized prior to Spring	2005			
Limite site, grading completed and sta	pinzea biloi ia obilili	y 2000.			
Which portion(s) (i.e. drainage basins) of the	site do not have grading	, earthwork, or ground d	isturbance scheduled in the ne	ext 14 days? :	
Entire site; grading completed and sta	bilized prior to Spring	g 2005.			
		1	ı	ı	

What temporary or permanent stabilization measures listed in this section are being implemented?							
Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.							
Comments:							

Comments:

Site is in overall good condition. Home construction is active on site.

12) Some maintenance is required in the BMP section.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Silt fence check East of lot 128 is undermined and needs to be backfilled and compacted. Boyer Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.
- 2) Silt fence checks West of lot 128 are undermined and needs to be backfilled and compacted. Bover Young was informed to complete by 10/30/08. On 3/13/09 Boyer Young was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last
- 3) Varies empty lots have concrete/debris on them and it needs to be cleaned up. Boyer Young was informed to complete by 3/18/09. Concrete/debris on varies empty lots was cleaned up prior to inspection on 4/5/10 by Boyer Young.
- 4) Silt fence needs to be installed on the back of lot 118. Boyer Young was informed to complete maintenance by 3/18/09. As of inspection on 4/5/10 the lot has been stabilized therefore silt fence is no longer needed.
- 5) It is recommended to Boyer Young that silt fence should be installed on the front of lot 60. Boyer Young was informed to complete installation of 6) Lot 123 lot level silt fence is down/damaged and needs to be repaired, replaced if needed. Builder Steve Faller w/ Landmark Homes was inform 7) Lot 191 lot level silt fence is down/damaged needs to be repaired, replaced if needed. Also the back silt fence run is undermined in a few areas 8) Lot 43 lot level silt fence is down/damaged and needs to be repaired, replaced if needed. Some additional silt fence needs to be installed on the 9) Lot 191 has a full dumpster and needs to be emptied or covered. Shawn w/ Loos Construction was informed to complete maintenance by 4/13/ 10) Lot 191 has concrete spoils on the lot and they need to be cleaned up. Shawn w/ Loos Construction was informed to complete maintenance by 11) Lot 191 needs additional silt fence installed on the back corner of the lot. Shawn w/ Loos Construction was informed to complete maintenance

	Projected Install					
Unique Name	Type	Location	Date	Status	Maintenance	
	Permanent	N00d00m00s				
PDP A	Detention Pond	W00d00m00s	In Place	Active	No	
Current Condition:	Good Condition					
		N00d00m00s				
SF 1	Silt Fence	W00d00m00s		Removed		
Current Condition:	Silt fence was removed prior to inspection on 4/5/10 by Boyer Young as it is no longer needed.					
		N00d00m00s				
SF 2	Silt Fence	W00d00m00s		Removed		
Current Condition:	Removed due to g	ood vegetation, but will	need to be reinstalled	once home constru	iction starts up in this	
	area.	T	T		1	
		N00d00m00s				
SF 3	Silt Fence	W00d00m00s	In Place	Active	Yes	
Current Condition:		rtially removed due to go	ood vegetation, but will	need to be reinsta	lled once home	
	construction start u	ıp in this area.				
	A (
	A few areas area of	lown/damaged and nee	as to be repaired.			
	Royer Voung was i	informed to complete m	aintenance by 7/24/08	On 3/13/00 Boyer	Voung was reminded	
		needs to be completed				
	triat maintenance i	recus to be completed ?	torti : Maintenance ne	t completed as of t	dot mopeotion.	
		N00d00m00s				
SF 4	Silt Fence	W00d00m00s		Removed		
Current Condition:	Removed due to g		l .		I	
		N00d00m00s				
SF 5	Silt Fence	W00d00m00s	In Place	Active	Yes	
Current Condition:	Fair Condition	VVOOdoomoos	III Flace	Active	165	
Current Condition.	Tall Condition					
	One area is down/damaged and full and needs to be repaired and cleaned out.					
	one area to acting damaged and rail and needs to be repaired and oldaned out.					
	Boyer Young was informed to complete by 6/6/08. On 3/13/09 Boyer Young was reminded that					
	maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.					
		N00d00m00s				
SF 6	Silt Fence	W00d00m00s		Removed		
Current Condition:	Removed due to d	evelopment.	!		!	
		N00d00m00s				
SF 7	Silt Fence	W00d00m00s		Removed		
Current Condition:	Removed due to d		ı		l .	
	N00d00m00s					
STR	Streets	W00d00m00s	In Place	Active	No	
Current Condition:	0	o major signs of track of		,		
Tanta de la constitución		mjer engine en tradit en				

SWPPP Sign	SWPPP Sign	Three signs of site	8/8/2008	Active	No
Current Condition:	Good Condition - A sign has been installed at Club House Drive and Hwy 6 and at Iron Horse Drive and				
	Hwy 6. South Lakeview Way & South Bend Road entrance.				
	During inspection on 4/29/09 inspector found a SWPPP sign in a pile of concrete debris at the entrance at				
	South Lakeview Way & South Bend Road and re-installed during inspection. Therefore there are know				
	three signs on site.				
Inspector Signature:				Reviewed By:	ochany L. Jilek