E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services Dept. I	Manager	E&A- P2006.0	NEC 001	
Inchestory Broncon Storns		E&A- P2000.0	356.001	Stage
Inspector: Branson Starns		luc	on Horse	Stage
Project Name:				3
-			R110574	
For Week Ending:		4	/8/2017	
Project Location:	Hwy 6 8	k Iron Horse Drive	e- Ashland, NE (Saunders County)	68003
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving: Seeding:	90%			
Utilities:	90%			
Overall Development:	60%			
	0070	I		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	
RAIN I ALL AMOUNTS	7 anount in tentro	Date inspected	Weather Conditions	Week '
Sunday:	0.01"			- Treek
Monday	0.00"			
Tuesday	0.01"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
	Ta	T		
Sunday:	0.00"			
Monday	0.00" 0.00"			
Tuesday	0.00"	02/22/47	Snow 52/24	
Wednesday Thursday	0.00"	03/22/17	Snow 52/34	
Friday	0.57"			
Saturday	0.43"			
outur uu j	0.10			
Sunday:	0.00"	03/26/17	Overcast 51/42	
Monday	0.00"			
Tuesday	0.00"			
Wednesday	1.14"			
Thursday	0.01"			
Friday	0.00"	03/31/17	Overcast 56/42	
Saturday	0.00"			
Sunday:	0.03"	I		<u> </u>
Monday	0.06"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
Sunday:	N/A			
Monday	N/A			
Tuesday	N/A			
Wednesday	N/A			
Thursday	N/A			
Friday Saturday	N/A N/A			
Jaturuay	IN/A	I		
	None			
Complaints:	TAOLIC			
				
Construction Sequencing:			•	+

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stab	ilized prior to Spring	g 2005.			
Which portion(s) (i.e. drainage basins) of the si	te do not have grading	, earthwork, or ground distur	rbance scheduled in the ne	xt 14 days? :	
Entire site; grading completed and stab	ilized prior to Spring	g 2005.			
What temporary or permanent stabilization mea	asures listed in this sec	ction are being implemented	?	•	•
Dense Vegetation, seeding/sodding, ma	atting, Re-seeding	5/2006, paving, and land	dscaping.		
Summary Questions:		•			
Are approved entrances and adjacent streets b	eing maintained adequ	ately?			
Yes					
Are receiving waters adjacent to the project free	e of any significant sig	gns of erosion or sediment tl	hat would be associated wi	th the construction act	ivity?
Yes	1		T	T	1
0	<u> </u>	<u> </u>	ļ	ļ	ļ
Checklist Questions:					
Are waste materials (concrete, construction ma	iterial, hazardous, etc.)	being managed properly?			
No- see BMP section.	Τ			1	1
Is dust associated with the construction activity	v adequately controller	d on the site?		1	1
Yes	y adequatery controlled	d on the site:			
Comments:		<u> </u>	<u> </u>	<u> </u>	<u> </u>
Comments:					
	4-				
Home construction is active on a few lo	lS.				
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date):					
1) Some maintenance is required in the	BMP section.				
2) Lot 35 has a fair amount of concrete		v some home owner. Di	iring the next inspection	n F&A will determi	ine which house re-
paved their driveway or sidewalk and co					
repairs. The Iron Horse Golf Club reque	• • • •	•			
i ·		•	•		
3) Lot 119/120 has a silt fence in the re-					
completed. Downspouts from the roofs	•	• •	•	•	
4) Lot 109/110 has a sediment basin wi					
and no plans were known of the basin.	The basin was full	of sediment, up to the tr	ash rack on the riser, a	and was spilling ove	er causing minor

5) Lot 80 has an area inlet that is being eroded around and the outfall has some erosion. Inspector will monitor the area.

deposition of silt on the golf course below. Inspector will now monitor the area. See SB1.

- 6) Lot 94 has a gazebo which was built into the existing berm disrupting storm water drainage in the area. Inspector will monitor the erosion in the area.
- 7) Lot 200 has erosion in the back yard possibly due to improper drainage. Inspector will continue to monitor the area.

			Projected Install		
Unique Name	Type	Location	Date	Status	Maintenance
Lot 7	Silt Fence	Lot 7		Removed	
Current Condition:	Removed-The lot i	s sodded and there are	no signs of runoff in th	e golf course turf a	s of inspection on
	4/20/15.				
Lot 8	Silt Fence	Lot 8	4/20/2015	Active	Yes
Current Condition:		inspector removed th	e silt fence during the	e inspection on 3/2	22/17. The gator
	guard still needs	removed.			
	The gator guard n	eeds removed.			
	PHI was requested	I to repair or remove the	BMPs by 4/27/15. No	t done as of last ins	spection. PHI was
		016. PHI was reminded	•		·
		·	· · ·	<u>, </u>	
Lot 18	Silt Fence	Lot 18	11/8/2016	Active	Yes
Current Condition:	Fair Condition- MK 3/26/17.	Builders repaired the	silt fence along the w	vest side and the i	north side prior to
	The portable toilet	needs secured to the g	ground		
	MK Builders was in	formed to complete by	12/27/16. Not done as	of last inspection. I	MK Builders was
		<u>//16, 1/19/17, 3/24/17.</u>			
Lot 33	Straw Wattles	Lot 33	1/15/2015	Active	No
Current Condition:		athan Homes had straw onstruction on lot 118 pr			o the lot being
Lot 36	Individual Lot	Lot 36		Removed	
Current Condition:	Fair Condition-Silve	erstone sodded the lot p	rior to inspection on 7/	27/15.	
Lot 37	Silt Fence	Lot 37		Removed	
Current Condition:	Removed-Kendel I	lomes sodded the lot p	rior to inspection on 12	/15/15.	
Lot 38	Silt Fence	Lot 38	12/29/2015	Pending	No
Current Condition:	Pending- The lot is inspection.	vegetated and no longe	er needs to be stabilize	ed by Kindle Homes	as of 6/4/16

Lot 61	Individual Lot	Lot 61		Removed	
Current Condition:	Removed-The dist	urbed portion of the lot i	s vegetated with natur	al vegetation as of i	nspection on
	10/29/15.				
		ı		1	
Lot 89	Silt Fence	Lot 089		Removed	
Current Condition:		Iders sodded the lot prio	r to 9/27/16.		
Lot 93	Silt fence	Lot 93		Removed	
Current Condition: Lot 114	Silt Fence	sodded the lot prior to in Lot 114	8/19/2015	Active	Yes
Current Condition:		ver Const. installed sil			
		rear of the lot needs rep			
	,	base of the slope needs			
		the side of the lot needs the rear of the property			
		in the rear of the property			
		ar are rear or are proper	.y		
		tion was informed to cor			
		reminded on 11/9/16, 11			oice mail on 12/21/16.
		n was reminded on 12/2			acation Cover
		tion was informed to cor reminded on 11/9/16, 11			
		n was reminded on 12/2			5100 maii 611 12/2 1/10.
		tion was informed to cor			spection. Gaver
		reminded on 11/25/16. G			on 12/21/16. Gaver
		reminded on 12/27/16 vi			
		tion was informed to cor		done as of last inspe	ection. Gaver
		reminded on 1/19/17, 3/2 tion was informed to cor		done as of last inspe	action Gaver
	Construction was a	reminded on 1/19/17 3/2		·	cetion. Gaver
Lot 138	Silt Fence	Lot 138		Removed	
Current Condition:	Removed- the silt	fence was removed by t	he inspector on 3/22/1	7.	
Lot 139	Silt Fence	Lot 139		Removed	
Current Condition:		nith Construction sodded	the lot prior to inspec		
Lot 147	Silt Fence	Lot 147		Removed	-
Current Condition: Lot 153	Individual Lot	noved the silt fence and s Lot 153	sodded the lot prior to	Removed	0.
Current Condition:		n Custom Homes sodde	d the lot prior to inspe		
Lot 154	Silt Fence	Lot 154	8/19/2015	Active	No
Current Condition:	Fair Condition- Wi	dhalm Custom Homes ir	nstalled more silt fence	prior to inspection	on 4/15/16.
	Silt fence needs to	be cleaned out and rep	aired		
	Oilt icrice riceds to	be cleaned out and rep	alica.		
		Homes was informed to			
	Custom Homes wa	as reminded on 6/5/16, 8	<mark>3/8/16. Widhalm was</mark> (reminded on 3/24/	17.
Lot 159	Silt Fence	Lot 159		Removed	
Current Condition:	Removed- The Ho	me Company sodded th		n on 6/3/16.	
Lot 160	Individual Lot	Lot 160	3/10/2016	Active	Yes
Current Condition:		was sodded, silt fence in			
	to inspection on 8/	13/16. The streets arour	ia the lot need to be cl	eanea. See STR se	ection.
L at 4.64	Individual Lat	L at 101	7/12/2016	Antivo	NI.
Lot 161 Current Condition:	Individual Lot	Lot 161 THC retied/repaired the	7/13/2016	Active	No
Current Condition.	Sood Condition-	THO retied/repaired the	s silt ferice along the	10t prior to 3/22/17	•
Lot 162	Individual Lot	Lot 162	7/13/2016	Active	No
Current Condition:		was removed from the			
		r will monitor for stabil the seeding window op		wiii recommena s	odding if not
Lot 163	Individual Lot	Lot 163	7/13/2016	Active	No
Current Condition:		was removed from the			
		r will monitor for stabil			· · · · · · · · · · · · · · · · · · ·
	completed once t	he seeding window op	ens.		
1 1 1 2 1	1.00.11.11.1	1.40	7/10/00 : 5		
Lot 164 Current Condition:	Individual Lot	Lot 164 was removed from the	7/13/2016	Active	Yes
Current Condition:		was removed from the r will monitor for stabil		•	· · · · · · · · · · · · · · · · · · ·
		he seeding window op			g // // // // // // // // // // // // //
	The portable toile	et needs re-secured to	the ground.		
	THE was inf	d to complete by 0/00/	17. Net demands	of image office	
	I HC was informe	d to complete by 3/29/	 Not done as of las 	st inspection.	

Lot 1CE						
Lot 165 Current Condition:	Silt Fence	Lot 165 HC repaired the silt fend	7/13/2016	Active	No	
		•	e prior to 172310.			
Lot 188	Silt Fence	Lot 188		Removed	C/4/4C T b	
Current Condition:		ouge sodded the lot and				
Lot 189	Silt Fence	Lot 189	6/12/2015	Active	Yes	
Current Condition:		fence is no longer need				
Guirent Gonation.		alled the silt fence to p		-		
		on. The inspector wan				
	silt fence is still n	· · · · · · · · · · · · · · · · · · ·				
	The silk force along	ld be seened				
	The silt fence shou	id be removed.				
	PHI was informed	to complete by 12/27/16	Not done as of last in	nspection Inspecto	r will remove the	
	fence during the w					
	Permanent	41°02'43.47"N				
PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No	
Current Condition:	Good Condition	1 1 100	I. Bl.	A.C.	L NI.	
SB 1	Sediment Basin	Lot 109	In Place	Active	No	
Current Condition:	Good Condition- The sediment basin was not known of when E&A took over the project and was cover					
	by dense vegetation. It was discovered when looking at problems silting in the golf course. Boyer You					
	,		• .		•	
	,	n. It was discovered wh rack and cleaned out th	• .		•	
	,	rack and cleaned out th	• .		•	
SF 3	removed the trash storage or sedimer	rack and cleaned out th t capacity. Lot 197	e basin prior inspectio	n on 8/31/16 as the	•	
SF 3 Current Condition:	removed the trash storage or sedimer	rack and cleaned out that capacity.	e basin prior inspectio	n on 8/31/16 as the	•	
Current Condition: SF 5	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence	rack and cleaned out that capacity. Lot 197 ector removed the silt for South side of lake	e basin prior inspectio	Removed ction on 3/22/17.	•	
Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence	rack and cleaned out th nt capacity. Lot 197 ector removed the silt fe	e basin prior inspectio	Removed ction on 3/22/17.	•	
Current Condition: SF 5	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence	rack and cleaned out that capacity. Lot 197 ector removed the silt for South side of lake	e basin prior inspectio	Removed ction on 3/22/17.	•	
SF 5 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp	rack and cleaned out the tapacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for the s	e basin prior inspection ence during the inspection ence during the inspection	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed	•	
SF 5 Current Condition: SF 8 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5	e basin prior inspection ence during the inspection ence during the inspection	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed	•	
SF 5 Current Condition: SF 8 Current Condition: SF 8 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection. In Place	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active	basin had no w	
SF 5 Current Condition: SF 8 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 e was associated with control of the silt for south side of the silt for sou	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection ence during the inspection In Place completed lots prior to	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the	No e project. The	
SF 5 Current Condition: SF 8 Current Condition: SF 8 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from ti	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 e was associated with content of the roofs of the houses as	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection in Place completed lots prior to are causing erosion in	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the	No e project. The	
SF 5 Current Condition: SF 8 Current Condition: SF 8 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from ti	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 e was associated with control of the silt for south side of the silt for sou	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection in Place completed lots prior to are causing erosion in	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the	No e project. The	
SF 5 Current Condition: SF 8 Current Condition: SF 8 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from ti	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 e was associated with content of the roofs of the houses as	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection in Place completed lots prior to are causing erosion in	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the	No e project. The	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 9 STR	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 er was associated with one roofs of the houses at the coming inspections 41°02'28.55"N 96°20'36.35"W	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection ence during the inspection In Place completed lots prior to our causing erosion in the inspection.	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the	No e project. The	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 er was associated with come roofs of the houses at the coming inspections 41"02'28.55"N	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection ence during the inspection In Place completed lots prior to our causing erosion in the inspection.	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the area. Inspector	No e project. The will continually	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 9 STR	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in Streets Good Condition- no	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 ee was associated with one roofs of the houses at the coming inspections 41°02'28.55"N 96'20'36.35"W or major signs of track out Three signs on site	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection In Place or causing erosion in the inspection In Place It. 8/8/2008	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the area. Inspector Active Active	No e project. The will continually	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 9 Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in Streets Good Condition- no	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 er was associated with come roofs of the houses at the coming inspections 41°02'28.55"N 96°20'36.35"W or major signs of track of the total signs of track of the context of the coming inspections are the coming inspections of the coming inspections are the coming inspections of the complete the coming inspections are the coming inspections of the complete the co	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection In Place or causing erosion in the inspection In Place It. 8/8/2008	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the area. Inspector Active Active	No e project. The will continually	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 9 Current Condition: STR Current Condition: SWPPP Sign	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in Streets Good Condition- no SWPPP Sign Good Condition - A	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 ee was associated with one roofs of the houses at the coming inspections 41°02'28.55"N 96'20'36.35"W or major signs of track out Three signs on site	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection In Place or causing erosion in the inspection In Place ut. 8/8/2008 If at Club House Drive	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the area. Inspector Active Active	No e project. The will continually	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: STR Current Condition: STR Current Condition: SWPPP Sign Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in Streets Good Condition- no SWPPP Sign Good Condition - A Hwy 6. South Lake	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 er was associated with one roofs of the houses at the coming inspections 41°02'28.55"N 96°20'36.35"W or major signs of track of Three signs on site a sign has been installed.	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection In Place or causing erosion in the inspection In Place ut. 8/8/2008 If at Club House Drive	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the area. Inspector Active Active	No e project. The will continually	
SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: STR Current Condition: STR Current Condition: SWPPP Sign Current Condition:	removed the trash storage or sedimer Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Active- the silt fence downspouts from the monitor the area in Streets Good Condition- no SWPPP Sign Good Condition - A	rack and cleaned out that capacity. Lot 197 ector removed the silt for south side of lake ector removed the silt for 40' South of SF 5 ector removed the silt for East of Lots 119 and 120 er was associated with one roofs of the houses at the coming inspections 41°02'28.55"N 96°20'36.35"W or major signs of track of Three signs on site a sign has been installed.	e basin prior inspection ence during the inspection ence during the inspection ence during the inspection In Place or causing erosion in the inspection In Place ut. 8/8/2008 If at Club House Drive	Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active E&A taking over the area. Inspector Active Active	No e project. The will continually	