E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

**Engineering Answers** 

		E&A- P2006.0	56.001			
nspector: Matthew Russell					Stage	
		Iro	n Horse		3	
Project Name:		NER110574 8/12/2017 Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)				
For Week Ending:						
Project Location:	Hwv 6 8					
	, <b>,</b>					
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	90%					
Seeding:	100%					
Jtilities:	90%					
Overall Development:	60%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
CAIN FALL AMOUNTS	Amount in Chins	Date inspected	Weather Conditions		We	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Vednesday	0.12"					
Thursday Thursday	0.31"					
riday	0.00"					
Saturday	0.00"					
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.01"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Supplies to	lo 00"	l		1	1	
Sunday: Monday	0.00"					
Tuesday	0.00"					
Wednesday	1.20"					
Thursday	0.00"	07/27/17	Tstorm 85/69			
Friday	0.00"	07/27/17	15(01111 05/09			
Saturday	0.00"					
Juliaruay	0.00					
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
<b>N</b> ednesday	0.00"					
Thursday	0.00"					
riday	0.03"					
Saturday	0.03"					
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Vednesday	0.00"					
Thursday	0.05"					
riday	0.00"					
Saturday	0.00"					
On any lateral	None					
Complaints:						

Which portion(s) (i.e. drainage basins) of the	site have had a tempor	rary or permanent cessation	n of grading, earthwork, o	r ground disturbance i	in the last 14 days?	
Entire site; grading completed and stab	ilized prior to Sprin	g 2005.				
Which portion(s) (i.e. drainage basins) of the	site do not have gradir	ng, earthwork, or ground dis	sturbance scheduled in th	e next 14 days? :		
Entire site; grading completed and stab	ilized prior to Sprin	g 2005.				
What temporary or permanent stabilization measures listed in this section are being implemented?						
Dense Vegetation, seeding/sodding, m	atting, Re-seeding	5/2006, paving, and lan	dscaping.			
Summary Questions:						
Are approved entrances and adjacent streets	being maintained ade	quately?				
No- see BMP section		1	,			
		<u> </u>				
Are receiving waters adjacent to the project to Yes	ree of any significant s	signs of erosion or sedimen	it that would be associate	d with the constructio	n activity?	
res	Ī		T	1		
Checklist Questions:			1	1		
Are waste materials (concrete, construction n	naterial, hazardous, etc	c.) being managed properly	?			
No- see BMP section.	,	or, some managea property				
Is dust associated with the construction activ	ity adequately control	led on the site?	•	•	•	
Yes						
Comments:						
Comments:						
Home construction is active on a few lo	ots.					
Findings / Corrective Actions (Date):						
Findings / Corrective Actions (Date):						
1) Some maintenance is required in the BMP section.						
2) Lot 35 has a fair amount of concrete debris deposited by some home owner. During the next inspection, E&A will determine which house re-						
paved their driveway or sidewalk and contact the appropriate persons involved. E&A was able to determine that the concrete was from street						
repairs. The Iron Horse Golf Club requested that the debris be placed on that lot as they would be used as rip rap in the near future.						
3) Lot 119/120 has a silt fence in the rear of the lot. This silt fence was installed prior to E&A's takeover of the project and the lot was previously						
completed. Downspouts from the roofs are causing erosion on the slopes depositing silt on the golf course. Inspector will now monitor the area.						
4) Lot 109/110 has a sediment basin with a riser that was present before E&A took over the project. The lots were completed prior to takeover,						
and no plans were known of the basin. The basin was full of sediment, up to the trash rack on the riser, and was spilling over causing minor						
deposition of silt on the golf course below. Inspector will now monitor the area. See SB1.						
5) Lot 80 has an area inlet that is being eroded around and the outfall has some erosion. Inspector will monitor the area.						
6) Lot 94 has a gazebo which was built into the existing berm disrupting storm water drainage in the area. Inspector will monitor the erosion in						
the area.						
lilo di ca.						

			Projected Install			
Unique Name	Type	Location	Date	Status	Maintenance	
Lot 7	Silt Fence	Lot 7		Removed		
Current Condition:	Removed-The lot is sodded and there are no signs of runoff in the golf course turf as of inspection on 4/20/15.					
Lot 8	Silt Fence	Lot 8	4/20/2015	Active	Yes	
Current Condition:	Fair Condition-The inspector removed the silt fence during the inspection on 3/22/17. The gator guard still needs removed.  The gator guard needs removed.  PHI was requested to repair or remove the BMPs by 4/27/15. Not done as of last inspection. PHI was reminded on 3/3/2016. PHI was reminded on 8/8/16, 12/21/16, 12/27/16, 3/24/17, 6/20/17.					
Lot 18	Silt Fence	Lot 18	11/8/2016	Active	Yes	
Current Condition:	Fair Condition- MK Builders repaired the silt fence along the west side and the north side prior to 3/26/17. MK Builders secured the portable toilet to the ground prior to 4/20/17.  The silt fence in the northwest corner of the lot needs joined.  MK Builders was informed to complete by 4/27/17. Not done as of last inspection. MK Builders were reminded on 5/3/17.					
Lot 33	Straw Wattles	Lot 33	1/15/2015	Active	No	
Current Condition:	Good Condition-Nathan Homes had straw wattles installed along the curb line due to the lot being disturbed during construction on lot 118 prior to inspection on 1/15/15.					
Lot 36	Individual Lot	Lot 36		Removed		
Current Condition:	Fair Condition-Silverstone sodded the lot prior to inspection on 7/27/15.					
Lot 37	Silt Fence	Lot 37		Removed		
Current Condition:	Removed-Kendel Homes sodded the lot prior to inspection on 12/15/15.					

7) Lot 200 has erosion in the back yard possibly due to improper drainage. Inspector will continue to monitor the area.

Current Condition:	Silt Fence	Lot 38	12/29/2015	Pending	No			
Carrent Contaition.	Pending- The lot is	vegetated and no longe	er needs to be stabilize		s as of 6/4/16			
	inspection.							
Lot 61	Individual Lot Lot 61 Removed							
Current Condition:		turbed portion of the lot i	is vegetated with natur	al vegetation as of	inspection on			
	10/29/15.							
			Г	1				
Lot 89	Silt Fence	Lot 089		Removed				
Current Condition:	Removed- MK Bui	lders sodded the lot price	or to 9/27/16.					
Lot 93	Silt fence	Lot 93		Removed				
Current Condition: Lot 114	Removed- Al Belt s	sodded the lot prior to in Lot 114	spection on 8/20/16. 8/19/2015	Active	Yes			
Current Condition:		ver Const. sodded the fi						
	still exposed with s			, , ,				
		rear of the lot needs rep						
		base of the slope needs the side of the lot needs						
		t the rear of the property						
		in the rear of the propert						
	,							
		ction was informed to con						
		reminded on 11/9/16, 11 construction was reminde						
		ction was informed to co			,			
	,	reminded on 11/9/16, 11			· ·			
		onstruction was reminde						
		tion was informed to co						
		reminded on 11/25/16. ( reminded on 12/27/16 vi						
		ction was informed to co						
		reminded on 1/19/17, 3/2			John Guro.			
	5) Gaver Construc	tion was informed to co	mplete by 1/2/16. Not	<mark>done as of last insp</mark>	ection. Gaver			
	Construction was r	reminded on 1/19/17, 3/2	24/17, 5/12/17.					
Lot 138	Silt Fence	Lot 138	l	Removed				
Current Condition:		fence was removed by t	L the inspector on 3/22/1					
Lot 139	Silt Fence	Lot 139		Removed				
Current Condition: Lot 147	Silt Fence	nith Construction sodded	a the lot prior to inspec I	Removed				
Current Condition:		noved the silt fence and	sodded the lot prior to		5.			
Lot 153	Individual Lot	Lot 153	'	Removed				
Current Condition:		n Custom Homes sodde						
Lot 154	Silt Fence	Lot 154	8/19/2015	Active	No			
Current Condition:	Fair Condition- wil	dhalm Custom Homes in	nstalled more slit tence	e prior to inspection	i on 4/15/16.			
	Silt fence needs to	be cleaned out and rep	Silt fance needs to be closed out and renaired					
	Silt fence needs to be cleaned out and repaired.							
			dalled.					
		Homes was informed to	complete by 5/18/16.					
		Homes was informed to as reminded on 6/5/16, 8	complete by 5/18/16.					
			complete by 5/18/16.					
Lot 158			complete by 5/18/16.					
Lot 158  Current Condition:	Custom Homes was	as reminded on 6/5/16, 8	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017	eminded on 3/24/1 Active	7. Yes			
	Custom Homes was Silt Fence Fair Condition- An	as reminded on 6/5/16, 8 Lot 158	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017	eminded on 3/24/1 Active	7. Yes			
	Silt Fence Fair Condition- An and west side of the	Lot 158  unknown builder started the lot prior to 6/19/17.	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017 d construction on the le	eminded on 3/24/1 Active	7. Yes			
	Silt Fence Fair Condition- An and west side of the	Lot 158  unknown builder started	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017 d construction on the le	eminded on 3/24/1 Active	7. Yes			
	Silt Fence Fair Condition- An and west side of the	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017 d construction on the le	Active  Active ot and installed silt	Yes fence along the north			
	Silt Fence Fair Condition- An and west side of the	Lot 158  unknown builder started the lot prior to 6/19/17.	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017 d construction on the le	Active  Active ot and installed silt	Yes fence along the north			
Current Condition:	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the poidentifty the builder as	complete by 5/18/16. 8/8/16. Widhalm was referenced from the lot.  of 6/19/17. Not done as	Active ot and installed silt as of last inspection Removed	Yes fence along the north			
Current Condition:  Lot 159	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the builder as Lot 159	complete by 5/18/16. 8/8/16. Widhalm was referenced from the lot.  of 6/19/17. Not done as	Active ot and installed silt as of last inspection Removed	Yes fence along the north			
Current Condition:  Lot 159  Current Condition:	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the builder as Lot 159  me Company sodded the	complete by 5/18/16. 8/8/16. Widhalm was r 6/19/2017 d construction on the lot e front of the lot. of 6/19/17. Not done a le lot prior to inspectio 3/10/2016	Active  Active ot and installed silt  as of last inspection Removed n on 6/3/16. Active	Yes fence along the north  Yes			
Lot 159 Current Condition:  Lot 160	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot of Removed-The lot	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the builder as Lot 159  me Company sodded the Lot 160	complete by 5/18/16. 8/8/16. Widhalm was reference front of the lot. of 6/19/17. Not done at least of the lot	Active  as of last inspection  Removed n on 6/3/16.  Active  59/160 boundary to	Yes fence along the north  Yes protect the inlet prior			
Lot 159 Current Condition:  Lot 160	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot of Removed-The lot	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the builder as Lot 159  me Company sodded the Lot 160  was sodded, silt fence in	complete by 5/18/16. 8/8/16. Widhalm was reference front of the lot. of 6/19/17. Not done at least of the lot	Active  as of last inspection  Removed n on 6/3/16.  Active  59/160 boundary to	Yes fence along the north  Yes protect the inlet prior			
Lot 159 Current Condition:  Lot 160	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot was to inspection on 8/	Lot 158  Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the poidentiffy the builder as Lot 159  me Company sodded the Lot 160  was sodded, silt fence in 13/16. The streets around the lot 161	complete by 5/18/16. 8/8/16. Widhalm was referenced from the lot. of 6/19/17. Not done at the lot prior to inspection of the lot of 1/10/2016 installed along the lot 1 and the lot need to be completed.	Active  as of last inspection  Removed n on 6/3/16.  Active  59/160 boundary to	Yes fence along the north  Yes protect the inlet prior			
Lot 159 Current Condition:  Lot 160 Current Condition:	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot was to inspection on 8/	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the prior to 159 to 160 to 160 to 160 was sodded, silt fence in 13/16. The streets around the started to 160 t	complete by 5/18/16. 8/8/16. Widhalm was referenced from the lot. of 6/19/17. Not done at the lot prior to inspection of the lot of 1/10/2016 installed along the lot 1 and the lot need to be completed.	Active  as of last inspection Removed n on 6/3/16. Active 59/160 boundary to leaned. See STR s	Yes fence along the north  Yes protect the inlet prior			
Lot 159 Current Condition:  Lot 160 Current Condition:  Lot 161 Current Condition:	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot to inspection on 8/ Individual Lot Removed- THC so	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the poidentiffy the builder as  Lot 159  me Company sodded the Lot 160  was sodded, silt fence in 13/16. The streets around the lot prior to 6/19  Lot 161  bodded the lot prior to 6/19	complete by 5/18/16. 8/8/16. Widhalm was referenced from the lot. of 6/19/17. Not done at the lot prior to inspection of the lot of 1/10/2016 installed along the lot 1 and the lot need to be completed.	Active  ot and installed silt:  as of last inspection  Removed n on 6/3/16.  Active 59/160 boundary to leaned. See STR s	Yes fence along the north  Yes protect the inlet prior			
Lot 159 Current Condition:  Lot 160 Current Condition:  Lot 161 Current Condition:  Lot 162	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot to inspection on 8/ Individual Lot Removed- THC so Individual Lot	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the poidentiffy the builder as  Lot 159  me Company sodded the Lot 160  was sodded, silt fence in 13/16. The streets around the lot prior to 6/19  Lot 161  Lot 161  Lot 162	complete by 5/18/16. 8/8/16. Widhalm was reference front of the lot. of 6/19/17. Not done at least of the lot prior to inspection of the lot at least of the lot indicate along the lot 1 and the lot need to be complete.	Active  as of last inspection Removed n on 6/3/16. Active 59/160 boundary to leaned. See STR s	Yes fence along the north  Yes protect the inlet prior			
Lot 159 Current Condition:  Lot 160 Current Condition:  Lot 161 Current Condition:	Silt Fence Fair Condition- An and west side of the The silt fence need E&A was unable to Silt Fence Removed- The Ho Individual Lot Removed-The lot to inspection on 8/ Individual Lot Removed- THC so Individual Lot	Lot 158  unknown builder started the lot prior to 6/19/17.  ds cleaned out along the poidentiffy the builder as  Lot 159  me Company sodded the Lot 160  was sodded, silt fence in 13/16. The streets around the lot prior to 6/19  Lot 161  bodded the lot prior to 6/19	complete by 5/18/16. 8/8/16. Widhalm was reference front of the lot. of 6/19/17. Not done at least of the lot prior to inspection of the lot at least of the lot indicate along the lot 1 and the lot need to be complete.	Active  ot and installed silt:  as of last inspection  Removed n on 6/3/16.  Active 59/160 boundary to leaned. See STR s	Yes fence along the north  Yes protect the inlet prior			

Current Condition:	Removed- THC sodded the lot prior to 6/19/17.						
Lot 164	Individual Lot	Lot 164		Removed			
Current Condition:		dded the lot prior to 6/1	9/17.				
				I			
Lot 165	Silt Fence	Lot 165		Removed			
Current Condition:	Removed- THC so	dded the lot prior to 6/1	9/17.				
Lot 188	Silt Fence	Lot 188		Removed			
Current Condition:		ouge sodded the lot and	removed the silt fend		n on 6/4/16. The		
	adjacent lots veget	ation appears adequate	e and no temporary se	eding is needed.			
Lot 189	Silt Fence	Lot 189	6/12/2015	Active	No		
Current Condition:	Good Condition-Silt fence is no longer needed and should be removed. The inspector is uncertain if Boyer Young installed the silt fence to prevent silt inundation of the golf course or if it was from lot 189 construction. The inspector wants to monitor the slope after a rain event to determine if the silt fence is still needed. The inspector is recommending leaving the silt fence installed as of 5/11/17.						
Lot 207	Silt Fence	Lot 207	6/19/2017	Active	Yes		
Current Condition:	Fair Condition- TH	C started construction o	on the lot and installed	silt fence along the	north and west side		
	of the lot prior to 6/19/17. THC installed an additional line of silt fence along the north side of the lot prior to 6/27/17.  1. The silt fence needs cleaned out along the northwest corner and west side of the lot.  2. Silt fence needs to be reinstalled on the corner of the lot.  1. THC was informed to complete by 6/26/17. Not done as of last inspection.  2. THC was informed to complete by 8/3/17.						
	Permanent	41°02'43.47"N					
PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No		
Current Condition:	Good Condition			•			
SB 1	Sediment Basin Lot 109 In Place Active No Good Condition- The sediment basin was not known of when E&A took over the project and was						
SF 3	covered by dense vegetation. It was discovered when looking at problems silting in the golf course.  Boyer Young removed the trash rack and cleaned out the basin prior inspection on 8/31/16 as the basin had no water storage or sediment capacity. Silt fence is behind the sediment basin riser.						
Current Condition:	Silt Fence Lot 197 Removed  Removed- the inspector removed the silt fence during the inspection on 3/22/17.						
SF 5	Silt Fence	South side of lake	anaa during tha inana	Removed			
Current Condition:	Removed- the inspector removed the silt fence during the inspection on 3/22/17.						
SF 8	Silt Fence 40' South of SF 5 Removed						
Current Condition:	Removed- the inspector removed the silt fence during the inspection on 3/22/17.						
		East of Lots 119 and					
SF 9	Silt Fence	120	In Place	Active	Yes		
Current Condition:	Fair Condition-		· · · · · · · · · · · · · · · · · · ·				
	The silt fence needs cleaned out and repaired.  Boyer Young was informed to complete by 6/26/17. Not done as of last inspection.						
		41°02'28.55"N					
STR	Streets	96°20'36.35"W	In Place	Active	Yes		
Current Condition:	The intersection on Eagle View and Mumm Rd needs cleaned of silt.  THC was informed to complete by 5/18/17. Not done as of last inspection.						
CIMIDED O:		, ,		<u> </u>	N I		
SWPPP Sign	SWPPP Sign	Three signs on site	8/8/2008	Active	No		
Current Condition:		a sign has been installed view Way & South Ben		and Hwy 6 and at I	IOII HOISE DIIVE AND		
Inspector Signature:	lno			Reviewed By:	Posts Sol		