E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services Dent				Engineerin	ig Answers
Environmental Services Dept. I	wanager	E&A- P2006.05	SE 004		
		E&A- P2006.03	1 00.00		T 0.
Inspector: Colton Reeder					Stage
Dunings Name		Iror	n Horse		
Project Name:		NER	R110574		3
For Week Ending:			11/2017		
Project Location:	Hwy 6 8	Iron Horse Drive-	Ashland, NE (Saunders	County)	68003
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	90%				
Seeding:	100%				
Utilities:	90%				
Overall Development:	67%				
	1				_
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.03"				
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday	MM"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.00"				1
Monday	0.00"				1
Tuesday	0.00"				-
Wednesday	0.00"				
Thursday	0.00"	44101001=	01		1
Friday	0.00"	11/3/2017	Clear 48/42		1
Saturday	0.00"				106-
Sunday:	N/A				Week
Sunday: Monday	N/A N/A				+
	N/A N/A				+
Tuesday Wednesday	N/A N/A				
Thursday	N/A N/A				+
Friday	N/A N/A				-
Saturday	N/A N/A				+
Jaturuay	IVA	l			1
	None				
Complaints:	inone				
Complaints.					
		I			1
Construction Conversions		L			
Construction Sequencing:					

Which portion(s) (i.e. drainage basins) of the	site have had a tempor	rary or permanent cessation	n of grading, earthwork, o	ground disturbance i	n the last 14 days?
Entire site; grading completed and state	ilized prior to Sprin	g 2005.			
Which portion(s) (i.e. drainage basins) of the	site do not have gradir	ng, earthwork, or ground dis	sturbance scheduled in th	e next 14 days? :	•
Entire site; grading completed and state	ilized prior to Sprin	g 2005.			
What temporary or permanent stabilization m	easures listed in this s	ection are being implement	ted?	•	
Dense Vegetation, seeding/sodding, m	atting, Re-seeding	5/2006, paving, and lan	dscaping.		
Summary Questions:					
Are approved entrances and adjacent streets	being maintained ade	quately?			
No- see BMP section					
Are receiving waters adjacent to the project	free of any significant	signs of erosion or sedimer	nt that would be associate	d with the construction	n activity?
Yes	ı	T	1	1	1
Checklist Questions:					
Are waste materials (concrete, construction n	naterial, hazardous, etc	c.) being managed properly	?		
No- see BMP section.			,	,	
Is dust associated with the construction activ	ity adequately control	led on the site?			
Yes	ı	T	T	T	ı
Comments:					

Comments:

Home construction is active on a few lots.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) Lot 80 has an area inlet that is being eroded around and the outfall has some erosion. Inspector will monitor the area. No significant erosion was observed as of the last inspection on 10/11/17. E&A inspector will continue to monitor.
- 3) Lot 94 has a gazebo which was built into the existing berm disrupting storm water drainage in the area. Inspector will monitor the erosion in the area. No significant erosion was observed due to gazebo installation as of the last inspection on 10/11/17. E&A inspector will continue to monitor
- 4) Lot 200 has erosion in the back yard possibly due to improper drainage. Inspector will continue to monitor the area. No significant erosion was observed as of the last inspection on 10/11/17. E&A inspector will continue to monitor.

			Projected Install		
Unique Name	Type	Location	Date	Status	Maintenance
Lot 7	Silt Fence	Lot 7		Removed	
Current Condition:	4/20/15.	s sodded and there are	no signs of runoff in th	ne golf course turf a	s of inspection on
Lot 8	Silt Fence	Lot 8		Removed	
Current Condition:	Active - The lot owned by PHI has become vegetated and is covered in gravel. Due to this level of stabalization, silt fence will not be recommended in the back of the lot at this time. E&A inspector will continue to monitor.				
Lot 18	Silt Fence	Lot 18		Removed	
Current Condition:	Removed - MK Bu	ilders sodded the lot pri	or to inspection on 8/1	7/17.	
Lot 33	Straw Wattles	Lot 33	1/15/2015	Active	No
Current Condition:		athan Homes had straw onstruction on lot 118 pr			to the lot being
Lot 36	Individual Lot	Lot 36		Removed	
Current Condition:		erstone sodded the lot p	orior to inspection on 7		
Lot 37	Silt Fence	Lot 37		Removed	
Current Condition:		Homes sodded the lot p	rior to inspection on 12		
Lot 38	Silt Fence	Lot 38		Removed	
Current Condition:	Removed - The lo	t is vegetated and no	longer needs to be s	tabilized by Kindl	e Homes as of
Lot 61	Individual Lot	Lot 61		Removed	
Current Condition:	Removed-The dist 10/29/15.	urbed portion of the lot	is vegetated with natur	al vegetation as of	inspection on
Lot 89	Silt Fence	Lot 089		Removed	
Current Condition:	Removed- MK Bui	lders sodded the lot price	or to 9/27/16.		
Lot 93	Silt fence	Lot 93		Removed	
Current Condition:	Removed- Al Belt	sodded the lot prior to in	spection on 8/20/16.		
Lot 113	Silt Fence	Lot 113	8/17/2017	Active	Yes

Current Condition:	Fair Condition-				
	Silt fence in the rea	ar of the lot needs to be	cleaned and repaired		
	Boyer Young was i	nformed to complete by	/ 8/24/2017. Not done	as of last inspection	. Boyer Young was
Lot 114	Silt Fence	Lot 114	8/19/2015	Active	Yes
Current Condition:		ver Const. sodded the f			
Surfeit Condition.	still exposed with s 1) Silt fence in the 2) Silt fence at the 3) Silt fence at the 3) Silt fence along 4) The silt fence at 5) A couple inlets in 1) Gaver Construct Construction was r 12/21/16. Gaver Construction was r 12/21/16. Gaver Construct Construction was r Construction was r 4) Gaver Construct Construction was r 4) Gaver Construct Construction was r Construction was r	ilt fence in place. rear of the lot needs replace of the slope need the side of the lot needs the rear of the property in the rear of the property in the rear of the	paired. s cleaned out. s repaired. y needs backfilled. ty needs silt removed. mplete by 10/4/16. No 1/25/16. Gaver Const. ed on 12/27/16 via em mplete by 10/4/16. No 1/25/16. Gaver Const. ed on 12/27/16 via em mplete by 11/15/16. No Gaver Const. was rem ia email and on 1/19/1 mplete by 1/2/16. Not 24/17, 5/12/17.	at done as of last insp was reminded via w nail and on 1/19/17, 3 t done as of last insp was reminded via w nail and on 1/19/17, 3 ot done as of last insp inded via voice mail 7, 3/24/17, 5/12/17, done as of last inspe	pection. Gaver bice mail on 3/24/17, 5/12/17. bection. Gaver bice mail on 3/24/17, 5/12/17. spection. Gaver on 12/21/16. Gaver
		tion was informed to co eminded on 1/19/17, 3/		done as of last inspe	ection. Gaver
Lot 119/120	Silt Fence	119/120	8/17/2017	Active	Yes
	The silt fence need	the slopes depositing sides to be cleaned out at the slope to complete by 1/17.	he back of the lots by	the trail.	
Lot 139	Silt Fence	Lot 139		Removed	
Current Condition:	Removed-Mick Sm	ith Construction sodde	d the lot prior to inspe	ction on 6/12/15.	
Lot 147	Silt Fence	Lot 147		Removed	
Current Condition:		oved the silt fence and	sodded the lot prior to		5.
Lot 153	Individual Lot	Lot 153		Removed	
Current Condition:		n Custom Homes sodde Lot 154			Voc
Lot 154 Current Condition:	Silt Fence	dhalm Custom Homes i	8/19/2015	Active Active	Yes
Guilent Gondition.	Due to established	vegetation, silt fence c	an be removed from tl	ne lot.	
Lot 158	Silt Fence	Lot 158	6/19/2017	Active	Yes
Current Condition:	and west side of the the 10/11/17 inspe		d construction on the l		
	The silt fence needs cleaned out along the front of the lot. E&A was unable to identify the builder as of 6/19/17. Not done as of last inspection.				
Lot 159	Silt Fence	Lot 159		Removed	
Current Condition:		me Company sodded th	ı ne lot prior to inspectio		
Lot 160	Individual Lot	Lot 160	3/10/2016	Removed	
Current Condition:	Removed - The lot	was sodded, silt fence on 8/13/16. The streets	installed along the lot	159/160 boundary to	
Lot 161	Individual Lot	Lot 161		Removed	
Current Condition:	Removed- THC so	dded the lot prior to 6/1	9/17.		
Lot 162	Individual Lot	Lot 162		Removed	
Current Condition:	Removed- THC so	dded the lot prior to 6/1	9/17.		

Current Condition:	Individual Lot	Lot 163	0/47	Removed		
Current Condition.	Removed- THC so	dded the lot prior to 6/1	9/17.			
Lot 164	Individual Lot	Lot 164		Removed		
Current Condition:	Removed- THC so	dded the lot prior to 6/1	9/17.		1	
Lot 165	Silt Fence	Lot 165		Removed		
Current Condition:	Removed- THC so	dded the lot prior to 6/1	9/17.			
Lot 188	Silt Fence	Lot 188		Removed		
Current Condition:		ouge sodded the lot an ation appears adequate			n on 6/4/16. The	
			e and no temporary sec		T	
Lot 189 Current Condition:	Silt Fence	Lot 189 was sodded as of last	inamantian an 0/10/201	Removed		
Current Condition:	Removed - The lot	was souded as of last	inspection on 9/19/201	7.		
Lot 197	Silt Fence	Lot 197	9/19/2017	Active	Yes	
Current Condition:	Fair Condition - Bu	ilder was identified as I	MK Builders Custom Ho	omes		
	Silt fence needs to	Silt fence needs to be cleaned out in the back of the lot.				
	MK Custom Home	s was requested to con	nplete by 10/2/17. Not	done as of the last	inspection.	
L at 207		Lot 207	I	Active	Yes	
Lot 207 Current Condition:	Silt Fence		6/19/2017			
Current Condition.	of the lot prior to 6/to 6/27/17. 1. The silt fence ne	Fair Condition- THC started construction on the lot and installed silt fence along the north and west side of the lot prior to 6/19/17. THC installed an additional line of silt fence along the north side of the lot prior to 6/27/17. 1. The silt fence needs cleaned out along the northwest corner and west side of the lot.				
	3. Sediment needs	2. Silt fence needs to be reinstalled on the corner of the lot. 3. Sediment needs removed from adjacent lot 208.				
	 THC was informed to complete by 6/26/17. Not done as of last inspection. Reminded on 9/19/17, 10/11/17. THC was informed to complete by 8/3/17. Not done as of last inspection. Reminded on 9/19/17, 10/11/17. 					
		ed to complete by 10/1	8/17. Not done as of I	ast inspection.		
PDP A	Permanent Detention Pond	41°02'43.47"N 96°20'36.65"W	In Place	Active	No	
IDIA		30 ZU 30.03 VV				
Current Condition:	Good Condition		11111400	710070	140	
Current Condition: SB 1	Good Condition Sediment Basin	Lot 109	In Place	Active	No	
SB 1 Current Condition:	Sediment Basin Good Condition- T covered by dense Boyer Young remo had no water stora	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit	In Place not known of when E8 vered when looking at cleaned out the basin	Active A took over the propolems silting in prior inspection on the sediment basin	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197	In Place not known of when E& vered when looking at cleaned out the basin y. Silt fence is behind t	Active A took over the proposed problems silting in prior inspection on the sediment basin Removed	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt	In Place not known of when E& vered when looking at cleaned out the basin y. Silt fence is behind t	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition: SF 5	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt of South side of lake	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind to ence during the inspec	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind to ence during the inspec	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8	Sediment Basin Good Condition-Ticovered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt is south side of lake hector removed the silt is 40' South of SF 5	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspec	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17. Removed Stion on 3/22/17. Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition:	Sediment Basin Good Condition-Ticovered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt of South side of lake hector removed the silt of the sector removed th	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspec	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17. Removed Stion on 3/22/17. Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt of South side of lake hector removed the silt of South of SF 5 hector removed the silt of South side of SF 5 hector removed the silt of South side of SF 5 hector removed the silt of South of SF 5 hector removed the silt of South of SF 5 hector removed the silt of South of SF 5	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t ence during the inspec	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17. Removed Stion on 3/22/17. Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the basi	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 8	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Removed- the insp Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt of South side of lake hector removed the silt of the sector removed th	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspec	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17. Removed Stion on 3/22/17. Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt of South side of lake hector removed the silt of South of SF 5 hector removed the silt of South side of SF 5 hector removed the silt of South side of SF 5 hector removed the silt of South of SF 5 hector removed the silt of South of SF 5 hector removed the silt of South of SF 5	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspect fence during the inspect fence during the inspect	Active A took over the proproblems silting in prior inspection on the sediment basin Removed Stion on 3/22/17. Removed Stion on 3/22/17. Removed Stion on 3/22/17.	No oject and was the golf course. 8/31/16 as the bas riser.	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 8	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp The silt fence	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt in South side of lake hector removed the silt in 40' South of SF 5 hector removed the silt in East of Lots 119 and 120 his cleaned out and repairs	In Place not known of when E8 evered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspect fence during the inspect fence during the inspect fence during the inspect fin Place	Active A took over the proproblems silting in prior inspection on the sediment basin Removed betton on 3/22/17. Removed betton on 3/22/17. Removed betton on 3/22/17. Active	No Dject and was the golf course. 8/31/16 as the basi riser. Yes	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 8	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Begin Condition- The silt fence need Boyer Young was i reminded on 8/18/2 Silt Fence	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt in South side of lake hector removed the silt in 40' South of SF 5 hector removed the silt in East of Lots 119 and 120 Its cleaned out and repair of the second of the second out and repair out the second o	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspect fence during the inspect fence during the inspect In Place In Place In Place In Place In Place	Active A took over the proproblems silting in prior inspection on he sediment basin Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active	No Dject and was the golf course. 8/31/16 as the basi riser. Yes Boyer Young was No	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Boyer Young was i reminded on 8/18/2 Silt Fence Good Condition- T	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt of South side of lake hector removed the silt of South of SF 5 hector removed the silt of East of Lots 119 and 120 he cleaned out and repair of the second of the silt of SF 5 hector removed the silt of SF 5 hector rem	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspect fence during the inspect fence during the inspect In Place	Active A took over the proproblems silting in prior inspection on he sediment basin Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active	No Dject and was the golf course. 8/31/16 as the basi riser. Yes Boyer Young was No	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Boyer Young was i reminded on 8/18/2 Silt Fence Good Condition- T	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt in South side of lake hector removed the silt in 40' South of SF 5 hector removed the silt in East of Lots 119 and 120 he selected out and repair of the silt in 120 he silt	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind t fence during the inspect fence during the inspect fence during the inspect In Place	Active A took over the proproblems silting in prior inspection on he sediment basin Removed ction on 3/22/17. Removed ction on 3/22/17. Removed ction on 3/22/17. Active	No Dject and was the golf course. 8/31/16 as the basi riser. Yes Boyer Young was No	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 9 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Fair Condition- The silt fence need Boyer Young was i reminded on 8/18/2 Silt Fence Good Condition - T inspection on 10/1 Streets Good Condition - S	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt in South side of lake hector removed the silt in 40' South of SF 5 hector removed the silt in East of Lots 119 and 120 his cleaned out and repair informed to complete by 2017, 10/09/17. Behind Lot 190 he silt fence was instal 1/17. E&A inspector will 41°02'28.55"N	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind to fence during the inspect fence during the inspect in Place In Place In Place led by Boyer Young to continue to monitor. In Place	Active A took over the proproblems silting in prior inspection on the sediment basin Removed ation on 3/22/17. Removed ation on 3/22/17. Removed ation on 3/22/17. Active Active Active Active	No Description of the second of the second was the golf course. 8/31/16 as the basing riser. Yes Boyer Young was No Urse trail prior to the second of th	
SB 1 Current Condition: SF 3 Current Condition: SF 5 Current Condition: SF 8 Current Condition: SF 9 Current Condition: SF 9 Current Condition:	Sediment Basin Good Condition-T covered by dense Boyer Young remo had no water stora Silt Fence Removed- the insp Silt Fence Fair Condition- The silt fence need Boyer Young was i reminded on 8/18/2 Silt Fence Good Condition - T inspection on 10/1 Streets Good Condition - S	Lot 109 he sediment basin was vegetation. It was discoved the trash rack and ge or sediment capacit Lot 197 hector removed the silt in South side of lake hector removed the silt in sector removed the silt in East of Lots 119 and 120 he silt fence was instal in 1/17. E&A inspector will 41°02'28.55"N 96°20'36.35"W Streets do not have significated in the silt in the	In Place not known of when E8 vered when looking at cleaned out the basin y. Silt fence is behind to fence during the inspect fence during the inspect in Place In Place In Place led by Boyer Young to continue to monitor. In Place	Active A took over the proproblems silting in prior inspection on the sediment basin Removed ation on 3/22/17. Removed ation on 3/22/17. Removed ation on 3/22/17. Active Active Active Active	No Description of the second of the second was the golf course. 8/31/16 as the basing riser. Yes Boyer Young was No Urse trail prior to the second of th	

Inspector Signature: Calton R. Reeder

Reviewed By:

Pet Su