E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

nspector: Aaron Tulley		<u> </u>			Stage
Project Name:		Iron Horse NER110574			
For Week Ending:			2/9/2019		
Project Location:	Hwy	68003			
		T	ı		
Grading: Ganitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Itilities:	100%				
verall Development:	72%				
AIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		W
unday:	0.00"				Wee
londay	0.00"				
uesday	0.00"				
/ednesday	0.00"				
hursday	0.01"				
riday	0.00"				
aturday	0.00"				10/
undove	0.00"				Wee
unday: londay	0.00"				
londay uesday	0.00" 0.01"				
		4/02/0040	Cm avv 20/42		
/ednesday	0.00"	1/23/2019	Snow 28/13		
hursday	0.00"				
riday	0.00" 0.01"				
aturday	0.01				Wee
unday:	0.00"				Wet
londay	0.00"				
uesday	0.00"				
/ednesday	0.00"				
hursday	0.00"				
riday	0.00"				
aturday	0.00"				
attirday	0.00				Wee
unday:	0.00"				1100
londay	0.00"				
uesday	0.00"				
/ednesday	0.01"				
hursday	0.00"				
riday	0.00"				
aturday	0.00"				
•					Wee
unday:	N/A	N/A			
londay	N/A	N/A			
uesday	N/A	N/A			
/ednesday	N/A	N/A			
hursday	N/A	N/A			
riday	N/A	N/A			
aturday	N/A	N/A			
omplaints:	None				
omplanto.					
onstruction Sequencing:					
			ion of grading, earthwork, or gro	and the state of t	not 14 days?

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:
Entire site; grading completed and stabilized prior to Spring 2005.
What temporary or permanent stabilization measures listed in this section are being implemented?
Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.
Summary Questions:
Are approved entrances and adjacent streets being maintained adequately?
Yes
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?
Yes
Checklist Questions:
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Is dust associated with the construction activity adequately controlled on the site?
Yes
Comments:
Comments:
Home construction is active on a few lots. During inspection on 1/23/19, the site was covered with 3-4 inches of snow.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1) Some maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
IF 1	Inlet	Lot 110	In Place	Active	No		
Current Condition:	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe.						
Lot 8	Silt Fence	Lot 8		Removed			
Current Condition:	Removed - The lot	Removed - The lot is inactive and stabilized.					
Lot 32	Individual Lot	Lot 32	8/1/2018	Pending	Yes		
Current Condition:	Pending - Nathan Homes began construction on the lot prior to the 6/27/18 inspection. During the 7/26/18 inspection, evidence of illicit discharge of concrete wash water into the street and storm drain was noted. As of the 8/22/18 inspection, Nathan Homes had removed the concrete washout debris. Streets were cleaned in front of the lot prior to inspection on 12/5/18. Silt fence or other BMPs need to be installed along the front of the lot. Nathan Homes was informed to complete by 8/1/18. Not done as of the las inspection. Nathan Homes was reminded on 8/23/18, 9/22/18, 11/1/18.						
Lot 33	Straw Wattles	Lot 33	T	Removed			
Current Condition:		is inactive and stabilize	d.	removed			
Garrent Gorianion.	Tromovou Tilo lot	o maonito ana otabiliba	Ť				
Lot 60	Individual Lot	Lot 60		Removed			
Current Condition:	Removed - No cons	struction activity has oc	curred as-of the 7/26/18 insp	ection. Disturbed a	reas have re-established		
	volunteer vegetation	n. ·					
Lot 90	Individual Lot	Lot 90	7/26/2018	Active	Yes		
Current Condition:	Fair Condition - Grace Homes began construction on the lot prior to the 7/26/18 inspection. Grace Homes installed silt fence along the front and side of the lot prior to the 7/26/18 inspection. A small section of silt fence on the south side was damaged, but is not receiving runoff as-of the 8/16/18 inspection. E&A inspector will continue to monitor. The silt fence on the sides of the lot needs to be repaired. Grace Homes was informed to complete by 11/8/18. Not done as of the last inspection.						
	side was damaged, The silt fence on the	but is not receiving rur	off as-of the 8/16/18 inspectito be repaired.	on. E&A inspector			
Lot 113	side was damaged, The silt fence on the	but is not receiving rur	off as-of the 8/16/18 inspectito be repaired.	on. E&A inspector			
Lot 113 Current Condition:	Side was damaged, The silt fence on the Grace Homes was i Silt Fence Fair Condition - Boy 1) The lot needs to 2) Silt fence on the 1) Boyer Young was reminded on 9/22/1	but is not receiving run e sides of the lot needs informed to complete b Lot 113 ver Young repaired the be stabilized lot needs to be repaire s informed to complete 8.	to be repaired. y 11/8/18. Not done as of the 8/17/2017 silt fence on the lot prior to the don the east side next to the by 7/4/18. Not done as of the	last inspection. Active le 7/3/18 inspection sodded lot.	Yes		
	Side was damaged, The silt fence on the Grace Homes was i Silt Fence Fair Condition - Boy 1) The lot needs to 2) Silt fence on the 1) Boyer Young was reminded on 9/22/1	but is not receiving run e sides of the lot needs informed to complete b Lot 113 ver Young repaired the be stabilized lot needs to be repaire s informed to complete 8.	to be repaired. y 11/8/18. Not done as of the 8/17/2017 silt fence on the lot prior to the don the east side next to the	last inspection. Active le 7/3/18 inspection sodded lot.	Yes		
Current Condition:	side was damaged, The silt fence on the Grace Homes was i Silt Fence Fair Condition - Boy 1) The lot needs to 2) Silt fence on the 1) Boyer Young was reminded on 9/22/1 2) Boyer Young was Silt Fence	but is not receiving run e sides of the lot needs informed to complete b Lot 113 rer Young repaired the be stabilized lot needs to be repaire s informed to complete s. informed to complete Lot 114	to be repaired. y 11/8/18. Not done as of the 8/17/2017 silt fence on the lot prior to the don the east side next to the by 7/4/18. Not done as of the	last inspection. Active le 7/3/18 inspection sodded lot. le last inspection. Both le last inspection. Removed	Yes		
Current Condition: Lot 114 Current Condition:	side was damaged, The silt fence on the Grace Homes was i Silt Fence Fair Condition - Boy 1) The lot needs to 2) Silt fence on the 1) Boyer Young was reminded on 9/22/1 2) Boyer Young was Silt Fence	but is not receiving run e sides of the lot needs informed to complete b Lot 113 rer Young repaired the be stabilized lot needs to be repaire s informed to complete s. informed to complete Lot 114	anoff as-of the 8/16/18 inspective to be repaired. y 11/8/18. Not done as of the 8/17/2017 silt fence on the lot prior to the don the east side next to the by 7/4/18. Not done as of the by 9/28/18. Not done as of the silve 9/28/18. Not done as of the silve 9/28/18. Not done as of the silve 9/28/18.	last inspection. Active le 7/3/18 inspection sodded lot. le last inspection. Both le last inspection. Removed	Yes		
Current Condition: Lot 114	side was damaged, The silt fence on the Grace Homes was i Silt Fence Fair Condition - Boy 1) The lot needs to 2) Silt fence on the 1) Boyer Young was reminded on 9/22/1 2) Boyer Young was Silt Fence Removed - Homeov Silt Fence	but is not receiving run e sides of the lot needs informed to complete b Lot 113 rer Young repaired the be stabilized lot needs to be repaire s informed to complete 8. s informed to complete Lot 114 wher Brian Mikkelsen s 119/120	anoff as-of the 8/16/18 inspective to be repaired. y 11/8/18. Not done as of the 8/17/2017 silt fence on the lot prior to the don the east side next to the by 7/4/18. Not done as of the by 9/28/18. Not done as of the silve 9/28/18. Not done as of the silve 9/28/18. Not done as of the silve 9/28/18.	last inspection. Active le 7/3/18 inspection sodded lot. le last inspection. Removed 6/18 inspection.	Yes		

Current Condition:	Fair Condition - Construction began on the lot prior to the 7/3/18 inspection (builder unknown) with silt fence installed around the perimeter of the lot. Prior to the 7/26/18 inspection, Additional silt fence was installed around the lot to replace the original silt fence that was not entrenched/backfilled. Additional silt fence was installed and existing silt fence was re-enforced prior to the 8/16/18 inspection. During the 9/3/18 inspection, most of the silt fence had been removed for retaining wall installation, and sediment was going off-site. Silt fence had been reinstalled prior to the 9/6/18 inspection, and attempts to remove off-site sediment were apparent. The E&A inspector					
	installed prior to the 9/6/18 inspection, and attempts to remove off-site sediment were apparent. The E&A inspector will continue to monitor. Additional silt fence was installed around the lot prior to the 10/11/18 inspection. 1) The silt fence around the lot need to be repaired and gaps need to be closed. 2) Accumulated sediment needs to be removed from the golf course. 1) Homeowners (Nygren) were informed to complete by 11/8/18. Not done as of the last inspection.					
			complete by 11/2/18. Not do			
Lot 129	Silt Fence	Lot 129		Removed		
Current Condition: Lot 130	Removed - Lot was Individual Lot	s incorrectly identified as Lot 130	Lot 129. See Lot 130. 5/23/2018	Active	Yes	
Current Condition:			lot prior to the 5/23/18 inspe			
	the lot by the builder prior to the 5/23/18 inspection. Additional silt fence was installed in the rear of the lot prior to the 8/16/18 inspection. Streets had been partially cleaned in front of the lot by homeowner prior to the 8/22/18 inspection. Streets were clean in front of the lot during the 9/21/18 inspection. New silt fence was installed in the rear of the lot prior to the 10/11/18 inspection. The silt fence in the rear of the lot needs to be repaired and/or replaced. Homeowner (Torpy) was informed to complete by 12/3/18. Not done as of last inspection.					
Lot 137	Individual Lot	Lot 137	1/23/2019	Active	Yes	
Current Condition:	1.) The silt fence in 2.) The dirt pile sho	the rear of the lot needs ould be removed from the apany was informed to co	s to be cleaned out/repaired e ROW. complete by 1/30/19 or as we complete by 1/30/19 or as we	ather allows.	ck of the lot prior to the	
Lot 138	Individual Lot	Lot 138	1/23/2019	Active	Yes	
Current Condition:	1.) The silt fence in 2.) The dirt pile sho	the rear of the lot needs ould be removed from the apany was informed to co	s to be cleaned out/repaired e ROW. complete by 1/30/19 or as we complete by 1/30/19 or as we	ather allows.	sk of the fol phor to the	
Lot 154	Silt Fence	Lot 154		Removed		
Current Condition:	Removed - Widhal south side to prote		ed the lot prior to the inspect	tion on 9/3/18 and ir	nstalled silt fence on the	
Lot 155	Silt Fence	Lot 155	9/3/2018	Active	No	
Current Condition:	on 9/3/18.		installed silt fence on the lo		lot 154 prior to inspection	
Lot 157 Current Condition:	Silt Fence	Lot 157	Legion Leg	Removed		
Lot 197	Silt Fence	Lot 197	lic lot during the 11/20/10 in	Removed		
Current Condition:			dded the lot prior to the 7/26	6/18 inspection.	1	
PDP A	Permanent Detention Pond	41°02'43.47"N 96°20'36.65"W	In Place	Active	No	
Current Condition:	Good Condition - T	his is a pond as of 1993				
SB 1 Current Condition:			on, this structure is no longe opears to be an area inlet/slo			
SF 3	Silt Fence	Lot 197		Removed		
Current Condition:		ector removed the silt fe	nce during the inspection or			
SF 5	Silt Fence	South side of lake		Removed		
Current Condition:	Removed- the insp	ector removed the silt fe	nce during the inspection or	n 3/22/17.		
SF 8	Silt Fence	40' South of SF 5		Removed		
Current Condition:	Removed- the insp		nce during the inspection or	n 3/22/17.		
SF 9	Silt Fence	East of Lots 119 and 120	In Place	Active	Yes	
Current Condition:			partially removed the silt fer depth of the	ice prior to inspection	OIT OIT 12/3/17.	
	Boyer Young was i 6/28/18, 9/24/18.	nformed to complete by	3/24/18. Not done as of last	inspection. Boyer \	Young was reminded on	
SF 10	Silt Fence	Behind Lot 190	12/5/2018	Active	No	

Current Condition:	Good Condition - The silt fence was mistakenly removed from the report in July, however it is still in place and in good condition. E&A will monitor.					
		41°02'28.55"N				
STR	Streets	96°20'36.35"W	In Place	Active	No	
Current Condition:	Good Condition - N	Good Condition - No signs of trackout				
SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No	
Current Condition:	Good Condition - A Road entrance.	sign has been installed	at Iron Horse Drive and Hw	y 6. South Lakeviev	v Way & South Bend	
Inspector Signature:	47			Reviewed By:	Set Sel	