E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	Manager	E&A- P2006	S 056 001			
Inspector: Avery Dresser					Stage	
Project Name:		Iron Horse NER110574				
For Week Ending:		8	3/10/2019			
Project Location:	Hwy	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)				
Grading:	100%	, I				
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	72%	0				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		11/	
Sunday:	0.00"				Week 1	
Monday	0.00"				+	
Tuesday	0.41"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week 2	
Sunday:	0.74"					
Monday	0.00"					
Tuesday	0.00"	7/23/2019	Sunny 81/58			
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week 3	
Sunday:	0.21"					
Monday	0.00"					
Tuesday	0.04"					
Wednesday	0.01"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
outuruuy	0.00				Week 4	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.02"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Cundam	NI/A				Week 5	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
	None					
Complaints:	1.55					
Construction Sequencing:						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire site; grading completed and stabilized prior to Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No, see BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Home construction is active on a few lots.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) There is disturbed ground on either side of the newly-sodded Lot 32 as of inspection on 7/23/19. The lot is flat and doesn't have runoff potential to waterbodies or the street therefore immediate stabilization or installation of BMPs is not necessary at this time. E&A inspector will continue to monitor the area for revegetation.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
IF 1	Inlet	Lot 110	In Place	Active	No		
Current Condition:	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe.						
Lot 8	Silt Fence	Lot 8		Removed			
Current Condition:	Removed - The lot	is inactive and stabilize	ed.				
Lot 2	Individual Lot	Lot 2	5/29/2019	Active	No		
Current Condition:		Good Condition - Pacesetter Homes began construction on the lot and installed silt fence along the west and north sides prior to inspection on 5/29/19.					
Lot 32	Individual Lot	Lot 32		Removed			
Current Condition:	Removed - Nathar 7/23/19.	Removed - Nathan Homes removed the concrete debris and sodded the lot prior to inspection on 7/23/19.					
Lot 33	Straw Wattles	Lot 33		Removed			
Current Condition:	Removed - The lot	Removed - The lot is inactive and stabilized.					
Lot 60	Individual Lot	Lot 60		Removed			
Current Condition:		Removed - No construction activity has occurred as-of the 7/26/18 inspection. Disturbed areas have re- established volunteer vegetation.					
Lot 90	Individual Lot	Lot 90		Removed			
Current Condition:	Removed - Grace Homes sodded the lot prior to inspection on 7/02/19.						
Lot 113	Silt Fence	Lot 113	8/17/2017	Active	No		
Current Condition:	Good Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removed some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. At the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding no longer required at this time.						
Lot 114	Silt Fence	Lot 114		Removed			
Current Condition:	Removed - Homeov	wner Brian Mikkelsen s	sodded the lot prior to the 8/	16/18 inspection.			
Lot 119/120	Silt Fence	119/120	·	Removed			
Current Condition:	Removed - The silt	Removed - The silt fence is listed in the report as SF 9 as of 12/19/17.					
Lot 126	Individual Lot						

Current Condition:	Fair Condition - Construction began on the lot prior to the 7/3/18 inspection (builder unknown) with silt fence installed around the perimeter of the lot. Prior to the 7/26/18 inspection, Additional silt fence was installed around the lot to replace the original silt fence that was not entrenched/backfilled. Additional silt fence was installed and existing silt fence was re-enforced prior to the 8/16/18 inspection. During the 9/3/18 inspection, most of the silt fence had been removed for retaining wall installation, and sediment was going off-site. Silt fence had been reinstalled prior to the 9/6/18 inspection, and attempts to remove off-site sediment were apparent. The E&A inspector will continue to monitor. Additional silt fence was installed around the lot prior to the 10/11/18 inspection. The homeowners (Nygren) installed silt fence along the west side of the lot prior to inspection on 4/15/19. The homeowners (Nygren) removed portions of the old silt fence on the western side of the lot prior to inspection on 4/15/19. The portable toilet was removed prior to inspection on 7/23/19. 1) The old run of silt fence around the lot need to be repaired and gaps need to be closed. 2) Accumulated sediment needs to be removed from the golf course. 3) New run of silt fence along the west side of the lot needs to be repaired near retaining wall 4) The old run of silt fence on the east side of the lot needs to be repaired near retaining wall 4) The old run of silt fence and is the east side of the lot should be reinstalled or removed 1) Homeowners (Nygren) were informed to complete by 11/8/18. Not done as of the last inspection. The inspector met with the builder on site and discussed recommendations for the lot during inspection on 3/15/19. Homeowners (Nygren) were informed to complete by 4/22/19. Not done as of last inspection. Homeowners (Nygren) were reminded on 6/06/19. 3) Homeowners (Nygren) were informed to complete by 4/22/19. Not done as of last inspection. Homeowners (Nygren) were reminded on 6/06/19.					
Lot 129	Silt Fence	Lot 129		Removed		
Current Condition:	Removed - Lot was ir	ncorrectly identified a	s Lot 129. See Lot 130.			
Lot 130 Current Condition:	Individual Lot	Lot 130	Lot prior to inspection on 5/2	Removed		
Lot 137 Current Condition:	Individual Lot	Lot 137	1/23/2019 an construction and installed	Active	Yes	
	 The silt fence should be cleaned out where full in the back of the lot. Sediment should be removed from the adjacent lot. The Home Company was informed to complete by 1/30/19 or as weather allows. Not done as of the last inspection. The Home Company was reminded on 3/19/19, 4/30/10, 5/30/19, 7/02/19, 7/24/19 The Home Company was informed to complete 3/22/19. Not done as of the last inspection. The Home Company was reminded on 4/30/19, 5/30/19, 7/02/19, 7/24/19 					
Lot 138	Individual Lot	Lot 138	1/23/2019	Active	Yes	
Current Condition:	Fair Condition - The Home Company began construction and installed silt fence on the back of the lot prior to the inspection on 1/23/19. The Home Company removed the dirt pile from the ROW prior to the inspection on 2/21/19. The Home Company cleaned out / repaired the silt fence and extended it in the rear of the lot prior to inspection on 7/02/19. 1. Sediment should be removed from the adjacent lot 2. The portable toilet on the vacant lot across the street (Lot 141) should be staked down. 1. The Home Company was informed to complete 3/22/19. Not done as of the last inspection. The Home Company was reminded on 4/30/19, 5/30/19, 7/02/19, 724/19 2. The Home Company was informed to complete 3/22/19. Not done as of the last inspection. The Home Company was reminded on 4/30/19, 5/30/19, 7/02/19, 7/24/19 Silt Fence Lot 154 Removed					
Current Condition:			ded the lot prior to the inspe		installed silt fence on	
1 -2 455	the south side to prote		0/0/0040	A =45	NJ-	
Lot 155 Current Condition:	Silt Fence Good Condition - Wid	Lot 155 Ihalm Custom Home	9/3/2018 s installed silt fence on the	Active lot to protect sodde	No d lot 154 prior to	
	inspection on 9/3/18.				- F	
Lot 157	Silt Fence	Lot 157	the lot during the 11/26/18	Removed		
Current Condition: Lot 197	Silt Fence	Lot 197	the lot during the 11/20/18	Removed		
Current Condition:			odded the lot prior to the 7/	26/18 inspection.		
PDP A	Permanent Detention Pond	41°02'43.47"N 96°20'36.65"W	In Place	Active	No	
Current Condition:	Good Condition - This					
SB 1	Sediment Basin	Lot 109	4: 41: 4 1	Removed	d - b - i i - d	
Current Condition:	have any sediment st	orage capacity and a	tion, this structure is no long appears to be an area inlet/s	slope drain. See IF		
SF 3	Silt Fence	Lot 197		Removed		
Current Condition:	Removed- the inspec	tor removed the silt t	ence during the inspection	on 3/22/17.		

SF 5	Silt Fence	South side of lake		Removed		
Current Condition:	Removed- the inspector removed the silt fence during the inspection on 3/22/17.					
SF 8	Silt Fence	40' South of SF 5		Removed		
Current Condition:	Removed- the inspector removed the silt fence during the inspection on 3/22/17.					
		East of Lots 119 and				
SF 9	Silt Fence	120	In Place	Active	Yes	
Current Condition:	Fair Condition - Boyer Young repaired and partially removed the silt fence prior to inspection on 12/5/17. The					
	sediment was removed from the golf course and cart path prior to inspection on 4/29/19.					
	The silt fence is fu	<mark>ll and needs to be clean</mark>	ed behind lots 114 and 115			
	Boyer Young was informed to complete by 3/24/18. Not done as of last inspection. Boyer Young was reminded					
	on 6/28/18, 9/24/18, 3/19/19, 6/06/19					
SF 10	Silt Fence	Behind Lot 190	12/5/2018	Active	No	
Current Condition:	Good Condition -	The silt fence was mista	kenly removed from the rep	ort in Julv. however	r it is still in place and in	
	Good Condition - The silt fence was mistakenly removed from the report in July, however it is still in place and in good condition. E&A will monitor.					
		41°02'28.55"N				
STR	Streets	96°20'36.35"W	In Place	Active	No	
Current Condition:	Good Condition - No signs of trackout					
SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No	
Current Condition:	Good Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Bend					
	Road entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again due to					
	the surrounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Horse					
	Drive had been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed					
	SWPPP sign during inspection on 7/23/19.					
	Citi i Cigii aani			ı		
8	S					
	Juj				Got Sol	
Inspector Signature:				Reviewed By:		