E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	. Manager	E&A- P2006	056 004	Liigineerin		
Inchestory Avery Dresser		E&A- P2000	0.000.001		Stage	
Inspector: Avery Dresser		Ir	on Horse		Stage	
Project Name:		Iron Horse NER110574				
For Week Ending:		9	/14/2019			
Project Location:	Hwy	Hwy 6 & Iron Horse Drive- Ashland, NE (Saunders County)				
Cradina	100%	1		1		
Grading: Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities: Overall Development:	100% 72%					
Overall Development.	1270	'				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
Overday:	4.000				Week 1	
Sunday: Monday	1.32" 0.34"	 				
Tuesday	0.00"	8/13/2019	Sunny 89/72			
Wednesday	0.00"	5 0. 20 . 0	Ca.miy con a			
Thursday	0.23"					
Friday	0.00"					
Saturday	0.00"					
	0.048				Week 2	
Sunday:	0.01"					
Monday	0.00"					
Tuesday Wednesday	0.29"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Cataraay	0.00				Week 3	
Sunday:	0.00"					
Monday	0.33"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.05"					
					Week 4	
Sunday:	0.00"					
Monday	0.00"	-				
Tuesday	0.00"					
Wednesday	0.00"	-				
Thursday Friday	0.00"	+				
Saturday	0.00"					
					Week 5	
Sunday:	0.00"					
Monday	0.02"					
Tuesday	0.05"					
Wednesday	0.02"	09/11/19	Sunny 90/72			
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	None					
Complaints:	INOTIE	None				
Construction Sequencing:						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and stabilized prior to Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site; grading completed and stabilized prior to Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Dense Vegetation, seeding/sodding, matting, Re-seeding 5/2006, paving, and landscaping.

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No, see BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Home construction is active on a few lots.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) There is disturbed ground on either side of the newly-sodded Lot 32 as of inspection on 7/23/19. The lot is flat and doesn't have runoff potential to waterbodies or the street therefore immediate stabilization or installation of BMPs is not necessary at this time. E&A inspector will continue to monitor the area for revegetation.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
IF 1	Inlet	Lot 110	In Place	Active	No	
Current Condition:	drain/area inlet. As	Active - This structure was previously referred to as a sediment basin, but is actually functioning as a slope drain/area inlet. As-of the 11/26/18 inspection, silt fence is in place behind the structure and straw wattles are located downhill from the outlet pipe.				
Lot 8	Silt Fence	Lot 8		Removed		
Current Condition:	Removed - The lot	is inactive and stabiliz	ed.	•		
Lot 2	Individual Lot	Lot 2	5/29/2019	Active	No	
Current Condition:		Good Condition - Pacesetter Homes began construction on the lot and installed silt fence along the west and north sides prior to inspection on 5/29/19.				
Lot 32	Individual Lot	Lot 32		Removed		
Current Condition:	Removed - Nathar	Removed - Nathan Homes removed the concrete debris and sodded the lot prior to inspection on 7/23/19.				
Lot 33	Straw Wattles	Lot 33		Removed		
Current Condition:	Removed - The lot	Removed - The lot is inactive and stabilized.				
Lot 60	Individual Lot	Lot 60		Removed		
Current Condition:		emoved - No construction activity has occurred as-of the 7/26/18 inspection. Disturbed areas have retablished volunteer vegetation.				
Lot 90	Individual Lot	Lot 90		Removed		
Current Condition:	Removed - Grace	Removed - Grace Homes sodded the lot prior to inspection on 7/02/19.				
Lot 113	Silt Fence	Lot 113	8/17/2017	Active	No	
Current Condition:	removed some of the inspection on 7	Good Condition - Boyer Young repaired the silt fence on the lot prior to the 7/3/18 inspection. Boyer Young removed some of the damaged silt fence and repaired the runs left in place prior to inspection on 7/02/19. As of the inspection on 7/02/19, volunteer vegetation has filled in sufficiently to prevent erosion, therefore seeding is no longer required at this time.				
Lot 114	Silt Fence	Lot 114		Removed		
Current Condition:		Removed - Homeowner Brian Mikkelsen sodded the lot prior to the 8/16/18 inspection.				
Lot 119/120	Silt Fence	119/120		Removed		
Current Condition:	Removed - The sil	Removed - The silt fence is listed in the report as SF 9 as of 12/19/17.				
Lot 126	Individual Lot	Lot 126	7/3/2018	Active	Yes	

Current Condition:	Fair Condition - Construction began on the lot prior to the 7/3/18 inspection (builder unknown) with silt fence installed around the perimeter of the lot. Prior to the 7/26/18 inspection, Additional silt fence was installed around the lot to replace the original silt fence that was not entrenched/backfilled. Additional silt fence was installed and existing silt fence was re-enforced prior to the 8/16/18 inspection. During the 9/3/18 inspection, most of the silt fence had been removed for retaining wall installation, and sediment was going off-site. Silt fence had been reinstalled prior to the 9/6/18 inspection, and attempts to remove off-site sediment were apparent. The E&A inspector will continue to monitor. Additional silt fence was installed around the lot prior to the 10/11/18 inspection. The homeowners (Nygren) installed silt fence along the west side of the lot prior to inspection on 4/15/19. The homeowners (Nygren) removed portions of the old silt fence on the western side of the lot prior to inspection on 4/15/19. The portable toilet was removed prior to inspection on 7/23/19. 1) The old run of silt fence around the lot need to be repaired and gaps need to be closed. 2) Accumulated sediment needs to be removed from the golf course. 3) New run of silt fence along the west side of the lot needs to be repaired near retaining wall 4) The old run of silt fence on the east side of the lot should be reinstalled or removed 1) Homeowners (Nygren) were informed to complete by 11/8/18. Not done as of the last inspection. The inspector met with the builder on site and discussed recommendations for the lot during inspection on 3/15/19. Homeowners (Nygren) were reminded on 6/06/19, 8/15/19 2) Homeowners (Nygren) were informed to complete by 11/2/18. Not done as of the last inspection. The inspector met with the builder on site and discussed recommendations for the lot during inspection on 3/15/19. Homeowners (Nygren) were informed to complete by 4/22/19. Not done as of last inspection. Homeowners (Nygren) were info				
	, ,	ninded on 6/06/19, 8/15/	19	_	
Lot 129	Silt Fence	Lot 129	o Let 100 Coo Let 100	Removed	
Current Condition: Lot 130	Individual Lot	s incorrectly identified a Lot 130	S LOT 129. See LOT 130.	Removed	
Current Condition:			ot prior to inspection on 5/2		
1,1107			· ·		
Lot 137 Current Condition:	Individual Lot	Lot 137	 d the lot and removed the	Removed	ant let prier te
current condition.	inspection on 8/1	•	a the lot and removed the	Silt Hom the aujac	ent lot prior to
Lot 138	Individual Lot	Lot 138		Removed	
Current Condition:		ome Company remov	ed the portable toilet and	sodded the lot pri	or to inspection on
	8/13/19.				
Lot 154	Silt Fence	Lot 154		Removed	
Current Condition:			ded the lot prior to the inspe	ction on 9/3/18 and	installed silt fence on
1 -4 455	<u> </u>	rotect the new sod.	0/0/0040	I A -45	NI-
Lot 155 Current Condition:	Silt Fence	Lot 155	9/3/2018 s installed silt fence on the	Active	No No lot 154 prior to
Current Condition.	inspection on 9/3/		s installed slit leffee on the	iot to protect soude	a lot 134 prior to
Lot 157	Silt Fence	Lot 157		Removed	
Current Condition:			the lot during the 11/26/18		
Lot 197	Silt Fence	Lot 197		Removed	
Current Condition:	Permanent	41°02'43.47"N	odded the lot prior to the 7/2	26/18 inspection.	
PDP A	Detention Pond	96°20'36.65"W	In Place	Active	No
Current Condition:		This is a pond as of 199	3.		
SB 1	Sediment Basin	Lot 109		Removed	d - b 1 14 d 4
Current Condition:			tion, this structure is no long uppears to be an area inlet/s		
SF 3	Silt Fence	Lot 197		Removed	
Current Condition:			ence during the inspection		
SF 5	Silt Fence	South side of lake		Removed	
Current Condition: SF 8	Silt Fence	1 40' South of SF 5	ence during the inspection	Removed	
Current Condition:			ence during the inspection		
		East of Lots 119 and			
SF 9	Silt Fence	120	In Place	Active	Yes
Current Condition:			partially removed the silt for		tion on 12/5/17. The
	sediment was removed from the golf course and cart path prior to inspection on 4/29/19. The silt fence is full and needs to be cleaned behind lots 114 and 115. Boyer Young was informed to complete by 3/24/18. Not done as of last inspection. Boyer Young was reminded on 6/28/18, 9/24/18, 3/19/19, 6/06/19, 8/15/19				
SF 10	Silt Fence Behind Lot 190 12/5/2018 Active No				
Current Condition:	Good Condition - 3	A will monitor.	kenly removed from the rep	ort in July, however	it is still in place and in
етр	Ctroots	41°02'28.55"N	In Diage	Active	N ₀
STR Current Condition:	Streets Good Condition - N	96°20'36.35"W	In Place re observed during the last i	Active	No
Guitent Condition:	10000 Condition - I	to algina of trackout Wel	C CD3CI VCG GGIIIIG IIIE IASI I	nopeouon.	

SWPPP Sign	SWPPP Sign	Two signs on site	8/8/2008	Active	No
Current Condition:	Good Condition - A sign has been installed at Iron Horse Drive and Hwy 6. South Lakeview Way & South Be Road entrance. The sign at the South Lakeview Way and South Bend Road entrance was visible again due the surrounding grass being mowed prior to inspection on 7/02/19. The SWPPP sign by Hwy 6 and Iron Hor Drive had been knocked over prior to inspection on 7/23/19. E&A inspector reinstalled the downed SWPPP during inspection on 7/23/19.				
Inspector Signature:				Reviewed By:	Get Sul